


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5185L
Ref. No : TAX/01/18/2091
Reg. Date : 01/11/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : MOHAMED RAMZAN BIN MOHD DALI
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 16/01/2018 08:30:00 AM
Accident Reported Date / Time : 16/01/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094122
Special Instruction to ARC,if any :
SKE1728X - AXA
Prepared Date : 16/01/2018 01:58:21 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FUX03573209

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	676.00	0.00
Total Spray Painting Charges :	1,314.00	0.00
Total Material Charges :	5,663.68	5,663.68
Other Charges :	340.00	0.00
TOTAL :	7,993.68	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	5.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	16/01/2018 05:08:47 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 16/01/2018 05:08:47 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	676.00	0.00
Total Labour	676.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00
TO REPSRAY FRONT HOOD	378.00	0.00
TO RESPRAY FRONT FENDER LH	378.00	0.00
Total Spray Painting & Panel Beating	1,314.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	340.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5211947962			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace	No
5212847906			COVER, FR BUMPER LH	1	28.10	25.00	21.07	Replace	Replace	No
5310147080			GRILLE SUB-ASSY	1	335.60	25.00	251.70	Replace	Replace	No
8118547691			UNIT, HEADLAMP , LH	1	2,558.90	10.00	2,303.01	Replace	Replace	No
8122047020			LAMP ASSY, FOG, LH	1	910.20	10.00	819.18	Replace	Replace	No
5211647050			SUPPORT, FR BUMPER LH	1	82.30	25.00	61.72	Replace	Replace	No
5321447050			SUPPORT, RADIATOR UPPER LH	1	76.70	25.00	57.52	Replace	Replace	No
1656337010			SEAL, RADIATOR TO LH	1	24.80	25.00	18.60	Replace	Replace	No
5320347901			SUPPORT S/A LH	1	237.00	25.00	177.75	Replace	Replace	No
5261147140			ABSORBER, FR BUMPER	1	70.30	25.00	52.72	Replace	Replace	No
5330147110			HOOD SUB-ASSY	1	938.40	25.00	703.80	Replace	Replace	No
5341047130			HINGE ASSY, HOOD, RH	1	57.00	25.00	42.75	Replace	Replace	No
5342047130			HINGE ASSY, HOOD, LH	1	57.00	25.00	42.75	Replace	Replace	No
5380247100			FENDER SUB-ASSY, FR , LH	1	933.10	25.00	699.82	Replace	Replace	No
7537447140			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	No
TOTAL MATERIALS							5,663.72	5,663.68		
TOTAL MATERIALS(Discounted)							5,663.68	5,663.68		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									