



Automotive Pte Ltd

Main Office
Mova Building
No. 22, Jalan Kilang
Singapore 159411
Tel : (65) 6476 3333
Fax : (65) 6271 589
www.mova.com.sg

Workshop Dept
Block 1008
Bukit Merah Lane 3
#01-04/06/08/9
Singapore 159727

Tel : (65) 6272 3894
Fax : (65) 6270 8314
Co. Reg. 198904033C
GST Reg. M2-0088864-7

Estimate

16/01/2018

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Attention :- XA039

Page # :- 1

Veh # :- SKB9800H

Veh Model :- BMW 523i

Estimate# :- CK416925

Claim # :-

ACC. Date :- 13/01/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT BUMPER	1 PC	1,398.00 DE	1,398.00
2.	FRONT BUMPER LOGO	1 PC	90.00 na	90.00
3.	FRONT BUMPER GRILLE LH	1 PC	130.00 su	130.00
4.	FRONT BUMPER GRILLE RH	1 PC	130.00 su	130.00
5.	FRONT CENTER PARKING SENSOR	2 PC	265.00 au	1,060.00
6.	FRONT BUMPER LOWER GRILLE	1 PC	80.00 DE	80.00
7.	FRONT FOG LAMP COVER RH	1 PC	125.00 DE	125.00
8.	FRONT FOG LAMP COVER LH	1 PC	125.00 DE	125.00
9.	FRONT WASHER JET COVER RH - CHECK	1 PC		
10.	FRONT WASHER JET RH - CHECK	1 PC		
11.	FRONT BUMPER SPONGE	1 PC	65.00 ?	65.00
12.	FRONT BUMPER REINFORCEMENT	1 PC	736.00 ?	736.00
13.	FRONT BUMPER CLIPS	10 PC	3.00 na	30.00
14.	FRONT BUMPER UNDER COVER - CHECK	1 PC		
15.	FRONT RADIATOR AIR GUIDE	1 PC	405.00 ?	405.00
16.	A/C CONDENSER	1 PC	1,250.00 ?	1,250.00
17.	RADIATOR - CHECK	1 PC		
18.	HEADLAMP LH	1 PC	2,827.00 ?	2,827.00
19.	HEADLAMP RH	1 PC	2,827.00 ?	2,827.00
20.	HEADLAMP PANEL LH	1 PC	155.00 ?	155.00
21.	HEADLAMP PANEL RH	1 PC	155.00 ?	155.00
22.	FRONT SUPPORT FR PANEL	1 PC	188.00 ?	188.00
23.	FRONT BRACE PANEL LH	1 PC	25.00 ?	25.00
24.	FRONT BRACE PANEL RH	1 PC	25.00 ?	25.00
25.	FRONT FENDER TOP GARNISH RH	1 PC	115.00 X	115.00
26.	FRONT FENDER TOP GARNISH CLIPS	10 PC	3.00 X	30.00
27.	BOOTLID	1 PC	1,715.00 BT	1,715.00
28.	BOOTLID LOGO	1 PC	75.00 na	75.00
29.	BOOTLID EMBLEM (523i)	1 PC	78.00 na	78.00
30.	BOOTLID REFLECTOR LAMP LH - CHECK	1 PC		
31.	BOOTLID LOCK	1 PC	245.00 BT	245.00
32.	BOOTLID WEATHERSTRIP	1 PC	130.00 na	130.00
33.	REAR BUMPER	1 PC	1,585.00 DE	1,585.00
34.	REAR BUMPER CENTER BRACKET	1 PC	105.00 ?	105.00
35.	REAR BUMPER ADAPTER	1 PC	88.00 ?	88.00
36.	REAR BUMPER CENTER LOWER GUIDE	1 PC	103.00 ?	103.00
37.	REAR BUMPER RETAINER LH	1 PC	168.00 X	168.00
38.	REAR BUMPER RETAINER RH	1 PC	168.00 X	168.00
39.	REAR BUMPER REINFORCEMENT	1 PC	258.00 ?	258.00
40.	REAR REVERSE SENSOR	2 PC	265.00 na	1,060.00
41.	REAR END PANEL - CHECK	1 PC		
42.	REAR END PANEL TOP GARNISH	1 PC	155.00 ?	155.00
43.	HEADREST LH	1 PC	1,158.00 AC	1,158.00
44.	HEADREST RH	1 PC	1,158.00 AC	1,158.00
45.	SEATBELT BUCKLE LH	1 PC	388.00 AC	388.00
46.	SEATBELT BUCKLE RH	1 PC	388.00 AC	388.00

price?

price?
1 PC repair kit
1 PC photo
1 PC photo



Automotive Pte Lt

Main Office

Mova Buildin
No. 22, Jalan Kilang
Singapore 15941
Tel : (65) 6476 333
Fax : (65) 6271 589
www.mova.com.s

Workshop Dep

Block 1001
Bukit Merah Lane :
#01-04/06/08/9
Singapore 15972

Tel : (65) 6272 389
Fax : (65) 6270 831

Co. Reg. 198904033
GST Reg. M2-0088864-

Estimate

16/01/2018

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Attention :- XA039

Page # :- 1 130519

Veh # :- SKB9800H

Veh Model :- BMW 523I

Estimate# :- CK416925

Claim # :-

ACC. Date :- 13/01/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	LIST TOTAL SS			20,996.00
	5% DISCOUNT SS			-1,049.80
				19,946.20
	SPECIAL NET ITEMS :			
1.	TOWING CHARGE	1 PC	88.00	88.00 70
2.	FRONT NUMBER PLATE	1 PC	40.00	40.00 40
3.	RADIATOR COOLANT	1 PC	20.00	20.00 20
	SPECIAL NET TOTAL SS			148.00
	LABOUR :			
	TO CUT/WELD REAR END PANEL. TO KNOCK & STRAIGHTEN FRONT CHASSIS LH & RH, REAR CHASSIS LH & RH, BONNET, REAR FLOOR PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. TO REALIGN ALL CONNECTION			1000 1,450.00
	TO SPRAY PAINT ON BONNET, FRONT BUMPER, REAR BUMPER, BOOTLID, REAR END PANEL			800 1,100.00
	REMOVE AND REPLACE A/C CONDENSER, A/C PIPE, A/C HOSE AND RADIATOR			100 140.00
	TO REMOVE AND REPLACE SEAT BELT BUCKLES & HEADREST			100 180.00
	TO DIAGNOSE & REPROGRAM AFTER REPAIR			100 300.00
	TO APPLY SEAL ON WELDING JOINT			X 80.00
	TO APPLY RUST PROOF ON AFFECTED AREAS			80 120.00
	TO REMOVE AND REPLACE FRONT AND REAR PARKING SENSOR AND CHECK FUNCTION WELL			80.00
	TO REMOVE AND REFIX REAR LUGGAGE COMPARTMENT TRIM			80 180.00
	LABOUR TOTAL SS			3,630.00



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

16/01/2018

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Attention :- XA039

Page # :- 1 130519

Veh # :- SKB9800H

Veh Model :- BMW 523i

Estimate# :- CK416925

Claim # :-

ACC. Date :- 13/01/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 23,724.20

GST @ 7 % 1,660.69

AMOUNT DUE S\$ 25,384.89

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
10 days
43
18/01/18 @ 1720
Resy after repair