

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD5127U - EQ

AAD1801-172

Not Authored
Running By paint

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 5127U - JHOW
 VF1ABL15AUC283357
 RENAULT
 LATITUDE
 15.01.2018
EQ

		PART		LIST
1	1	BUMPER COVER REAR	\$	B 1,108.46 —
2	1	BUMPER LOWER REAR	\$	B 768.84 —
3	1	BUMPER BRACKET CTR REAR	\$	D 113.47 —
4	1	BUMEPR BRACKET SIDE LH REAR	\$	S 135.97 X
5	1	BUMEPR BRACKET CTR LH REAR	\$	S 44.99 X
6	1	BUMEPR BRACKET SIDE RH REAR	\$	S 135.97 X
7	1	BUMEPR BRACKET CTR RH REAR	\$	D 44.99 —
8	1	BUMPER BEAM REAR	\$	B 777.52 —
9	1	BUMPER BEAM BRACKET LH REAR	\$	R 225.95 X
10	1	BUMPER BEAM BRACKET RH REAR	\$	B 225.95 —
11	1	BUMPER REFLECTOR LH	\$	S 43.61 X
12	1	BUMPER REFLECTOR RH	\$	B 43.61 —
13	1	BOOT REAR	\$	B 2,872.68 —
14	2	BOOT RUBBER PLUG	\$	S 221.81 X
15	1	BOOT FINISHER	\$	C 470.06 —
16	1	BOOT SWITCH	\$	S 168.13 X
17	1	BOOT TRIM BOARD	\$	S 914.87 X
18	1	BOOT LOCK	\$	D 202.67 —
19	1	BOOT LOCK CATCH	\$	R 74.40 X
20	1	BOOT LOCK LINKAGE	\$	S 34.53 X
21	1	BOOT LOCK LINKAGE HOLDER	\$	S 154.52 X
22	1	BOOT LOCK CATCH TRIM BOARD	\$	S 249.24 X
23	1	BOOT WHEATERSTRIP	\$	S 323.05 X
24	1	BOOT REFLECTOR LAMP LH	\$	C 493.35 —
25	1	BOOT REFLECTOR LAMP RH	\$	C 493.35 —
26	1	BOOT BADGE 'RENAULT'	\$	A 225.36 —
27	1	BOOT BADGE	\$	A 225.36 —
28	1	BOOT STRUT LH	\$	S 276.08 X
29	1	BOOT STRUT RH	\$	S 276.08 X
30	1	BOOT HINGE LH	\$	D 367.84 —
31	1	BOOT HINGE RH	\$	B 367.84 —
32	2	LICENCE PLATE LAMP	\$	S 50.52 X
33	1	WINDSCREEN REAR	\$	S 1,463.28 X
34	1	WINDSCREEN GARNISH INNER LH	\$	S 263.74 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-172**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5127U - EQ

35	1	WINDSCREEN GARNISH INNER RH	\$	Sm	263.74 X
36	1	TAILLAMP LH	\$	Sm	552.55 X
37	1	TAILLAMP PANEL LH	\$	R	986.70 X
38	1	TAILLAMP RH	\$	CM	552.55 ✓
39	1	TAILLAMP PANEL RH	\$	Ry	986.70 ✓
40	1	CHASSIS PANEL REAR RH	\$	R	3,766.43 X
41	1	FENDER PANEL REAR LH	\$	R	3,299.13 X
42	1	FENDER PANEL REAR RH	\$	Bu	3,299.13 ✓
43	1	WHEELARCH REAR LH	\$	Sm	543.47 X
44	1	WHEELARCH REAR RH	\$	Sm	543.47 X
45	1	FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45 X
46	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	R	3,039.04 X
47	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88 X
48	1	SPARE WHEEL PANEL TRIM (Luggage Floor Panel)	\$	Sm	612.21 X
49	1	SPARE WHEEL PANEL BRACKET LH	\$	R	123.73 X
50	1	SPARE WHEEL PANEL BRACKET RH	\$	R	121.36 X
51	1	OUTER PANEL REAR (End Panel)	\$	Ry	1,471.77 ✓
52	1	OUTER PANEL REAR (End Panel)TRIM	\$	Rd	401.02 ✓
53	1	EXHAUST REAR	\$	Ry	7,489.05 ✓
54	1	EXHAUST CAP REAR	\$	Ry	230.49 ✓
55	1	EXHAUST MOUNTING REAR	\$	Sm	31.97
56	1	EXHAUST BRACKET REAR	\$	R	39.86
57	1	EXHAUST HEAT SHIELD REAR	\$	R	99.06
58	1	SHIELD - HEAT - TUNNEL	\$	R	225.16
59	1	DOOR PANEL REAR LH	\$	R	2,844.66
60	1	DOOR SEAL REAR LH	\$	Sm	187.08
61	1	DOOR PANEL REAR RH	\$	R	2,844.66
62	1	DOOR SEAL REAR RH	\$	Sm	162.02

TOTAL	\$	51,436.47
10%	\$	5,143.65
	\$	46,292.82

Specical Nett

1	1SET	BUMPER RR CLIP	\$	Na	66.00 ✓
2	1SET	BUMPER BEAM BOLT	\$	na	22.22 X
3	1SET	PARKING AID	\$	Short	600.00 ✓
4	1	BUMPER BRACKET CLIP CTR REAR	\$	na	15.00 X
5	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	na	12.00 X
6	1	BUMEPR RETAINER CLIP LH REAR	\$	Na	10.40 X
7	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	na	12.00 X
8	1	BUMEPR RETAINER CLIP RH REAR	\$	na	10.40 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-172**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5127U - EQ

9	1	CAP HUB LH RR	\$	Sn	35.00	
10	1	RIM LH RR	\$	Sn	385.00	
11	1	TYRE LH RR	\$	Sn	330.00	
12	1	CAP HUB RH RR	\$	Sn	35.00	
13	1	RIM RH RR	\$	Sn	385.00	
14	1	TYRE RH RR	\$	Sn	330.00	
15	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	
16	1	SPARE TYRE	\$	Sn	330.00	
17	1SET	BOOT FINISHER CLIP	\$	na	25.10	
18	1	Rear boots sticker "trans-cab"	\$	na	30.00	
19	1	Rear boots sticker "6555-3333"	\$	na	30.00	
20	1	FENDER PANEL INNER TRIM CLIP REAR RH	\$	na	22.00	X
21	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	na	22.00	X
22	1SET	WHEELARCH CLIP LH RR	\$	na	32.34	X
23	1SET	WHEELARCH CLIP RH RR	\$	na	32.34	X
24	2	Rear windscreen sealant	\$	Spec	80.00	Yes
25	1	Windscreen moulding	\$	na	100.00	
26	1	Rear Windscreen Inner Sponge Seal	\$	na	100.00	Yes
27	1	EXHAUST MOUNTING REAR	\$	Sn	65.50	X
28	1	EXHAUST BRACKET REAR	\$	n	22.22	X
29	1SET	Rear licence plate with holder	\$	Sn	80.00	X
30	1	DOOR STICKER "6555-3333" LH	\$	na	80.00	X
31	1	DOOR STICKER "6555-3333" RH	\$	na	80.00	X

TOTAL	\$	3,764.52
TOTAL PARTS	\$	50,057.34

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 5,400.00 ¹²⁰⁰

Towing Fees.

\$ na 120.00 X

To apply paint protection system (PPS) maintain and enhancement

\$ na 380.00 X

Putty and spray painting of the affected portion.

\$ 5,600.00 ⁸⁰⁰

To rust-proofing of the affected areas.

\$ 170.00 ⁹⁰⁰

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 ¹⁰⁰⁰

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-172**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5127U - EQ

To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 601
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of tailgate fittings and conduct water seepage test.	\$	170.00 601
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00 120
To reinstall rear bumper parking sensor.	\$	170.00 601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00
To repair and realign rear exhaust pipe.	\$	170.00

} 801

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5127U - EQ**AAD1801-172**

To drop rear axle assy, remove and renewal of the
necessary parts

\$ *nn* 380.00 *X*

TOTAL \$ **16,190.00**

Over All Total \$ **66,247.34**

< parts by parts > Repair Days

~~20~~ DAYS

8 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: