



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32291

EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

DATE : 29/12/2017
CLAIM NO. : 11082
POLICY NO. : AVFMSB0000621700
FROM : RAYMOND

VEHICLE NO. : FBK9036G
MAKE/MODEL : YAM / YBR125

N.F. Akmal
hir
P/P
to be phd after up
17/1/18
4 day.

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER SIDE RH (BLACK) P/N: 53724	REPLACE	1.00	\$78.00	647 78.00
2	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	\$90.00	647 90.00
3	COVER TAIL RH (RED) P/N: 45138	REPLACE	1.00	\$85.00	647 85.00 X
4	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	647 195.00
5	FOOT REST 1 P/N: 50005	REPLACE	1.00	\$55.00	647 55.00
6	FOOTREST REAR ASSY LH P/N: 25348	REPLACE	1.00	\$15.00	647 15.00
7	FOOTREST REAR ASSY RH P/N: 25347	REPLACE	1.00	\$12.00	647 12.00
8	HEADLIGHT ASSY P/N: 50950	REPLACE	1.00	\$320.00	647 320.00 X
9	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.		5.00	\$35.00	160 175.00
10	LAMP SIGNAL FRONT LH P/N: 43433	REPLACE	1.00	\$21.00	647 21.00
11	LAMP SIGNAL REAR LH P/N: 44190	REPLACE	1.00	\$21.00	647 21.00
12	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$19.00	647 19.00 X
13	LEVER CLUTCH P/N: 26342	REPLACE	1.00	\$19.00	647 19.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERTIFICATE 2012-10-03
ISO 9001:2008

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
14	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$200.00	Svc 200.00 X
15	MIRROR LH P/N: 26137	REPLACE	1.00	\$15.00	Cut 15.00 ✓
16	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$98.00	Cut 98.00 ✓
17	PROTECTOR EXHAUST P/N: 50024	REPLACE	1.00	\$120.00	cre 120.00 ✓
18	PROTECTOR EXHAUST CAP P/N: 50006	REPLACE	1.00	\$56.00	Cut 56.00 ✓
19	RIM SPORT FRONT P/N: 45153	REPLACE	1.00	\$275.00	n 275.00 X
20	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	2.00	\$14.00	70.00 ✓
21	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	Scr 12.00 10
22	TRANSPORT CHARGES P/N: 07169		2.00	\$35.00	35 70.00
23	VISOR P/N: 43130	REPLACE	1.00	\$30.00	Scr 30.00 ✓

SUB TOTAL

\$2,009.00

GST @ 7 %

\$140.63

GRAND TOTAL

\$2,149.63

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

