

ASS. REC. BY:

REF: QBE1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 09 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S11D 97385 Yr Regn: 12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitude c.c. 1835

Colour: n. white / R / AC: Insured / Std / NI / NA

Sp. Reading: 360069 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABL15AUC 276143

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 13/1/18 D.O.I. 16/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/1 File pass to Catherine

5/4 11 Reg 66502 Confirm Tazmin (4+1/2 x 99.32 + 275)

1/11V listing

L/S - \$6650 (Red \$30389.52 / 826)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS \$

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/QBE18001049/Kwb3		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 17-01-2018		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 631D	Veh. Inspected	SHD 9738E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/01/2018	Inspection Date	16/01/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS. WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/QBE18001049/Kwb3

Date: 17.01.2018

The Motor Claims Department
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD9738E

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16.01.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	37,039.32
Revised Estimate Amount	: S\$	6,650.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9738E - QBE**AAD1801-159***Not Authorised
11/1/2018 8 6650*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD9738E - CANDY
VF1ABL15AUC276143
RENAULT
LATITUDE
13.01.2018
QBE

PART			LIST	
1	1	BUMPER COVER FRT	\$	Sum 1,259.42 X
2	1	BUMPER RETAINER FRT LH	\$	Sum 151.41 X
3	1	BUMPER BRACKET FRT LH	\$	Sum 181.75 X
4	1	HEADLAMP LH	\$	Sum 1,184.43 X
5	1	HEADLAMP PANEL FRT LH	\$	R 152.15 X
6	1	FENDER PANEL FRT LH	\$	R 783.83 X
7	1	FENDER BRACKET FRT LH	\$	R 34.14 X
8	1	WHEELARCH FRT LH	\$	Sum 278.84 X
9	1	DOOR PANEL FRT LH	\$	Ry 2,844.66 ✓
10	1	DOOR HINGE UPPER LH	\$	R 274.50 X
11	1	DOOR HINGE LOWER LH	\$	R 300.55 X
12	1	DOOR CHECK FRT LH	\$	Sum 194.77 X
13	1	DOOR LOCK FRT LH	\$	Tm 908.75 ✓
14	1	DOOR CATCH FRT LH	\$	R 131.23 X
15	1	DOOR HANDLE OUTER FRT LH	\$	CRM 258.12 ✓
16	1	DOOR HANDLE CAP FRT LH	\$	Sum 26.44 X
17	1	DOOR HANDLE SEAL FRT LH	\$	Sum 7.89 X
18	1	DOOR HANDLE COVER FRT LH	\$	Sum 13.22 X
19	1	DOOR HANDLE MODULE FRT LH	\$	Sum 133.60 X
20	1	DOOR REGULATOR FRT LH	\$	Ry 505.19 ✓
21	1	DOOR REGULATOR MOTOR FRT LH	\$	Tm 796.46 ✓
22	1	DOOR REGULATOR GUIDE FRT LH	\$	Sum 120.97 X
23	1	DOOR FINISHER FRT LH	\$	Sum 515.06 X
24	1	DOOR MOULDING FRT LH	\$	Bu 176.82 ✓
25	1	DOOR GRAB HANDLE FRT LH	\$	Sum 210.96 X
26	1	DOOR MIRROR LH	\$	CRM 1,483.40 ✓
27	1	DOOR MIRROR GLASS LH	\$	Sum 148.20 X
28	1	DOOR MIRROR BACK COVER LH	\$	Sum 218.46 X
29	1	DOOR WHETHERSTRIP FRT LH	\$	Sum 474.21 X
30	1	DOOR SEAL FRT LH	\$	Sum 68.67 X
31	1	DOOR SEAL LOWER FRT LH	\$	Sum 105.18 X
32	1	DOOR WAIST SEAL OUTER FRT LH	\$	Sum 291.27 X
33	1	ROCKER PANEL OUTER LH	\$	R 987.49 X
34	1	DOOR PANEL REAR LH	\$	R 2,844.66 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-159**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9738E - QBE

35	1	DOOR GUIDE REAR LH	\$	176.82	}
36	1	DOOR HINGE UPPER LH	\$	315.74	
37	1	DOOR HINGE LOWER LH	\$	300.55	
38	1	DOOR CHECK REAR LH	\$	203.06	
39	1	DOOR SEAL RR LH	\$	75.54	
40	1	DOOR GRAB HANDLE REAR LH	\$	210.96	
41	1	DOOR HANDLE OUTER REAR LH	\$	126.49	
42	1	DOOR HANDLE CAP REAR LH	\$	35.52	
43	1	DOOR HANDLE SEAL REAR LH	\$	7.89	
44	1	DOOR HANDLE COVER REAR LH	\$	13.22	
45	1	DOOR HANDLE MODULE REAR LH	\$	133.60	
46	1	DOOR FINISHER REAR LH	\$	423.10	
47	1	DOOR MOULDING REAR LH	\$	176.82	
48	1	DOOR WHEATHESTRIIP REAR LH	\$	474.60	
49	1	DOOR SEAL REAR LH	\$	187.08	
50	1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69	
51	1	FENDER PANEL REAR LH	\$	3,299.13	
52	1	WHEELARCH REAR LH	\$	543.47	
53	1	TAILLAMP PANEL LH	\$	986.70	}
54	1	TAILLAMP LH	\$	552.55	
55	1	BUMPER COVER REAR	\$	1,108.46	
56	1	BUMEPB BRACKET SIDE LH REAR	\$	135.97	
57	1	BUMEPB RETAINER LH REAR	\$	44.99	

TOTAL	\$	27,933.69
10%	\$	2,793.37
	\$	25,140.32

Special Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	66.00	X
3	1	RIM LH FRT	\$	385.00	X
4	1	TYRE LH FRT	\$	330.00	X
5	1	DOOR STICKER "Trans-cab"	\$	80.00	60.00
6	1	DOOR STICKER "Classic"	\$	30.00	15.00
7	1	DOOR STICKER "6555-3333"	\$	80.00	60.00
8	2	Rear Windscreen Sealant	\$	100.00	X
9	1	Rear Windscreen Inner Sponge Seal	\$	150.00	X
10	1SET	WHEELARCH CLIP RR LH	\$	66.00	X
11	1	FENDER FINISHER COVER CLIP REAR LH	\$	20.00	X
12	1SET	REAR BUMPER CLIP	\$	66.00	X
13	1SET	BUMEPB RETAINER LH CLIP RR	\$	20.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-159**

NO 2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9738E - QBE

TOTAL	\$	1,459.00
TOTAL PARTS	\$	26,599.32

To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00 <i>600</i>
Putty and spray painting of the affected portion.	\$	4,500.00 <i>1100</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>22</i> 380.00 <i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>22</i> 170.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>22</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>22</i> 220.00 <i>X</i>
Towing fees	\$	<i>22</i> 120.00 <i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>22</i> 170.00 <i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>1200</i>
To rust-proofing of the affected areas.	\$	170.00 <i>600</i>

TOTAL	\$	10,440.00
Over All Total	\$	37,039.32

(PARTS BY PARTS) Repair Days**15 Days**

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD9738E
Vehicle to be Exported:	Yes
Intended De-registration Date:	15 Jan 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000758
Chassis No.:	VF1ABL15AUC276143
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	04 Dec 2013
First Registration Date:	04 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Dec 2021
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	03 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$62,740.00
COE Rebate Amount:	\$30,452.00
Total Rebate Amount:	\$39,825.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Jan 2018

OK

Shu Pei (LKKAuto)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Thursday, 18 January 2018 9:12 AM
To: Shu Pei (LKKAuto)
Cc: Admin A; Vivian Lau (LKKAuto); Joy Irene (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018
Attachments: GBE631D.pdf

Our Ref. VC011080

Dear Shu Pei

Attached OI Gia report for your attention.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 17 January, 2018 5:48 PM
To: Joyce Foo <joyce.foo@qbe.com>
Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Subject: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018

WITHOUT PREJUDICE

Dear Sir /Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHD 9738E at M/s Trans-cab Auto Services Pte Ltd.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Hsiao Tong (LKKAUTO)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Tuesday, 8 January 2019 3:23 PM
To: Vivian Lau (LKKAUTO); Admin A; Joy Irene (LKKAUTO)
Subject: FW: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018
Attachments: GBE631D.pdf

Our Ref. VC011080

Hi

Please advise status of the claim and let us have your report soon.

Thanks & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Joyce Foo
Sent: Thursday, 18 January 2018 9:11 AM
To: 'Shu Pei (LKKAUTO)' <shupeil@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>; Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018

Our Ref. VC011080

Dear Shu Pei

Attached OI Gia report for your attention.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAuto) [<mailto:shupeai@lkkauto.com>]
Sent: Wednesday, 17 January, 2018 5:48 PM
To: Joyce Foo <joyce.foo@qbe.com>
Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Joy Irene (LKKAuto) <joyirene@lkkauto.com>
Subject: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018

WITHOUT PREJUDICE

Dear Sir /Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHD 9738E at M/s Trans-cab Auto Services Pte Ltd.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeai@lkkauto.com | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the

intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

To : Jia LE

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1801-159

Your Ref : GBE631D

Date : 12.September 2019

QBE INSURANCE INT'L LTD

Dear Sir/Madam,

**ACCIDENT INVOLVING SHD9738E AND GBE631D ON 13/01/18 04:25 AM ALONG
JALAN TOA PAYOH TOWARDS BENDEMEER ROAD**

It appears that the above accident was caused by your insured's negligence. We, therefore, seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	7,115.50
2.	Loss of Rental for <u>5.5</u> days @ <u>\$99.33</u> per day	\$	546.26
3.	Loss of Income for <u>5.5</u> days @ <u>\$50</u> per day	\$	275.00
4.	LTA Search Fee	\$	7.45
5.	Survey Fee	\$	0.00
	Total	\$	7,944.21

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)



Auto
Consultants
Pte Ltd

51 UBI AVE L, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/QBE18001049/Kwb3

23 January 2018

NKH Building Services Pte Ltd

75 Geylang bahru

#01-2896/8

Singapore 339683

Dear Sir/Madam,

ACCIDENT INVOLVING GBE 631D & SHD 9738E ON 13/01/2018

We refer to the above accident where we are acting for QBE Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 06/02/2018, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau

Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c. *QBE Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act


We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHD9738E and GBE631D along JALAN TOA PAYOH TOWARDS BENDEMEER ROAD on 13/01/18 04:25 AM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 12 (day) of September 2019

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan
General Manager

DISCHARGE VOUCHER

Without Prejudice
Save As to CostsYour Reference : AAD1801-159
Our Reference : VC011080

I/We, **TRANS-CAB SERVICES PTE LTD** do hereby acknowledge the sum of Singapore Dollars: **THREE THOUSAND NINE HUNDRED ONLY (S\$3,900.00)** being full discharge and satisfaction of all claims against QBE Insurance (Singapore) Pte Ltd and their Insured, '**NKH BUILDING SERVICES PTE LTD**', over damage to my/our vehicle **SHD 9738E** from an accident involving **GBE 631D** at/along **JALAN TOA PAYOH TOWARDS BENDEMEER ROAD**, which occurred on **13/01/2018** at about **04:25hours**.

Further, I/we hereby acknowledge and accept that the above said sum paid to me is 'strictly on a without admission of liability basis' and I/we hereby discharge and release the said QBE Insurance (Singapore) Pte Ltd and their Insured '**NKH BUILDING SERVICES PTE LTD**', from all claims, demands or action of damages as a result of the said accident.

Also, I/we hereby agree to indemnify and keep indemnified the said QBE Insurance (Singapore) Pte Ltd against all and any claims whatsoever made or to be made by any person or persons on my/our behalf in respect of the said accident.

Dated this (day) 24 of (month) SEP (year) 2019

Signature

Ng Wai Yin
G2815702P

Claimant's Name

FIN/NRIC No.

TRANS-CAB SERVICES PTE LTDNo. 2 Ang Mo Kio Street 63
Singapore 569111

Tel: 6287 5555 Fax: 6287 7704

Address



Company stamp if applicable

Witness's Signature

Witness's Name

FIN/NRIC No.

TRANS-CAB SERVICES PTE LTDNo. 2 Ang Mo Kio Street 63
Singapore 569111

Address

Please return to:
General Claims Department
QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay
#29-10 South Tower
Singapore 048583
Fax: 6534 5356

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO: QBE INSURANCE (SINGAPORE) PTE LTD 60 Anson Road #11-01 079914 Singapore ATTENTION:	INVOICE NO. : INV1909-061 DATE : 13. September 2019 REFERENCE NO : AAD1801-159 TERMS : DUE DATE : 13. September 2019 PAGE : 1
---	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
		Invoice No. INV1801-139:			
1	6050101	REPAIR-SHD9738E;DOA 13.01.18(LUMP SUM-18)	1	7,115.50	7,115.50

Total SGD Excl. GST :	6,650.00
7% GST :	465.50
Total SGD Incl. GST :	7,115.50

****** SEVEN THOUSAND ONE HUNDRED FIFTEEN AND FIFTY SGD ONLY ******

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.**THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE**

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

12 September, 2019

To Whom It May Concern

Dear Sir / Madam,

Accident on 13/01/18 04:25 AM at JALAN TOA PAYOH TOWARDS BENDEMEER ROAD

1. We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the registered owner of the taxi bearing vehicle registration no. SHD9738E. The taxi was hired to CHOONG YIN SHIN a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$99.32 per day (inclusive of GST).
2. Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan
General Manager

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

13-01-2018

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.
Accident No.	AAD1801-159	Accident Date 13-01-2018
13/1/2018 05:30	18/1/2018 17:30	SHD9738E

Yours Faithfully,

Trans-Cab Services Pte Ltd**Jasmine Tan****General Manager**

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
GY6657B	13 Jan 2018 / 22:00:00	NTUC INCOME INS CO-OP LTD
SLL3375T	13 Jan 2018 / 18:30:00	NTUC INCOME INS CO-OP LTD
PC1404G	15 Jan 2018 / 03:30:00	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
GBE681D	13 Jan 2018 / 04:25:00	QBE INSURANCE (SINGAPORE) PTE LTD

[Print](#)[OK](#)[Save as PDF](#)

Jia Le (LKK Auto)

From: Janice Goh Siew Geok <janice.goh@qbe.com>
Sent: Tuesday, 17 September 2019 4:23 PM
To: Jia Le (LKK Auto)
Subject: RE: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kdb3) on 13.01.2018

Hi Jia Le

Refer to our tele-conversation earlier.
You have confirmed that insured agreeable to settle at 50:50.

Please proceed to offer as per recommendation at 50% - \$3,938.50.
Thank you.

Janice Goh

Executive, Claims

Claims | Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6477 1243

Website LinkedIn Twitter



From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Sent: Friday, 13 September 2019 2:04 PM
To: Janice Goh Siew Geok <janice.goh@qbe.com>
Subject: RE: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kdb3) on 13.01.2018

Your ref : **VC011080**

Our ref : CC3/QBE18001049/Kdb3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING GBE 631D(OI) & SHD 9738E(TP) ON 13/01/2018

We refer to the above matter.

We are of the opinion that this is a case of **conflicting versions**. There is no conclusive evidence to substantiate either's parties version. We propose the settlement at 50/50.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer **"TRANS-CAB AUTO SERVICES PTE LTD"** at **\$3,938.50(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 39,632.03	\$ 7,115.50
2. Loss of Rental (5.5days x \$99.32)	\$ 546.26	\$ 496.60 (5days x \$99.32)
3. Loss of Income (5.5days x \$50)	\$ 275.00	\$ 250.00 (5days x \$50)
		\$ 7,862.10
@50%		\$ 3,931.05
4. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$10,404.33	\$ 3,938.50

**04 days recommendation for repair + 1Sun = 5days.

Enclosed here with all the relevant documents for your perusal.

For your approval/instruction please.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Goh Siew Geok [<mailto:janice.goh@qbe.com>]

Sent: Tuesday, 30 July, 2019 2:53 PM

To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018

Hi Vivian

We have received an email from TP claimant, Trans-cab. Please refer to the attachment.

Please update us on the status.

Thank you.

Janice Goh

Executive, Claims

Claims | Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6477 1243

Website: [LinkedIn](#) [Twitter](#)



From: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Sent: Monday, 8 April 2019 4:01 PM

To: Joyce Foo <joyce.foo@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018

Dear Joyce,

We refer to the above matter.

Please be informed that we are pending LOD from TP repairer to seek your mandate approval

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo [<mailto:joyce.foo@qbe.com>]

Sent: Thursday, 4 April, 2019 8:23 AM

To: Shu Pei (LKKAuto) <shupe@lkkauto.com>

Cc: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018

Our Ref. VC011080

Hi

Please advise status of the claim and let us have your report ASAP.

Thanks & Best Regards

Joyce Foo

Senior Assistant

Claims Dept/Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 64771184 | +65 62246633

Website LinkedIn Twitter



From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Sent: Tuesday, 8 January 2019 5:00 PM

To: Joyce Foo <joyce.foo@qbe.com>

Cc: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: FW: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018

Dear Sirs/Mdm,

Thank you for your email.

We will look into the matter and get back to you.

By copy to Hsiao Tong,

Case reassign to you.

Best Regards,

Shu Pei Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo <joyce.foo@qbe.com>

Sent: Tuesday, 8 January 2019 3:23 PM

To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Subject: FW: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018

Our Ref. VC011080

Hi

Please advise status of the claim and let us have your report soon.

Thanks & Best Regards

Joyce Foo

Senior Assistant - Claims

QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd

Phone: +65 6477 1184

Email: joyce.foo@qbe.com

Visit us on the web at www.qbe.com.sg



From: Joyce Foo

Sent: Thursday, 18 January 2018 9:11 AM

To: 'Shu Pei (LKKAuto)' <shupeil@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018

Our Ref. VC011080

Dear Shu Pei

Attached OI Gia report for your attention.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Wednesday, 17 January, 2018 5:48 PM

To: Joyce Foo <joyce.foo@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBE631D (OI : QBE - TBA) and SHD9738E (TP : LKK REF - CC3/QBE18001049/Kwb3) on 13.01.2018

WITHOUT PREJUDICE

Dear Sir /Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHD 9738E at M/s Trans-cab Auto Services Pte Ltd.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank you.

Best Regards,

Shu Pei Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

----- IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/QBE18001049/Kdb3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 14-10-2019



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 631D	Veh. Inspected	SHD 9738E
Policy No.	8-V0013686-MVA-R001	Coverage (\$)	0.00
Claim No.	VC011080	Excess (\$)	0.00
Assign From		Assign Date	16/01/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC276143	Colour	METALLIC WHITE / RED
Odometer	560069	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	LING LONG	7 mm
L/H Front Tyre	215/60 R16	LING LONG	7 mm
R/H Rear Tyre	215/60 R16	LING LONG	7 mm
L/H Rear Tyre	215/60 R16	LING LONG	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/01/2018	Inspection Date	16/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9738E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT	SERVICEABLE	1,259.42	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER BRACKET FRT LH	SERVICEABLE	181.75	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	FENDER BRACKET FRT LH	TO REPAIR SEE LABOUR	34.14	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	DOOR PANEL FRT LH	BENT	2,844.66	2,844.66
1	DOOR GUIDE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT LH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT LH	JAMMED	908.75	908.75
1	DOOR CATCH FRT LH	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE OUTER FRT LH	CRACKED	258.12	258.12
1	DOOR HANDLE CAP FRT LH	SERVICEABLE	26.44	-
1	DOOR HANDLE SEAL FRT LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER FRT LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT LH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT LH	BENT	505.19	505.19
1	DOOR REGULATOR MOTOR FRT LH	JAMMED	796.46	796.46
1	DOOR REGULATOR GUIDE FRT LH	SERVICEABLE	120.97	-
1	DOOR FINISHER FRT LH	SERVICEABLE	515.06	-
1	DOOR MOULDING FRT LH	BUCKLED	176.82	176.82
1	DOOR GRAB HANDLE FRT LH	SERVICEABLE	210.96	-
1	DOOR MIRROR LH	CRACKED	1,483.40	1,483.40
1	DOOR MIRROR GLASS LH	SERVICEABLE	148.20	-

Report Ref No. CC3/QBE18001049/Kdb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR MIRROR BACK COVER LH	SERVICEABLE	218.46	-
1	DOOR WEATHERSTRIP FRT LH	SERVICEABLE	474.21	-
1	DOOR SEAL FRT LH	SERVICEABLE	68.67	-
1	DOOR SEAL LOWER FRT LH	SERVICEABLE	105.18	-
1	DOOR WAIST SEAL OUTER FRT LH	SERVICEABLE	291.27	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	987.49	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR LH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	315.74	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH	TO REPAIR SEE LABOUR	203.06	-
1	DOOR SEAL RR LH	SERVICEABLE	75.54	-
1	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR LH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR LH	SERVICEABLE	176.82	-
1	DOOR WEATHERSTRIP REAR LH	SERVICEABLE	474.60	-
1	DOOR SEAL REAR LH	SERVICEABLE	187.08	-
1	DOOR WAIST SEAL OUTER REAR LH	SERVICEABLE	334.69	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	-

Report Ref No. CC3/QBE18001049/Kdb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
	LESS 10% DISCOUNT		-2,793.37	-697.34
			25,140.28	6,276.06
	<u>SPECIAL NETT ITEMS</u>			
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	66.00	-
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	RIM LH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN)	SERVICEABLE	330.00	-
1	DOOR STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	60.00
1	DOOR STICKER 'CLASSIC' (SN)	NECESSARY	30.00	15.00
1	DOOR STICKER '6555-3333' (SN)	NECESSARY	80.00	60.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	150.00	-
1	SET WHEELARCH CLIP RR LH (SN)	NOT NECESSARY	66.00	-
1	FENDER FINISHER COVER CLIP REAR LH (SN)	SERVICEABLE	20.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET BUMPER RETAINER LH CLIP RR (SN)	NOT NECESSARY	20.00	-
			1,459.00	135.00
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL FRT LH,FENDER PANEL FRT LH,FENDER BRACKET FRT LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER LH,DOOR CATCH FRT LH,ROCKER PANEL OUTER LH,DOOR PANEL REAR LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER LH, DOOR CHECK REAR LH,FENDER PANEL REAR LH,TAILLAMP PANEL LH AND BUMPER COVER REAR .		4,200.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	1,100.00
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CC3/QBE18001049/Kdb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	120.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
			10,440.00	1,900.00
GRAND TOTAL			37,039.28	8,311.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,650.00

Report Ref No. CC3/QBE18001049/Kdb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.