

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD9738E - QBE

AAD1801-159

Not Authen
11/1/18 @ 66501

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD9738E - CANDY
 VF1ABL15AUC276143
 RENAULT
 LATITUDE
 13.01.2018
QBE

		PART		LIST
1	1	BUMPER COVER FRT	\$	Sn 1,259.42 X
2	1	BUMPER RETAINER FRT LH	\$	Sn 151.41 X
3	1	BUMPER BRACKET FRT LH	\$	Sn 181.75 X
4	1	HEADLAMP LH	\$	Sn 1,184.43 X
5	1	HEADLAMP PANEL FRT LH	\$	R 152.15 X
6	1	FENDER PANEL FRT LH	\$	R 783.83 X
7	1	FENDER BRACKET FRT LH	\$	R 34.14 X
8	1	WHEELARCH FRT LH	\$	Sn 278.84 X
9	1	DOOR PANEL FRT LH	\$	R 2,844.66 ✓
10	1	DOOR HINGE UPPER LH	\$	R 274.50 X
11	1	DOOR HINGE LOWER LH	\$	R 300.55 X
12	1	DOOR CHECK FRT LH	\$	Sn 194.77 X
13	1	DOOR LOCK FRT LH	\$	Tm 908.75 ✓
14	1	DOOR CATCH FRT LH	\$	R 131.23 X
15	1	DOOR HANDLE OUTER FRT LH	\$	CRM 258.12 ✓
16	1	DOOR HANDLE CAP FRT LH	\$	Sn 26.44 X
17	1	DOOR HANDLE SEAL FRT LH	\$	Sn 7.89 X
18	1	DOOR HANDLE COVER FRT LH	\$	Sn 13.22 X
19	1	DOOR HANDLE MODULE FRT LH	\$	Sn 133.60 X
20	1	DOOR REGULATOR FRT LH	\$	R 505.19 ✓
21	1	DOOR REGULATOR MOTOR FRT LH	\$	Tm 796.46 ✓
22	1	DOOR REGULATOR GUIDE FRT LH	\$	Sn 120.97 X
23	1	DOOR FINISHER FRT LH	\$	Sn 515.06 X
24	1	DOOR MOULDING FRT LH	\$	Bu 176.82 ✓
25	1	DOOR GRAB HANDLE FRT LH	\$	Sn 210.96 X
26	1	DOOR MIRROR LH	\$	CRM 1,483.40 ✓
27	1	DOOR MIRROR GLASS LH	\$	Sn 148.20 X
28	1	DOOR MIRROR BACK COVER LH	\$	Sn 218.46 X
29	1	DOOR WHETHERSTRIP FRT LH	\$	Sn 474.21 X
30	1	DOOR SEAL FRT LH	\$	Sn 68.67 X
31	1	DOOR SEAL LOWER FRT LH	\$	Sn 105.18 X
32	1	DOOR WAIST SEAL OUTER FRT LH	\$	Sn 291.27 X
33	1	ROCKER PANEL OUTER LH	\$	R 987.49 X
34	1	DOOR PANEL REAR LH	\$	R 2,844.66 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9738E - QBE**AAD1801-159**

35	1	DOOR GUIDE REAR LH	\$	Sn	176.82	}
36	1	DOOR HINGE UPPER LH	\$	R	315.74	
37	1	DOOR HINGE LOWER LH	\$	R	300.55	
38	1	DOOR CHECK REAR LH	\$	R	203.06	
39	1	DOOR SEAL RR LH	\$	Sn	75.54	
40	1	DOOR GRAB HANDLE REAR LH	\$	Sn	210.96	
41	1	DOOR HANDLE OUTER REAR LH	\$	Sn	126.49	
42	1	DOOR HANDLE CAP REAR LH	\$	Sn	35.52	
43	1	DOOR HANDLE SEAL REAR LH	\$	Sn	7.89	
44	1	DOOR HANDLE COVER REAR LH	\$	Sn	13.22	
45	1	DOOR HANDLE MODULE REAR LH	\$	Sn	133.60	
46	1	DOOR FINISHER REAR LH	\$	Sn	423.10	
47	1	DOOR MOULDING REAR LH	\$	Sn	176.82	
48	1	DOOR WHEATHESTRIIP REAR LH	\$	Sn	474.60	
49	1	DOOR SEAL REAR LH	\$	Sn	187.08	
50	1	DOOR WAIST SEAL OUTER REAR LH	\$	Sn	334.69	
51	1	FENDER PANEL REAR LH	\$	R	3,299.13	
52	1	WHEELARCH REAR LH	\$	Sn	543.47	
53	1	TAILLAMP PANEL LH	\$	R	986.70	
54	1	TAILLAMP LH	\$	Sn	552.55	
55	1	BUMPER COVER REAR	\$	R	1,108.46	}
56	1	BUMEPR BRACKET SIDE LH REAR	\$	Sn	135.97	
57	1	BUMEPR RETAINER LH REAR	\$	Sn	44.99	

TOTAL	\$	27,933.69
10%	\$	2,793.37
	\$	25,140.32

Specical Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	na	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	na	66.00	X
3	1	RIM LH FRT	\$	Sn	385.00	X
4	1	TYRE LH FRT	\$	Sn	330.00	X
5	1	DOOR STICKER "Trans-cab"	\$	me	80.00	60sn
6	1	DOOR STICKER "Classic"	\$	na	30.00	15sn
7	1	DOOR STICKER "6555-3333"	\$	na	80.00	60sn
8	2	Rear Windscreen Sealant	\$	na	100.00	X
9	1	Rear Windscreen Inner Sponge Seal	\$	na	150.00	X
10	1SET	WHEELARCH CLIP RR LH	\$	na	66.00	X
11	1	FENDER FINISHER COVER CLIP REAR LH	\$	Sn	20.00	X
12	1SET	REAR BUMPER CLIP	\$	na	66.00	X
13	1SET	BUMEPR RETAINER LH CLIP RR	\$	na	20.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9738E - QBE**AAD1801-159**

TOTAL	\$	1,459.00
TOTAL PARTS	\$	26,599.32

To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00 <i>600</i>
Putty and spray painting of the affected portion.	\$	4,500.00 <i>1100</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
Towing fees	\$	<i>nn</i> 120.00 <i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>1201</i>
To rust-proofing of the affected areas.	\$	170.00 <i>601</i>

TOTAL	\$	10,440.00
Over All Total	\$	37,039.32

(PARTS BY PARTS) Repair Days**15 Days**

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: