

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD147U -

AAD1801-163

Not Authored
Revised By paim

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD147U - CANDY
 VF1ABL15AUC282253
 RENAULT
 LATITUDE
 15.01.2018
CHINA TAIPING

PART			LIST	
1	1	BUMPER COVER FRT	\$	CN 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	211 181.75 ✓
3	1	BUMPER ABSORBER FRT	\$	CN 394.68 ✓
4	1	BUMPER RETAINER FRT LH	\$	DI 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	SL 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	SL 150.77 X
7	1	BUMPER SUPPORT FRT	\$	SL 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	DI 472.83 ✓
9	1	BUMPER GRILLE LOWER FRT	\$	DI 266.80 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	SL 207.21 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	SL 207.21 X
12	1	BUMPER BEAM FRT	\$	B 914.08 ✓
13	1	TOW COVER FRT	\$	SL 28.61 X
14	1	RADAITOR GRILLE	\$	CN 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	CN 225.36 ✓
16	1	RADAITOR GRILLE FRAME	\$	CN 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	CN 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	R 89.79 X
19	1	FRONT BRACE PANEL	\$	R 177.22 X
20	1	HORN	\$	SL 314.17 X
21	1	HORN BRACKET	\$	R 40.45 X
22	1	HEADLAMP LH	\$	DI 1,184.43 ✓
23	1	HEADLAMP RH	\$	DI CN 1,184.43 ✓
24	1	HEADLAMP PANEL FRT LH	\$	R 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	R 152.15 X
26	1	BONNET	\$	B 1,941.63 ✓
27	1	BONNET INSULATOR	\$	SL 405.73 X
28	1	BONNET STRUT LH	\$	SL 88.61 X
29	1	BONNET STRUT RH	\$	SL 88.61 X
30	1	BONNET HINGE LH	\$	R 348.31 X
31	1	BONNET HINGE RH	\$	R 348.31 X
32	1	BONNET LOCK	\$	DI 305.48 ✓
33	1	BONNET CABLE	\$	SL 119.19 X
34	1	BONNET CABLE COVER	\$	SL 161.03 X

35	1	BONNET SEAL OUTER	\$	S ₂	92.36	}	X
36	1	BONNET SEAL INNER	\$	S ₂	157.28		
37	1	FENDER PANEL FRT LH	\$	R	783.83		
38	1	FENDER PANEL FRT RH	\$	R	783.83		
39	1	WHEELARCH FRT LH	\$	S ₂	278.84		
40	1	WHEELARCH FRT RH	\$	S ₂	278.84		
41	1	FENDER BRACKET LOWER LH	\$	S ₂	15.79		
42	1	FENDER BRACKET LOWER RH	\$	S ₂	15.79		
43	1	FENDER INSULATOR LH	\$	S ₂	130.84		
44	1	FENDER INSULATOR RH	\$	S ₂	130.84		
45	1	WIPER RESERVOIR	\$	S ₂	348.25	}	X
46	1	WIPER RESERVOIR NECK	\$	S ₂	136.11		
47	1	WIPER RESERVOIR MOTOR	\$	S ₂	270.06		
48	1	AIR CLEANER LOWER	\$	S ₂	271.26		
49	1	AIR CLEANER HOSE	\$	S ₂	76.14		
50	1	STEERING PUMP ELECTRIC	\$	S ₂	2,306.90		
51	1	A/C CONDENSER	\$	S ₂	2,020.37		
52	1	A/C CONDENSER GARNISH LH UPPER	\$	S ₂	39.67		
53	1	A/C CONDENSER GARNISH RH UPPER	\$	S ₂	39.67		
54	1	A/C CONDENSER GARNISH LH	\$	S ₂	58.81		
55	1	A/C CONDENSER GARNISH RH	\$	S ₂	59.60	}	X
56	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	S ₂	208.39		
57	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	S ₂	658.72		
58	1	A/C PIPE COMPRESSOR	\$	S ₂	334.29		
59	1	A/C PIPE	\$	S ₂	658.72		
60	1	A/C COMRPRESSOR	\$	S ₂	2,684.61		
61	1	AIR COOLER	\$	S ₂	792.60		
62	1	AIR INTERCOOLER HOSE (LONG)	\$	S ₂	1,014.13		
63	1	AIR INTERCOOLER HOSE (Short)	\$	S ₂	375.14		
64	1	TRANSMISSION COOLER	\$	S ₂	1,219.30		
65	1	TRANSMISSION COOLER PAD	\$	S ₂	17.96	}	X
66	1	RADIATOR	\$	S ₂	1,202.20		
67	2	RADIATOR STUD UPPER	\$	S ₂	14.41		
68	2	RADIATOR BUSH UPPER	\$	S ₂	50.12		
69	2	RADIATOR MTG LOWER	\$	S ₂	55.85		
70	1	RADAITOR FAN COWLING	\$	S ₂	820.54		
71	1	RADIATOR FAN MOTOR LH	\$	S ₂	967.36		
72	1	RADIATOR FAN MOTOR RH	\$	S ₂	1,479.46		
73	1	RADIATOR TANK	\$	S ₂	324.62		
74	1	RADIATOR HOSE UPPER	\$	S ₂	240.56		
75	1	RADIATOR HOSE LOWER	\$	S ₂	491.18	}	X
76	1	RADIATOR TANK HOSE	\$	S ₂	61.18		

TOTAL	\$	37,453.43
10%	\$	3,745.34
	\$	33,708.09

Specical Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00	}
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	
7	1	TOW COVER FRT	\$	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
13	1SET	WHEELARCH CLIP FRT LH	\$	30.50	}
14	1SET	WHEELARCH CLIP FRT RH	\$	29.40	
15	1	CAP HUB LH FRT	\$	35.00	
16	1	RIM LH FRT	\$	385.00	
17	1	TYRE LH FRT	\$	330.00	
18	1	CAP HUB RH FRT	\$	35.00	
19	1	RIM RH FRT	\$	385.00	
20	1	TYRE RH FRT	\$	330.00	
21	1SET	Front licence plate with holder	\$	80.00	450
22	1	DOOR STICKER "6555-3333" LH	\$	80.00	X
23	1	DOOR STICKER "6555-3333" RH	\$	80.00	X

TOTAL	\$	2,182.40
TOTAL PARTS	\$	35,890.49

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 5,400.00 *500*

Towing Fees.

\$ 120.00 *50*

To apply paint protection system (PPS) maintain and enhancement

\$ 380.00 *X*

Putty and spray painting of the affected portion.

\$ 5,600.00 *600*

To rust-proofing of the affected areas.	\$	170.00 <i>30</i>
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	<i>22</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>22</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>22</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>20</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>22</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 <i>100</i>
To replace, refix and top up coolant for radiator	\$	170.00 <i>50</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 <i>50</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>22</i> 170.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>22</i> 440.00 X

TOTAL	\$	14,320.00
Over All Total	\$	50,210.49

< parts by parts > Repair Days

~~20 DAYS~~
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: