



**Main Office :** No. 22, Jalan Kilang, Singapore 159419  
Tel: 6476 3333 Fax: 6271 5891

**Service Centre :** Block 1008, Bukit Merah Lane 3,  
#01-04/06/08/115, Singapore 159722  
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0088864-2

**Mova Spray Centre**  
2K Oven Spray Painting System

**Power-M Automotive Pte Ltd**  
Specialise In Car Air-con Services,  
Car Audio & Hi-Fi System.

**Hilton Car Rental Centre**

**Hilton Auto Trading**

Dealing In New/Used Cars, Hire Purchase & Insurance.



**TP INSURER:** India International Insurance Pte Ltd (HQ)  
**UNKNOWN**

Singapore

**Claimant Insurer:** AIG Asia Pacific Insurance Pte. Ltd.

#### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	05/01/2018
Vehicle Reg. No.:	SGD6008K	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	MARK SEOW CHOW KEN		
Make/Model:	BMW 325CI, 2.5 CABRIOLET (A)	Vehicle Reg. Date:	14/10/2009
Vehicle Colour:	BLUE	Chassis No:	WBAWL12040PD76695
Engine No:	13107205N52B25AF		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	5.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

*Tanpin 91495745  
WP  
Cumpsum 4 days  
Resurvey after repair  
sur @ Kluang*

#### COST OF CLAIMS

#### Amount

Parts	1,453.50
Miscellaneous Items	10.00
Labour	1,770.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>3,233.50</b>
<b>+ GST 7.00% (S\$)</b>	<b>226.35</b>
<b>Nett Amount (S\$)</b>	<b>3,459.85</b>

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 15 Jan 2018)**Parts:** N/A BMW 325CI 2.5 Cabriolet (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SGD6008K)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RH DOOR	5.00	0.00	*1,350.00 FL
2	1		*RH DOOR RUBBER	5.00	0.00	*130.00 FL
3	10		*RH DOOR RIVET	5.00	0.00	*50.00 FL
4	1		*R/R FENDER - REPAIR	5.00	0.00	-
5	1		*RH ROCKER GARNISH - REPAIR	5.00	0.00	-
Sub Total (\$\$)						1,530.00
- List Item Discount on L Items (\$\$)						76.50
Total Parts (\$\$)						1,453.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	✓ 10.00
Sub Total (\$\$)			10.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR REAR FENDER RH. ROCKER GARNISH RH, TO REMOVE AND REFIX DAMAGED PARTS. TO STRAIGHTEN AND REALIGN AFFECTED AREAS	New	500 700.00
2	TO SPRAY REAR FENDER RH, DOOR RH ROCKER PANEL RH. FRONT FENDER RH AND AFFECTED AREAS	New	600 800.00
3	TO REMOVE AND REFIX DOOR MECHANISM CHECK & TEST POWER WINDOW MOTOR AND CENTER LOCKING SYSTEM	New	*40 80.00
4	TO REST SRS SYSTEM	New	100 150.00
5	TO RUST PROOF AFFECTED AREAS	New	30 40.00
Gross Labour Cost (\$\$)			1,770.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >