REF:	
Sinveyor:	SSIGNMENT
£ 33	2013 Sept
From: Date:	
Estimated Cost:	Type McCar M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Meredes Benz E2501 00 1991
at Workshop m/s	Colour Silver A/C: Insured / Std / NI / NA
of	Sp.Reading 104936. T/Radio: Insured / Std / NI / NA
Insured:	Eng/No: WDD2120362A787985,
Policy No.	0.110
Claims No.	Gen. Cond: 6000 / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S/Rim) / STD A/Rim or
4	Tyre Size: F: 265/35 R18 -
(Policy Condition)	R: 265/35P18
	D/S BS / DUN / EXNOVA / GY / FS / LIZA (MIC) OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 96 mm L/Bal. 06 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 18/01/18
Lum Sum: % 3 Val.: Yes or No	Survey held at Torque 5.
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / OS / N/S / U/C / Rooftop or
Vehicle: IN /	OUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
77 Alg.	
,	
3	
	- 1,18°
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
Final Danast	Resurvey No. of Trip: Survey Fee:
1) : Final Report Date/Time, File Return to?	Transportation
	# Fee: Site Insp (\$)S+RSSI
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$:Weekend (\$

.