

REF:

CC3 / ALN 18001064 / Acd3e2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 2100510210

Claims No. 6043922658 56

Sum Insured:

Excess: \$1000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

190K.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

35 days

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLQ724M.

V. Regn:

2017 Jne

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q5

cc 1984

Colour:

White

A/C

Insured / Std / NI / NA

Sp. Reading

21732

T. Radio

Insured / Std / NI / NA

Eng No:

C/No:

WAUZZ2FY3H2022AT3

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R19.

R:

235/55R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

OK

mm

R/Bal.

OK

mm

L/Bal.

OK

mm

L/Bal.

OK

mm

D.O.A.

D.O.I.

17/01/18

Survey held at

Premium.

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

OD A/G.

18/1/18 Sent preli through nximen

22/1/18 Author's repair & inform repair proceed to repair.

MV 190K

PV: 84.3K

Net: 105.7K

SLQ 724M - X

28/3 10:14am Confirmed final by 873,302,64 and 35 days with Carine. (Red 34,632,66,332)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

35

1)

☐

: Final Report

Resurvey No. of Trip:

1

Survey Fee:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Invs: \$

☐

Weekend: \$

Report Format:

00

Lump Sum / 100:

100:

873,302,64

Transistor:

34,632,66

Rooftop:

Times:

200

11

211



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18001064/Arb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-01-2018	
Code : AIG			
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.	Veh. Inspected		SLQ 724M
Policy No. 2100510210	Coverage (\$)		0.00
Claim No.	Excess (\$)		0.00
Assign From	Assign Date		17/01/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No. HIDDEN	Year of Reg.		
Chassis No.	Colour		
Odometer -	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/01/2018	Inspection Date	17/01/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Celine Fong (LKKAUTO)

From: Celine Fong (LKKAUTO)
Sent: Thursday, 28 March 2019 10:14 AM
To: 'Boo seng yak'; Adrian Ling (LKKAUTO); SUR; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SLQ724M - OD AIG - SURVEYED 17 JAN 18

Dear Carrine,

Confirm repair cost of \$73,302.64 @ 35 days of repairs.

Kindly send us Invoice and Discharge Voucher for us to close file.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Tuesday, 12 February 2019 4:24 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SLQ724M - OD AIG - SURVEYED 17 JAN 18

Hi Adrian and all,

Revised estimate, Car O liner report is attached. Photographs can be obtained from our Ubi office.

Please confirm repair cost of \$73,302.64 @ 81 days of repairs exclude 13 Sundays and 3 Public Holiday.

Your early closure is well appreciated.

Best regards - jb

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Wui, Shawn-KJ

Date: 18 Jan 2018

Preliminary Advice

Vehicle No	: SLQ724M	Accident Date	: 09/01/2018
Make	: AUDI Q5	Policy No.	: 2100510210
Assignment Date	: 17/01/2018	Excess	: S\$0.00
Date of Inspection	: 17/01/2018	Est. Duration of Repair	: 28.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident. The undercarriage affected due to collision

Repairer's Estimate (Gross)	:S\$	97,370.00
Revised Amount	:S\$	53,561.00
Check Items (Estimated)	:S\$	25,306.00
Total	:S\$	78,867.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	190,000.00
COE / PARF Rebate	:S\$	84,330.00
Salvage Value	:S\$	
Margin for Repair	:S\$	105,670.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

***SLQ724M (6043922658SG)**

OD

Jan 9 2018 2:50PM

[CHUA NGEOK YIN]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 18/01/2018 17:34 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$78867.00) - SLQ724M - Claim Handler: Chan, Kian Meng

Approved:78867.00:to commence repairs, Check items and supplementary to be quantified with damaged photographs to reconfirm replacement of front windscreen to facilitate replacement of roof lining.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, January 22, 2018 8:51 AM
To: 'Claims Dept'
Cc: SUR
Subject: RE: SLQ 724 M Own Damage Claims

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLQ 724M (excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Saturday, January 20, 2018 5:31 PM
To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; claims@premiumauto.com.sg
Subject: RE: SLQ 724 M Own Damage Claims

Dear all,

Kindly assist in the approval for this case.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Janice Lee (LKKAuto) [<mailto:JaniceLee@lkkauto.com>]
Sent: Thursday, 18 January, 2018 1:42 PM
To: Claims Dept <claims@premiumauto.com.sg>; Carrine Leong <carrine.leong@premiumauto.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLQ 724 M Own Damage Claims

Dear Carrine,

As spoken with Alan, please provide the repair manual for the removal of the front windscreen in order to replace roof liner.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler (on behalf Adrian)

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]
Sent: Wednesday, January 17, 2018 2:32 PM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: SLQ 724 M Own Damage Claims

Dear all,

Kindly assist in the approval for the above mentioned vehicle.

Survey was carried out earlier this morning.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Janice Lee (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Monday, June 25, 2018 11:42 AM
To: Varsha.Paramchand@aig.com; SUR
Cc: JoycelineCH.Quek@aig.com; Nurashikin.Mutalip@aig.com; kianmeng.chan@aig.com;
Subject: Admin A; assignments; CS A Team
RE: - SID 12680448 & CLAIM NO 6043922658SG - INSD DISPUTE ON THE OD CLAIM
AMT
Attachments: SLQ 724M.pdf

Dear Sir / Madam,

Thank you for your email.

Dear Janice,

Kindly assist. Our Ref: CC3/AIG18001064/Arb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Paramchand, Varsha [<mailto:Varsha.Paramchand@aig.com>]

Sent: Monday, 25 June 2018 10:36 AM

To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: Quek, Joyceline-CH <JoycelineCH.Quek@aig.com>; Mutalip, Nurashikin <Nurashikin.Mutalip@aig.com>; Chan, Kian Meng <KianMeng.Chan@aig.com>

Subject: RE: - SID 12680448 & CLAIM NO 6043922658SG - INSD DISPUTE ON THE OD CLAIM AMT



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

Your password will expire in 14 days. [Click here to change it.](#)

RE: - SID 12680448 & CLAIM NO 6043922658SG - INSD DISPUTE ON THE OD CLAIM AMT

From: Paramchand, Varsha
To: CS A Team, Admin A
Cc: Quek, Joyceline-CH; Mutalip, Nurashikin, Chan, Kian Meng
Sent: Monday, 25 June, 2018 10:36:12 AM

Hi LKK,

Any updates?
Tq

Varsha

- According to repairer, they had address
insurer contact. no further issue

Repairer has spoken to insurer
for the repair cost. There is a
no further issue

From: Paramchand, Varsha
Sent: Tuesday, June 12, 2018 4:54 PM
To: CS A Team; Admin A
Cc: Quek, Joyceline-CH; Mutalip, Nurashikin; Chan, Kian Meng
Subject: aigencrypt - SID 12680448 & CLAIM NO 6043922658SG - INSD DISPUTE ON THE OD CLAIM AMT

Hi LKK,

Insd asking why the amt is so high & disputing. Insd needs more details on the OD claim. Appreciate if you can ctc insd & advise accordingly @ 96529099.

tq

Varsha

From: Paramchand, Varsha [mailto:cl.svc.amb2@aig.com]
Sent: Tuesday, June 12, 2018 4:50 PM
To: Paramchand, Varsha
Subject: SID 12680448 & CLAIM NO 6043922658SG - INSD DISPUTE ON THE OD CLAIM AMT

Referral & Escalation Form

Staff: Paramchand, Varsha
Vehicle number : SLQ724M
Third Party Vehicle number:
Type of Claim:
Type of Account:
Policy number : 2100510210
Policy Holder Name : Chua Ngeok Yin
Caller Name : Chua Ngeok Yin
Claims Amount :

Contact Number : 96529099

Fax:

Email : chua_ng@wansearn.com.sg

Service Description:Renewal - Inquiry

HI LKK,

Insd asking why the amt is so high & disputing. Insd needs more details on the OD claim.
Appreciate if you can ctc insd & advise accordingly
tq

Varsha

**** Entered By: SSPNUA (Abdullah, Nur-Aishah) @ 12/06/2018 04:32 PM ****

Hi Claims,

Please assist to check about claims amount

Insured disputing that claims amount is too high

Insured only remember the claims amount should be few thousand only but until \$78k+++

Insured want to get more details about this claim

Insured request if there is any report to support this claims amount

Insured want to renew under AIG but need more details for the claim amount :

O00096399 2018/01/09 00:00:00 Chain Reaction AUTOMOBILE Own Damage - Not Total Loss SGD
78,867.00 O 100 CHUA NGEOK YIN

Please advice

Thanks

Powered by Onyx Software. Please do not remove the following text as it helps us to serve you better.

[[-1808281.2722921--]]

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7053B
Vehicle Details	
Vehicle No.:	SLQ724M
Vehicle to be Exported:	Yes
Intended De-registration Date:	17 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	Q5 SPORT 2.0 TFSI QU S TRONIC (PSR)
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	DAX005220
Chassis No.:	WAUZZZF3H2022473
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$46,410.00
Original Registration Date:	27 Jun 2017
First Registration Date:	27 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$56,974.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2027
PARF Rebate Amount:	\$42,730.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jun 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$41,600.00
Total Rebate Amount:	\$84,330.00


The information contained herein is correct as at 17 Jan 2018

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SLQ724M
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1:	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	AUDI
Vehicle Model :	Q5 SPORT 2.0 TFSI QU S TRONIC (PSR)
Chassis No. :	WAUZZZF3H2022473
Propellant :	Petrol
Engine No. :	DAX005220
Engine Capacity :	1984 cc
Maximum Power Output :	185.0 kW (248 bhp)
Maximum Laden Weight :	2400 kg
Unladen Weight :	1795 kg
Year Of Manufacture :	2017
Original Registration Date :	27 Jun 2017
Lifespan Expiry Date :	-
COE Category :	E - Open - all except motorcycle
Quota Premium :	\$52,000.00
COE Expiry Date :	26 Jun 2027

https://vrl.lta.gov.sg/lta/vrl/action/enquireTransferFeeDetailsProxy?FUNCTION_ID=... 09/01/2018



TEL: (65) 6471-1060
FAX: (65) 6471-1371

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1989
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1989 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100510210-00000

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$1000.00 (1)
WINDSCREEN EXCESS S\$100.00

(For policies with effect from 1st November 2007)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes
SLQ724M

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

CHUA NGEOK YIN

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

27 Jun 2017

4) DATE OF EXPIRY OF INSURANCE

26 Jun 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

SUBJECT TO AGE CONDITION: All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the insured's business.
The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Briddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Elhoz - 30 Bukit Balok Cres (Tel: 66547777) 5. Glass-Flx - 52 Ubi Ave 3 (Tel: 62780687) - For windscreen only

6. Kan Fook Sing Motor - 61 Delu Lane 12 (Tel: 67479560) 7. Lai Hui (Mang Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Nova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67416336)

10. SME Motor - 1 Kall Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER

NA

HIRE PURCHASE COMPANY United Overseas Bank Limited
EMPLOYER'S LOAN

Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 65 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 14 Jul 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-223
PREMIUM LEASING - SH
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORIZED REPRESENTATIVE

PCLTY



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/01/2018 19:15
Date Of Accident	09/01/2018 14:50
Exact Location Of Accident	GELANG PATAH NUSA CEMERLANG IND PARK
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ724M
Insured/Policyholder	
Name Of Registered Owner	CHUA NGEOK YIN
NRIC No	S1727053B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96529099
Alternative Phone No	HOME-96529099
Vehicle Particulars	
Manufacturer	AUDI
Model	Q5 SPORT 2.0 TFSI QU STRONIC (PSR)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100510210
Cover Note Number	

Driver	
Name of Driver	CHUA NGEOK YIN
NRIC No	S1727053B
Date Of Birth	18/03/1965
Occupation	INDOOR
Date Of Driving Pass	16/12/2013
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96529099
Fax Number	
Contact Number	HOME-96529099
Email Address	NOEMAIL

Address JALAN LENGKOK SEMBAWANG SINGAPORE 759240
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES
 Foreign Vehicle Registration Number JQJ4691 (PRIVATE CAR)
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] TRAFIK ISKANDAR PUTERI
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number JQJ4691
 Vehicle Make/Model/Colour NISSAN
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 09/01/18

GIA/SEC SketchPlanForm_7.2

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/PIN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report -


Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE** WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.


☐	- Reporting Only
☐	- Claim OD
☐	- Claim TP
☒	- Claim <u>OD</u> TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.


 Policyholder's signature
 Date & Time 09/01/18
 19:30pm

 Driver's Signature
 (If driver not the policyholder)
 Date & Time


 Reporting Centre Personnel's Signature
 Name: _____
 Nric/Fin No. _____

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR ACCIDENT INTERVIEW FORM

NAME (DRIVER) : Chua Ngeok Yin
VEHICLE NUMBER : SLW 724M
DATE/TIME OF ACCIDENT : 09/01/2018, 2.50pm
PLACE OF ACCIDENT : Malaysia, gelang patch
THIRD PARTY VEHICLE (IF ANY) : JQJ 4691

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

From Singapore to Malaysia: To travel to Malaysia factory for a visit.

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT IS THE RESULT?


NO.

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

HEAD TO REAR COLLISION : DAMAGE TO THE REAR PORTION.

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

No.


Name: Chua Ngeok Yin.

I Affirmed The Above Information Is Given To My Best Knowledge.



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : TRAFIK ISKANDAR PUTERI
 Daerah : ISKANDAR PUTERI
 Kontinjen : JOHOR
 No Repot : TRAFIK IPUTERI/000333/18
 Tarikh : 09/01/2018
 Waktu : 1607 PM
 Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R175641

Butir-butir Penerima Repot

Nama : MUHAMAD FAHMI BIN ABDUL MANAF
 Butir-butir Jurubahasa (Jika Ada)
 Nama : —
 No Pasport : —
 Alamat : —

No Personel : R194525

Pangkat : KONST/P

No K/P (Baru) : —

No Polis/Tentera : —

Bahasa Asal : —

Butir-butir Pengadu

Nama : CHUA NGEOK YIN

No K/P (Baru) : —

No Polis/Tentera : —

No Pasport : S1727053B

No Sijil Beranak : —

Jantina : Lelaki

Tarikh Lahir : 18/03/1965

Umur : 52 tahun 9 bulan

Keturunan : Cina

Warganegara : Singapore

Pekerjaan : SWASTA

Alamat Tempat Tinggal : 59 JALAN LENGKOK SEMBAWANG SINGAPURA, 759240

Alamat Ibu/Bapa : —

Alamat Pejabat : —

No Tel (Rumah) : —

No Tel (Pejabat) : —

No Tel (HP) : 6596529096

Emel : —

Pengadu Menyatakan:-

PADA 09/01/2018 JAM LEBIH KURANG 1450HRS, SAYA SEDANG MEMANDU M/KAR NO:SLQ724M DARI SINGAPURA HENDAK MENGHALA KE NUSA CEMERLANG. KETIKA DI JALAN MEGA 1/1, SAYA SEDANG MEMBUAT PUSINGAN U. TIBA-TIBA SEBUAH M/KAR NO:JQJ4691 DATANG DARI ARAH BELAKANG LALU MELANGGAR M/KAR SAYA DI BAHAGIAN BELAKANG SEBELAH KIRI. SAYA TIDAK CEDERA. M/KAR SAYA MENGALAMI KEROSAKAN DI BAHAGIAN BELAKANG SEBELAH KIRI BUMPER, SET LAMPU, MUDGUARD, RIM/ARM/TAYAR, PINTU, BONET, REVERSE SENSOR, AIRBAG DEPAN/BELAKANG KIRUKANAN DAN LAIN-LAIN KEROSAKAN BELUM PASTI. SEMASA REPOT DIBUAT, KENDERAAN TIDAK DI BAWA KE BALAI TRAFIK ISKANDAR PUTERI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

: R194525 | 09/01/2018 04:18:50 PM

Sketch Plan Pg. 4

(Poli 257-Pin. 1A3)
P.11(A) 104/2008

JADUAL
SCHEDULE

CARSI80006079
0218969090333118

PENDUA

Borang 1
Form 1

[perenggan 2 (a)]
[paragraph 2 (a)]

AKTA PENGANGKUTAN JALAN 1987
ROAD TRANSPORT ACT 1987

ROAD TRANSPORT NOTICE UNDER SUBSECTION 30(1) RULES 2003

AREA CODE			
6	2	2	5

Kepada CHUA NGEOK YIN

To

No. Kad Pengangkutan

NRIC No.

Alamat

Address

59 JALAN LENGKOK SEMBAWAN

G SINGAPURA

759140

No. Pendaftaran Kendaraan

Motor Vehicle Registration No.

Jenis Kendaraan

Vehicle Type

MOTOKAR

BAHAWASANYA saya mempunyai sebab-sebab yang munasabah untuk menganggap

bahawa kamu telah melakukan kesalahan yang berikut di bawah:

WHEREAS I have reasonable ground to believe that you have committed an offence as follows:

Sekiranya Akta Pengangkutan Jalan 1987

Solesnya

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

NOTA: Kesalahan ini boleh/didak boleh disampunkan
NOTE: This offence is compoundable/not compoundable

"Jika kesalahan ini boleh disampunkan, kamu dinasihatkan boleh mengampunkan"

"If the offence is compoundable, you are advised to have the offence compounded"

kesalahan ini di: masa-masa sebelum penyampaian surat tarikh: 09/01/2018

FORM

at any F.O.R.D. manner payment shall be/for 09/01/2018

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

point 9.00
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

point 04:42
time 04:42
pagi/ptg a.m/p.m

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0064/2018/GW
Date : 16-Jan-18

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chua Ngeok Yin
Address : 59 Jalan Lengkok Sembawang
Singapore 759240
Telephone : HP +65 - 96529099
Type of Claim : Own Damage Claims
Policy No. : 2100510210
Vehicle No : **SLQ 724 M**
Model Code : Q5 sport 2.0 TFSI QU
Model / Year : Jun-17
Engine No : DAX 005220
Chassis No : WAUZZZF3H2022473
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Jan-18
Place of Accident : GELANG PATAH NUSA CEMERLANG IND PARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLQ 724 M.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To set up car on car-o-liner for first measurement.	S/N \$ 800.00	✓
2	To remove and renew rear parking aid . Check function.	S/N \$ 280.00	✓
3	To remove and transfer lhs rear door 's multi - lock system, power window devices and roller sunblind. Inspect for damages and renew if necessary.	S/N \$ 360.00	✓
4	To dislodge and reinstall rear wire harness, all electrical trays for fuse and relays, audio equipment , control units, uncluding rear lid wiring and multi-lock and hydraulic system.	S/N \$ 1,800.00	✓
5	To remove and reinstall all rear passenger seats, luggage compartment trims, pillars, curtain air bags, roof liner.	S/N \$ 1,800.00	✓
6	To renew front and rear windscreens, and lhs rear side window.	S/N \$ 1,000.00	✓ 600
7	To remove and reinstall centre console, renew air bag control unit, both front seat belts, curtain airbags and roof liner.	S/N \$ 2,800.00	✓
TOTAL LABOUR CHARGES		: \$ 8,840.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLQ 724 M.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
8	To suspend engine, remove and install front suspension for car -O- liner repairs.	S/N \$ 2,800.00	X
9	To remove rear exhaust silencers, dismantle rear suspension assy. Inspect for damages and renew accordingly.	S/N \$ 3,200.00	✓
10	To set up and place vehicle on car -O- liner.	S/N \$ 2,400.00	✓ 1200
11	To dismantle lhs rear door, rear bumper and rear lid. Cut out and weld rear cross panel, reinforcements, lhs rear fender, outer wheel house, C-pillar, connecting plates and lhs sill panel. Renew lhs rear door, rear bumper assy and rear lid. Align to position. reinstall all parts reomved.	\$ 15,400.00	7500 9500 15 days
12	To carry out joint sealer works, stone chip treatment. Respray lhs rear door, door cover, rear bumper assy, lower spoiler, wheel arch trims, rear lid, lhs rear fender, connecting plates, wheel housing, sill panel, door entrance, drain panel, roof channel and end panel.	\$ 8,500.00	3850 4400 4950
13	To renew lhs rear rim and trye. Carry out wheel alignment.	S/N \$ 280.00	✓
14	To carry out diagnostic check.	S/N \$ 576.00	✓
TOTAL LABOUR CHARGES		: \$ 41,996.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 724 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR - LH <i>Distorted</i>	\$ 2,792.00 ✓	2233.60
2	REAR OUTER DOOR SEAL - LH <i>per</i>	2 \$ 373.00 ✓	298.00
3	BONDING AGENT <i>Not per</i>	\$ 43.00 X	
4	CLEANING SOLUTION <i>Not per</i>	\$ 64.00 X	
5	SEALING STRIP <i>Not per</i>	\$ 14.00 X	
6	REAR DOOR CATCH - LH <i>per</i>	\$ 127.00 ✓	101.60
7	SILL PANEL SEAL - LH <i>per</i>	\$ 223.00 ✓	178.40
8	REAR DOOR LOCK - LH <i>Not per</i>	\$ 580.00 X	
9	REAR SIDE WINDOW GUIDE RAIL - LH <i>per</i>	\$ 62.00 ✓	
8	REAR WINDOW REGULATOR WITHOUT MOTOR - LH <i>per</i>	\$ 267.00 ✓	
9	REAR DOOR COVER - LH <i>Distorted</i>	\$ 553.00 ✓	442.00
10	REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH <i>Not per</i>	\$ 509.00 X	
11	REAR DOOR TRIM - LH <i>per</i>	\$ 1,671.00 ✓	
12	SIDE PANEL - LH <i>Distorted</i>	\$ 3,913.00 ✓	3130.40
13	REAR INNER SIDE PANEL - LH <i>Not per</i>	\$ 1,414.00 X	
14	REAR D- PILLAR REINFORCEMENT - LH <i>Not per</i>	\$ 477.00 ✓	381.60
15	REAR WHEEL HOUSING - LH <i>Distorted</i>	\$ 575.00 ✓	461.00
16	REAR BOTTOM PLATE - LH <i>Distorted</i>	\$ 428.00 ✓	342.00
17	REAR C - PILLAR REINFORCEMENT - LH <i>Not per</i>	\$ 199.00 ✓	159.20
18	REAR SIDE MEMBER - LH <i>Not per</i>	\$ 629.00 X	
19	REAR WHEEL HOUSING LINER - LH <i>Not per</i>	\$ 231.00 ✓	184.80
20	WHEEL HOUSING LINER ATTACHEMNT PARTS <i>per</i>	32.10 TBC ✓	25.68
SUB - TOTAL SPARE PARTS		\$ 15,144.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 724 M.

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
21	REAR SILL TRIM STRIP -LH <i>new</i>	\$	123.00 ✓	98.40
22	REAR WHEEL COVER -LH/RH <i>new</i>	2 \$	938.00 ✓	749.60
23	REAR SIDE WINDOW -LH <i>new</i>	\$	724.00 ✓	579.20
24	PRIMER <i>new</i>	\$	19.00 ✓	14.56
25	REAR BUMPER <i>Distorted</i>	② \$	2,512.00 ✓	2009.60
26	REAR BUMPER SPOILER <i>Replaced</i>	\$	718.00 ✓	574.00
27	REAR TRIM - LH <i>new</i>	\$	201.00 +	
28	TAIL LIGHT - LH <i>Replaced</i>	\$	619.00 ✓	494.80
29	REAR BUMPER CARRIER <i>Not new</i>	\$	786.00 X	
30	REAR BUMPER HOLDING STRAP <i>Not new</i>	\$	142.00 X	
31	REAR BUMPER GUIDE SECTION - LH <i>Replaced</i>	\$	71.00 ✓	56.80
32	REAR BUMPER SENSOR <i>new</i>	2 \$	421.00 +	
33	REAR BUMPER SENSOR SEAL - O-RING <i>new</i>	\$	15.00 +	
34	REAR BUMPER WIRING SET <i>new</i>	\$	440.00 +	
35	REAR LID <i>Replaced</i>	\$	3,776.00 ✓	3020.80
36	WHEATHER STRIP <i>Not new</i>	\$	338.00 X	
37	REAR LID STOP BUFFER <i>new</i>	\$	48.00 +	
38	ADHESIVE PACKING	\$	15.00 ✓	11.60
39	AUDI EMBLEM	\$	108.00 ✓	86.00
40	INSCRIPTION " Q5 "	\$	83.00 ✓	66.16
SUB - TOTAL SPARE PARTS		:	\$ 12,097.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 724 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	INSCRIPTION " TFSI " <i>3 new</i>	\$ 83.00 ✓	66.16
42	INSCRIPTION " QUATTRO " <i>3 new</i>	\$ 83.00 ✓	66.16
43	REAR BUMPER SPOILER FIXING PARTS <i>1 new</i>	\$ 17.00 ✓	13.04
44	FOAM STRIPS <i>1 new</i>	\$ 17.00 ✓	13.04
45	REAR WINDOW <i>1 new</i>	\$ 1,020.00 ✓	816.00
46	PRIMER <i>1 new</i>	\$ 19.00 ✓	14.56
47	LED TAIL LIGHT <i>1 new</i>	\$ 1,432.00 X	
48	REAR ALUMINIUM RIM -LH <i>1 new</i>	\$ 914.00 ✓	731.20
49	REAR SUMMER RADIAL TYRE - LH <i>1 new</i>	\$ 1,111.00 ??	480.00
50	TRYE RUBBER VALVE <i>1 new</i>	\$ 12.00 X	
51	REAR SUBFRAME <i>1 new</i>	\$ 2,804.00 ✓	2243.20
52	CONTROL ARM- LOWER <i>1 new</i>	\$ 762.00 ✓	609.20
53	CONTROL ARM - UPPER FRONT <i>1 new</i>	\$ 524.00 ✓	419.20
54	CONTROL ARM - LEFT FRONT <i>1 new</i>	\$ 163.00 ✓	130.40
55	CONTROL ARM - LEFT REAR <i>1 new</i>	\$ 492.00 ✓	393.20
56	STEERING TIE ROD <i>1 new</i>	\$ 226.00 ✓	180.80
57	REAR WHEEL BEARING HOUSING - LH <i>1 new</i>	\$ 960.00 ✓	768.00
58	REAR SPEED SENSOR <i>1 new</i>	\$ 87.00 ✓	69.04
59	REAR STONE CHIP GUARD - LH <i>1 new</i>	\$ 38.00 ✓	23.76
60	REAR DRIVE SHAFT - LH <i>1 new</i>	\$ 1,750.00 ✓	1400.00
SUB - TOTAL SPARE PARTS		\$ 12,514.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 724 M.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
61	REAR GAS SHOCK ABSORBER <i>Back</i>	\$ 1,287.00	<i>1029.60</i>
62	REAR COUPLING ROD <i>Back</i>	\$ 77.00	<i>60.96</i>
63	REAR EXHAUST SILENCER	\$ 1,216.00	<i>X</i>
64	REAR EXHAUST SILENCER DUAL CLIP <i>Back</i>	\$ 43.00	<i>X</i>
65	REAR EXHAUST SILENCER BRACKET	\$ 35.00	<i>X</i>
66	<i>Front</i> REAR WINDSCREEN <i>Back</i>	\$ 1,270.00	<i>X</i>
67	PRIMER	\$ 19.00	<i>14.56</i>
68	GEL FOIL FOR RAIN SENSOR <i>Back</i>	\$ 127.00	<i>101.20</i>
69	MOULDED HEADLINER <i>Sampled</i>	\$ 3,216.00	<i>2572.80</i>
70	HEAD AIR BAG UNIT <i>LH Activated</i>	2 TBC	<i>2707.20</i>
71	AIR BAG CRASH SENSOR <i>Activated</i>	\$ 267.00	<i>213.20</i>
72	AIR BAG CONTROL UNIT <i>Activated</i>	\$ 1,870.00	<i>1496.00</i>
73	A-PILLAR TRIM - LH <i>Back</i>	\$ 208.00	<i>166.40</i>
74	A-PILLAR TRIM - RH <i>Back</i>	\$ 208.00	<i>166.40</i>
75	B-PILLAR TRIM - LH UPPER	\$ 264.00	<i>T</i>
76	B-PILLAR TRIM - LH LOWER	\$ 264.00	<i>T</i>
77	C-PILLAR TRIM	2 \$ 550.00	<i>T</i>
78	AUTOMATIC SEAT BELT WITH BELT TENSIONER <i>Activated</i>	2 \$ 1,912.00	<i>1529.60</i>
79	SEAT BELT HEIGHT ADJUSTER <i>Back</i>	\$ 306.00	<i>244.80</i>
80	SUNDRIES <i>Back</i>	\$ 1,000.00	<i>518.16</i>
SUB - TOTAL SPARE PARTS		\$ 14,139.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 724 M.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
81	STONE CHIP	S/N \$ 360.00 ✓	360
82	CAVITY WAX	S/N \$ 180.00 ✓	180
83	ACRYLIC SEALER	S/N \$ 360.00 ✓	360
84	METAL FILLER POWDER	S/N \$ 280.00 ✓	280
85	REAR WINDSCREEN SEALANT	S/N \$ 200.00 ✓	200
86	QUARTER GLASS SEALANT	S/N \$ 100.00 ✓	100
TOTAL SPARE PARTS		: \$ 55,374.00	
TOTAL LABOUR CHARGES		: \$ 41,996.00	
GRANDTOTAL		: \$ 97,370.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

*Need to supplement Front w/screen Sealant &

110935.70

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 17/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 28 Days.


18/1/2018

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0064/2018/GW
Date	:	16-Jan-18

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

You recommended 28 days

We took 81 days exclude 13 Sundays

3 Public Holiday - Jb - 12 Feb 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Chua Ngeok Yin
Address	:	59 Jalan Lengkok Sembawang Singapore 759240
Telephone	:	HP +65 - 96529099
Type of Claim	:	Own Damage Claims
Policy No.	:	2100510210
Vehicle No	:	SLQ 724 M
Model Code	:	Q5 sport 2.0 TFSI QU
Model / Year	:	Jun-17
Engine No	:	DAX 005220
Chassis No	:	WAUZZZF3H2022473
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	9-Jan-18
Place of Accident	:	GELANG PATAH NUSA CEMERLANG IND PARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLQ 724 M.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To set up car on car-o-liner for first measurement.	S/N	\$ 800.00	\$ 800.00
2	To remove and renew rear parking aid . Check function.	S/N	\$ 280.00	\$ 280.00
3	To remove and transfer lhs rear door 's multi - lock system, power window devices and roller sunblind. Inspect for damages and renew if necessary.	S/N	\$ 360.00	\$ 360.00
4	To dislodge and reinstall rear wire harness, all electrical trays for fuse and relays, audio equipment , control units, uncluding rear lid wiring and multi-lock and hydraulic system.	S/N	\$ 1,800.00	\$ 1,800.00
5	To remove and reinstall all rear passenger seats, luggage compartment trims, pillars, curtain air bags, roof liner.	S/N	\$ 1,800.00	\$ 1,800.00
6	To renew front and rear windscreens, and lhs rear side window.	S/N	\$ 1,000.00	\$ 600.00
7	To remove and reinstall centre console, renew air bag control unit, both front seat belts, curtain airbags and roof liner.	S/N	\$ 2,800.00	\$ 2,800.00
TOTAL LABOUR CHARGES		:	<u>\$ 8,840.00</u>	<u>\$ 8,440.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLQ 724 M.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 8,440.00
8	To suspend engine, remove and install front suspension for car -O- liner repairs.	S/N	\$ 2,800.00	
9	To remove rear exhaust silencers, dismantle rear suspension assy. Inspect for damages and renew accordingly.	S/N	\$ 3,200.00	\$ 3,200.00
10	To set up and place vehicle on car -O- liner.	S/N	\$ 2,400.00	\$ 1,800.00
11	To dismantle lhs rear door, rear bumper and rear lid. Cut out and weld rear cross panel, reinforcements, lhs rear fender, outer wheel house, C-pillar, connecting plates and lhs sill panel. Renew lhs rear door, rear bumper assy and rear lid. Align to position. reinstall all parts reomved. (Added 4 days \$2000/- for D pillar structures, wheelhouse etc)		\$ 15,400.00	\$ 9,500.00
12	To carry out joint sealer works, stone chip treatment. Respray lhs rear door, door cover, rear bumper assy ,lower spoiler , wheel arch trims, rear lid, lhs rear fender, connecting plates, wheel housing, sill panel, door entrance, drain panel, roof channel and end panel. (Added \$550/- for added repairs)		\$ 8,500.00	\$ 4,950.00
13	To renew lhs rear rim and trye. Carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
14	Added labour charges	S/N	\$ 480.00	\$ 480.00
15	To carry out diagnostic check.	S/N	\$ 576.00	\$ 576.00
TOTAL LABOUR CHARGES		:	\$ 42,476.00	\$ 29,226.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 724 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR -LH	\$ 2,792.00	\$ 2,233.60
2	REAR OUTER DOOR SEAL - LH	2 \$ 373.00	\$ 298.00
3	BONDING AGENT	\$ 43.00	
4	CLEANING SOLUTION	\$ 64.00	
5	SEALING STRIP	\$ 14.00	
6	REAR DOOR CATCH - LH	\$ 127.00	\$ 101.60
7	SILL PANEL SEAL - LH	\$ 223.00	\$ 178.40
8	REAR DOOR LOCK - LH	\$ 580.00	
9	REAR SIDE WINDOW GUIDE RAIL - LH	\$ 62.00	
8	REAR WINDOW REGULATOR WITHOUT MOTOR -LH	\$ 267.00	
9	REAR DOOR COVER - LH	\$ 553.00	\$ 442.00
10	REAR WINDOW SLOT SEAL WITH TRIM STRIP -LH	\$ 509.00	
11	REAR DOOR TRIM -LH	\$ 1,671.00	
12	SIDE PANEL -LH	\$ 3,913.00	\$ 3,130.40
13	REAR INNER SIDE PANEL - LH	\$ 1,414.00	
14	REAR D- PILLAR REINFORCEMENT - LH	\$ 477.00	\$ 381.60
15	REAR WHEEL HOUSING -LH	\$ 575.00	\$ 461.20
16	REAR BOTTOM PLATE - LH	\$ 428.00	\$ 342.00
17	REAR C - PILLAR REINFORCEMENT - LH	\$ 199.00	\$ 159.20
18	REAR SIDE MEMBER - LH	\$ 629.00	
19	REAR WHEEL HOUSING LINER - LH	\$ 231.00	\$ 184.80
20	WHEEL HOUSING LINER ATTACHEMNT PARTS	\$ 32.10	\$ 25.68
SUB - TOTAL SPARE PARTS		\$ 15,176.10	\$ 7,938.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 724 M.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 7,938.48
21	REAR SILL TRIM STRIP -LH		\$ 123.00	\$ 98.40
22	REAR WHEEL COVER -LH/RH	2	\$ 938.00	\$ 749.60
23	REAR SIDE WINDOW -LH		\$ 724.00	\$ 579.20
24	PRIMER		\$ 19.00	\$ 14.56
25	REAR BUMPER	2	\$ 2,512.00	\$ 2,009.60
26	REAR BUMPER SPOILER		\$ 718.00	\$ 574.00
27	REAR TRIM - LH		\$ 201.00	
28	TAIL LIGHT - LH		\$ 619.00	\$ 494.80
29	REAR BUMPER CARRIER		\$ 786.00	
30	REAR BUMPER HOLDING STRAP		\$ 142.00	
31	REAR BUMPER GUIDE SECTION - LH		\$ 71.00	\$ 56.80
32	REAR BUMPER SENSOR	2	\$ 421.00	
33	REAR BUMPER SENSOR SEAL - O-RING		\$ 15.00	
34	REAR BUMPER WIRING SET		\$ 440.00	
35	REAR LID		\$ 3,776.00	\$ 3,020.80
36	WHEATHER STRIP		\$ 338.00	
37	REAR LID STOP BUFFER		\$ 48.00	
38	ADHESIVE PACKING		\$ 15.00	\$ 11.60
39	AUDI EMBLEM		\$ 108.00	\$ 86.00
40	INSCRIPTION " Q5 "		\$ 83.00	\$ 66.16
SUB - TOTAL SPARE PARTS			\$ 12,097.00	\$ 15,700.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 724 M.

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
			\$	15,700.00
41	INSCRIPTION " TFSI "	\$ 83.00	\$	66.16
42	INSCRIPTION " QUATTRO "	\$ 83.00	\$	66.16
43	REAR BUMPER SPOILER FIXING PARTS	\$ 17.00	\$	13.04
44	FOAM STRIPS	\$ 17.00	\$	13.04
45	REAR WINDOW	\$ 1,020.00	\$	816.00
46	PRIMER	\$ 19.00	\$	14.56
47	LED TAIL LIGHT	\$ 1,432.00		
48	REAR ALUMINIUM RIM -LH	\$ 914.00	\$	731.20
49	REAR SUMMER RADIAL TYRE - LH	\$ 1,111.00	\$	480.00
50	TRYE RUBBER VALVE	\$ 12.00		
51	REAR SUBFRAME	\$ 2,804.00	\$	2,243.20
52	CONTROL ARM- LOWER	\$ 762.00	\$	609.20
53	CONTROL ARM - UPPER FRONT	\$ 524.00	\$	419.20
54	CONTROL ARM - LEFT FRONT	\$ 163.00	\$	130.40
55	CONTROL ARM - LEFT REAR	\$ 492.00	\$	393.20
56	STEERING TIE ROD	\$ 226.00	\$	180.80
57	REAR WHEEL BEARING HOUSING - LH	\$ 960.00	\$	768.00
58	REAR SPEED SENSOR	\$ 87.00	\$	69.04
59	REAR STONE CHIP GUARD - LH	\$ 38.00	\$	23.76
60	REAR DRIVE SHAFT - LH	\$ 1,750.00	\$	1,400.00
SUB - TOTAL SPARE PARTS		\$ 12,514.00	\$	24,136.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 724 M.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 24,136.96
61	REAR GAS SHOCK ABSORBER		\$ 1,287.00	\$ 1,029.60
62	REAR COUPLING ROD		\$ 77.00	\$ 60.96
63	REAR EXHAUST SILENCER		\$ 1,216.00	
64	REAR EXHAUST SILENCER DUAL CLIP		\$ 43.00	
65	REAR EXHAUST SILENCER BRACKET		\$ 35.00	
66	REAR WINDSCREEN		\$ 1,270.00	
67	PRIMER		\$ 19.00	\$ 14.56
68	GEL FOIL FOR RAIN SENSOR		\$ 127.00	\$ 101.20
69	MOULDED HEADLINER		\$ 3,216.00	\$ 2,572.80
70	HEAD AIR BAG UNIT	2	TBC	\$ 2,707.20
71	AIR BAG CRASH SENSOR		\$ 267.00	\$ 213.20
72	AIR BAG CONTROL UNIT		\$ 1,870.00	\$ 1,496.00
73	A-PILLAR TRIM -LH		\$ 208.00	\$ 166.40
74	A-PILLAR TRIM -RH		\$ 208.00	\$ 166.40
75	B-PILLAR TRIM - LH UPPER		\$ 264.00	
76	B-PILLAR TRIM - LH LOWER		\$ 264.00	
77	C-PILLAR TRIM	2	\$ 550.00	
78	AUTOMATIC SEAT BELT WITH BELT TENSIONER	2	\$ 1,912.00	\$ 1,529.60
79	SEAT BELT HEIGHT ADJUSTER		\$ 306.00	\$ 244.80
80	SUPPLEMENTARY		\$ 9,556.00	\$ 7,638.80
81	SUNDRIES		\$ 1,000.00	\$ 518.16
SUB - TOTAL SPARE PARTS			\$ 23,695.00	\$ 42,596.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Netf.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 724 M.

S/N	Parts Description	Damage Parts & Prices			
		S/NETT	REMARKS		
		<i>c/f</i>	\$		42,596.64
81	STONE CHIP	S/N \$	360.00	\$	360.00
82	CAVITY WAX	S/N \$	180.00	\$	180.00
83	ACRYLIC SEALER	S/N \$	360.00	\$	360.00
84	METAL FILLER POWDER	S/N \$	280.00	\$	280.00
85	REAR WINDSCREEN SEALENT	S/N \$	200.00	\$	200.00
86	QUARTER GLASS SEALENT	S/N \$	100.00	\$	100.00
TOTAL SPARE PARTS		:	\$ 64,962.10	\$	44,076.64
TOTAL LABOUR CHARGES		:	\$ 42,476.00	\$	29,226.00
GRANDTOTAL		:	\$ 107,438.10	\$	73,302.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0064/2018/GW
2-Apr-18
JB
1-Jan
SLQ724M
Q5 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	LHS rear level sensor <i>2nd</i>	\$ 286.00	\$ 228.80 ✓
2	Roof grab handle x 4 <i>2nd</i>	\$ 496.00	\$ 396.80 ✓
3	Adhesive tape x 2 <i>new</i>	\$ 106.00	\$ 83.52 ✓
4	LHS rear D pillar reinforcement (Top) <i>But</i>	\$ 393.00	\$ 314.40 ✓
5	LHS rear fender inner trim <i>2nd</i>	\$ 880.00	\$ 704.00 ✓
6	LHS front seat leather cover <i>new</i>	\$ 2,698.00	\$ 2,158.40 ✓
7	LHS front seat airbag <i>Activated.</i>	\$ 1,378.00	\$ 1,102.40 ✓
8	Luggage comp light switch <i>damaged.</i>	\$ 80.00	\$ 64.00 ✓
9	LHS rear seat remote control cable <i>2nd.</i>	\$ 126.00	\$ 100.40 ✓
10	Rear lid lock Bowen cable <i>2nd</i>	\$ 43.00	\$ 34.16 ✓
11	Battery fuse unit <i>2nd</i>	\$ 470.00	\$ 376.00 ✓
12	LHS rear underbody trim <i>new</i>	\$ 116.00	\$ 92.80 ✓
13	Wire joints x 5 <i>2nd</i>	\$ 274.00	\$ 218.80 ✓
14	LHS rear wheel cap <i>distorted</i>	\$ 87.00	\$ 69.44 ✓
15	LHS rear vent trim <i>distorted</i>	\$ 60.00	\$ 47.44 ✓
16	LHS/RHS rear windscreen spoilers <i>new</i>	\$ 402.00	\$ 320.80 ✓
17	2k sound insulation foam pack x 2 <i>new</i>	\$ 236.00	\$ 188.00 ✓
18	Control unit for Convenience system <i>2nd</i>	\$ 1,357.00	\$ 1,085.60 ✓
19	Mounting for control unit <i>2nd</i>	\$ 31.00	\$ 24.08 ✓
20	Mounting for fuse holder	\$ 37.00	\$ 28.96 ✓
		\$ 9,556.00	\$ 7,638.80
LABORS			
1	To remove and renew LHS front leather seat (S/N)	\$ 480.00	\$ 480.00 ✓
TOTAL		\$ 10,036.00	\$ 8,118.80

For Premium Automobiles Pte Ltd

Adrian Ling

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLQ 724 M

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0064/2018/MAS

11 Apr 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLQ 724 M, Audi Q5 Sport 2.0 TFSI Qu S-Tro

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLQ 724 M**, claimant, **Mr. Chua Ngeok Yin**, please find the related document per attached.

1. A copy of the Original invoice no. 85013674 – S\$77,363.82
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLQ 724 M



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159108
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159108
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408711

Customer Service
Service Appointment:
Singapore 6388 2223
Email: customer.care@premiumauto.com.sg

6386 2223
6628 1233

INSURANCE INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 1 17:18

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013674 Date : 03/04/2019 Order : SL00724M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SL00724M (V 33890)	Regn Dates: 27/06/2017	Mileage: 59354	WIP No.: 51818
Model: Q5 SPORT 2.0 TFSI quattro S tronic	Chassis: WAUZZZF3420022473	Engine: DAX 005220	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO RENEW LHS FRONT SEAT LEATHER.	480.00	1.00	480.00
Q	EXC	M: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	M: TO SET UP CAR ON CAR-O-LINER FOR FIRST MEASUREMENT	800.00	1.00	800.00
S	BODYWORK	M: TO REMOVE AND RENEW REAR PARKING AID. CHECK FUNCTION	280.00	1.00	280.00
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI LOCK SYSTEM, POWER WINDOW DEVICES AND ROLLER SUNBLIND. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	360.00	1.00	360.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS, ALL ELECTRICAL TRAYS FOR FUSE AND RELAYS, AUDIO	1800.00	1.00	1,800.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159108
Main Telephone: 6394 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159108
Telephone: 6394 2223
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 338111

Customer Service
Service Appointment:
Singapore 3386 1111
Email: customer.care@premiumauto.com.sg

6394 2323
6628 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 17:18

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013674
Date : 03/04/2019
Order : SL00724M
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SL00724M (V 33890) Regn Date: 27/06/2017 Mileage: 59354 WIP No.: 51818
Model: Q5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZF342022473 Engine: DAX 005220 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	EQUIPMENT, CONTROL UNITS, INCLUDING REAR LID WIRING AND MULTI-LOCK AND HYDRAULIC SYSTEM M:	1000.00	1.00	1,000.00
S	BODYWORK	TO REMOVE AND REINSTALL ALL REAR PASSENGER SEATS, LUGGAGE COMPARTMENT TRIMS, PILLAR, CURTAIN AIR BAG AND ROOF LINER M:	600.00	1.00	600.00
S	BODYWORK	TO RENEW REAR WINDSCREEN AND LHS SIDE WINDOW M:	2800.00	1.00	2,800.00
S	BODYWORK	TO REMOVE AND REINSTALL CENTRE CONSOLE, RENEW AIR BAG CONTROL UNIT, BOTH FRONT SEAT BELTS, CURTAIN AIRBAG AND ROOF LINER M:	3200.00	1.00	3,200.00
S	BODYWORK	TO REMOVE REAR EXHAUST SILENCER, DISMANTLE REAR SUSPENSION ASSY, INSPECT FOR DAMAGES AND RENEW ACCORDINGLY M:	1000.00	1.00	1,000.00
		TO SET UP AND PLACE VEHICLE ON CAR-O-LINER			
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159038
Main Telephone: 6886 2222
Main Telefax: 6471 2703

Alexandra Service Centre
281 Alexandra Road
Singapore 159038
Telephone: 6886 2222
Telexfax: 6475 1023

Ubi Service Centre
35 Ubi Road 1
Singapore 408721
Telephone: 6886 2222

Customer Service
Service Appointment
Singapore Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 2323
9628 1233

INS TAX INVOICE

Company Reg. No. 199902271M
GST Reg. No. 199902271M

Page 3 17:18

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice: 85013674 Date : 03/04/2019 Order : SL00724M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
Regn No.: SL00724M (V 33890)		Regn Date: 27/06/2017	Mileage: 59354	WIP No.: 51818	
Model: Q5 SPORT 2.0 TFSI qu S tronic		Chassis: WAUZZZF3H2022473	Engine: DAX 005220	Dept: U	
VSB No.:					
You have been assisted by :- UB-Jiayee		(33)			
		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO DISMANTLE LHS REAR DOOR, REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR CROSS PANEL, REINFORCEMENTS, LHS REAR FENDER, OUTER WHEEL HOUSE, C PILLAR, CONNECTING PLATES AND LHS SILL PANEL. RENEW LHS REAR BUMPER, REAR DOOR AND REAR LID. ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	9500.00	1.00	9,500.00
S	BODYWORK	M: TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT. RESPRAY LHS REAR DOOR, DOOR COVER, REAR BUMPER ASSY, LOWER SPOILER, WHEEL ARCH TRIM, REAR LID, LHS REAR FENDER, CONNECTING PLATE, WHEEL HOUSING AND END PANEL	4950.00	1.00	4,950.00
S	BODYWORK	M: TO RENEW LHS REAR RIM AND TYRE. CARRY OUT WHEEL ALIGNMENT	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	576.00	1.00	576.00
				Sub-Total	
				7% GST	
				Grand Total	



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road

Singapore 159938

Main Telephone: 6366 2223

Page 4 64710:18

Alexandra Service Centre

281 Alexandra Road

Singapore 159938

Telephone: 6366 2223

Telex: 6475 1033

Ulti Service Centre

5511 Upper Serangoon

Singapore 556899

Telephone: 6366 2223

Telex: 6475 1033

Customer Service

281 Alexandra Road

Singapore 159938

24-hour Breakdown Service

Email: customer.care@premiumauto.com.sg

6366 2223

6366 2223

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Invoice: 85013674	Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD	AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT	MOTOR CLAIM DEPT
AIG BUILDING	AIG BUILDING
78 SHENTON WAY	78 SHENTON WAY
#07-16	#07-16
SINGAPORE 079120 079120	SINGAPORE 079120
Date : 03/04/2019	
Order : SLO0724M	
Term : 30	

Regn No.: SLO0724M (V 33890)	Regn Date: 27/06/2017	Mileage: 59354	WIP No.: 51818
Model: Q5 SPORT 2.0 TFSI qu S tronic	Chassis: WAUZZZF3H2022473	Engine: DAX 005220	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee	(33)		

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO SUPPLY STONE CHIP,CAVITY WAX,ACRYLIC SEALER,METAL FILLER POWDER,REAR WINDSCREEN SEALANT AND QUARTER GLASS SEALANT	1480.00	1.00	1,480.00
X	A00A033051A STL	DOOR(V) (G)	Less 020%	1.00	2732.00
X	A00A045297H NVB	SIDE WINDO(A)	Less 020%	1.00	724.00
X	A00A0707092	SCREW (TECH)	Less 020%	1.00	15.40
X	A00A05053236	CONTR ARM (TECH) (A)	Less 020%	1.00	524.00
X	AN 91236301	BOLT (TECH)	Less 020%	2.00	12.30
X	A00A0927007C	SENSOR (TECH) (A)	Less 020%	1.00	86.30
X	A00A0505465B	CONN LINK (TECH) (A)	Less 020%	1.00	76.20
X	A00A067505AP10J	ROOFLINING (TECH) (A) (	Less 020%	1.00	3216.00
X	A00A080741J	AIRBAG (TECH) (A) (G)	Less 020%	1.00	1692.00
X	A00A080742J	AIRBAG (TECH) (A) (G)	Less 020%	1.00	1692.00
X	A00A0959651D	SENSOR (TECH) (A) (G)	Less 020%	1.00	266.50
X	A00A0959655N	MODULE (TECH) (A) (G)	Less 020%	1.00	1870.00
X	A00A067233F 10J	LINING (TECH) (A) (G)	Less 020%	1.00	208.00
X	A00A067234F 10J	LINING (TECH) (A) (G)	Less 020%	1.00	208.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119908
Main Telephone: 6336 2222
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119908
Telephone: 6336 2222
Telefax: 6475 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408721
Telephone: 6186 2711

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6336 2222
6475 1033

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 5 17:18

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013674 Date : 03/04/2019 Order : SLO0724M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLO0724M (V 33690)	Regn Date: 27/06/2017	Mileage: 59354	WIP No.: 51818
Model: 05 SPORT 2.0 TFSI qu S tronic	Chassis: WAUZZZF34H022473	Engine: DAX 005220	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
X	A00A857705 V04	SEAT BELT (TECH) (A) (G)	Less 020%	1.00	956.00
X	A00A857706 V04	SEAT BELT (TECH) (A) (G)	Less 020%	1.00	956.00
X	A00A839911B	SEAL (V) (G)	Less 020%	1.00	181.00
X	A00A853969A GRU	COVER (V) (G)	Less 020%	1.00	532.50
X	A00A802015A STL	FLOOR PAN (V) (G)	Less 020%	1.00	427.50
X	A00A853375 989	SCUFF PLAT (V) (G)	Less 020%	1.00	123.00
X	A00A809837 STL	SUBPART (V) (G)	Less 020%	1.00	3913.00
X	A00A505235S	SUB FRAME (TECH) (A) (G)	Less 020%	1.00	2804.00
X	AN 91227901	SCREW (TECH) (A) (G)	Less 020%	1.00	15.40
X	A00A505311A	CONTR ARM (TECH) (A) (G)	Less 020%	1.00	761.50
X	AN 91237101	SCREW (TECH) (A) (G)	Less 020%	2.00	7.70
X	A4HT007725	FLANGE NUT (TECH) (A) (G)	Less 020%	2.00	7.70
X	A00A505291	CONTR ARM (TECH) (A) (G)	Less 020%	1.00	163.00
X	A4M0505397L	CONTR ARM (TECH) (A) (G)	Less 020%	1.00	491.50
X	A4HT007726	FLANGE NUT (TECH) (A) (G)	Less 020%	1.00	10.00
X	A00A505431G	HOUSING (TECH) (A) (G)	Less 020%	1.00	960.00
X	A00A833177	SEAL (A)	Less 020%	1.00	223.00
X	A4HT006496	SCREW (TECH)	Less 020%	4.00	12.30

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6384 2222
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6388 2121
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408724

Customer Service
Service Appointment
Singapore Breakdown Service
Email: customer.care@premiumauto.com.sg

6384 2222
9628 1231

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 6 17:18

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013674 Date : 03/04/2019 Order : SL00724M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SL00724M (V 33890) Regn Date: 27/06/2017 Mileage: 59354 WIP No.: 51818

Model: Q5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZF34H0202473 Engine: DAX 005220 Dept: U

USB No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	AN 91229001	BOLT (TECH) Less 020%	1.00	7.70	6.16
X	AN 91235501	SCREW (A) Less 020%	2.00	5.70	9.12
X	A00A941309C	LEVELSENSE (V) (G) Less 020%	1.00	286.00	228.80
X	A00A057607J DT4	HANDLE (V) (G) Less 020%	1.00	124.00	99.20
X	AD 438515A1	ADHESIVE TAPE Less 020%	1.00	52.20	41.76
X	A00A009409TASTL	HOUSING (V) (G) Less 020%	1.00	576.50	461.20
X	A00A009027 STL	PILLAR D (V) (G) Less 020%	1.00	393.00	314.40
X	A00A009263A STL	REINFORCEM (V) (G) Less 020%	1.00	199.00	159.20
X	A00A063800S HCM	LINING (V) (G) Less 020%	1.00	690.00	704.00
X	A00A907368	MOUNTING (V) (G) Less 020%	1.00	30.10	24.08
X	A00A971845	MOUNTING (V) (G) Less 020%	1.00	36.20	28.96
X	A600972726	HOUSING (V) (G) Less 020%	1.00	18.50	14.80
X	A4L0067460E 4PK	TONGUE (V) (G) Less 020%	1.00	13.10	10.48
X	AN 91227901	SCREW (V) (G) Less 020%	1.00	15.40	12.32
X	A00A501203G	DRIVESHAFT (V) (G) Less 020%	1.00	1750.00	1,400.00
X	A00A001805E 250	COVER (V) (G) Less 020%	1.00	2630.00	2,158.40
X	A00A616025Q	SHOCK ABS (V) (G) Less 020%	1.00	1287.00	1,029.60
X	A4M0512137D	BOOT (V) (G) Less 020%	1.00	15.00	12.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre-Singapore
281 Alexandra Road
Singapore 119938
Main telephone 6836 1213
Main Telefax 6471 9733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408721
Telephone 6886 2711

Customer Service
Service Appointment
Your Breakdown Service
Email customer.care@premiumauto.com.sg

6386 2223
6828 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 7 17:18

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoices: 85013674 Date : 03/04/2019 Order : SLD0724M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SLD0724M (V 33890)	Regn Date: 27/06/2017	Mileage: 59354	WIP No.: 51818
Model: Q5 SPORT 2.0 TFSI qu S tronic	Chassis: WAUZZZF3H2022473	Engine: DAX 005220	Dept: U
USB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
X	AAM0501529L	TIE ROD(V)	1.00	226.00	180.80
X	ZC235/55R19CSC5	CONTINENTAL SP CONTA	1.00	480.00	480.00
X	A00A601025E	RIM 19" C11	1.00	914.00	731.20
X	A00A877203	HOSE	1.00	25.00	20.00
X	A00A839267	COVER	1.00	13.10	10.48
X	A00C959121	SWITCH	1.00	80.00	64.00
X	A00A885681E	CABLE	1.00	125.50	100.40
X	A00A887623C	BOWD CABLE	1.00	42.70	34.16
X	A00A839119A	DOOR SEAL (V) (G)	1.00	191.50	153.20
X	A00A915459	FUSE UNIT (V) (G)	1.00	470.00	376.00
X	A00A810171A	WHEEL HOUS	1.00	231.00	184.80
X	A6Q0972736	HOUSING	1.00	4.90	3.92
X	A00A880241F	SIDEAIRBAG	1.00	1378.00	1,102.40
X	A00A809387	FOIL	1.00	29.70	23.76
X	A00A825215B	LINING (V) (G)	1.00	116.00	92.80
X	A00A807434B TB2	SPOILER	1.00	717.50	574.00
X	A00A853817A GRU	COVER	1.00	468.50	374.80
X	A00A807527 GRU	COVER	1.00	1024.00	819.20

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6336 1223
Fax: 6336 1224

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6336 2221
Fax: 6475 1023

Ubi Service Centre
55 Ubi Avenue 1
Singapore 408722
Telephone: 6733 8888
Fax: 6733 8889

Customer Service
24 Hour Appointment
24 Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 1225
6628 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 8 of 1718

Invoice: 85013674	Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
Date : 03/04/2019	
Order : SLD0724M	
Term : 30	

Regn No.: SLD0724M (V 33890)	Regn Date: 27/06/2017	Mileage: 59354	WIP No.: 51818
Model: Q5 SPORT 2.0 TFSI qu S tronic	Chassis: WAUZZIFY3H2022473	Engine: DAX 005220	Dept: U
VS8 No.:			
You have been assisted by :- UB-Jiayee	(33)		

		Details		Qty	Unit Price	Amount
X	AB0A045501 NVB	REARWINDOW (A)	Less 020%	1.00	1020.00	816.00
X	AB0A007067A GRU	COVER	Less 020%	1.00	1488.00	1,190.40
X	AB0A027025D STL	LID (V) (G)	Less 020%	1.00	3776.00	3,020.80
X	A000979942	CONNECTOR (BLUE)	Less 020%	1.00	9.00	7.20
X	A000979034EA	WIRES (RED)	Less 020%	1.00	54.70	43.76
X	A000979034EA	WIRES (RED)	Less 020%	4.00	54.70	175.04
X	AB40601170	WHEEL CAP	Less 020%	1.00	86.00	69.44
X	AD 007000A2	SILICSPRAY (DG)	Less 020%	1.00	29.30	23.44
X	AB0A098629	ATT PARTS(V) (G)	Less 020%	1.00	32.10	25.68
X	ABR0053741 22Z	INSCRIPTION 'Q5'	Less 020%	1.00	82.70	66.16
X	A4H0053737D 22Z	INSCRIPTION 'TFSI'	Less 020%	1.00	82.70	66.16
X	A4G5053742 22Z	AUDI SIGN	Less 020%	1.00	107.50	86.00
X	AB0A098941	PARTS KIT (V) (G)	Less 020%	1.00	16.30	13.04
X	A4M0057819	Adjuster (A)	Less 020%	2.00	153.00	244.80
X	AB0A039249	CHECK ROD	Less 020%	1.00	127.00	101.60
X	AB0A009307A STL	REINFORCE(V) (G)	Less 020%	1.00	477.00	381.60
X	A6R0019465A	TRIM	Less 020%	1.00	59.30	47.44
X	ABD0053419F	PACKING	Less 020%	1.00	14.50	11.60
Sub-Total						
7% GST						
Grand Total						



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159138
Main Telephone: 6886 2223
Main Telefax: 6471 2733

Alexandra Service Centre
281 Alexandra Road
Singapore 159138
Telephone: 6886 2223
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408722

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2323
9626 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 9 17:18

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013674 Date : 03/04/2019 Order : SLD0724M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLD0724M (V 33890) Regn Date: 27/06/2017 Mileage: 59354 WTP No.: 51818
Model: 05 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZIFY3H2022473 Engine: DAX 005220 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	A8R0857607H DT4	HANDLE(A)	2.00	124.00	198.40
X	A8W9853737 22Z	NAME PLATE(A)	1.00	82.70	66.16
X	A80A886373	BROWNET	10.00	3.80	38.40
X	A8Y0827654	SCREW	2.00	1.00	1.60
X	A8E0407643A	SCREW (TECH)	1.00	23.60	18.88
X	A1K0407357C	PLATE	3.00	3.10	7.44
X	A4L0863783 9B9	WASHER	1.00	1.80	1.44
X	A8R0857608D DT4	HANDLE(V) (G)	1.00	124.00	99.20
X	A80A887453	GUIDE (V)	1.00	71.00	56.80
X	A80A512182	LOC. PIN	4.00	6.10	19.52
X	A80A854871 5FD	SPOILER (V)	1.00	200.50	160.40
X	A80A854872 5FD	SPOILER (V)	1.00	200.50	160.40
X	A80A898940	REPAIR KIT (V) (G)	1.00	16.30	13.04
X	A000979242EA	WIRES	1.00	27.80	22.24
X	A000979941	CONNECTOR (RED)	1.00	9.00	7.20
X	A000979940	CONNECTOR (WHITE)	5.00	9.00	36.00
X	A000979151EA	WIRES	1.00	27.80	22.24
X	A000979308E	WIRES	1.00	43.50	34.80

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 2733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6471 2733

Ubi Service Centre
55 Ubi Road 1
Singapore 408721
Telephone: 6388 2211
Telefax: 6475 1521

Customer Service
Service Appointment
Your breakdown service
Email: customer.care@premiumauto.com.sg

6386 2223
6388 1218

Page 10 17:18

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoices: 85013674 Date : 03/04/2019 Order : SL00724M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SL00724M (V 33890)	Regn Date: 27/06/2017	Mileage: 59354	WIP No.: 51818
Model: Q5 SPORT 2.0 TFSI qu S tronic	Chassis: WAUZZIFY3H222473	Engine: DAX 005220	Dept: U
VS8 No.:			
You have been assisted by :- UB-Jiayee	(33)		

		Details	Qty	Unit Price	Amount
X	ABW0972416	HOUSING	1.00	8.30	6.64
X	AD 00920002	PRIMER (DG)	3.00	18.20	43.68
X	AD 438515A1	ADHERSIVE TAPE	1.00	52.20	41.76
X	AD 506KD1A3	2K FOAM	2.00	117.50	188.00
X	ABW0907064CH	CONTR UNIT	1.00	1357.00	1,085.60
X	A00A945069	TAILLIGHT	1.00	618.50	494.80
X	AAHT003497	BOLT	2.00	2.00	3.20
X	AAHT003237	BOLT	2.00	1.00	1.60
X	AN 91108201	BOLT (REQ12)	6.00	5.90	28.32
X	AAHT000011	NUT	4.00	1.50	4.80
X	AAHT003307	SCREW (A)	2.00	1.00	1.60
X	AN 90923602	POP-RIVET	1.00	1.40	1.12
X	AAHT007610	NUT (TECH) (TECH) (A) (	3.00	4.60	11.04
X	AN 10272302	NUT (TECH)	3.00	2.60	6.24
X	AN 01508210	NUT	1.00	1.00	0.80
X	AN 90648102	NUT	2.00	4.60	7.36
X	AN 01474011	BOLT (TECH)	1.00	0.70	0.56
X	AAHT005180	BOLT	2.00	7.70	12.32
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6846 2222
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6846 2222
Telefax: 6471 3733

Ubi Service Centre
55 Ubi Road 1
Singapore 408721
Telephone: 6886 2211

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6366 2323
6828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 11 17:10

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013674
Date : 03/04/2019
Order : SLO0724M
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLO0724M (V 33890)

Regn Date: 27/06/2017

Mileage: 59354

WIP No.: 51818

Model: Q5 SPORT 2.0 TFSI qu S tronic

Chassis: WAUZZZF3H0022473

Engine: BAX 005220

Dept: U

VS8 No.:

You have been assisted by :- UB-Jiayee

(33)

		Details		Qty	Unit Price	Amount
X	AWHT007090A	SCREW (TECH)	Less 020%	1.00	11.30	9.04
X	AWHT007096	BOLT (TECH)	Less 020%	2.00	10.00	16.00
X	AN 10106403	NUT (TECH)	Less 020%	4.00	3.20	10.24
X	AN 91228001	SCREW (TECH)	Less 020%	2.00	18.50	29.60
X	AN 91228901	BOLT (TECH)	Less 020%	4.00	4.60	14.72
X	AN 91236401	BOLT (TECH)	Less 020%	1.00	7.70	6.16
X	A00A853810A GRU	COVER	Less 020%	1.00	468.50	374.80

Parts 42,596.64
Labour 0.00
Sublet 30,706.00
Menus 0.00
Lubricant 0.00

Sub-Total 72,302.64

7% GST 5,061.18

Grand Total 77,363.82

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLQ 724 M

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0064/2018/JT
30 April 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 Sport 2.0 TFSI qu
Vehicle Chassis No. : WAUZZZF3H2022473
Vehicle Regn No. : SLQ 724 M
Vehicle Mileage : 21,732 km
Vehicle Owner : Mr. Chua Ngeok Yin
Certificate No : 2100510210
Policy Excess : S\$1,070.00 (inclusive 7% GST)
Accident Date : 09th January 2018
Place : Gelang Patah Nusa Cemerlang Ind. Park
Repair Cost : S 77,363.82
WIP No. : 51818
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :

30/04/2018

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1727053B



CHUA NGEOK YIN

CHINESE

10-03-1968

SINGAPORE

Male

17/10/2011



REPUBLIC OF SINGAPORE DRIVING LICENCE

CHUA NGEOK YIN

10-03-1968

18 Dec 2013

10027053B1A



5515337

Barcode

21-08-2015

59 JALAN LENGKOK SEMBAWANG
SINGAPORE 759240



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EXP. DATE

Class 2 Motor Car<= 3000kg with <= 7 passengers, ex cl ass 18 Dec 2013
of the driver, and a l ier motor vehicles <= 2500kg

Barcode

MP 423A

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jan 2018		17 Jan 2018 17:13 Edit Adj Rpt	S\$73,302.64 Edit Estimates	S\$73,302.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: CHUA NGEOK YIN , ID: S1727053B, Tel: +6596529099, Email: NOEMAIL									
Vehicle Reg. No.: SLQ724M		Date of Loss: 09/01/2018 14:00 - :59 [6 Months and 13 Days From LTA Reg Date (Mon.Yr)]							
Claim Type: OD / 6043922658SG		Policy/Cover Note No.: 2100510210 (Comprehensive)							
		Excess: S\$1,000.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Azlan, Syazairdina] syazairdina.azlan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/01/2018]									
Driver/Custodian: CHUA NGEOK YIN (52 / Male) , NRIC: S1727053B, Tel: +6596529099 Email: NOEMAIL									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (11/09/2019): Alert - Adj Mandate Approved (S\$73302.64) - SLQ724M - Claim Handler: Azlan, Syaz... - AIG_SG (16/04/2019): Alert - Adj Mandate Approved (S\$8001.00) - SLQ724M - Claim Handler: Chan, Kian M... - AIG_SG (18/01/2018): Alert - Adj Mandate Approved (S\$78867.00) - SLQ724M - Claim Handler: Chan, Kian ... - AIG_SG (18/01/2018): SLQ724M / OD / 09/01/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ724M (6043922658SG)

OD

Jan 9 2018 2:50PM

[CHUA NGEOK YIN]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Assessment Reports												1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	18/01/18 11:28	Adjuster Immediate Advice												Load HTM			
Photos/Images												3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	18/01/18 11:45	General View												Load JPG ☒			
2	18/01/18 11:45	General View												Load JPG ☒			
3	18/01/18 11:45	General View												Load JPG ☒			
4	18/01/18 11:45	General View												Load JPG ☒			
5	18/01/18 11:45	General View												Load JPG ☒			
6	18/01/18 11:45	General View												Load JPG ☒			
7	18/01/18 11:45	General View												Load JPG ☒			
8	18/01/18 11:45	General View												Load JPG ☒			
9	18/01/18 11:45	General View												Load JPG ☒			
10	18/01/18 11:45	General View												Load JPG ☒			
11	18/01/18 11:45	General View												Load JPG ☒			
12	18/01/18 11:45	General View												Load JPG ☒			
13	18/01/18 11:45	General View												Load JPG ☒			
14	18/01/18 11:45	General View												Load JPG ☒			
15	18/01/18 11:45	General View												Load JPG ☒			
16	18/01/18 11:45	General View												Load JPG ☒			
17	18/01/18 11:45	General View												Load JPG ☒			
18	18/01/18 11:45	General View												Load JPG ☒			
19	18/01/18 11:45	General View												Load JPG ☒			
20	18/01/18 11:45	General View												Load JPG ☒			
21	18/01/18 11:45	General View												Load JPG ☒			
22	18/01/18 11:45	General View												Load JPG ☒			
23	18/01/18 11:45	General View												Load JPG ☒			
24	18/01/18 11:45	General View												Load JPG ☒			
25	18/01/18 11:45	General View												Load JPG ☒			
26	18/01/18 11:45	General View												Load JPG ☒			
27	18/01/18 11:45	General View												Load JPG ☒			
28	18/01/18 11:45	General View												Load JPG ☒			
29	18/01/18 11:45	General View												Load JPG ☒			
30	18/01/18 11:45	General View												Load JPG ☒			
31	18/01/18 11:45	General View												Load JPG ☒			
32	18/01/18 11:45	General View												Load JPG ☒			
33	18/01/18 11:45	General View												Load JPG ☒			
34	18/01/18 11:45	General View												Load JPG ☒			
35	18/01/18 11:45	General View												Load JPG ☒			
36	18/01/18 11:45	General View												Load JPG ☒			
37	18/01/18 11:45	General View												Load JPG ☒			
38	18/01/18 11:45	General View												Load JPG ☒			
39	18/01/18 11:45	General View												Load JPG ☒			
40	18/01/18 11:45	General View												Load JPG ☒			
41	18/01/18 11:45	General View												Load JPG ☒			

Assessment Reports			1 per page	☒	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
42	18/01/18 11:45	General View		Load JPG	☒
43	18/01/18 11:45	General View		Load JPG	☒
44	18/01/18 11:45	General View		Load JPG	☒
45	18/01/18 11:45	General View		Load JPG	☒
46	18/01/18 11:45	General View		Load JPG	☒
47	18/01/18 11:45	General View		Load JPG	☒
48	18/01/18 11:45	General View		Load JPG	☒
49	18/01/18 11:45	General View		Load JPG	☒
50	18/01/18 11:45	General View		Load JPG	☒
51	18/01/18 11:45	General View		Load JPG	☒
52	18/01/18 11:45	General View		Load JPG	☒
53	18/01/18 11:45	General View		Load JPG	☒
54	18/01/18 11:45	General View		Load JPG	☒
55	18/01/18 11:45	General View		Load JPG	☒
56	18/01/18 11:45	General View		Load JPG	☒
57	18/01/18 11:45	General View		Load JPG	☒
58	25/03/19 17:27	Reinspection Photo		Load JPG	☒
59	25/03/19 17:27	Reinspection Photo		Load JPG	☒
60	25/03/19 17:27	Reinspection Photo		Load JPG	☒
61	25/03/19 17:27	Reinspection Photo		Load JPG	☒
62	25/03/19 17:27	Reinspection Photo		Load JPG	☒
63	25/03/19 17:27	Reinspection Photo		Load JPG	☒
64	25/03/19 17:27	Reinspection Photo		Load JPG	☒
65	25/03/19 17:27	Reinspection Photo		Load JPG	☒
66	25/03/19 17:27	Reinspection Photo		Load JPG	☒
67	25/03/19 17:27	Reinspection Photo		Load JPG	☒
68	25/03/19 17:27	Reinspection Photo		Load JPG	☒
69	25/03/19 17:27	Reinspection Photo		Load JPG	☒
70	25/03/19 17:27	Reinspection Photo		Load JPG	☒
71	25/03/19 17:27	Reinspection Photo		Load JPG	☒
72	25/03/19 17:27	Reinspection Photo		Load JPG	☒
73	25/03/19 17:27	Reinspection Photo		Load JPG	☒
74	25/03/19 17:27	Reinspection Photo		Load JPG	☒
75	25/03/19 17:27	Reinspection Photo		Load JPG	☒
76	25/03/19 17:27	Reinspection Photo		Load JPG	☒
77	25/03/19 17:27	Reinspection Photo		Load JPG	☒
78	25/03/19 17:27	Reinspection Photo		Load JPG	☒
79	25/03/19 17:27	Reinspection Photo		Load JPG	☒
80	25/03/19 17:27	Reinspection Photo		Load JPG	☒
81	25/03/19 17:27	Reinspection Photo		Load JPG	☒
82	25/03/19 17:27	Reinspection Photo		Load JPG	☒
83	25/03/19 17:27	Reinspection Photo		Load JPG	☒
84	25/03/19 17:27	Reinspection Photo		Load JPG	☒
85	25/03/19 17:27	Reinspection Photo		Load JPG	☒
86	25/03/19 17:27	Reinspection Photo		Load JPG	☒
87	25/03/19 17:27	Reinspection Photo		Load JPG	☒
88	25/03/19 17:27	Reinspection Photo		Load JPG	☒
89	25/03/19 17:27	Reinspection Photo		Load JPG	☒
90	25/03/19 17:27	Reinspection Photo		Load JPG	☒
91	25/03/19 17:27	Reinspection Photo		Load JPG	☒
92	25/03/19 17:27	Reinspection Photo		Load JPG	☒
93	25/03/19 17:27	Reinspection Photo		Load JPG	☒
94	25/03/19 17:27	Reinspection Photo		Load JPG	☒
95	25/03/19 17:27	Reinspection Photo		Load JPG	☒
96	25/03/19 17:27	Reinspection Photo		Load JPG	☒
97	25/03/19 17:27	Reinspection Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
98	25/03/19 17:27	Reinspection Photo		☒
99	25/03/19 17:27	Reinspection Photo		☒
100	25/03/19 17:27	Reinspection Photo		☒
101	25/03/19 17:27	Reinspection Photo		☒
102	25/03/19 17:27	Reinspection Photo		☒
103	25/03/19 17:27	Reinspection Photo		☒
104	25/03/19 17:27	Reinspection Photo		☒
105	25/03/19 17:27	Reinspection Photo		☒
106	25/03/19 17:27	Reinspection Photo		☒
107	25/03/19 17:27	Reinspection Photo		☒
108	25/03/19 17:27	Reinspection Photo		☒
109	25/03/19 17:27	Reinspection Photo		☒
110	25/03/19 17:27	Reinspection Photo		☒
111	25/03/19 17:27	Reinspection Photo		☒
112	25/03/19 17:27	Reinspection Photo		☒
113	25/03/19 17:27	Reinspection Photo		☒
114	25/03/19 17:27	Reinspection Photo		☒
115	25/03/19 17:27	Reinspection Photo		☒
116	25/03/19 17:27	Reinspection Photo		☒
117	25/03/19 17:27	Reinspection Photo		☒
118	25/03/19 17:27	Reinspection Photo		☒
119	25/03/19 17:27	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/01/18 11:44	Certificate of Insurance		☒
2	18/01/18 11:44	Workshop estimate		☒
3	18/01/18 11:44	Singapore Accident Statement		☒
4	18/01/18 11:44	Interview form		☒
5	18/01/18 11:44	Insured Person's NRIC & DL		☒
6	18/01/18 11:44	Police Report		☒
7	12/04/19 15:26	Supplementary		☒
8	11/09/19 16:48	Workshop Invoice		☒
9	11/09/19 16:48	Discharge Voucher		☒

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	09/01/18 19:38	Accident Statement		☒
Photos/Images			3 per page	☒
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	09/01/18 19:35	Accident Photo		☒
2	09/01/18 19:35	Accident Photo		☒
3	09/01/18 19:35	Accident Photo		☒
4	09/01/18 19:35	Accident Photo		☒
5	09/01/18 19:35	Accident Photo		☒
6	09/01/18 19:35	Accident Photo		☒
7	09/01/18 19:35	Accident Photo		☒
8	09/01/18 19:35	REPORTING MILEAGE		☒
9	09/01/18 19:35	Accident Photo		☒
10	09/01/18 19:35	Accident Photo		☒
11	09/01/18 19:35	Accident Photo		☒
12	09/01/18 19:35	Accident Photo		☒
13	09/01/18 19:35	Accident Photo		☒
14	09/01/18 19:35	Accident Photo		☒

			1 per page	☒
Assessment Reports			Thumbnail	Print
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	1 per page	☒
Documentation			Thumbnail	Print
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Load TIF	
1	09/01/18 19:37	Sketch Plan		

Documents Checklist

Reset	Save	Print
-------	------	-------

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18001064/ACD3E2

Date: 11/09/2019

REFERENCE

Insured/Claimant: CHUA NGEOK YIN Policy No: 2100510210
Date of Loss: 09/01/2018 Nature of Claim: OD Claim No: 6043922658SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ724M**
Make & Model: AUDI Q5, 2.0 (A) Engine No: DAX005220
Reg. Date: 27/06/2017 (Man. Year: 2017) Chassis No: WAUZZZF3H2022473
Colour: White Odometer: 21732 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$190,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	68,459.30	44,076.64	24,382.66	35.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	42,476.00	29,226.00	13,250.00	31.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	110,935.30	73,302.64	37,632.66	33.92
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	109,935.30	72,302.64	37,632.66	34.23
+ GST 7.00/7.00% (S\$)	7,695.47	5,061.18	2,634.29	34.23
Nett Amount (S\$)	117,630.77	77,363.82	40,266.95	34.23

INSPECTION

Date of Assignment: 17/01/2018

Date Inspected: 17/01/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 35.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR DOOR - LH	Distorted	2,792.00 FS	*2,233.60 FS
2	2	*REAR OUTER DOOR SEAL - LH	Necessary	373.00 FS	*298.00 FS
3	1	*BONDING AGENT	Not Necessary	43.00 FS	*- FS
4	1	*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
5	1	*SEALING STRIP	Not Necessary	14.00 FS	*- FS
6	1	*REAR DOOR CATCH - LH	Damaged	127.00 FS	*101.60 FS
7	1	*SILL PANEL SEAL - LH	Necessary	223.00 FS	*178.40 FS
8	1	*REAR DOOR LOCK - LH	Not Necessary	580.00 FS	*- FS
9	1	*REAR SIDE WINDOW GUIDE RAIL - LH	Not Necessary	62.00 FS	*- FS
10	1	*REAR WINDOW REGULATOR WITHOUT MOTOR - LH	Not Necessary	267.00 FS	*- FS
11	1	*REAR DOOR COVER - LH	Distorted	553.00 FS	*442.00 FS
12	1	*REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH	Not Necessary	509.00 FS	*- FS
13	1	*REAR DOOR TRIM - LH	Not Necessary	1,671.00 FS	*- FS
14	1	*SIDE PANEL - LH	Distorted	3,913.00 FS	*3,130.40 FS
15	1	*REAR INNER SIDE PANEL - LH	Repair	1,414.00 FS	*- FS
16	1	*REAR D-PILLAR REINFORCEMENT - LH	Bent	477.00 FS	*381.60 FS
17	1	*REAR WHEEL HOUSING - LH	Distorted	575.00 FS	*461.20 FS
18	1	*REAR C - PILLAR REINFORCEMENT - LH	Bent	199.00 FS	*159.20 FS
19	1	*REAR SIDE MEMBER - LH	Repair	629.00 FS	*- FS
20	1	*REAR WHEEL HOUSING LINER - LH	Torn	231.00 FS	*184.80 FS
21	1	*WHEEL HOUSING LINER ATTACHEMENT PARTS	Necessary	32.10 FS	*25.68 FS
22	1	*REAR SILL TRIM STRIP - LH	Necessary	123.00 FS	*98.40 FS
23	2	*REAR WHEEL COVER - LH/RH	Necessary	938.00 FS	*749.60 FS
24	1	*REAR SIDE WINDOW - LH	Necessary	724.00 FS	*579.20 FS
25	1	*PRIMER	Necessary	19.00 FS	*14.56 FS
26	2	*REAR BUMPER	Distorted	2,512.00 FS	*2,009.60 FS
27	1	*REAR BUMPER SPOILER	Deformed	718.00 FS	*574.00 FS
28	1	*REAR TRIM - LH	Not Necessary	201.00 FS	*- FS
29	1	*TAIL LIGHT - LH	Cracked	619.00 FS	*494.80 FS
30	1	*REAR BUMPER CARRIER	Not Necessary	786.00 FS	*- FS
31	1	*REAR BUMPER HOLDING STRAP	Not Necessary	142.00 FS	*- FS
32	1	*REAR BUMPER GUIDE SECTION - LH	Damaged	71.00 FS	*56.80 FS
33	2	*REAR BUMPER SENSOR	Not Necessary	421.00 FS	*- FS
34	1	*REAR BUMPER SENSOR SEAL - O-RING	Not Necessary	15.00 FS	*- FS
35	1	*SET REAR BUMPER WIRING	Not Necessary	440.00 FS	*- FS
36	1	*REAR LID	Buckled	3,776.00 FS	*3,020.80 FS
37	1	*WHETHER STRIP	Not Necessary	338.00 FS	*- FS
38	1	*REAR LID STOP BUFFER	Not Necessary	48.00 FS	*- FS
39	1	*ADHESIVE PACKING	Necessary	15.00 FS	*11.60 FS
40	1	*AUDI EMBLEM	Necessary	108.00 FS	*86.00 FS
41	1	*INSCRIPTION Q5	Necessary	83.00 FS	*66.16 FS
42	1	*INSCRIPTION TFSI	Necessary	83.00 FS	*66.16 FS
43	1	*INSCRIPTION QUATTRO	Necessary	83.00 FS	*66.16 FS
44	1	*REAR BUMPER SPOILER FIXING PARTS	Necessary	17.00 FS	*13.04 FS
45	1	*FOAM STRIP	Necessary	17.00 FS	*13.04 FS
46	1	*REAR WINDOW	Necessary	1,020.00 FS	*816.00 FS
47	1	*PRIMER	Necessary	19.00 FS	*14.56 FS
48	1	*LED TAIL LIGHT	Not Necessary	1,432.00 FS	*- FS
49	1	*REAR ALUMINIUM RIM - LH	Cut	914.00 FS	*731.20 FS
50	1	*REAR SUMMER RADIAL TYRE - LH	Punctured	1,111.00 FS	*480.00 FS
51	1	*TYRE RUBBER VALVE	Not Necessary	12.00 FS	*- FS
52	1	*REAR SUBFRAME	Bent	2,804.00 FS	*2,243.20 FS
53	1	*CONTROL ARM - LOWER	Bent	762.00 FS	*609.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*CONTROL ARM - UPPER FRONT	Bent	524.00 FS	*419.20 FS
55	1		*CONTROL ARM - LEFT FRONT	Bent	163.00 FS	*130.40 FS
56	1		*CONTROL ARM - LEFT REAR	Bent	492.00 FS	*393.20 FS
57	1		*STEERING TIE ROD	Bent	226.00 FS	*180.80 FS
58	1		*REAR WHEEL BEARING HOUSING - LH	Damaged	960.00 FS	*768.00 FS
59	1		*REAR SPEED SENSOR	Damaged	87.00 FS	*69.04 FS
60	1		*REAR STONE CHIP GUARD - LH	Necessary	38.00 FS	*23.76 FS
61	1		*REAR DRIVE SHAFT - LH	Damaged	1,750.00 FS	*1,400.00 FS
62	1		*REAR GAS SHOCK ABSORBER	Bent	1,287.00 FS	*1,029.60 FS
63	1		*REAR COUPLING ROD	Bent	77.00 FS	*60.96 FS
64	1		*REAR EXHAUST SILENCER	Not Necessary	1,216.00 FS	*- FS
65	1		*REAR EXHAUST SILENCER BRACKET	Not Necessary	35.00 FS	*- FS
66	1		*FRONT WINDSCREEN	Not Necessary	1,270.00 FS	*- FS
67	1		*PRIMER	Necessary	19.00 FS	*14.56 FS
68	1		*GEL FOIL FOR RAIN SENSOR	Necessary	127.00 FS	*101.20 FS
69	1		*MOULDED HEADLINER	Crumpled	3,216.00 FS	*2,572.80 FS
70	1		*HEAD AIR BAG UNIT	N/S Activated	5,414.40 FS	*2,707.20 FS
71	1		*AIR BAG CRASH SENSOR	Activated	267.00 FS	*213.20 FS
72	1		*AIR BAG CONTROL UNIT	Activated	1,870.00 FS	*1,496.00 FS
73	1		*A-PILLAR TRIM - LH	Deformed	208.00 FS	*166.40 FS
74	1		*A-PILLAR TRIM - RH	Deformed	208.00 FS	*166.40 FS
75	1		*B-PILLAR TRIM - LH UPPER	Not Necessary	264.00 FS	*- FS
76	1		*B-PILLAR TRIM - LH LOWER	Not Necessary	264.00 FS	*- FS
77	2		*C-PILLAR TRIM	Not Necessary	550.00 FS	*- FS
78	2		*AUTOMATIC SEAT BELT WITH BELT TENSIONER	N/S Activated	1,912.00 FS	*1,529.60 FS
79	1		*SEAT BELT HEIGHT ADJUSTER	Damaged	306.00 FS	*244.80 FS
80	1		*SUNDRIES	Necessary	1,000.00 FS	*518.16 FS
81	1		*STONE CHIP	Necessary	360.00 FS	*360.00 FS
82	1		*CAVITY WAX	Necessary	180.00 FS	*180.00 FS
83	1		*ACRYLIC SEALER	Necessary	360.00 FS	*360.00 FS
84	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
85	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
86	1		*QUARTER GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
87	1		*LHS REAR LEVEL SENSOR	Damaged	228.80 FS	*228.80 FS
88	4		*ROOF GRAB HANDLE	Damaged	396.80 FS	*396.80 FS
89	2		*ADHESIVE TAPE	Necessary	83.52 FS	*83.52 FS
90	1		*LHS REAR D PILLAR REINFORCEMENT (TOP)	Bent	314.40 FS	*314.40 FS
91	1		*LHS REAR FENDER INNER TRIM	Deformed	704.00 FS	*704.00 FS
92	1		*LHS FRONT SEAT LEATHER COVER	Torn	2,158.40 FS	*2,158.40 FS
93	1		*LHS FRONT SEAT AIRBAG	Activated	1,102.40 FS	*1,102.40 FS
94	1		*LUGGAGE COMPT LIGHT SWITCH	Damaged	64.00 FS	*64.00 FS
95	1		*LHS REAR SEAT REMOTE CONTROL CABLE	Damaged	100.40 FS	*100.40 FS
96	1		*REAR LID LOCK BOWEN CABLE	Damaged	34.16 FS	*34.16 FS
97	1		*BATTERY FUSE UNIT	Damaged	376.00 FS	*376.00 FS
98	1		*LHS REAR UNDERBODY TRIM	Torn	92.80 FS	*92.80 FS
99	5		*WIRE JOINTS	Damaged	218.80 FS	*218.80 FS
100	1		*LHS REAR WHEEL CAP	Distorted	69.44 FS	*69.44 FS
101	1		*LHS REAR VENT TRIM	Distorted	47.44 FS	*47.44 FS
102	1		*LHS/RHS REAR WINDSCREEN SPOILERS	Necessary	320.80 FS	*320.80 FS
103	2		*2K SOUND INSULATION FOAM PACK	Necessary	188.00 FS	*188.00 FS
104	1		*CONTROL UNIT FOR CONVENIENCE SYSTEM	Damaged	1,085.60 FS	*1,085.60 FS
105	1		*MOUNTING FOR CONTROL UNIT	Damaged	24.08 FS	*24.08 FS
106	1		*MOUNTING FOR FUSE HOLDER	Damaged	28.96 FS	*28.96 FS
107	1		*REAR BOTTOM PLATE - LH	Distorted	428.00 FS	*342.00 FS
108	1		*REAR EXHAUST SILENCER DUAL CLIP	Not Necessary	43.00 FS	*- FS

F=Franchise part. S=SpcNett

Total Parts (\$\$) 68,459.30 44,076.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SET UP CAR ON CAR-O-LINER FOR FIRST MEASUREMENT	New	800.00	800.00
2	TO REMOVE AND RENEW REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS, ALL ELECTRICAL TRAYS FOR FUSE AND RELAYS, AUDIO EQUIPMENT, CONTROL UNITS, UNCLUDING REAR LID WIRING AND MULTI-LOCK AND HYDRAULIC SYSTEM	New	1,800.00	1,800.00
4	TO REMOVE AND REINSTALL ALL REAR PASSENGER SEATS, LUGGAGE COMPARTMENT TRIMS, PILLARS, CURTAIN AIR BAGS, ROOF LINER	New	1,800.00	1,800.00
5	TO RENEW FRONT AND REAR WINDSCREENS, AND LHS REAR SIDE WINDOW	New	1,000.00	600.00
6	TO REMOVE AND REINSTALL CENTRE CONSOLE, RENEW AIR BAG CONTROL UNIT, BOTH FRONT SEAT BELTS, CURTAIN AIRBAGS AND ROOF LINER	New	2,800.00	2,800.00
7	TO SUSPEND ENGINE, REMOVE AND INSTALL FRONT SUSPENSION FOR CAR-O-LINER REPAIRS	New	2,800.00	0.00
8	TO REMOVE REAR EXHAUST SILENCERS, DISMANTLE REAR SUSPENSION ASSY. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	New	3,200.00	3,200.00
9	TO SET UP AND PLACE VEHICLE ON CAR-O-LINER	New	2,400.00	1,800.00
10	TO DISMANTLE LHS REAR DOOR, REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR CROSS PANEL, REINFORCEMENTS, LHS REAR FENDER, OUTER WHEEL HOUSE, C-PILLAR, CONNECTING PLATES AND LHS SILL PANEL. RENEW LHS REAR DOOR, REAR BUMPER ASSY AND REAR LID. ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	New	15,400.00	9,500.00
11	TO RENEW LHS REAR RIM AND TYRE. CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	576.00	576.00
13	TO REMOVE AND RENEW LHS FRONT LEATHER SEAT	New	480.00	480.00
14	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM, POWER WINDOW DEVICES AND ROLLER SUNBLIND. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	360.00	360.00
15	TO CARRY OUT JOINT SEALER WORKS, STONE CHIP TREATMENT. RESPRAY LHS REAR DOOR, DOOR COVER, REAR BUMPER ASSY, LOWER SPOILER, WHEEL ARCH TRIMS, REAR LID, LHS REAR FENDER, CONNECTING PLATES, WHEEL HOUSING, SILL PANEL, DOOR ENTRANCES, DRAIN PANEL, ROOF CHANNEL AND END PANEL	New	8,500.00	4,950.00
Gross Labour Cost (S\$)			42,476.00	29,226.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >