

REF: CC3 / ATG 18001065 / ABn2

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 2100136019
 Claims No. 7133080208
 Sum Insured: _____ Excess: \$1400
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 53K.
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 05 hrs days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: STQ 700E. Yr Regn: 2009 May.
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi TTC c.c. 1984
 Colour: Grey. A/C: Insured / Std / NI / NA
 Sp Reading: 17020 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: TRU2228J591024838
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/50R17.
 R: 225/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm
L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
D.O.A. _____		D.O.I. <u>17/01/18</u>	
Survey held at: <u>Premium.</u>			
Des. of Damages: <u>Fr</u> / Rear / O/S / N/S / U/C / Rooftop or			

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD ALG.

RT-1 Report via merimen

MV: 53K

PV: 29.6K

Nett: 23.4K

STQ 700E - X

19/1 - 12:04pm authorise repair by victor
 19/1 @ 1:47pm email premium authorise repair
 excess \$1400

Part by Part \$9047.96, 5days

RECEIVED 04 JUL 2018 Cred. 9867.04; 52%.

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

00
 9047.96

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation

Add Fee:

☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Photo

Others

TOTAL

200

10

210




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18001065/Atb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-01-2018	
		Code : AIG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SJQ 700E
Policy No.	2100136019	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/01/2018	Inspection Date	17/01/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

1/18/2018

Adjuster Immediate Advice

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 18 Jan 2018

Preliminary Advice

Vehicle No	: SJQ700E	Accident Date	: 16/01/2018
Make	: AUDI TTC	Policy No.	: 2100136019-08000
Assignment Date	: 17/01/2018	Excess	: S\$0.00
Date of Inspection	: 17/01/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,863.00
Revised Amount	:S\$	8,458.00
Check Items (Estimated)	:S\$	6,680.00
Total	:S\$	15,138.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 19 January 2018 1:47 PM
To: Claims Dept; SUR
Subject: RE: SJQ 700 E Own Damage Claim (Veh IN)

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJQ 700E (Excess \$1,400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Wednesday, 17 January 2018 9:50 PM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: SJQ 700 E Own Damage Claim (Veh IN)

Dear all,

Kindly assist in the Own Damage Claim for the above mentioned vehicle.

Survey was done earlier this morning by Adrian.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with :

***SJQ700E (7133808020SG)**

OD

Jan 16 2018 2:25PM

[CHUA SOCK KOONG]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 19/01/2018 12:04 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8458.00) - SJQ700E - Claim Handler: Chan, Kian Meng

Approved:8458.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0930C
Vehicle Details	
Vehicle No.:	SJQ700E
Vehicle to be Exported:	Yes
Intended De-registration Date:	17 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	TTC 2.0 TFSI S-TRONIC
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	BWA262557
Chassis No.:	TRUZZZ8J591024838
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$52,734.00
Original Registration Date:	30 Mar 2009
First Registration Date:	30 Mar 2009
Transfer Count:	0
Actual ARF Paid:	\$52,734.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Mar 2019
PARF Rebate Amount:	\$29,003.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$5,001.00
COE Rebate Amount:	\$599.00
Total Rebate Amount:	\$29,602.00

The information contained herein is correct as at 17 Jan 2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0930C
Vehicle Details	
Vehicle No.:	SJQ700E
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	TTC 2.0 TFSI S-TRONIC
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	BWA262557
Chassis No.:	TRUZZZ8J591024838
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$52,734.00
Original Registration Date:	30 Mar 2009
First Registration Date:	30 Mar 2009
Transfer Count:	0
Actual ARF Paid:	\$52,734.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Mar 2019
PARF Rebate Amount:	\$29,003.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$5,001.00
COE Rebate Amount:	\$598.00
Total Rebate Amount:	\$29,601.00

The information contained herein is correct as at 18 Jan 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1240930C



Name

CHUA SOCK KOONG

蔡淑君

Race

CHINESE

Date of Birth

14-09-1957

Sex

F

Country of Birth

SINGAPORE



2251801



NRIC No. S1240930C

Blood Group

O+

Date of issue

08-08-1994

15A DEI TIONG HAM PARK
SINGAPORE 268302

NRIC No: S1240930C

Date: 04-07-2006

No: 5360903

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S1126802A

Name:

LEE SWEE KIAT

Birth Date: 31 Mar 1955

Issue Date: 26 Dec 2002



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

PASS DATE

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

04 Jan 1973



Licence No: S1126802A

NP 428A



HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100136019-08000

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$1400.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value

INSURING WITH COE/PAF Yes

1) VEHICLE REGISTRATION NO.

SJQ700E

2) NAME OF INSURED

Chua Sock Koong

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

30 Mar 2017

4) DATE OF EXPIRY OF INSURANCE

29 Mar 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

SUBJECT TO AGE CONDITION: All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Bld D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

* NAMED DRIVER Lee Swee Kiat

HIRE PURCHASE COMPANY NA
/EMPLOYER'S LOAN

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 9 Mar 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCSAN.



24-hours AIG Auto Hotline: (65) 6338 6200

Important: Keep this document in your car

What can the 24-hour AIG Auto Hotline do for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or approved workshops within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the Police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other vehicle(s) — if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or approved workshops within 24 hours or the next working day of the accident.

What to do in the event of an accident?

- Keep calm and move to a safe place
- Do not admit or discuss fault or blame
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or approved workshops within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party to AIG immediately.

15 DAYS LOSS OF USE / CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details.

Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certification of Insurance (CI) should be produced without demand when collecting the Rental Car and Premium Automobiles Pte Ltd reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder. The validity of this benefit is conditional upon the Motor Policy insured herein being in force.

Steps to activate Loss of Use / Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please call Premium Automobiles Pte Ltd at 64741223 after filing/reporting your accident claim.
2. Your rental car will be made available within 3 hours of activation with Premium Automobiles Pte Ltd, subject to availability.
3. At the time of collection of the Rental Car, the original insurance policy and scheduled issued by AIG, a copy of the Accident Report from the Authorised Workshop must be produced.
4. The number of days of loss of use entitlement is based on the period your vehicle is in the repair workshop subject to a maximum of 15 days.
5. A refundable security deposit of S\$350 is required by the rental company during each rental period.
6. The rental car will be picked up and returned at Premium Automobiles Pte Ltd upon activation of the benefit.
7. Rental cars are strictly for use in Singapore only. Additional premium of S\$35/- per day is applicable if the rental car is to be driven to Malaysia.
8. Extension of rental beyond repair period approved by AIG surveyor will be chargeable to customer by the rental company on per day basis.
9. Upgrade of Rental Car is available upon request subject to additional charges by the rental company.
10. Excess liability for all Rental Cars is S\$3,000. Customers may choose to reduce the liability to S\$1,600 per day and by paying the Collision Damage Waiver of S\$25 per day.

For use of Rental Car in Malaysia, additional excess liability of \$2,000 applies.

If owner fails to inform Premium Automobiles Pte Ltd that he is travelling into Malaysia using the Rental Car and if any accident happens, the entire cost of repair will be the owner's sole responsibility. Premium Automobiles Pte Ltd reserves the right to pursue the full repair cost against the owner.

Additional age requirement

Minimum 23 years old to maximum 65 years old with at least 2 years of driving experience

Premium Automobiles Pte Ltd Operations Hours

Monday to Friday: 0900hrs - 1800hrs

Saturday: 0900hrs to 1300hrs except Sundays and Public Holidays

Customer Service Line: 64741223 Facsimile: 67457823

55 Ubi Road 1 Singapore 408699

*Premium Automobiles' Terms & Conditions apply

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Insured is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

The Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agree to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Copyright in this Policy is reserved. No part of this Policy may be reproduced in whole or part without the express consent of AIG Asia Pacific Pte. Ltd.

AIG Building, 78 Shenton Way #07-16 Singapore 079120

AIG Asia Pacific Insurance Pte. Ltd.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0074/2018/JT
Date	:	17-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mdm Chua Sock Koong
Address	:	15A Oei Tiong Ham Park Singapore 268302
Telephone	:	HP +65 9633 9997
Type of Claim	:	Own Damage Claims
Policy No.	:	2100136019-08000
Vehicle No	:	SJQ 700 E
Model Code	:	Audi TTC 2.0 TFSI
Model / Year	:	Mar-09
Engine No	:	BWA 262557
Chassis No	:	TRUZZZ8J591024838
Mileage	:	
Date In	:	16-Jan-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	16-Jan-18
Place of Accident	:	Bt Timah Road just before Newton Circus

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJQ 700 E.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organize front crash management components. Reinstall all parts removed.	\$ 2,800.00 1000 ✓	✓
3	To respray front bumper and bonnet.	\$ 1,700.00 1100 ✓	✓
4	To respray and install front AGA bodykit.	S/N \$ 780.00 ?? ✓	✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 5,832.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJQ 700 E.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Rehd</i>	\$ 1,455.00	✓ 1164
2	FRONT REINFORCEMENT <i>NE NE</i>	\$ 765.00	X
3	FRONT BUMPER BOLTS <i>NE NE</i>	8 \$ 108.00	X
4	REINFORCEMENT BEAM FOAM PIECE <i>Rehd.</i>	\$ 90.00	? 7192
5	FRONT HOLDER FOR BUMPER - LHS/RHS <i>NE</i>	\$ 62.00	X
6	FRONT BUMPER RADIUS ROD <i>NE</i>	\$ 93.00	?
7	FRONT BUMPER CORNER COVER - LHS/RHS <i>NE</i>	\$ 134.00	+
8	FRONT AIR GRILLE - LHS/RHS <i>NE</i>	\$ 230.00	?
9	RADIATOR GRILLE <i>Conc'd</i>	\$ 679.00	✓ 542.20
10	CAUTION STICKER <i>NE</i>	\$ 12.00	✓ 9.28
11	FRONT BUMPER SKIRT <i>Rehd</i>	TBC	X 536.00
12	BONNET <i>Dented</i>	\$ 3,619.00	✓ 2895.20
13	BONNET CATCH HOOK <i>NE</i>	\$ 112.00	+
14	BONNET NOTICE STICKER <i>Not NE</i>	\$ 17.00	+
15	A/C STICKER <i>NE</i>	\$ 16.00	✓ 12.16
16	HEADLIGHT - LHS/RHS <i>NE</i>	\$ 4,314.00	?
17	FRONT NO. PLATE <i>NE</i>	S/N \$ 25.00	✓ 25
18	SUNDRIES <i>NE</i>	\$ 300.00	? 55.36
TOTAL SPARE PARTS		\$ 12,031.00	
TOTAL LABOUR CHARGES		\$ 5,832.00	
GRAND TOTAL		\$ 17,863.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 17/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : All Authorised, 05 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0074/2018/JT 23-Jan-18 CHANG 1 of 1 SJQ 700 E Audi TTC 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	SIGNAL HORN - LH/RH <i>2nd.</i>	\$ 318.00	\$ 253.60
2	Front bumper lower skirt sealant <i>new</i>	\$ 64.00	\$ 50.64
TOTAL PARTS :		\$ 382.00	\$ 304.24
GRAND TOTAL :		\$ 382.00	

Adrian Ling
sls

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0074/2018/JT
Date	:	17-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

5 days - ok - jb - 31 May 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mdm Chua Sock Koong
Address	:	15A Oei Tiong Ham Park Singapore 268302
Telephone	:	HP +65 9633 9997
Type of Claim	:	Own Damage Claims
Policy No.	:	2100136019-08000
Vehicle No	:	SJQ 700 E
Model Code	:	Audi TTC 2.0 TFSI
Model / Year	:	Mar-09
Engine No	:	BWA 262557
Chassis No	:	TRUZZZ8J591024838
Mileage	:	
Date In	:	16-Jan-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	16-Jan-18
Place of Accident	:	Bt Timah Road just before Newton Circus

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJQ 700 E.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organize front crash management components. Reinstall all parts removed.		\$ 2,800.00	\$ 1,000.00
3	To respray front bumper and bonnet.		\$ 1,700.00	\$ 1,100.00
4	To respray and install front AGA bodykit. (Body kit cannot be re-use)	S/N	\$ 780.00	\$ 780.00
5	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 5,832.00</u>	<u>\$ 3,432.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJQ 700 E.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,455.00	\$ 1,164.00
2	FRONT REINFORCEMENT	\$ 765.00	
3	FRONT BUMPER BOLTS	8 \$ 108.00	
4	REINFORCEMENT BEAM FOAM PIECE	\$ 90.00	\$ 71.92
5	FRONT HOLDER FOR BUMPER - LHS/RHS	\$ 62.00	
6	FRONT BUMPER RADIUS ROD	\$ 93.00	
7	FRONT BUMPER CORNER COVER - LHS/RHS	\$ 134.00	
8	FRONT AIR GRILLE - LHS/RHS	\$ 230.00	
9	RADIATOR GRILLE	\$ 679.00	\$ 542.80
10	CAUTION STICKER	\$ 12.00	\$ 9.28
11	FRONT BUMPER SKIRT	\$ 670.00	\$ 536.00
			*cannot be reuse
12	BONNET	\$ 3,619.00	\$ 2,895.20
13	BONNET CATCH HOOK	\$ 112.00	
14	BONNET NOTICE STICKER	\$ 17.00	
15	A/C STICKER	\$ 16.00	\$ 12.16
16	HEADLIGHT - LHS/RHS	\$ 4,314.00	
17	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00
55	SUPPLEMENTARY	\$ 382.00	\$ 304.24
20	SUNDRIES	\$ 300.00	\$ 55.36
	TOTAL SPARE PARTS	\$ 13,083.00	\$ 5,615.96
	TOTAL LABOUR CHARGES	\$ 5,832.00	\$ 3,432.00
	GRAND TOTAL	\$ 18,915.00	\$ 9,047.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SJQ 700 E

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0074/2018/MAS

29 June 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SJQ 700 E, Audi TTC 2.0T FSI

With reference to the above-mentioned vehicle, no. **SJQ 700 E**, claimant, **Mdm. Chua Sock Koong**, please find the related document per attached.

1. A copy of the Original invoice no. 85012659 – S\$8,183.32
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SJQ 700 E

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jan 2018 14:18		17 Jan 2018 17:18 Edit Adj Rpt	S\$9,047.96 Edit Estimates	S\$9,047.96 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

CHUA SOCK KOONG, ID: S1240930C, Tel: +6596339997

Vehicle Reg. No.:

SJQ700E

Date of Loss:

16/01/2018 14:00 - :59
[105 Months and 17 Days From LTA Reg Date (Man Yr)]

Claim Type:

OD / 7133808020SG

Policy/Cover Note No.:

2100136019 (Comprehensive)
Coverage: 30/03/2017 - 29/03/2018

Excess:

S\$1,400.00

Repairer:

Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng]
kianmeng.chan@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/01/2018]

Driver/Custodian:

LEE SWEE KIAT (62 / Male), NRIC: S1126802A, Tel: +6596788385

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

- AIG_SG (21/06/2018): Alert - Adj Mandate Approved (S\$9047.96) - SJQ700E - Claim Handler: Chan, Kian M...
- AIG_SG (19/01/2018): Alert - Adj Mandate Approved (S\$8458.00) - SJQ700E - Claim Handler: Chan, Kian M...
- AIG_SG (19/01/2018): SJQ700E / OD / 16/01/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJQ700E (7133808020SG)

OD














Jan 16 2018 2:00PM

[CHUA SOCK KOONG]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		Use Viewer	
Assessment Reports															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	18/01/18 14:34	Adjuster Immediate Advice													Load HTM			
2	21/06/18 10:31	Adjuster Immediate Advice													Load HTM			
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
2	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
3	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
4	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
5	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
6	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
7	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
8	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
9	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
10	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
11	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
12	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
13	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
14	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
15	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
16	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
17	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
18	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
19	18/01/18 14:11	General View													Load JPG	<input checked="" type="checkbox"/>		
20	01/06/18 16:00	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
21	01/06/18 16:00	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
22	01/06/18 16:00	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
23	01/06/18 16:00	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
24	01/06/18 16:00	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
25	01/06/18 16:00	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
26	01/06/18 16:00	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
27	01/06/18 16:00	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
28	01/06/18 16:01	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
Documentation															1 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	18/01/18 14:11	Certificate of Insurance													Load PDF			
2	18/01/18 14:11	Driver's Driving License													Load PDF			
3	18/01/18 14:11	Singapore Accident Statement													Load PDF			
4	18/01/18 14:38	ESTIMATE													Load PDF			
5	21/06/18 10:19	SUPPLEMENTARY													Load PDF			
6	21/06/18 10:19	ESTIMATE													Load PDF			
7	31/07/18 15:27	WORKSHOP INVOICE													Load PDF			
8	31/07/18 15:27	DISCHARGE VOUCHER													Load PDF			

Linked Accident Report Documents

			View	Use Viewer
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	16/01/18 18:00	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	16/01/18 17:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	16/01/18 17:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	16/01/18 17:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	16/01/18 17:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	16/01/18 17:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	16/01/18 17:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	16/01/18 17:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	16/01/18 17:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	16/01/18 17:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	16/01/18 17:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	16/01/18 17:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	16/01/18 17:49	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	16/01/18 17:49	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid #ccc; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18001065/ATBN2

Date: 31/07/2018

REFERENCE

Insured/Claimant: CHUA SOCK KOONG Policy No: 2100136019
Date of Loss: 16/01/2018 Nature of Claim: OD Claim No: 7133808020SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJQ700E
Make & Model: AUDI TTC, 2.0 TFSI S-TRONIC (A) Engine No: BWA262557
Reg. Date: 30/03/2009 (Man. Year: 2008) Chassis No: TRUZZZ8J591024838
Colour: Grey Odometer: 170120 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$53,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,871.24	5,615.96	7,255.28	56.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,832.00	3,432.00	2,400.00	41.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,703.24	9,047.96	9,655.28	51.62
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	17,303.24	7,647.96	9,655.28	55.80
+ GST 7.00/7.00% (S\$)	1,211.23	535.36	675.87	55.80
Nett Amount (S\$)	18,514.47	8,183.32	10,331.15	55.80

INSPECTION

Date of Assignment: 17/01/2018
Date Inspected: 17/01/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,455.00 FS	*1,164.00 FS
2	1		*FRONT REINFORCEMENT	Not Necessary	765.00 FS	*- FS
3	8		*FRONT BUMPER BOLTS	Not Necessary	108.00 FS	*- FS
4	1		*REINFORCEMENT BEAM FOAM PIECE	Deformed	90.00 FS	*71.92 FS
5	2		*FRONT HOLDER FOR BUMPER-LHS/RHS	Not Necessary	62.00 FS	*- FS
6	1		*FRONT BUMPER RADIUS ROD	Not Necessary	93.00 FS	*- FS
7	2		*FRONT BUMPER CORNER COVER-LHS/RHS	Not Necessary	134.00 FS	*- FS
8	2		*FRONT AIR GRILLE-LHS/RHS	Not Necessary	230.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	679.00 FS	*542.80 FS
10	1		*CAUTION STICKER	Necessary	12.00 FS	*9.28 FS
11	1		*FRONT BUMPER SKIRT	Deformed	536.00 FS	*536.00 FS
12	1		*BONNET	Dented	3,619.00 FS	*2,895.20 FS
13	1		*BONNET CATCH HOOK	Not Necessary	112.00 FS	*- FS
14	1		*BONNET NOTICESTICKER	Not Necessary	17.00 FS	*- FS
15	1		*A/C STICKER	Necessary	16.00 FS	*12.16 FS
16	2		*HEADLIGHT-LHS/RHS	Not Necessary	4,314.00 FS	*- FS
17	1		*FRONT NO PLATE	Necessary	25.00 FS	*25.00 FS
18	1		*SUNDRIES	Necessary	300.00 FS	*55.36 FS
19	2		*SIGNAL HORN-LH/RH	Damaged	253.60 FS	*253.60 FS
20	1		*FRONT BUMPER LOWER SKIRT SEALANT	Necessary	50.64 FS	*50.64 FS

F=Franchise part. S=SpcNett

Total Parts (\$\$)	12,871.24	5,615.96
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND BOTH HEADLIGHTS.RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	1,700.00	1,100.00
4	TO RESPRAY AND INSTALL FRONT AGA BODYKIT	New	780.00	780.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,832.00	3,432.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >