

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKM 8601 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle front bumper and renew rhs front fender. Inspect inner wheel housing for damage. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,500.00 ✓ 500 / 1000	✓
3	To respray rhs front fender.	\$ 800.00 ✓ 550	✓
4	To carry out wheel alignment.	S/N \$ 240.00 ✓	✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 3,092.00	