

CITYCAB PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 733H
 MAKE :
 MODEL : HYUNDAI i40

DATE 1/15/2018

AXA - Lsum

TS

6900

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender (LH) <i>X repair</i>			\$ 2,020.10	
	Rear Fender Inner Lining (LH/RH) <i>X</i>			\$ 164.40	
	Rear Windscreen Moulding <i>X</i>			\$ 60.00	
	Rear Door (LH)			\$ 1,351.10	
	Front Door Outer Handle (LH) <i>✓</i>			\$ 38.75	
	Front Door Mirror (LH) <i>✓</i>			\$ 980.50	
	SUB TOTAL			\$ 4,614.85	
	LESS 20%			\$ 922.97	
	DISCOUNTED TOTAL			\$ 3,691.88	
	Rear Windscreen Sealant <i>X</i>			\$ 46.00	Nett
	Rear Door Tel No. Sticker/Apps (LH) <i>✓</i>			\$ 10.00	Nett
	Front Door Coloured Comfort Logo (LH) <i>✓</i>			\$ 75.00	Nett
				\$ 131.00	
	Labour Charge				
	Panel Beating			\$ 850.00 <i>400</i>	
	Spray Painting Charge			\$ 700.00 <i>540</i>	
	Wiring Charge			\$ 30.00 <i>20</i>	
	Tuff Kote			\$ 50.00 <i>20</i>	
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 <i>50</i>	
	Remove/Refix Rear Windscreen Glass			\$ 120.00 <i>X</i>	
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X</i>	
	Transfer of Door			\$ 120.00 <i>50</i>	
	TOTAL LABOUR			\$ 2,140.00	
	ESTIMATE TOTAL			\$ 5,962.88	
	<i>1 Calm 16664</i> <i>17/1/18 1005hr.</i> <i>4 Days</i> <i>45</i> <i>After Repair photo</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before /after spray painting • To display damaged parts for resurvey • Parts prices are subject to resurvey • Third party surveyors on a "no liability" basis • No illegal modification(s) is allowed • Supplementary part(s) must be resurveyed • This estimate is subject to final approval from Insurance company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					