

22/03/2002

ASS. REC. BY:

REF: CS/FCL18001072/Agbez

Special Instruction:

SURVAYOR:

**ASSIGNMENT (Office)**

From (Person): CWS Karen Tan

of

FCL

Date/Time: 17/01/2018 6:01pm

Estimated Cost:

Bill to:

OD / TH / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 371211

Insured:

SHA 7256H

at Workshop m/s

New Hock Teck

Tel:

6747 9211

of

81k 1 Kaki Bukit Ave 6 #01-43

Policy No:

D18088936 MF5H

Claim No:

D18000130MF5H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/01/2018

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: 17/01/2018 6:08pm

Person Contacted:

Sukji

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ 371211 - CS / ALG / 3000911 / K12G3

XA: 150118

SHA 7256H - CS / FCL / 7000091 / T1G6

XA: 15112017

18/1/18 @ 4:42pm Informed Karen, we are pending estimate from repairer.

23/1/18 @ 7:27pm Revised to Karen Tan by email.

US \$12300, 12 days (Red \$ 9474.80, 44%)

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 78K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 12 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKZ3272H Yr Regd: 2006 Jan  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Mazda3 C.O. 1496  
 Colour: white A.C. Insured / Std / NI / NA  
 Sp. Reading: 66644 T. Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JM6BM42A8G0331676  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/60R16 Compasul  
 R: 205/60R16 Toy  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Compasul  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 17/01/18  
 Survey held at NHT  
 Des. of Damages Frn / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

MV: 78K  
 PV: 53K  
 Net: 25K

RECEIVED 26 FEB 2018

Date/Time. File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time. File Return to?

On \_\_\_\_\_

Days Of Repair: 12Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + PS \$

Photos 580

Others

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech. Adv \$☐ Weekend \$Report Format: TPLump Sum / I.B.I. (\$) 12300

16x15=240

170+240

50

50

18

645




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001072/Aqb	
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877		Date : 17-01-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHA 7256H	Veh. Inspected	SKZ 3272U
Policy No.		Coverage (\$)	0.00
Claim No.	D18000430MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	17/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	15/01/2018	Inspection Date	17/01/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	2911Z

### Vehicle Details

Vehicle No.:	SKZ3272U
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jan 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	P520344362
Chassis No.:	JM6BM42A8G0331676
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$15,269.00
Original Registration Date:	19 Jan 2016
First Registration Date:	19 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$10,269.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jan 2026
PARF Rebate Amount:	\$7,701.00

### Intended COE Rebate Details

COE Expiry Date:	18 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,989.00
COE Rebate Amount:	\$45,621.00
<b>Total Rebate Amount:</b>	<b>\$53,322.00</b>

The information contained herein is correct as at 16 Jan 2018

OK

## Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house?  
Sell it on Marketplace. Posting an advertisement is FREE!

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

2009 Toyota Rush 1.5X A At \$19.8K



Very Low Mileage And In A Good  
And Accident-Free Condition.  
Direct Owner - Noisy

**KA-HUP**

**HOTLINE: 6741 9997**

**VALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND**

[VIEW OUR CARS](#)

[Browse by Category](#)
[« Back \( 1 2 \) Next »](#)
[Sort by Date Posted](#)
[20 results/page](#)

24 vehicles

Mazda 3

Any Location Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>Mazda 3</b>		Any	Any	<b>2016</b>	Any	Any	Any	<b>Available</b>
	<b>Mazda 3 1.5A Deluxe</b>		<b>\$82,800</b>	<b>\$9,360 /yr</b>	<b>22-Feb-2016</b>	<b>1,496 cc</b>	<b>35,000 km</b>	<b>Sedan</b>	<b>Available</b>
Latest Arrival! Priced To Sell! 1 Careful Owner, Low Mileage Done At 35000km, 5 Years Warranty From Eurokars, Full Agent Service History, 3 Years Free Servicing Package, Low Depreciation At \$9200 Per ... Horizon Motoring Posted: 14-Jan-2018    Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	<b>Mazda 3 1.5A Deluxe</b>		<b>\$86,500</b>	<b>\$9,860 /yr</b>	<b>29-Feb-2016</b>	<b>1,496 cc</b>	<b>18,221 km</b>	<b>Sedan</b>	<b>Available</b>
Rare! Dark Blue Mazda 3 (Deluxe Model). Serviced At Eurokars With Valid Warranty, Last On Nov 17. Super Low Mileage Done 18221km, Totally Like New. 1 Lady Dentist Owner. 100% Accident Free. Call Now! Lake View Credit Pte Ltd Posted: 14-Jan-2018    Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	<b>Mazda 3 SP 1.5A</b>		<b>\$73,500</b>	<b>\$8,360 /yr</b>	<b>17-Mar-2016</b>	<b>1,496 cc</b>	<b>-</b>	<b>Sedan</b>	<b>Available</b>
Elegant White, With Sunroof, One Owner Only, Serviced By Agent, Low Maintenance Cost, Very Well Maintained, With Warranty, Drive Away With Minimum Down Payment, Flexible In House Loan Packages Availab... Prime Motor & Leasing Posted: 15-Jan-2018    Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	<b>Mazda 3 SP 1.5A</b>		<b>\$84,999</b>	<b>\$9,540 /yr</b>	<b>29-Mar-2016</b>	<b>1,496 cc</b>	<b>-</b>	<b>Sedan</b>	<b>Available</b>
High Spec! 1 Owner, Full Agent Service, Under Mazda Warranty, Premium 110 Points Check, Flexible Finance Package Can Be Arranged, Please SMS Now For Viewing And More Details! Premium Automobiles Posted: 04-Jan-2018    Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	<b>Mazda 3 1.5A Deluxe</b>		<b>\$82,800</b>	<b>\$9,260 /yr</b>	<b>15-Apr-2016</b>	<b>1,496 cc</b>	<b>31,000 km</b>	<b>Sedan</b>	<b>Available</b>
1 Owner And Lowest Mileage. Good Grey Mazda 3! Responsive And Reliable. Full Agent Serviced And Still Under Warranty, Condition As Good As New! Well Maintained By Owner! See To Believe, View By Appoin... Posted: 12-Jan-2018    Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	<b>Mazda 3 SP 1.5A</b>		<b>\$98,300</b>	<b>\$11,190 /yr</b>	<b>29-Apr-2016</b>	<b>1,496 cc</b>	<b>33,000 km</b>	<b>Sedan</b>	<b>Available</b>
Just Arrived Sporty White Mazda 3 Model! Most Popular Mazda Sedan For Your Family And Daily Usage. Fuel Consumption At 15Km/Litre. Very Clean Interior And Own By Non Smoker. Fuel Saving Yet Powerful D... Posted: 06-Dec-2017    Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	<b>Mazda 3 HB 1.5A SP</b>		<b>\$81,800</b>	<b>\$8,930 /yr</b>	<b>10-Jun-2016</b>	<b>1,496 cc</b>	<b>26,153 km</b>	<b>Hatchback</b>	<b>Available</b>
Viewing Strictly By Appointment Only. Three (3) Years Warranty By Agent. Posted: 03-Jan-2018    Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	<b>Mazda 3 SP 1.5A</b>		<b>\$78,800</b>	<b>\$8,510 /yr</b>	<b>30-Jun-2016</b>	<b>1,496 cc</b>	<b>40,000 km</b>	<b>Sedan</b>	<b>Available</b>

[Car Buying](#)
[Car Selling](#)
[Car Aftermarket](#)
[Car Ownership](#)
[On The Move](#)
[Lifestyle](#)

**Buddies Carplates**

**For Sale!**

MSME18008089 / SME Motor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 16/01/2018 15:38  
 SUBMITTED BY: Farida Wen Ya Ying

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/01/2018 15:38
Date Of Accident	15/01/2018 01:00
Exact Location Of Accident	COMMONWEALTH AVE WEST.
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ3272M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	BIZLINK RENT A- CAR PTE LTD
Co Reg No	200402911Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-92434885
<b>Vehicle Particulars</b>	
Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	0100782147
Cover Note Number	
<b>Driver</b>	
Name of Driver	KELVIN WONG JIA WEI
NRIC No	G6910236R
Date Of Birth	19/11/1992
Occupation	INDOOR
Date Of Driving Pass	07/09/2017
Driving Experience	0 YEAR AND 4 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91467898
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 15760 JALAN CAMER 9, BANDAR PUTRA 8100 KULAI, JOHOR  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I WAS DRIVING STRAIGHT ALONG COMMONWEALTH AVE WEST LANE OF 3 LANES. TRAFFIC LIGHT TURNED GREEN, I PROCEED TO MOVE ON. SUDDENLY, I FELT AN IMPACT VEHICLE B COLLIDED ONTO REAR PORTION OF MY VEHICLE AND CAUSED MY VEHICLES SURGED FORWARD COLLIDED ONTO VEHICLE C REAR PORTION. AFTER THE ACCIDENT, I ALIGHTED AND REALISED THERE WAS TOTAL 3 VEHICLES GET INVOLVED. I WISH MAKE A REPORT CLAIM AGAINST VEHICLE B.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHA7256H  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category TAXI  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)



## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHA2622S
Vehicle Make/Model/Colour	
Details Of Properties	VEH C
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to reudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 16/01/18

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Accident Sketch Plan Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight along Commonwealth Ave West at center lane of 3 lanes.

Traffic light turned green, I proceed to move on.

Suddenly, I felt an impact. Veh "B" collided onto rear portion of my vehicle and caused my vehicle surged forward collided onto veh "C" rear portion.

After the accident, I alighted and realised there was total 3 vehicles get involved.

I wish make a report claim against veh "B".

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

BIZLINK RENT A CAR PTE LTD

17/01/2018

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP 1st Cap  
Xiao Chen

JM6BM42A8G0331676

Accident date: 15/01/2018

Estimated repair cost for vehicle no: SKZ3272U MAZDA 3 4DR 1.5 A '16

CHASSIS: JM6BM42A8G0331676

S/n	Qty	Items	U/price	Amount
1	2	Front Head Lamp <i>cauled</i>	\$873.30	\$1,746.60 ✓
2	1	Front Bumper <i>delid</i>		\$925.10 ✓
3	10	Front Bumper Clip <i>m</i>	\$6.50	<del>\$65.00</del> 30
4	2	Front Bumper Side Retainer <i>m</i>	\$28.70	\$57.40 ✓
5	1	Front Bumper Emblem Logo <i>m</i>		\$74.40 ✓
6	1	Front Bumper Number Plate <i>cauled</i>		<del>\$50.00</del> 30 (sn)
7	2	Front Bumper Lower Side Cover <i>delid</i>	\$58.00	\$116.00 ✓
8	2	Front Bumper Fog Lamp <i>delid</i>	\$257.30	\$514.60 ✓
9	2	Front Bumper Fog Lamp Cover <i>delid</i>	\$42.70	\$85.40 ✓
10	1	Front Bumper Reinforcement <i>Best</i>		\$565.10 ✓
11	1	Front Bumper Reinforcement Centre Cover <i>cauled</i>		\$92.70 ✓
12	1	Front Grille <i>cauled</i>		\$233.70 ✓
13	8	Front Grille Clip <i>m</i>	\$6.50	<del>\$52.00</del> 20
14	2	Front Grille Side Chrome Moulding <i>at</i>	\$176.70	\$353.40 ✓
15	1	Front Grille Top Cover <i>delid</i>		\$335.00 ✓
16	1	Front Support Panel <i>cauled</i>		\$469.70 ✓
17	1	Front Support Panel Top Cover <i>cauled</i>		\$122.40 ✓
18	8	Front Support Panel Top Cover Clip <i>m</i>	\$6.50	<del>\$52.00</del> 20
19	1	Front Support Panel Top Panel <i>Best</i>		\$188.00 ✓
20	1	Front Air-Con Condenser <i>Best</i>		\$987.00 ✓
21	1	Front Radiator <i>m</i>		\$1,064.90
22	1	Body Logo (Special Nett) <i>m</i>		<del>\$750.00</del> 50 (20)
23	1	Rear Boot Lid <i>Buckled</i>		\$957.40 ✓
24	2	Rear Boot Lid Hinge <i>m</i>	\$145.30	\$290.60 ✓
25	1	Rear Boot Lid Emblem Logo <i>20</i>		\$74.40 ✓
26	1	Rear Boot Lid Mazda 3 Logo <i>m</i>		\$53.40 ✓
27	1	Rear Boot Lid Skyactiv Logo <i>↓</i>		\$63.60 ✓
28	2	Rear Boot Lid Side Reflector <i>10 m</i>	\$265.00	\$530.00 x

29	1	Rear Boot Lid Inner Lock	Dented		\$153.00	✓
30	1	Rear Boot Lid Inner Rubber	Lt		\$129.30	✓
31	1	Rear Boot Lid Inner Trim Board	2 m		\$120.20	✗
32	8	Rear Boot Lid Inner Trim Board Clip		\$6.50	\$52.00	✗
33	2	Rear Tail Lamp	Cracked	\$509.40	\$1,018.80	✓
34	4	Rear Tail Lamp Clip	Nm	\$8.00	\$32.00	✓
35	2	Rear Tail Lamp Lower Bracket	Nm	\$29.20	\$58.40	✗
36	1	Rear Bumper	Deformed		\$1,074.80	✓
37	8	Rear Bumper Clip	Nm	\$6.50	<del>\$52.00</del>	30
38	2	Rear Bumper Side Retainer	Nm	\$36.10	\$72.20	✓
39	2	Rear Bumper Side Reflector	Cracked	\$50.40	\$100.80	✓
40	2	Rear Bumper Towing Cover	LH Deformed	\$16.20	<del>\$32.40</del>	16.20
41	1	Rear Bumper Reinforcement	Bent		\$537.30	✓
42	1	Rear Bumper Reverse Sensor (Special Nett)	Downy		<del>\$380.00</del>	200/50
43	1	Rear End Panel	Dented		\$505.10	✓
44	1	Rear End Panel Top Garnish	Deformed		\$185.10	✓
45	2	Rear Fender Inner Trim Board	2 m	\$235.60	\$471.20	✗
46	16	Rear Fender Inner Trim Board Clip	2 m	\$6.50	\$104.00	✗
47	1	Rear Spare Tyre Panel Top Cover	Deformed		\$355.00	✓
48	1	Rear Spare Tyre Panel Inner Sponge	Cracked		\$223.00	✓
49	1	Rear Spare Tyre Panel & End Panel Sealant	Nm		<del>\$450.00</del>	600/50
50	1	Rear Exhaust	Bent		\$1,075.80	998.90
51	1	Rear Centre Exhaust	Nm		\$1,433.00	✗

Subtotal :- \$19,485.20

1351680

1081344

SN: 840

## Labour charges

To remove & refit cushion	<sup>60</sup> <del>\$280.00</del>
To remove & refit reverse sensor	<sup>50</sup> <del>\$100.00</del>
To remove & refit body logo	<sup>100</sup> <del>\$300.00</del>
To remove & refit air-con condenser, radiator, fan motor & top up gas	<sup>120</sup> <del>\$450.00</del>
To check wiring	<sup>60</sup> <del>\$100.00</del>
Tuff kote	<sup>40</sup> <del>\$150.00</del>
Towing fee	\$100.00 ✓
Panel beating	<sup>1800</sup> 3710. <del>\$3,000.00</del>
Spray painting	<del>\$2,400.00</del> <sup>1400</sup>
To remove and replace exhaust pipe	<sup>80</sup> <del>180</del>
Subtotal :-	<u>\$6,880.00</u>
Total:-	<u>\$21,774.80</u>

26545.2

total 15363.44  
1/5 D-3 K  
12 days

12.31K 12 days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001072/Aqbe2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 01-03-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7256H	Veh. Inspected	SKZ 3272U
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18000430MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	17/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6BM42A8G0331676	Colour	WHITE
Odometer	66644	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	COMPASAL	6 mm
L/H Front Tyre	205/60 R16	COMPASAL	6 mm
R/H Rear Tyre	205/60 R16	TOYO	6 mm
L/H Rear Tyre	205/60 R16	TOYO	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	15/01/2018	Inspection Date	17/01/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

## 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 3272U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
2	FRONT HEAD LAMP @\$873.30	CRACKED	1,746.60	1,746.60
1	FRONT BUMPER	DEFORMED	925.10	925.10
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$28.70	NECESSARY	57.40	57.40
1	FRONT BUMPER EMBLEM LOGO	NECESSARY	74.40	74.40
2	FRONT BUMPER LOWER SIDE COVER @\$58.00	DEFORMED	116.00	116.00
2	FRONT BUMPER FOG LAMP @\$257.30	CRACKED	514.60	514.60
2	FRONT BUMPER FOG LAMP COVER @\$42.70	DEFORMED	85.40	85.40
1	FRONT BUMPER REINFORCEMENT	BENT	565.10	565.10
1	FRONT BUMPER REINFORCEMENT CENTRE COVER	CRACKED	92.70	92.70
1	FRONT GRILLE	CRACKED	233.70	233.70
8	FRONT GRILLE CLIP @\$6.50	NECESSARY	52.00	20.00
2	FRONT GRILLE SIDE CHROME MOULDING @\$176.70	CUT	353.40	353.40
1	FRONT GRILLE TOP COVER	DEFORMED	335.00	335.00
1	FRONT SUPPORT PANEL	CRACKED	469.70	469.70
1	FRONT SUPPORT PANEL TOP COVER	CRACKED	122.40	122.40
8	FRONT SUPPORT PANEL TOP COVER CLIP @\$6.50	NECESSARY	52.00	20.00
1	FRONT SUPPORT PANEL TOP PANEL	BENT	188.00	188.00
1	FRONT AIR-CON CONDENSER	BENT	987.00	987.00
1	FRONT RADIATOR	NOT NECESSARY	1,064.90	-
1	REAR BOOT LID	BUCKLED	957.40	957.40
2	REAR BOOT LID HINGE @\$145.30	NOT NECESSARY	290.60	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	74.40	74.40
1	REAR BOOT LID MAZDA 3 LOGO	NECESSARY	53.40	53.40
1	REAR BOOT LID SKYACTIV LOGO	NECESSARY	63.60	63.60
2	REAR BOOT LID SIDE REFLECTOR @\$265.00	NOT NECESSARY	530.00	-
1	REAR BOOT LID INNER LOCK	DAMAGED	153.00	153.00
1	REAR BBOOT LID INNER RUBBER	CUT	129.30	129.30
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	120.20	-
8	REAR BOOT LID INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	52.00	-
2	REAR TAIL LAMP @\$509.40	CRACKED	1,018.80	1,018.80

Report Ref No. CS/FCI18001072/Aqbe2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	REAR TAIL LAMP CLIP @\$8.00	NECESSARY	32.00	32.00
2	REAR TAIL LAMP LOWER BRACKET @\$29.20	NOT NECESSARY	58.40	-
1	REAR BUMPER	DEFORMED	1,074.80	1,074.80
8	REAR BUMPER CLIP	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER @\$36.10	NECESSARY	72.20	72.20
2	REAR BUMPER SIDE REFLECTOR @\$50.40	CRACKED	100.80	100.80
2	REAR BUMPER TOWING COVER @\$16.20	N/S DEFORMED	32.40	16.20
1	REAR BUMPER REINFORCEMENT	BENT	537.30	537.30
1	REAR END PANEL	DENTED	505.10	505.10
1	REAR END PANEL TOP GARNISH	DEFORMED	185.10	185.10
2	REAR FENDER INNER TRIM BOARD @\$235.60	BROKEN	471.20	-
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	104.00	-
1	REAR SPARE TYRE PANEL TOP COVER	DEFORMED	355.00	355.00
1	REAR SPARE TYRE PANEL INNER SPONGE	CRACKED	223.00	223.00
1	REAR EXHAUST	BENT	1,075.80	998.90
1	REAR CENTRE EXHAUST	NOT NECESSARY	1,433.00	-
	LESS 20% DISCOUNT		-	-2,703.36
			17,855.20	10,813.44
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT BUMPER NUMBER PLATE (SN)	CRACKED	50.00	30.00
1	BODY LOGO (SN)	NECESSARY	750.00	550.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
1	REAR SPARE TYRE PANEL & END PANEL SEALANT (SN)	NECESSARY	450.00	60.00
			1,630.00	840.00
<b><u>LABOUR</u></b>				
	TO REMOVE & REFIT CUSHION.		280.00	60.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIT BODY LOGO.		300.00	100.00
	TO REMOVE & REFIT AIR-CON CONDENSER, FAN MOTOR & TOP UP GAS.		450.00	120.00
	TO CHECK WIRING.		100.00	60.00
	TUFF KOTE.		150.00	40.00
	TOWING FEE.	NOT NECESSARY	100.00	-

Report Ref No. CS/FCI18001072/Aqbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING.		3,000.00	1,800.00
	SPRAY PAINTING.		2,400.00	1,400.00
	TO REMOVE AND REPLACE EXHAUST PIPE.		180.00	80.00
			7,060.00	3,710.00
GRAND TOTAL			26,545.20	15,363.44

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			12,300.00
---	--	--	-----------

Report Ref No. CS/FCI18001072/Aqbe2

MARKET VALUE: \$78,000.00 (EST)-PAPER VALUE: \$53,000.00=NETT VALUE: \$25,000.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.