

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SH 8833T

DATE 15/1/2018

MAKE :

LKK - Calvin

0900

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ✓			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Advertisement Logo ✓			\$ 100.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 435.70	
	Labour Charge				
	Panel Beating			\$ 380.00 200	
	Spray Painting Charge			\$ 200.00 180	
	Wiring Charge			\$ 50.00 X	
	R/Refix Reverse Sensor			\$ 120.00 20	
	TOTAL LABOUR			\$ 750.00	
	ESTIMATE TOTAL			\$ 2,711.58	
	<i>Calvin 16/1/18</i>				
	<i>18/1/18 1000hrs</i>				
	<i>2 days</i>				
	<i>P/P</i>				
	<i>Before Paint photo</i>				
	<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part during resurvey • Parts prices • Third party survey • No illegal modifications • Supplemental work <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div> <div> <p>Prejudice" basis</p> <p>is all</p> <p>must be</p> <p>from insurance, or any</p> </div>				
	<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				