

ASS. REC. BY:

REF:

TM1 / CC3/TML18001084/Kb32

Kenseth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: GU 1068E

Policy No. MB 078445

Claims No. M1800369

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S170 99863 Yr Regn: 06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c. 1995

Colour

N. White / R.

A/C: Insured / Std / NI / NA

Sp. Reading

318283

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 278150

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S / Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Ling Long

Front

R/Bal.

7

mm

Rear

R/Bal.

D

mm

L/Bal.

7

mm

L/Bal.

D

mm

D.O.A.

15/1/18

D.O.I.

17/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/11

File parts to Centre

21 Rm @ 8250 (Red 37417.07, 82%)

S170 99863 - CC3 / MAXA 16007524 / Kb32

GU 1068E - NA / M1800369 / d2

18/11/18 @ 3.30 pm email GIA report & estimate to Shirley.

DIN: 200516

DIP: 010415

RECEIVED 1-3 JAN

Date/Time, File Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

2)

Report Format:

MER-78

Lump Sum / L.B.I: (\$

8250

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Photos

Others

TOTAL

250
10
260




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TOKIO MARINE INSURANCE SINGAPORE LTD		Ref : CC3/TMI18001084/Kqb		
20 MCCALLUM STREET #09-01 TOKIO MARINE CENTRESINGAPORE 069046		Date : 18-01-2018		
		Code : TMI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GU 1068E	Veh. Inspected	SHD 9996B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/01/2018	Inspection Date	17/01/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No. : CC2/Tail 8001084/K96
 Policy Type: OD / TP / TP RES / TL / EVA

SMD 9996B

Case Handler

Typist

Admin (Cath): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Kenneth): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By: Cath

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 18 January 2018 3:21 PM
To: Too Joon Hwa
Cc: Priscilla Tan; SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 15/01/2018, SHD 9996B (TP VEHICLE), GU 1068E (OI VEHICLE)
Attachments: SHD9996 EST.pdf; SHD9996 GIA & PR.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle SHD 9996B M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 17/01/2018.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD9996B

Vehicle to be Exported: Yes

Intended De-registration Date: 16 Jan 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2014

Engine No.: M9R8839C001430

Chassis No.: VF1ABL15AUC278150

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 13 Jun 2014

First Registration Date: 13 Jun 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 12 Jun 2022

PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date:	12 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$31,585.00
Total Rebate Amount:	\$40,958.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/01/2018 13:19
Date Of Accident	15/01/2018 14:40
Exact Location Of Accident	DEFU AVENUE 1 TOWARDS DEFU LANE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9996B
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	MOHAMED HUSIN BIN YAHAYA
NRIC No	S0575208F
Date Of Birth	18/09/1949
Occupation	OUTDOOR
Date Of Driving Pass	04/05/2010
Driving Experience	7 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97251443
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 527 HOUGANG AVE 6 #04-211
Postcode	530527
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180116/2033

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GU1068E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	RAHMAN SADUR
NRIC/Passport Number	G7925105X
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLK464U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

ABDUL MUHAJMIN BIN ADBDUL MALIK

NRIC/Passport Number

S8910768G

Contact Number

90023476

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MOHAMED HUSIN BIN YAHAYA

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHD9996B

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Defu Avenue 1

Towards

Defu Lane 4

A STD 99963

B GU 1068E

C SLK 464V

A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180116/2033

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No. T/20180116/2033

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/01/2018 10:21		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MOHAMED HUSIN BIN YAHAYA			Address: APT BLK 527 HOUGANG AVE 6 #04-211 HDB-HOUGANG SINGAPORE 530527		
ID Type / ID No.: NRIC NO / S0575208F			Contact No.: Home/Office: Mobile: 97251443		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 68	Date of Birth: 18/09/1949	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: TAXI DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident					
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 15/01/2018 14:40	Type of Location: T-Junction	
Location: Junction of Road 1 and Road 2 DEFU AVENUE 1 DEFU LANE 4					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light	
Type of Collision: CHAIN COLLISION				Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GU1068E	Lorry				Slightly Damaged	0
SHD9996B	TAXI				Slightly Damaged	1
SLK464U	Car				Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180116/2033

2 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180116/2033

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	RAHMAN SADUR	ID No.	G7925105X
Related Vehicle	GU1068E (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MOHAMED HUSIN BIN YAHAYA	ID No.	S0575208F
Related Vehicle	SHD9996B (TAXI)	Contact No.	97251443
Hospital/Clinic	RAFFLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	15/01/2018	Date Discharge	15/01/2018
No. of Days granted Medical Leave	05	Degree of Injury	NIL
Driver			
Name	ABDUL MUHAIMIN BIN ABDUL MALIK	ID No.	S8910768G
Related Vehicle	SLK464U (Car)	Contact No.	90023476
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE AND TIME

I WAS TRAVELLING ALONG DEFU AVENUE 1 INTENDING TO MAKE A RIGHT TURN TO DEFU LANE 4 BUT STOPPED WHEN THE TRAFFIC LIGHT TURNED RED. SUDDENLY THERE WAS A LORRY THAT HIT ME FROM BEHIND. I GOT OUT AND REALISED THAT ANOTHER CAR(SLK464U) HAD HIT THE BACK OF THE LORRY. WE EXCHANGED PARTICULARS. THE CAR DRIVER CALLED FOR THE POLICE AND AMBULANCE. POLICE CAME AND SHORTLY THE AMBULANCE CAME ALSO. THE CAR DRIVER AND I WAS CONVEYED TO RAFFLES HOSPITAL. I RECEIVED A 5-DAYS



**SINGAPORE
POLICE FORCE**



T/20180116/2033

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20180116/2033

CONTINUATION OF REPORT

MC FROM THE HOSPITAL.

**SINGAPORE
POLICE FORCE**

T/20180116/2033

4 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180116/2033

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

TP /
MUHAMMAD SYUKRI BIN ABU BAKAR

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /
Sr Staff Sgt RAZIZ BIN TAHAR
Contact No.: 65476200Authentication Stamp
NP168

Signature Of Informant:

Date/Time:

16/01/2018 10:21

Classification Of Case:

**SINGAPORE
POLICE FORCE**

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9996B - TOKIO**AAD1801-184***Not Authorised
1/15/2018 82506*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD9996B - CANDY

VF1ABL15AUC278150

RENAULT

LATITUDE

15.01.2018

TOKIO**PART****LIST**

1	1	BUMPER COVER REAR	\$	Bu 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	Not/In 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	Dii 113.47	✓
4	1	BUMEPR BRACKET SIDE RH REAR	\$	SL 135.97	X
5	1	BUMEPR RETAINER RH REAR	\$	SL 44.99	X
6	1	BUMPER REFLECTOR RH	\$	SL 43.61	X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	SL 135.97	X
8	1	BUMEPR RETAINER LH REAR	\$	SL 44.99	X
9	1	BUMPER REFLECTOR LH	\$	SL 43.61	X
10	1	BUMPER BEAM REAR	\$	R 777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	Dii 225.95	✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	R 225.95	X
13	1	BOOT REAR	\$	R 2,872.68	✓
14	1	BOOT FINISHER	\$	SL 470.06	X
15	1	BOOT WHEATERSTRIP	\$	SL 323.05	X
16	1	BOOT REFLECTOR LAMP LH	\$	CM 493.35	✓
17	1	BOOT REFLECTOR LAMP RH	\$	SL 493.35	X
18	1	BOOT BADGE 'RENAULT'	\$	MC 225.36	✓
19	1	BOOT BADGE	\$	MC 225.36	✓
20	1	BOOT STRUT LH	\$	SL 276.08	X
21	1	BOOT STRUT RH	\$	SL 276.08	
22	1	BOOT HINGE LH	\$	R 367.84	
23	1	BOOT HINGE RH	\$	R 367.84	
24	1	BOOT INNER TRIM	\$	SL 586.45	
25	1	BOOT SWITCH	\$	SL 168.13	
26	1	BOOT LOCK	\$	R 202.67	
27	1	BOOT LOCK CATCH	\$	R 74.40	
28	2	LICENCE PLATE LAMP	\$	SL 50.52	
29	2	BOOT RUBBER PLUG	\$	SL 221.81	
30	1	FENDER PANEL INNER TRIM REAR LH	\$	SL 671.45	X
31	1	FENDER PANEL REAR LH	\$	R 3,299.13	
32	1	WHEELARCH REAR LH	\$	SL 543.47	
33	1	FENDER PANEL INNER TRIM REAR RH	\$	SL 671.45	
34	1	FENDER PANEL REAR RH	\$	R 3,299.13	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-184**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9996B - TOKIO

35	1	WHEELARCH REAR RH	\$	<i>Pu</i> 543.47 X
36	1	TAILLAMP RH	\$	<i>Pu</i> 552.55 X
37	1	TAILLAMP PANEL RH	\$	<i>Pu</i> 986.70 X
38	1	TAILLAMP LH	\$	<i>ngim</i> 552.55 ✓
39	1	TAILLAMP PANEL LH	\$	<i>Pu</i> 986.70 X
40	1	OUTER PANEL REAR (End Panel)	\$	<i>Pu</i> 1,471.77 ✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>ngim</i> 404.56 ✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>Pu</i> 2,189.88 X
43	1	SPARE WHEEL PANEL TRIM	\$	<i>Pu</i> 612.21 X
44	1	EXHAUST REAR	\$	<i>Pu</i> 7,489.05 X
45	1	EXHAUST CAP REAR	\$	<i>Pu</i> 230.49 X

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET	PARKING AID	\$	<i>Shon</i> 700.00 ✓
2	1SET	REAR BUMPER CLIP	\$	<i>pu</i> 66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>pu</i> 33.00 ✓
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	<i>pu</i> 10.00 X
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	<i>pu</i> 20.00 X
6	1SET	BUMEP R BRACKET SIDE CLIP LH RR	\$	<i>pu</i> 10.00 X
7	1SET	BUMEP R RETAINER CLIP LH RR	\$	<i>pu</i> 20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>pu</i> 22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>pu</i> 66.00 ✓
10	1	EXHAUST MOUNTING REAR	\$	<i>Pu</i> 17.82 X
11	1SET	BOOT FINISHER CLIP	\$	<i>pu</i> 24.20 X
12	1	BOOT STICKER "Trans-cab"	\$	<i>pu</i> 30.00 ✓
13	1	BOOT STICKER "6555-3333"	\$	<i>pu</i> 30.00 ✓
14	1	BOOT INNER TRIM CLIP	\$	<i>pu</i> 45.00 X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>pu</i> 35.00 X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>pu</i> 35.00 X
17	1	FENDER INNER TRIM CLIP LH	\$	<i>pu</i> 28.00 X
18	1	FENDER INNER TRIM CLIP LH	\$	<i>pu</i> 28.00 X
19	1	TAILLAMP CLIP RH	\$	<i>pu</i> 5.00 X
20	1	TAILLAMP CLIP LH	\$	<i>pu</i> 5.00 ✓
21	2	REAR WINDSCREEN SELANT	\$	<i>pu</i> 80.00 X
22	1	WINDSCREEN MOULDING	\$	<i>pu</i> 100.00 X
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>pu</i> 100.00 X
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Pu</i> 385.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-184**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9996B - TOKIO

25	1	SPARE TYRE	\$	<i>330.00</i> X
			TOTAL	\$ 2,225.02
			TOTAL PARTS	\$ 34,507.07
Putty And Spray Painting Of The Affected Portion.			\$	4,500.00 <i>667</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same			\$	4,200.00 <i>667</i>
To Rust-Proofing Of The Affected Areas.			\$	170.00 <i>667</i>
To reinstall rear bumper parking sensor.			\$	170.00 <i>667</i>
To transfer of bootlid fittings, attachments and perform water seepage test.			\$	170.00 <i>667</i>
To repair and realign rear exhaust pipe.			\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.			\$	<i>nn</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.			\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.			\$	170.00
				<i>667</i>
To supply and re-do rear luggage floor panel insulation padding.			\$	<i>nn</i> 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.			\$	<i>nn</i> 380.00 X
Towing Fees			\$	<i>nn</i> 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.			\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment			\$	<i>nn</i> 220.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-184**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9996B - TOKIO

TOTAL	\$	11,160.00
Over All Total	\$	45,667.07

(PARTS BY PARTS)**Repair Days**~~15 Days~~

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before it is repaired.
- To display damaged parts in a prominent way.
- Repair work must be done properly.
- To display repaired parts with original body.
- To display damaged parts as followed.
- Any work on repairs must be resurveyed and is subject to final approval from insurance Company.

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jan 2018		19 Jan 2018 10:34 Edit Adj Rpt	S\$8,250.00 Edit Estimates	S\$8,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	EITA SERVICES PTE LTD , Co. Reg. No.: 199100274H		
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD9996B	Date of Loss:	15/01/2018 14:00 - :59
Claim Type:	TP / M1800369	Policy/Cover Note No.:	MB028445 (Third Party Only) Coverage: 16/01/2017 - 31/03/2018
Vehicle Reg. No. (Insured):	GU1068E	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/01/2018]		
Driver/Custodian (Insured):	RAHMAN SAIDUR (), NRIC: G7925105X, Tel: +6594460453		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD9996B (M1800369)**
[GU1068E]
TP
TRANS-CAB SERVICES PTE LTD
Jan 15 2018 2:00PM
[EITA SERVICES PTE LTD]
Trans-cab Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
2	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
3	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
4	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
5	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
6	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
7	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
8	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
9	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
10	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
11	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
12	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
13	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
14	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
15	19/01/18 11:15	Odometer Reading								Load JPG	<input checked="" type="checkbox"/>
16	19/01/18 11:15	Chassis Number								Load JPG	<input checked="" type="checkbox"/>
17	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
18	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
19	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
20	19/01/18 11:15	General View								Load JPG	<input checked="" type="checkbox"/>
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)								Thumbnail	Print
1	17/01/18 14:54	SHD9996B								Load PDF	
2	19/01/18 10:33	EST								Load PDF	
3	19/01/18 10:35	LKK NOTIFICATION TO SURVEY TRANS-CAB-ASSIGN								Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18001084/KQBE2

Date: 19/01/2018

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MB028445

Claimant Vehicle No : SHD9996B

Insured Vehicle No : GU1068E

Date of Loss: 15/01/2018

Nature of Claim: TP

Claim No: M1800369

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9996B

Make & Model: RENAULT LATITUDE, 2.0 L (A)

Engine No: M9R8839C001430

Reg. Date: 13/06/2014 (Man. Year: 2014)

Chassis No: VF1ABL15AUC278150

Colour: Metallic White/Red

Odometer: 318283 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Linglong 7 mm

Rear Left Side: Linglong 8 mm

Front Right Side: Linglong 7 mm

Rear Right Side: Linglong 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,507.05	9,245.88	25,261.17	73.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,160.00	1,500.00	9,660.00	86.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	45,667.05	10,745.88	34,921.17	76.47
Approved Total (Overridden) (\$\$)		8,250.00		
(\$\$)	45,667.05	8,250.00	37,417.05	81.93
+ GST 7.00/7.00% (\$\$)	3,196.69	577.50	2,619.19	81.93
Nett Amount (\$\$)	48,863.74	8,827.50	40,036.24	81.93

INSPECTION

Date of Assignment: 19/01/2018

Date Inspected: 17/01/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 19 Jan 2018)
Parts: 143 **RENAULT LATITUDE 2.0 L (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD9996B)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Distorted	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Distorted	225.95 FL	*225.95 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1		*BOOT REFLECTOR LAMP LH	Cracked	493.35 FL	*493.35 FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1		*BOOT LOCK	Repair	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
31	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
32	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
33	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
34	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
35	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
36	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
37	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
38	1		*TAILLAMP LH	MTG Cracked	552.55 FL	*552.55 FL
39	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
41	1		*OUTER PANEL REAR (END PANEL) TRIM	MTG Cracked	404.56 FL	*404.56 FL
42	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
43	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
44	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
45	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
46	1		*SET PARKING AID	Shorted	700.00 FS	*700.00 FS
47	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
48	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
49	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
50	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
51	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
52	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
53	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
54	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
55	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
56	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
57	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
58	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
59	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
60	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
61	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
62	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
63	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
64	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
65	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
66	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
67	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
68	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
69	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
70	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	38,093.94	10,169.87
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,586.89	923.99
Total Parts (\$\$)	34,507.05	9,245.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	660.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,200.00	600.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST}	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
11	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TOWING FEES	New	120.00	0.00
13	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
14	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (\$\$)			11,160.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >