

TRANS-CAB AUTO SERVICES PTE LTD
 NO.58 DEFU LANE 1 SINGAPORE 539498
 TEL NO.6287 6666 FAX NO.6281 1400
 CO/GST REG NO.201019626G
 SHD5324S - AXA

done
Not Authorized
11 Sep @ 325ch

ROEL

Vehicle No.: **SHD 5324S - ROEL**
 Chassis No.: **JTDGJ20W405002106***
 Vehicle Make: **TOYOTA**
 Vehicle Model: **WISH 2.0 BI-FUEL**
 Date of Accident : **11.12.2012**
 Third Party Insurer : **AXA**

PART		LIST
1	1 Rear Bumper	\$ <i>Pur</i> 585.36 ✓
2	1 Rear Bumper Stay LH	\$ <i>Sn</i> 82.08 X
3	1 Rear Bumper Bracket LH	\$ <i>Bt</i> 108.00 ✓
4	1 Rear Bumper Side Retainer LH	\$ <i>O/I</i> 68.76 ✓
5	1 Rear End Panel Outer	\$ <i>Bt</i> 623.76 ✓
6	1 Tailgate Lid	\$ <i>Bt</i> 1,480.44 ✓
7	1 Tailgate Lid Centre Logo Badge	\$ <i>nc</i> 66.82 ✓
8	1 Tailgate lid Weatherstrip	\$ <i>Sn</i> 344.28 X

TOTAL	\$	3,359.50
25%	\$	870.21
	\$	2,610.62

Special Nett

1 set	Rear Bumper Fastener Clip	\$ <i>nc</i> 30.00 ✓
1	Rear Bumper Parking Sensor	\$ <i>Sn</i> 300.00 X
1	CNG Sticker	\$ <i>nc</i> 15.00 ✓
1	Rear Windscreen Sealant	\$ <i>nc</i> 80.00 <i>40sn</i>
1	Rear Windscreen Inner Sponge Seal	\$ <i>nc</i> 60.00 <i>30sn</i>
1	Rear Bumper Advertisement Sticker	\$ <i>nc</i> 100.00 ✓

TOTAL	\$	585.00
-------	----	---------------

TOTAL PARTS \$ 3,185.62

TRANS-CAB AUTO SERVICES PTE LTD

ROEL

NO.58 DEFU LANE 1 SINGAPORE 539498

TEL NO.6287 6666 FAX NO.6281 1400

CO/GST REG NO.201019626G

SHD5324S - AXA

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,250.00	<i>600</i>
To Rust-Proofing Of The Affected Areas.	\$	150.00	<i>60</i>
To Check Electrical Lighting Concerned.	\$	100.00	<i>20</i>
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, To Enable Repair.	\$	250.00	<i>60</i>
Putty And Spray Painting Of The Affected Portion.	\$	900.00	<i>600</i>
To Transfer Of Tailgate Fittings, Attachments And Perform Water Seepage Test.	\$	150.00	<i>60</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	150.00	<i>120</i>
To Reinstall Rear Bumper Parking Sensor.	\$	150.00	<i>50</i>
To Reseal Sealant On Gap	\$	100.00	<i>50</i>
Towing Fee	\$	<i>~</i> 100.00	<i>X</i>

TOTAL	\$	3,300.00
-------	----	-----------------

Over All Total	\$	6,485.62
-----------------------	----	-----------------

Total Repair Days

05 Days
4 days