

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB7504L -

LI DAN

Not Authorized
LI Dan 81350/

Vehicle No.:	SHB 7504L - LI DAN
Chassis No.:	LK1LA69RJBB076818*
Vehicle Make:	CHEVROLET
Vehicle Model:	CHEVROLET EPICA 2.0
Date of Accident :	23.05.2013
Third Party Insurer :	<i>AIG</i>

PART			LIST	
1	1	Front Bumper (Bumper A-Frt)	\$	<i>R</i> 1,202.00 X
2	1	Front Bumper Retainer RH	\$	<i>Li</i> 102.00 X
3	1	Front Fender RH	\$	<i>B</i> 837.60 —
4	1	Front Door LH (Panel A-Frt DR LH)	\$	<i>R</i> 1,133.00 X

TOTAL	\$	3,274.60
25%	\$	818.65
	\$	2,455.95

Specical Nett

1 Set	Front Bumper Fastener Clip	\$	<i>nr</i> 24.00 X
1	Front Door Sticker 'Trans-Cab'	\$	<i>nr</i> 60.00 —

TOTAL	\$	84.00
-------	----	--------------

TOTAL PARTS \$ 2,539.95

Panel Beating, Knocking And Straightening
 The Necessary Portion, Remove And
 Renewal Of Parts, Adjust And Realign The
 Same

\$ 1,250.00 *400/*

To Rust-Proofing Of The Affected Areas.

\$ 200.00 *30/*

To Check Electrical Lighting Concerned.

\$ 100.00 *20/*

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHB7504L -

LI DAN

Putty and Spray Painting Of The Affected Portion. \$ 900.00 *540*

To Transfer Of Fender Fittings, Attachment And Perform Water Seepage Test. \$ *nn* 150.00 *X*

To Transfer Of Door Fittings, Attachment And Perform Water Seepage Test. \$ *nn* 150.00 *X*

TOTAL \$ 2,750.00

Over All Total \$ 5,289.95