

RICARDO AUTO CENTRE PTE LTD

GST: M2-0033787-4 RCN NO: 198102183M
160 SIN MING DRIVE #02-02/03 SIN MING AUTO CITY SINGAPORE 757722
TEL: 6475 2112 FAX: 6475 4666
Email: <http://www.ricardo.com.sg>



RICARDO

TAX INVOICE NO:

WINV082311

Owner's Information		Make	Technician:	Job Card No.:
A/C: C009946		TOYOTA	GRACE TAN	26961
MR TAN KEE SWEE DANIEL		Registration No.:	Make/Model:	Date of Invoice:
		SIL726M	TOYOTA Estima 2.4A AERAS	30/06/2017
BLK 637 JURONG WEST ST. 61		Mileage (km):	Next Mileage(km):	Next Service Date
#16-11 SINGAPORE 640637		0		08/04/2016
		Chassis No.:	Engine No.:	Promised Date/Time:
		ACR50-7063568		08/04/2016 12:21:00 PM

Service Description	Quantity	Unit Price	Amount
		S\$	S\$
BOOT LID ASSY	1 PC	1,139.25	1,139.25
RR BOOT GARNISH	1 PC	163.27	163.27
REAR Moulding WINDOW OUTSIDE	1 PC	99.18	99.18
BACK DOOR PLATE - ESTIMA	1 PC	34.95	34.95
BACK DOOR PLATE - AERAS	1 PC	40.72	40.72
BACK DOOR EMBLEM - TOYOTA	1 PC	48.75	48.75
LOCK ASSY, BACK DOOR	1 PC	293.70	293.70
BOARD ASSY, BACK DOOR	1 PC	586.05	586.05
WEATHERSTRIP, BACK DOOR	1 PC	264.60	264.60
BACK DOOR HANDLE PULL	1 PC	14.32	14.32
REAR FLOOR PAN	1 PC	741.18	741.18
BOX, LUGGAGE	1 PC	288.82	288.82
LID ASSY, LUGGAGE	1 PC	586.38	586.38
REAR END PANEL	1 PC	735.93	735.93
REAR BOOT GARNISH	1 PC	283.05	283.05
REAR BOOT GRANISH CENTRE	1 PC	217.42	217.42
REAR FENDER INNER TRIM, LH	1 PC	505.20	505.20
REAR FENDER INNER TRIM, RH	1 PC	505.20	505.20
REAR BUMPER	1 PC	361.50	361.50
REAR BUMPER SIDE RETAINER RH	1 PC	41.02	41.02
REAR BUMPER SIDE RETAINER LH	1 PC	41.02	41.02

RICARDO AUTO CENTRE PTE LTD

GST: ME 0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTO CITY SINGAPORE 575722
TEL: 6475 2112 FAX: 6475 4666
Email: <http://www.ricardo.com.sg>



RICARDO

TAX INVOICE NO:

WINV0823111

Owner's Information		Male	Technician:	Job Card No:
A/C: C009946	TOYOTA	GRACE TAN		26961
MR TAN KEE SWEE DANIEL		Registration No.:	Male/Model:	Date of Invoice:
		SL7226M	TOYOTA Estima 2.4A AERAS	30/06/2017
BLK 637 JURONG WEST ST. 61		Mileage (km):	Next Service Date	Date In:
#16-11 SINGAPORE 640637		0		08/04/2016
		Chassis No.:	Engine No.:	Time In:
		ACR50-7063568		08/04/2016 12:21:00 PM
			Promised Date/Time:	

Service Description	Quantity	Unit Price	Amount
REAR BUMPER SIDE SUPPORT NO.2 LH	1 PC	\$41.02	\$41.02
REAR BUMPER SIDE SUPPORT NO.2 RH	1 PC	\$41.02	\$41.02
REAR BUMPER TOW COVER	1 PC	\$34.57	\$34.57
REAR BUMPER ENERGY - RH	1 PC	\$98.81	\$98.81
REAR BUMPER ENERGY - LH	1 PC	\$98.81	\$98.81
RR FENDER RH	1 PC	\$735.93	\$735.93
REAR FENDER QUARTER GLASS RH	1 PC	\$679.57	\$679.57
FRAME, BACK DOOR OPENING SIDE RH	1 PC	\$198.94	\$198.94
REAR BLOWER ASSY, AIR-CON	1 PC	\$1,627.28	\$1,627.28
TAIL LAMP RH	1 PC	\$278.55	\$278.55
RR BOOT LAMP RH	1 PC	\$277.05	\$277.05
REAR BUMPER LAMP W/LIGHT, RL	1 SET	\$210.00	\$210.00
FRONT BUMPER	1 PC	\$1,284.19	\$1,284.19
FRONT BUMPER REINFORCEMENT UPPER	1 PC	\$105.60	\$105.60
FRONT GRILLE	1 PC	\$280.80	\$280.80
GRILLE EMBLEM	1 PC	\$51.90	\$51.90
HEADLAMP RH	1 PC	\$1,435.50	\$1,435.50
HEADLAMP LH	1 PC	\$1,435.50	\$1,435.50
RADIATOR ASSY	1 PC	\$1,537.88	\$1,537.88
SUPPORT TOP GARNISH (RADIATOR TOP COVER)	1 PC	\$181.13	\$181.13
SHROUD, FAN, NO.2	1 PC	\$57.30	\$57.30
AIR CON CONDENSER	1 PC	\$1,105.88	\$1,105.88

RICARDO AUTO CENTRE PTE LTD

GST: MQJ003751-4 RCN NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCTV SINGAPORE 575722
TEL: 6475 2112 FAX: 6475 4666
Email: <http://www.aticauto.com.sg>



RICARDO

TAX INVOICE NO:

WINV0823111

Owner's Information		Make	Technician	Job Card No :
A/C: C009946	MR TAN KEE SWEE DANIEL	TOYOTA	GRACE TAN	26961
		Registration No. :	Make/Model :	Date of Invoice :
		SJL7226M	TOYOTA Estima 2.4A AERAS	30/06/2017
BLK 637 JURONG WEST ST. 61		Mileage (km) :	Next Mileage (km) :	Date In : Time In :
#16-11 SINGAPORE 640637		0		08/04/2016 12:21 PM
		Chassis No. :	Engine No. :	Promised Date/Time :
		ACR50-7063568		08/04/2016 12:21:00 PM

Service Description	Quantity	Unit Price	Amount
COOLANT (NETT ITEM)	1 PC	\$20.00	\$20.00
FRT BUMPER CLIPS	1 LOT	31.50	31.50
FRONT RADIATOR COVER CLIP	1 LOT	18.00	18.00
RR LAMP CLIP	1 PC	9.00	9.00
FRONT BUMPER CLIPS	1 LOT	11.25	11.25
REINFORCEMENT SUB ASSY, RR SEAT HINGE	1 PC	139.58	139.58
MEMBER SUB ASSY, RR FLOOR CROSS NO.4	1 PC	203.03	203.03
FRONT & REAR NUMBER PLATE (NETT ITEM)	1 SET	60.00	60.00
REAR BUMPER SENSOR	1 SET	220.00	220.00
TOWING CHARGE	1 PC	120.00	120.00
MEMBER SUB- ASSY, RR FLOOR SIDE FRONT RH	1 PC	432.75	432.75
TO FOCUS HEADLAMP	1 SVC	30.00	30.00
TO REMOVE AND REPLACE AIR-CON CONDENSER, SVC	1 SVC	100.00	100.00
AND TOP UP AIR CON GAS INCLUDING REMOVE AND			
REPLACE RR AIR-CON COOLING SYSTEM.			
TO REMOVE RR CUSHION AND CAR SEATS ENABLE TO			
REPLACE RR END PANEL	1 SVC	150.00	150.00
TO REMOVE BACK DOOR GLASS & RH RR QUARTER			
GLASS & FIX SAME	1 SVC	180.00	180.00
SUPPLY WINDSCREEN & QUARTER GLASS SEALANT	1 SVC	80.00	80.00
TO CUT, WELD & STRAIGHTEN FRONT AND RR			
PORTION CAUSED BY ACCIDENT, REMOVE & REPLACE			
DAMAGE PARTS, REPAIR FRONT SUPPORT PANEL	1 SVC	2,200.00	2,200.00

42.75 ✓

RICARDO AUTO CENTRE PTE LTD

GST: N2-0033787-4 RCN NO: 19810182M
 160 SIN MING DRIVE #02-02/03 SIN MING AUTO CITY SINGAPORE 575722
 TEL: 6475 2112 FAX: 6475 4666
 Email: <http://www.ricardo.com.sg>



RICARDO

TAX INVOICE NO:

WINV0823111

Owner's Information		Make	Technician:	Job Card No.:
A/C: C009946		TOYOTA	GRACE TAN	26961
MR TAN KEE SWEE DANIEL		Registration No.:	Make/Model:	Date of Invoice:
		SIL7726M	TOYOTA Estima 2.4A AERAS	30/06/2017
BLK 637 JURONG WEST ST. 61		Mileage (km):	Next Service Date	Date In : Time In :
#16-11 SINGAPORE 640637		0	08/04/2016	12:21 PM
		Chassis No.:	Engine No.:	Promised Date/Time:
		ACR50-7063568		08/04/2016 12:21:00 PM

Service Description	Quantity	Unit Price	Amount
TO TUFF COAT REPAIRED AREA	1 SVC	\$120.00	\$120.00
TO SPRAY PAINT ON FRONT AND RR REPAIRED AREAS	1 SVC	\$1,600.00	\$1,600.00
TO CHECK & REPT WIRING SYSTEM	1 SVC	\$30.00	\$30.00
TO REPT FRONT ACCESSORIES LIGHTING	1 SVC	\$100.00	\$100.00
TOTAL			\$3 24,643.85
		ADD GST @ 7%	1,725.07
		GRAND TOTAL	\$3 26,368.92

SINGAPORE DOLLAR TWENTY SIX THOUSAND THREE HUNDRED SIXTY EIGHT AND CENTS NINETY TWO ONLY

Remarks: WE SUBMIT HEAR WITH OUR FINAL REPAIRED BILL TO ABOVE MENTIONED VEHICLE.

DOA : 7/1/2014
 ACCIDENT INVOLVING : SIL7726M & SIG2897K
 CLAIM TYPE: 3RD PARTY CLAIM AGAINST SIG2897K (SIG2897K INSURED WITH AIG)

Customer's Signature/Co. Stamp

E. & O. E.

Ricardo Auto Centre Pte Ltd