

ASS. REC. BY:

REF:

CS/ASM18001091/Krbez

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Kitty Teo

of

ASM

Date/Time:

18/01/2018 11:15am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 5127A

Insured:

at Workshop m/s

BH Auto

Tel:

6559 8940

of

Bik 1 Sm Ming Ind Est # 01-115

Policy No:

Claim No:

S8M007FV

Sum Insured:

Excess:

TBA

Make of Veh:

D.O.A.

13/01/2018

(Client's Record)

CA

/ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

18/01/2018 11:43am

Person Contacted:

Jarelyn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	Estimate not ready, will call survey after estimate done
	SKA 5127A x	
18/1/18	Sent preli through smart claim	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18001091/Krb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 18-01-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKA 5127A
Policy No.	Coverage (\$)	0.00
Claim No. S8M0077V	Excess (\$)	0.00
Assign From SMART CLAIM (KITTY TEO)	Assign Date	18/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 13/01/2018	Inspection Date 18/01/2018
Survey held at BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

LKK AUTO CONSULTANTS PTE LTD (OD) ▾



Service Request Details

Claim

S8M0077V

Reference

None 

Loss Date

January 13, 2018

Request Date

January 18, 2018

Due Date

January 25, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Incident Only

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKA5127A

Make

TOYOTA

Service Address

Blk 1 Sin Ming Industrial, , , 575636

Primary Contact/Insured

CHIN POR PHILIP TAN
BLK 331 YISHUN RING ROAD, #02-1392, 760331, Singapore, Singapore
92715129
TANCPHILIP@GMAIL.COM

Claim Handler

Kitty TEO
6568804602
kitty.teo@axa.com.sg

Additional Instructions
EXCESS TBA

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

New Message

TYPE 

SENT 1/18/18 11:21 AM

FROM Kitty TEO

SUBJECT SKA5127A - CAR @ BH

BODY Hi Excess TBA.



Your Ref: S8M0077V
Our Ref: CS/ASM18001091/Krb

Date: 18 January 2018

The Motor Claims Department
AXA INSURANCE PTE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SKA 5127A

We thank you for the instruction on 18/01/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle 18/01/2018 at the premises of m/s: BH AUTO SERVICES PTE LTD and have the following to report:-

Repairer's Estimate (Gross)	: S\$ <u>8,234.00</u>
Revised Estimate Amount	: S\$ <u>3,835.00</u>
"Check" Items (Estimated)	: S\$ <u>1,869.00</u>
Total Repair (Estimated)	: S\$ <u>5,704.00</u>
Pre-Accident Value	: S\$ <u>40,000.00</u>
COE/PARF value	: S\$ <u>23,493.00</u>
Nett Value	: S\$ <u>16,507.00</u>

Description of Damage:
The vehicle sustained damages
at the front portion.



Comments:
We have authorize repair.

Yours faithfully
KENNETH
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 3543E

Vehicle Details

Vehicle No.: SKA5127A
 Vehicle to be Exported: No
 Intended De-registration Date: 15 Jan 2018
 Vehicle Make: TOYOTA
 Vehicle Model: CAMRY 2.0 AUTO ABS AIRBAG
 Primary Colour: Silver
 Manufacturing Year: 2007
 Engine No.: 1AZE058834
 Chassis No.: MR053BK4107016818
 Maximum Power Output: 108.0 kW (144 bhp)
 Open Market Value: \$26,761.00
 Original Registration Date: 18 Sep 2007
 First Registration Date: 18 Sep 2007
 Transfer Count: 3
 Actual ARF Paid: \$29,438.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Sep 2022
 COE Category: E - Open Category
 COE Period(Years): 5
 PQP Paid: \$25,178.00
 COE Rebate Amount: \$23,527.00
Total Rebate Amount: \$23,527.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Jan 2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3543E

Vehicle Details

Vehicle No.: SKA5127A
Vehicle to be Exported: No
Intended De-registration Date: 18 Jan 2018
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour: Silver
Manufacturing Year: 2007
Engine No.: 1AZE058834
Chassis No.: MR053BK4107016818
Maximum Power Output: 108.0 kW (144 bhp)
Open Market Value: \$26,761.00
Original Registration Date: 18 Sep 2007
First Registration Date: 18 Sep 2007
Transfer Count: 3
Actual ARF Paid: \$29,438.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Sep 2022
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$25,178.00
COE Rebate Amount: \$23,493.00
Total Rebate Amount: \$23,493.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Jan 2018

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year/100,000km Renewal Toyota Motor 3.5L



\$258.10 (umpayment Monthly from \$500 Onwards, Lowest 3,641.00 A & GV Cars Financing GV Credit Pte Ltd. 13 Jan 2018

HIN LUNG AUTO
 HoBee Group

30 years
 of car sale

One Stop Car Hub
 Finance, Insurance, Workshop
 New and Used Cars

Browse by Category

Sort by Date Posted

20 results/page

8 vehicles

Toyota Camry

Advanced Search

	Make	Model	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Camry		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota Camry	2.0A (COE till 05/2027)	\$67,888	\$7,240 /yr	07-Jun-2007	1,998 cc	97,000 km	Luxury	Available
Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.									
Boeki Auto & Marine									
Posted: 15-Jan-2018 Tags: 2007 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									
	Toyota Camry	2.4A (COE till 08/2022)	\$43,000	\$9,410 /yr	11-Aug-2007	2,362 cc	168,000 km	Luxury	Available
Superbly Maintained By A Loving Mechanic, No Expense Spared! Call To Arrange A Viewing. Banks And In-house Loans Available.									
Posted: 13-Jan-2018 Tags: 2007 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									
	Toyota Camry	2.0A (COE till 03/2022)	\$39,800	\$9,580 /yr	13-Mar-2007	1,998 cc	170,000 km	Luxury	Available
Say No To Repairs! Brand New 4 Tyres, Brand New Shock Absorber x 4 And Front And Rear Absorber Link x 4.									
Posted: 11-Jan-2018 Tags: 2007 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									
	Toyota Camry	2.2A (New 5-yr COE)	\$35,800	\$7,160 /yr	20-May-1998	2,164 cc	-	Luxury	Available
Famous Best Selling Camry 2.2 In The Past, Accident Free, In House Warranty, Bank Loan/In House Loan Available, Trade In Welcome.									
Posted: 09-Jan-2018 Tags: 1998 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									
Car Buying			Car Selling			Car Aftermarket			
Car Ownership			On The Move			Lifestyle			
							▶ Buy Tyres Online! ▶ Latest Special Offers from Tyrepac!		
	Toyota Camry	2.0A (COE till 07/2022)	\$47,800	\$10,540 /yr	30-Jul-2007	1,998 cc	96,000 km	Luxury	Available
Excellent Condition From Borneo Motor, Low Mileage, Lowest Depreciation, Careful Owner, New Road Tax, Loan And Insurance Can Be Arranged. Call Now To View Before Its Gone.									
Posted: 24-Dec-2017 Tags: 2007 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									
	Toyota Camry	2.0A (COE till 05/2022)	\$48,833	\$11,230 /yr	22-May-2007	1,998 cc	100,000 km	Luxury	Available
Posted: 15-Dec-2017 Tags: 2007 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									
	Toyota Camry	2.4A (COE till 05/2026)	\$64,999	\$7,760 /yr	31-Aug-2006	2,362 cc	165,000 km	Luxury	Available
Very Low Depreciation. Beautiful And Extremely Good Condition. Why Pay \$11k Plus Yearly For Other Camry When You Can At Much Lower And Better Condition. Car Is Accident Free. Leather Seats And Body Pa...									
Posted: 04-Dec-2017 Tags: 2006 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2018 15:13
Date Of Accident	13/01/2018 12:50
Exact Location Of Accident	ANG MO KIO AVE 6 TWDS SIN MING
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA5127A
Insured/Policyholder	
Name Of Registered Owner	TAN CHIN POR PHILIP
NRIC No	S0123543E
Email Address	TANCPHILIP@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92715129
Alternative Phone No	OFFICE-92715129

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USED

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA058543/1
Cover Note Number	

Driver

Name of Driver	TAN CHIN POR PHILIP
NRIC No	S0123543E
Date Of Birth	18/04/1954
Occupation	INDOOR
Date Of Driving Pass	26/06/1978
Driving Experience	39 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92715129
Fax Number	
Contact Number	OFFICE-92715129
Email Address	TANCPHILIP@GMAIL.COM

Address	BLK 331 YISHUN RING ROAD #02-1392
Postcode	760331
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WIFE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP7126Y-C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

- SKETCH PLAN
- (A) SKA #5127A
- (B) SKR 62467
- (C) SJP 7126Y

Autu moxco

ST 24

SKR 62467 - SKA #5127A

Autu moxco

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 13/01/2018 at 12.50pm, the 1st car SJP 7126Y out of no where jammed the emergency brake because of a bump. The 2nd car SKR 62467 rammed onto the 1st car SJP 7126Y. Then, my car rammed onto the 2nd car due to the slippery road at that times it was raining.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Kr

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore (068811)
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6338 7288 Fax : 6880 4838



Not done
1-B1
Referring B4 pricing

6 days

DEAR SIR / MADAM :

OD Claim

Fax: 62584315

ACCIDENT REPAIR ON: SKA5127A
MODEL : TOYOTA CAMRY 2.0
POLICY NO : GA058543/1
CHASSIS NO : MR053BK4107016818
ENGINE NO : 1AZE058834

Date: 17/01/2018

Page : 1 of 2

DATE / TIME OF ACCIDENT: 13/01/2018 Time: 1250Hrs ALONG ANG MO KIO AVE 6 TWDS SIN MING
THIRD PARTY VEHICLE NO: OD

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
1 Bonnet	1	SS 400.00		SS 400.00 ✓
2 Bonnet Hinge LH *	1	30.00		DM 30.00 ✓
3 Bonnet Hinge RH *	1	30.00		DM 30.00 ✓
4 Bonnet Lock Assy	1	50.00		DM 50.00 ✓
5 Bonnet Damper x2ks	1	110.00		DM 110.00 x
6 Bonnet Insulator *	1	165.00		DM 165.00 x
7 Bonnet Insulator Clips	10	2.00		DM 20.00 ✓
8 Front Fender LH	1	185.00		DM 185.00 x
9 Front Fender Shield LH	1	70.00		DM 70.00 x
10 Front Fender Shield Clips	10	2.00		DM 20.00 x
11 Front Fender RH	1	185.00		DM 185.00 x
12 Front Fender Shield RH	1	70.00		DM 70.00 ✓
13 Front Fender Shield Clips	10	2.00		DM 20.00 x
14 Headlamp LH	1	275.00		DM 275.00 ✓
15 Headlamp RH	1	275.00		DM 275.00 ✓
16 Front Bumper	1	190.00		DM 190.00 ✓
17 Front Bumper Clips	10	2.00		DM 20.00 ✓
18 Front Bumper Side Retainer LH	1	30.00		DM 30.00 ✓
19 Front Bumper Side Retainer RH	1	30.00		DM 30.00 ✓
20 Front Bumper Upper Grille Chrome	1	140.00		DM 140.00 ✓
21 Front Bumper Emblem	1	55.00		DM 55.00 ✓
22 Front Bumper Lower Grille	1	40.00		DM 40.00 x
23 Front Bumper Tow Cover	1	10.00		DM 10.00 x
24 Fog Lamp LH	1	100.00		DM 100.00 x
25 Fog Lamp Cover LH *	1	30.00		DM 30.00 ✓
26 Fog Lamp Cover Lining Chrome LH *	1	45.00		DM 45.00 ✓
27 Fog Lamp RH	1	100.00		DM 100.00 x
28 Fog Lamp Cover RH	1	30.00		DM 30.00 x
29 Fog Lamp Cover Lining Chrome RH	1	45.00		DM 45.00 x
30 Front Bumper Reinforcement *	1	145.00		DM 145.00 ✓
31 Front Bumper Sponge	1	50.00		DM 50.00 ✓
32 Support Panel	1	310.00		DM 310.00 ✓
33 Support Panel Top Garnish	1	130.00		DM 130.00 x

34	Support Panel Top Garnish Clips	10	2.00	14.00	20.00	✓
35	Radiator Assy ✕	1	500.00	Pu	500.00	✓
36	Radiator Mounting and Rubber Upper	2	10.00	Sn	20.00	X
37	Radiator Mounting and Rubber Lower	2	12.00	Sn	24.00	X
38	Aircon Condenser Assy	1	350.00	Pu	350.00	✓
39	Aircon Pipe Discharge	1	130.00	Sn	130.00	X
40	Aircon Pipe Suction	1	280.00	Sn	280.00	X
41	Front Brace Panel Assy	1	40.00	Rs	40.00	✓
42	Radiator Fan Blade	1	60.00	Sn	60.00	X
43	Radiator Fan Motor	1	180.00	Sn	180.00	X
44	Radiator & Aircon Cowling	1	95.00	CM	95.00	✓
45	Aircon Fan Blade	1	60.00	Sn	60.00	X
46	Aircon Fan Motor ✕	1	180.00	Rs	180.00	✓
47	Fan Resistant	1		nn		
			Sub-Total:	5,344.00		
			Total Parts:	5,344.00		

Special Nett Items

1	Anti-rust coating	2	80.00	NI	160.00	X
2	Radiator Coolant	1	60.00	nn	60.00	20s.
3	Front number plate with casing	1	50.00	Br	50.00	25s.
4	Glue Sealant	1	60.00	nn	60.00	X
				160.00		
			Total Parts:	5,504.00		

Labour Charges For Front Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	1,400.00	700
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,200.00	600
3	Provide skill labour to disconnect and check electrical wiring	30.00	20
4	Provide skill labour to remove and replace air-con condenser, pipes and radiator, vacuum air-con system and refill gas	100.00	✓
Total Labour:		2,730.00	9813
Total Parts & Labour:		8,234.00	
GST 7%		576.38	
Grand Total:		8,810.38	
Estimate Repair Duration		13 days	

ACCIDENT VEHICLE OF : SKA5127A

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore (068811)
ATTN: MOTOR CLAIM DEPARTMENT
Tel: 6338 7288 Fax: 6880 4838

DEAR SIR / MADAM :

OD Claim SUPPLEMENTARY

Date: 17/01/2018
Page: 1 of 2

ACCIDENT REPAIR ON: SKA5127A
MODEL: TOYOTA CAMRY 2.0
POLICY NO: GA058543/1
CHASSIS NO: MR053BK4107016818
ENGINE NO: 1AZE058834

DATE / TIME OF ACCIDENT: 13/01/2018 Time: 1250Hrs ALONG ANG MO KIO AVE 6 TWDS SIN MING
THIRD PARTY VEHICLE NO: OD

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
1 Battery Top Bracket	1	S\$ 25.00		S\$ 25.00 ✓
2 Chassis Bracket LH	1	60.00		60.00 ✓
3 Chassis Bracket RH	1	60.00		60.00 ✓
4 Deflector Radiator Side LH	1	45.00		45.00 ✓
5 Deflector Radiator Side RH	1	45.00		45.00 ✓
6 Inlet Assy, Air Cleaner	1	80.00		80.00 ✓
7 ATF Pipe To Radiator(Metal)	2			
8 Bonnet Rubber	2	28.00		56.00 ✓
Sub-Total:				371.00
Total Parts:				371.00

Special Nett Items

1 Anti-rust coating	1	80.00		80.00 ✓
				80.00
Total Parts:				451.00

Labour Charges For Front Portion

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	500.00 ✓
Total Labour:		<u>500.00</u> X
Total Parts & Labour:		1,000.00
GST 7%		1,451.00
Grand Total:		<u>101.57</u>
		<u>1,552.57</u>

Estimate Repair Duration

4 days

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore (068811)
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6338 7288 Fax : 6880 4838

DEAR SIR / MADAM :

OD Claim SUPPLEMENTARY 2

ACCIDENT REPAIR ON: SKA5127A
MODEL : TOYOTA CAMRY 2.0
POLICY NO : GA058543/1
CHASSIS NO : MR053BK4107016818
ENGINE NO : 1AZE058834
DATE / TIME OF ACCIDENT: 13/01/2018 Time: 1250Hrs ALONG ANG MO KIO AVE 6 TWDS SIN MING
THIRD PARTY VEHICLE NO: OD

Date: 17/01/2018
Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	BONNET CABLE	1	28.00	JA	28.00
2	HORN , HIGH PITCH	1	50.00	CM	50.00
3	HORN , LOW PITCH	1	50.00	CM	50.00
Sub-Total:					128.00
Total Parts:					128.00

Special Nett Items

1

Parts - 3858.00
Labour - 1420.00
MISC - 65.00

Total Parts: 128.00

Labour Charges For Front Portion

1

2

Total Labour:

Total - \$5343.00 ✓ OK

Total Parts & Labour:	128.00
GST 7%	8.96
Grand Total:	136.96

Estimate Repair Duration 4 days

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore (068811)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6338 7288 Fax : 6880 4838

FM
Not handw
1-B.1
Referring B4 pain
6 days

DEAR SIR / MADAM :

OD Claim

Fax: 62564315

ACCIDENT REPAIR ON: SKA5127A

MODEL : TOYOTA CAMRY 2.0

POLICY NO : GA058543/1

CHASSIS NO : MR053BK4107016818

ENGINE NO : 1AZE058834

DATE / TIME OF ACCIDENT: 13/01/2018 Time: 1250Hrs ALONG ANG MO KIO AVE 6 TWDS SIN MING

THIRD PARTY VEHICLE NO: OD

Date: 17/01/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Bonnet	1	400.00		<i>Rn</i> 400.00 ✓
2	Bonnet Hinge LH	1	30.00		<i>Dls R</i> 30.00 ✓
3	Bonnet Hinge RH	1	30.00		<i>Dls R</i> 30.00 ✓
4	Bonnet Lock Assy	1	50.00		<i>Rn</i> 50.00 ✓
5	Bonnet Damper	1	110.00		<i>Rn</i> 110.00 x
6	Bonnet Insulator	1	165.00		<i>Rn</i> 165.00 x
7	Bonnet Insulator Clips	10	2.00		<i>Rn</i> 20.00 ✓
8	Front Fender LH	1	185.00		<i>R</i> 185.00 x
9	Front Fender Shield LH	1	70.00		<i>Rn</i> 70.00 x
10	Front Fender Shield Clips	10	2.00		<i>Rn</i> 20.00 x
11	Front Fender RH	1	185.00		<i>R</i> 185.00 x
12	Front Fender Shield RH	1	70.00		<i>Rn</i> 70.00 x
13	Front Fender Shield Clips	10	2.00		<i>Rn</i> 20.00 x
14	Headlamp LH	1	275.00		<i>CM</i> 275.00 ✓
15	Headlamp RH	1	275.00		<i>CM</i> 275.00 ✓
16	Front Bumper	1	190.00		<i>CM</i> 190.00 ✓
17	Front Bumper Clips	10	2.00		<i>Rn</i> 20.00 ✓
18	Front Bumper Side Retainer LH	1	30.00		<i>B/S</i> 30.00 ✓
19	Front Bumper Side Retainer RH	1	30.00		<i>B/S</i> 30.00 ✓
20	Front Bumper Upper Grille Chrome	1	140.00		<i>B/S</i> 140.00 ✓
21	Front Bumper Emblem	1	55.00		<i>Rn</i> 55.00 ✓
22	Front Bumper Lower Grille	1	40.00		<i>Sv</i> 40.00 x
23	Front Bumper Tow Cover	1	10.00		<i>Rn</i> 10.00 x
24	Fog Lamp LH	1	100.00		<i>Rn</i> 100.00 x
25	Fog Lamp Cover LH	1	30.00		<i>Rn</i> 30.00 x
26	Fog Lamp Cover Lining Chrome LH	1	45.00		<i>Sv</i> 45.00 x
27	Fog Lamp RH	1	100.00		<i>Rn</i> 100.00 x
28	Fog Lamp Cover RH	1	30.00		<i>Rn</i> 30.00 x
29	Fog Lamp Cover Lining Chrome RH	1	45.00		<i>Rn</i> 45.00 x
30	Front Bumper Reinforcement	1	145.00		<i>Bt</i> 145.00 ✓
31	Front Bumper Sponge	1	50.00		<i>CM</i> 50.00 ✓
32	Support Panel	1	310.00		<i>Rn</i> 310.00 ✓
33	Support Panel Top Garnish	1	130.00		130.00 ?

34	Support Panel Top Garnish Clips	10	2.00	20.00 ✓
35	Radiator Assy	1	500.00	500.00 ✓
36	Radiator Mounting and Rubber Upper	2	10.00	20.00 ?
37	Radiator Mounting and Rubber Lower	2	12.00	24.00 ?
38	Aircon Condenser Assy	1	350.00	350.00 ✓
39	Aircon Pipe Discharge	1	130.00	130.00 ?
40	Aircon Pipe Suction	1	280.00	280.00 ?
41	Front Brace Panel Assy	1	40.00	40.00 ✓
42	Radiator Fan Blade	1	60.00	60.00 ?
43	Radiator Fan Motor	1	180.00	180.00 ?
44	Radiator & Aircon Cowling	1	95.00	95.00 ✓
45	Aircon Fan Blade	1	60.00	60.00 ?
46	Aircon Fan Motor	1	180.00	180.00 ?
47	Fan Resistant	1		-
			Sub-Total:	5,344.00
			Total Parts:	5,344.00

Special Nett Items

1	Anti-rust coating	2	80.00	160.00 X
2	Radiator Coolant	1	60.00	60.00 20sn
3	Front number plate with casing	1	50.00	50.00 45sn
4	Glue Sealant	1	60.00	60.00 ?
				160.00
			Total Parts:	5,504.00

Labour Charges For Front Portion

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	1,400.00	700
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,200.00	600
3	Provide skill labour to disconnect and check electrical wiring	30.00	200
4	Provide skill labour to remove and replace air-con condenser, pipes and radiator, vacuum air-con system and refill gas	100.00	✓
Total Labour:		2,730.00	
		Total Parts & Labour:	8,234.00
		GST 7%	576.38
		Grand Total:	8,810.38

Estimate Repair Duration 13 days

ACCIDENT VEHICLE OF : SKA5127A

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Survey attended by:

Name : Henrich
Company : LK/C
Date : 18/1/18
Time : 1.20pm
Contact No : 96910663
Email :



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: BH AUTO SERVICES PTE LTD

BLK 1, SECTOR C,
SIN MING INDUSTRIAL ESTATE
#01-111/113/115/117 S(575636)
CAMRY
KELVIN

NO: DLI9198677
PAGE: 1
DATE: 19/01/2018
A/C CODE: LDBH111
TERMS: CR
P/O NO: 01-1967

VEH NO: SKA5127A

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
1	T53301-06110 BONNET ①	DB1HS	1	400.00	400.00
2	T53510-06101 BONNET LOCK ④	DUIB1	X	50.00	50.00
3	T90467-08124 CLIP -INSULATOR ⑦	DUIAD11-10	10	2.00	20.00
4	T81170-06241 H/LAMP LH ④	DB1HS	1	275.00	275.00
5	T81130-06241 H/LAMP RH ⑤	DB1H10	1	275.00	275.00
6	T52119-06922 BUMPER FR ⑥	DB2E	1	190.00	190.00
7	T52161-16010 CLIP FRT BUMPER ⑦	DUIAD11-3	10	1.50	15.00
8	T52535-06080 ⑧ BUMPER RETAINER FR RH	DUIAD13-1	X	30.00	30.00
9	T52536-06070 ⑨ BUMPER RETAINER FR LH	DUIAD14-1	X	30.00	30.00
10	T53111-06130 ⑩ GRILLE	DB2H	1	140.00	140.00
11	T90975-02064 ⑪ FRT LOGO	DDIAS2-28	1	30.00	30.00
12	T75311-06070 ⑫ BASE-GRILLE LOGO	DUIAS3-61	X	25.00	25.00
13	T52611-06110 BUMPER SPONGE FR ⑬	DB1E49	1	50.00	50.00
14	T53201-06172 SUPPORT ASSY ⑭	DB1E4	1	310.00	310.00
15	T88460-06170 CONDENSER ⑮	DB2H	1	350.00	350.00
16	T53208-06040 BRACE PANEL ⑯	DUIE24-1	X	40.00	40.00
17	T16711-0H170 FAN SHROUD ⑰	DBAA1S	1	95.00	95.00
18	T90467-07211 CLIP TOP GARNISH ⑱	DDIAS3	7	2.00	14.00

Print / LSK / 19/1/2018 10:26:57 AM

...Cont'd



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: BH AUTO SERVICES PTE LTD

BLK 1, SECTOR C,
SIN MING INDUSTRIAL ESTATE
#01-111/113/115/117 S(575636)
CAMRY
ANTHONY

NO: DLI9198834
PAGE: 1
DATE: 23/01/2018
A/C CODE: LDBH111
TERMS: CR
P/O NO: 01-1972

VEH NO: SKA5127A

Part No	Description	Location	Qty	Unit Price	Amount
1	T74404-06100 <i>supp 1</i>	DU1D40-3	X	SIN 25.00	SIN 25.00
2	T57117-33050 X REINF RH BKT	DU1C5-1	X	60.00	60.00
3	T57118-33050 X REINF LH BKT	DU1C5-1	X	60.00	60.00
4	T53293-06050 <i>supp 7</i> DEFLECTOR RH	DU1AB25-2	X	45.00	45.00
5	T53294-06050 <i>3/4</i> DEFLECTOR LH	DU1AB25-5	X	45.00	45.00
6	T17750-0H070 <i>supp 6</i> INLET AIR CLEANER	DU1G28-1	X	80.00	80.00
7	T53183-06050 SEAL HEADLAMP	DU1G1-2	X	28.00	28.00
8	T53381-06050 <i>supp 8</i> BONNET RUBBER	DU1G2-1	X	28.00	28.00
9	T53410-06130 2 BONNET HINGE RH	DU1AD17-1	X	30.00	30.00
10	T53420-06130 3 BONNET HINGE LH	DU1AD22-1	X	30.00	30.00
11	T53341-06160 X BONNET INSULATOR	DB2DD6S	1	165.00	165.00
12	T52021-06060 30 BUMPER REINF FR	DB1G24L	1	145.00	145.00
13	T16400-0H250 35 RADIATOR	DB1A27S	1	500.00	500.00
TOTAL QUANTITY:			13	TOTAL	SIN 1,241.00
				ADD GST @ 7%	86.87
				GRAND TOTAL	<u>SIN 1,327.87</u>

Print / LSK / 23/1/2018 9:18:46 AM


SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & Q. E. T.
P. 11/15

GOODS RECEIVED BY



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: BH AUTO SERVICES PTE LTD

BLK 1, SECTOR C,

SIN MING INDUSTRIAL ESTATE

#01-111 113 115/117 S(575636)

CANRY

WEN ZHENG

NO: DL9199124

PAGE: 1

DATE: 30-01-2018

A/C CODE: LDBH111

TERMS: CK

VEH NO: SKA5127A

Part No	Description	Location	Qty	Unit Price	Amount
1	T53630-06110	DUNLOP	1	28.00	28.00
TOTAL QUANTITY			1	TOTAL	SIN 28.00
				ADD GST @ 7%	1.96
				GRAND TOTAL	<u>SIN 29.96</u>

Print: LSK / 30-01-2018 9:02:13 AM


SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

F. & O. E.

GOODS RECEIVED BY



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: BH AUTO SERVICES PTE LTD

BLK 1, SECTOR C.

SIN MING INDUSTRIAL ESTATE

#01-111/113/115/117 S(575636)

CAMRY

WEN ZHENG

NO: DLI9198974

PAGE: 1

DATE: 25/01/2018

A/C CODE: LDBH111

TERMS: CR

P/O NO: 01-1979

VEH NO: SKA5127A

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T86510-06110	SUPP 2, 2 HORN RH (HIGH)	DDISH1T12	✓	50.00	50.00
2 T86520-06100	HORN LH (LOW) SUPP 2, 3	DDISH1T12	✓	50.00	50.00
3 T52040-06010	25 COVER FOG LAMP LH	DUIAD48-6	✓	30.00	30.00
4 T52713-06010	26 MOULDING RT BP LH	DUIAB46-3	✓	45.00	45.00
5 T16363-0H130	43 FAN MOTOR RAD	DUIQ22	✓	180.00	180.00
6 T16363-0H140	46 FAN MOTOR AIR-CON	DUIQ3	✓	180.00	180.00
TOTAL QUANTITY:			6	TOTAL	SIN 535.00
				ADD GST @ 7%	37.45
				GRAND TOTAL	<u>SIN 572.45</u>

Print / LSK / 25/1/2018 10:31:27 AM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E & O.E.

GOODS RECEIVED BY