

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO.201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1890088/AMK

Date: 26 Jan 2018

Policy No: 5091193042

Veh Reg No: SLM4724H

Make/Model: VOLKSWAGEN CC TSI
 1.8A

Chassis No: WVWZZZ3CZCE702358

Engine No: CDA284786

Reg. Date: 15/05/2012

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 17/01/2018

TP Veh Reg No: SJW303L

Not Notified

1:3:1

Putty B4 paint

5 days

Estimate Repair Cost to Vehicle No :SLM4724H

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	1,293.90	1 PC	<i>Bu</i> 1,293.90	—
2 FRONT BUMPER RH SIDE RETAINER	39.00	1 PC	<i>dry</i> 39.00	—
3 FRONT RH FENDER	874.00	1 PC	<i>Ry</i> 874.00	—
4 FRONT RH FENDER INNER SHIELD	383.80	1 PC	<i>Sm</i> 383.80	x
5 FRONT RH FENDER INNER BRACKET	81.70	1 PC	81.70	?
6 HEADLAMP RH	2,432.00	1 PC	<i>cm</i> 2,432.00	✓
7 HEADLAMP RH LOWER BRACKET	43.50	1 PC	43.50	?
8 FRONT LH RIM 17"	1,890.00	1 PC	<i>nd</i> 1,890.00	✓
9 BONNET	1,252.68	1 PC	<i>Bu</i> 1,252.68	✓
			8,290.58	
		Less 10%	829.06	7,461.52
Special Net				
10 FRONT LH TYRE 17"	300.00	1 PC	<i>Cur</i> 300.00	<i>608sm</i>
			300.00	300.00
Labour				
11 REMOVE & REFIX FRT BUMPER,GRILLE,HEADLAMP,FRT RH FENDER;KNOCKING & REPAIR FRT RH FENDER INNER PANEL & REALIGN BONNET THE SAME	600.00	1 LA	600.00	<i>500l</i>
12 PUTTY & RESPRAY FRT BUMPER,FRT RH FENDER & INNER PANEL,BONNET & ALL AFFECTED AREAS	700.00	1 LA	700.00	<i>650l</i>
13 REMOVE & REFIX FRT LH RIM,ROTATE & BALANCE & REALIGN THE SAME	50.00	1 LA	50.00	<i>20l</i>
14 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	80.00	1 PC	80.00	<i>60l</i>
15 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,490.00	1,490.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 17/01/2018
TP Veh Reg No: SJW303L

Estimate No: ES1890088/AMK
Date: 26 Jan 2018
Policy No: 5091193042
Veh Reg No: SLM4724H
Make/Model: VOLKSWAGEN CC TSI
1.8A
Chassis No: WVVWZZZ3CZCE702358
Engine No: CDA284786
Reg. Date: 15/05/2012

Estimate Repair Cost to Vehicle No :SLM4724H

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 9,251.52
			Add GST @ 7%	647.61
			Total Amount Payable	<u>S\$ 9,899.13</u>

VEHICLE LYING AT:
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE