FAX Number : 63685592





60 Woodlands Industrial Park E4, Singapore 757705

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No SHB913K

Ref. No TAX/01/18/2084

Reg. Date 19/12/2017

Vehicle Type TAXI

Make TOYOTA PRIUS

Model PRIUS4

Name of Driver CHUA CHEE KHIAN

Type of Accident **OTHERS**

Date / Time of Accident : 13/01/2018 08:05:00 PM

Accident Reported Date / Time: 15/01/2018 12:00:00 AM

Surveyor is Required? Yes

Survey by

Vehicle is Towed Back? Yes

Towed Back Date/Time 13/01/2018

Replacement Vehicle issued? :

Accident Repair Job Card No : 000024094085

Special Instruction to ARC, if any :

TOWED \$ 40 / SLK4172K All Resony by point

Prepared Date 15/01/2018 11:56:35 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKB3FU403576879

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Total Spray Painting Charges

Arc / Surveyor Sing Off Date

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

845.00

1,314.00

0.00 0.00

Total Material Charges

4,871.58

Other Charges

4,871.58

420.00

0.00

TOTAL

7,450.58

5.00

0.00

Lum Sum Total

0.00

0.00

No. of Repair Days

Prepared / Adjusted By

15/01/2018 03:53:20 PM

0.00 5 days /p/P

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 15/01/2018 03:53:20 PM

16/01/18 (1535

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

LKK Auto Consultants hence notify

the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	845.00	0.00 600
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO RESPRAY FRONT FENDER LH	378.00	0.00	200		
TO REPSRAY FRONT BUMPER	378.00	0.00	Son		
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00	(50		
TO REPSRAY FRONT HOOD	378.00	0.00	200		
Total Spray Painting & Panel Beating	1,314.00	0.00			

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ? recript
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 60
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00 40
Total Other Costs	420.00	0.00

ΓAX/01/18/2084

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen	Surveyor Approved	Photos Attached
53802471 00			FENDER SUB-ASSY, FR , LH	1	933.10	25.00	699.82	Replace	Reptace	No
75374471 40			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	No
52119479 62			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace	No
52116470 50			SUPPORT, FR BUMPER LH	1	82.30	25.00	61.72	Replace	Replace	No
52128479 06			COVER, FR BUMPER LH	1	28.10	25.00	21.07	Replace	Replace ?	No
			NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace	No
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace	No
53101470 80			GRILLE SUB-ASSY	1	335.60	25.00	251.70	Replace	Replace	No
53205479 00			SUPPORT S/A UPPER	1	364.90	25.00	273.67	Replace	Replace	No
81185476 91			UNIT, HEADLAMP , LH	1	2,558.90	10.00	2,303.01	Replace	Replace	No
53301471 10			HOOD SUB-ASSY	1	938.40	25.00	703.80	Replace	Replace	No
53420471 30			HINGE ASSY, HOOD, LH	1	57.00	25.00	42.75	Replace	Replace 9	No
TOTAL MATERIALS								4,828.86	4,828.83	
TOTAL MATERIALS(Discounted)					4,871.58 4,871.58					

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS								Oncon	Oncor