

REF: CS/ICS18001106/R1qd367

ASSIGNMENT (Office)

Re: Phoebe Jay of ECICS Date: 18/01/2018 @ 9:18am

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / DV / MV / CS

To Inspect Vehicle No: SCM 8636J Insured: _____

at Workshop ref: Performance Tel: 9116 5199

of: 303 Alexandra Road

Policy No: _____ Claim No: DMP C180105H

Sum Insured: _____ Excess: TBA

Make of Veh: _____ Date: 08/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 9:50am @ 18/01/18 Person Contacted: Merina Vehicle: SCM 8636J

Date/Time	Action/Instruction (✓)	Remarks
	SCM 8636J-x	Flood Case
19/1/18 @ 1:21pm	revert to Phoebe by email.	
19/1/18 @ 1:46pm	Phoebe informed c/A as ex: of by email.	
19/1/18 @ 1:49pm	Informed Merina c/A as ex: of by email.	
12/4/18 @ 5:51pm	2nd revert to Phoebe by email. (supplementary).	
03/5/18 @ 11:51am	Janice Goh informed c/A as our recommended third email.	

Flood Case

REP: ECICS

70672

ASSIGNMENT

From: Date: 18/01/2018

Estimated Cost:

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCM 8636J

at Workshop no: Performance
of 303 Alexandra Road

Insured

Policy No:

Claims No:

Sum Insured: Excess TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 140K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

FLOOD

N/S	O/S

Veh No: SCM 8636J Yr Reg: 2013 APR

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 730 LI CC 2996

Colour: GRN A/C Insured / Std / Nil / NA

Sb. Reading: 30768 T-Radio Insured / Std / Nil / NA

Eng No:

Q/No: WBA4E 2209 00 2209 38

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/50R18

R:

BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 08/01/18 D.O.I: 18/01/18

Survey held at: PERFORMANCE

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

FLOOD

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

03/5/18 @ 12.09pm confirmed with Caroline final Ag \$19559.90, 7 days.
CR & \$1058.50, 5%

3/5/18

RECEIVED 07 MAY 2018

Date/Time File Pass to:

04/5/18

☐ : Preli. Report

☐ : Final Report

Date/Time File Return to:

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee

Transportation

3 - 5

Access

Cost

Cost

Add Fee:

☐

Site Insp \$

☐

Inter. Insp \$

☐

Test. Insp \$

☐

Rep. Insp \$

Report Format:

OD

Lump Sum / L.Bill \$

19559.90

140

140

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18001106/R1qd3

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987 &

Date : 18-01-2018



Code : ICS

Policy Particulars :- OWN DAMAGE

1.

1.	Policy Particulars :- OWN DAMAGE		SCM 8636J
	Insured Veh.	Veh. Inspected	
	Policy No.	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	18/01/2018
	PHOEBE JAY		

Vehicle Particulars & Condition

2.

2. Vehicle Particulars & Condition	
Make & Model	c.c 0
Engine No. HIDDEN	Year of Reg.
Chassis No.	Colour
Odometer -	Steering
Brakes	Modification
General	

Conditions of Tyres

3.

3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages	Amount	Date

4.

4.	Description of Damages

General Information

5.

5.		General Information	
	Accident Date	08/01/2018	Inspection Date 18/01/2018
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

Remarks

5a.

5a.		Remarks
	A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)	
	B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.	

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Thursday, 18 January 2018 9:18 AM
To: assignments
Subject: FW: SCM8636J - Own Damage Claim - Flood - Car In Workshop
Attachments: SCM8636J Quotation.pdf

Importance: High

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Phoebe Jay Xie (ECICS, Claims) [mailto:PhoebeJay_Xie@ecics.com.sg]
Sent: Thursday, 18 January 2018 9:14 AM
To: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: ECICS Claims <claims@ecics.com.sg>
Subject: FW: SCM8636J - Own Damage Claim - Flood - Car In Workshop
Importance: High

Dear LKK,

Please survey vehicle.

Thank you.

Best Regards,

Phoebe Jay Xie

ECICS Limited

DID: +65 6303 0180

FAX: +65 6338 9267

Email: phoebejay_xie@ecics.com.sg

From: Merina Chia San San [<mailto:merina.chia.sansan@simedarby.com.sg>]
Sent: Thursday, 18 January, 2018 8:54 AM
To: ECICS Claims
Subject: SCM8636J - Own Damage Claim - Flood - Car In Workshop
Importance: High

Dear Sir/Mdm,

Please kindly assist to arrange survey for the above mentioned vehicle. Car in workshop.

Thank you

Regards,

Merina Chia

Customer Service Advisor | Body and Paint
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Hp (+65) 9116 5199 | Fax (+65) 6479 4601
merina.chia.sanson@sime-darby.com.sg



<https://www.pml-bmw.com.sg/en/ssl/test-drive.html>



Please consider the environment before printing this e-mail.

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

follow us on  facebook follow us on  twitter visit our website  ecics.com.sg

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 3 May 2018 12:09 PM
To: PBSP
Cc: SUR
Subject: RE: Final Report / SCM8636J

Dear Caroline,

Confirm final fig \$19,559.90 before GST and 7 repair days.

Kindly send the relevant documents to ECICS company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 27 April 2018 11:25 AM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Final Report / SCM8636J

Dear Caroline,

Yes, still pending for insurance's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Thursday, 26 April 2018 6:01 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: Re: Final Report / SCM8636J

Dear Shiau Chan

Have your side secure the mandate from ECICS?

Thank you.

Shiau Chan (LKKAUTO)

From: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>
Sent: Thursday, 3 May 2018 11:45 AM
To: Shiau Chan (LKKAUTO)
Cc: SUR
Subject: RE: SCM8636J - Own Damage Claim - Flood - Car In Workshop ; Our ref DMPC1800005H

Dear Shiau

Please proceed as recommended.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, 2 May, 2018 10:15 AM
To: Janice Goh Siew Geok (ECICS, Claims)
Cc: SUR
Subject: RE: SCM8636J - Own Damage Claim - Flood - Car In Workshop

Dear Janice,

Any updates?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 27 April 2018 11:24 AM
To: 'Janice Goh Siew Geok (ECICS, Claims)' <Janice_Goh@ecics.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: FW: SCM8636J - Own Damage Claim - Flood - Car In Workshop

Dear Janice,

As spoken with you.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 13 April 2018 5:51 PM
To: Phoebe Jay Xie (ECICS, Claims); assignments
Cc: SUR
Subject: RE: SCM8636J - Own Damage Claim - Flood - Car In Workshop
Attachments: SCM8636 SUPP.pdf; CSICS18001106R1qd3(2).pdf

Dear Phoebe,

Enclosed herewith 2nd preliminary advice of SCM 8636J.
Kindly approve on supplementary.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Friday, 19 January 2018 1:45 PM
To: Phoebe Jay Xie (ECICS, Claims) <PhoebeJay_Xie@ecics.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SCM8636J - Own Damage Claim - Flood - Car In Workshop

Dear Phoebe,

Thank you for the email.

We are recommend 7 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Phoebe Jay Xie (ECICS, Claims) [mailto:PhoebeJay_Xie@ecics.com.sg]
Sent: Friday, 19 January 2018 1:46 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SCM8636J - Own Damage Claim - Flood - Car In Workshop

Dear Shiau Chan,

Excess \$0, please proceed with repairs and advise on days of repair

Thank you.

Best Regards,

Phoebe Jay Xie



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SCM 8636J

Date: 13th April 2018

Our Ref: CS/ICS18001106/R1qd3

The Motor Claims Department
ECICS Limited

Attn: Phoebe

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SCM 8636J


We thank you for the instruction on 18/01/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/01/2018 at the premises of M/s PERFORMANCE MOTORS LIMITED and have the following to report:-

Workshop Estimate Amount	: S\$ 20,618.40 (EST \$11,006.30 + SUPP \$9,612.10)
Revised Estimate Amount	: S\$ 19,559.90 (INCLUSIVE OF SUPPLEMENTARY)
"Check" Items Amount	: S\$ -
Market Value	: S\$ 140,000.00
Salvage Value	: S\$ 104,863.00
Nett Value	: S\$ 35,137.00

Description of Damage:

The vehicle recovered from flood. Many electrical & mechanism parts found damaged and contaminated by flood water at the time of inspection.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Kindly approve on supplementary.

Yours faithfully

MOHD RASUL
Automobile Assessor

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 19 January 2018 1:47 PM
To: Merina Chia San San
Cc: Gary Poh Chai Hoon; SUR
Subject: VEHICLE SCM 8636J (DOA: 08/01/2018)

Dear Merina,

As instructed by our client ECICS , please proceed to repair the insured vehicle **SCM 8636J (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 19 January 2018 1:45 PM
To: Phoebe Jay Xie (ECICS, Claims); assignments
Cc: SUR
Subject: RE: SCM8636J - Own Damage Claim - Flood - Car In Workshop

Dear Phoebe,

Thank you for the email.

We are recommend 7 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Phoebe Jay Xie (ECICS, Claims) [mailto:PhoebeJay_Xie@ecics.com.sg]
Sent: Friday, 19 January 2018 1:46 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SCM8636J - Own Damage Claim - Flood - Car In Workshop

Dear Shiau Chan,

Excess \$0, please proceed with repairs and advise on days of repair

Thank you.

Best Regards,

Phoebe Jay Xie

ECICS Limited

DID: +65 6303 0180

FAX: +65 6338 9267

Email: phoebejay_xie@ecics.com.sg

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Friday, 19 January, 2018 1:21 PM
To: Phoebe Jay Xie (ECICS, Claims); assignments
Cc: SUR
Subject: RE: SCM8636J - Own Damage Claim - Flood - Car In Workshop

Dear Phoebe,

Enclosed herewith preliminary advice of SCM 8636J.
We have not authorise repair.

Kindly advise us the authorisation and excess.

Merina Chia San San

From: Phoebe Jay Xie (ECICS, Claims) <PhoebeJay_Xie@ecics.com.sg>
Sent: Thursday, 18 January, 2018 9:20 AM
To: Merina Chia San San
Cc: ECICS Claims; 甯珺 ©; SUR
Subject: RE: SCM8636J - Own Damage Claim - Flood - Car In Workshop

Dear Merina,

We have appointed LKK for the survey. Please proceed to order the parts and excess to be waived.

Thank you.

Best Regards,

Phoebe Jay Xie

ECICS Limited

DID: +65 6303 0180

FAX: +65 6338 9267

Email: phoebejay_xie@ecics.com.sg

From: Phoebe Jay Xie (ECICS, Claims)
Sent: Thursday, 18 January, 2018 9:14 AM
To: Admin A; SUR
Cc: ECICS Claims
Subject: FW: SCM8636J - Own Damage Claim - Flood - Car In Workshop
Importance: High

Dear LKK,

Please survey vehicle.

Thank you.

Best Regards,

Phoebe Jay Xie

ECICS Limited

DID: +65 6303 0180

FAX: +65 6338 9267

Email: phoebejay_xie@ecics.com.sg

From: Merina Chia San San [<mailto:merina.chia.sansan@simedarby.com.sg>]
Sent: Thursday, 18 January, 2018 8:54 AM
To: ECICS Claims
Subject: SCM8636J - Own Damage Claim - Flood - Car In Workshop
Importance: High

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 19 January 2018 1:21 PM
To: 'Phoebe Jay Xie (ECICS, Claims)'; assignments
Cc: SUR
Subject: RE: SCM8636J - Own Damage Claim - Flood - Car In Workshop
Attachments: CSICS18001106R1qd3.pdf

Dear Phoebe,

Enclosed herewith preliminary advice of SCM 8636J.
We have not authorise repair.

Kindly advise us the authorisation and excess.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 18 January 2018 10:06 AM
To: 'Phoebe Jay Xie (ECICS, Claims)' <PhoebeJay_Xie@ecics.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SCM8636J - Own Damage Claim - Flood - Car In Workshop

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Phoebe Jay Xie (ECICS, Claims) [mailto:PhoebeJay_Xie@ecics.com.sg]
Sent: Thursday, 18 January 2018 9:14 AM
To: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: ECICS Claims <claims@ecics.com.sg>
Subject: FW: SCM8636J - Own Damage Claim - Flood - Car In Workshop
Importance: High

Dear LKK,

Please survey vehicle.

Thank you.

Best Regards,

Phoebe Jay Xie



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SCM 8636J

Date: 19th January 2018

Our Ref: CS/ICS18001106/R1qd3

The Motor Claims Department
ECICS Limited

Attn: Phoebe

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SCM 8636J .


We thank you for the instruction on 18/01/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/01/2018 at the premises of M/s PERFORMANCE MOTORS LIMITED and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,904.45</u> .
Revised Estimate Amount	: S\$ <u>9,850.45</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>140,000.00</u> .
Salvage Value	: S\$ <u>104,863.00</u> .
Nett Value	: S\$ <u>35,137.00</u> .

Description of Damage:

The vehicle recovered from flood. Many electrical & mechanism parts found damaged and contaminated by flood water at the time of inspection.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

We have not authorize repair.

Yours faithfully

MOHD RASUL
Automobile Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7067Z
Vehicle Details	
Vehicle No.:	SCM8636J
Vehicle to be Exported:	Yes
Intended De-registration Date:	18 Jan 2018
Vehicle Make:	B.M.W.
Vehicle Model:	730LI AT D/AB 4DR SR LED DSC NAV HUD
Primary Colour:	Brown
Manufacturing Year:	2012
Engine No.:	08628329N52B30AF
Chassis No.:	WBAYE22090DZ20938
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$73,089.00
Original Registration Date:	15 Apr 2013
First Registration Date:	15 Apr 2013
Transfer Count:	0
Actual ARF Paid:	\$73,089.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Apr 2023
PARF Rebate Amount:	\$54,816.00
Intended COE Rebate Details	
COE Expiry Date:	14 Apr 2023
COE Category:	E - Open Category

COE Period(Years):	10
QP Paid:	\$97,889.00
COE Rebate Amount:	\$50,047.00
Total Rebate Amount:	\$104,863.00

The information contained herein is correct as at 18 Jan 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2012, 185HP Audi A1 Sportback @ \$62,888



Very Low Mileage, Serviced At
PA, Problem Free, Clean And
Polished On 16/1/18!
Direct Owner - Steal Ad

HIN LUNG AUTO
HoBee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

Sort by Date Posted

20 results/page

Advanced Search

3 vehicles

bmw 730

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 730	Any	Any	2013	Any	Any	Any	Available
	BMW 7 Series 730Li Sunroof	\$139,800	\$19,590 /yr	15-Apr-2013	2,996 cc	98,000 km	Luxury	Available
Only Owner, New Facelifted 730Li Sunroof With Adaptive LED Headlights, Fully Maintained By PML, 100% Accident Free, Kick Open Auto Boot System, Tip Top Conditions With No Repairs Required, Bank / High...								
Posted: 18-Jan-2018 Tags: 2013 BMW 730Li, BMW 730Li, BMW, 730Li, Used BMW								
	BMW 7 Series 730Li Sunroof	\$159,688	\$19,680 /yr	25-Jun-2013	2,996 cc	61,251 km	Luxury	Available
New Facelift LED Headlight Model! HIGH ARF \$106K! Promo 1.78% Interest Rate! Low Mileage! 1 MD Owner! Fully Agent (PML) Servicing Records Since Days 1. Free 1 Year Extended Premium Warranty And 1 Year...								
Hamilton Autohub Pte Ltd								
Posted: 17-Jan-2018 Tags: 2013 BMW 730Li, BMW 730Li, BMW, 730Li, Used BMW								
	BMW 7 Series 730Li Sunroof	\$140,800	\$19,650 /yr	26-Apr-2013	2,996 cc	72,000 km	Luxury	Available
1 Owner, Low Mileage Done, Full Serviced Histories With PML, Up To 80% Loan Available, Ex-Bankruptcy And Bad Credit Welcome, High Trade In.								
Faster Auto Trading								
Posted: 06-Jan-2018 Tags: 2013 BMW 730Li, BMW 730Li, BMW, 730Li, Used BMW								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

20 results/page

For old advertisements, view Expired ads

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used bmw 730, bmw 730 Singapore, used bmw 730 Singapore, used bmw 730, used vehicles Singapore or even buy used bmw 730 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/01/2018 10:26
Date Of Accident	08/01/2018 09:30
Exact Location Of Accident	BEDOK NORTH AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCM8636J
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	TEO CHEN THYE
NRIC No	S0187067Z
Email Address	GTEO@GABRIELTEO.COM
Mobile Phone No	(LOCAL) +65-96720851
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	BMW
Model	730LI AT D/AB 4DR SR LED DSC NAV HUD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC17A00235000
Cover Note Number	

Driver

Name of Driver	TEO CHEN THYE
NRIC No	S0187067Z
Date Of Birth	23/04/1951
Occupation	INDOOR
Date Of Driving Pass	13/01/1971
Driving Experience	46 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96720851
Fax Number	
Contact Number	OTHERS-NOPHONE
EMail Address	GTEO@GABRIELTEO.COM

Address	33 LI HWAN CLOSE
Postcode	557156
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	FLOOD
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DOA: 08/01/2018 around Bedok North Ave 4 at 09:30AM

Weather - heavy rain, flood

I was driving along Bedok North Ave 4 and drive thru a pool of water. All of a ^{sudden} my dashboard light all lights up, my steering wheel restraint, air con not working.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

E-DRIVE AUTHORISED
WORKSHOPS

MZ300
COMPREHENSIVE
ORIGINAL

CERTIFICATE NO: **MPC17A00235000**
Agency Name: **Falcon-Air Auto Services Pte Ltd**
Agency Code: **A0000071**

Chassis No: **WBAYE22090DZ20938**
Engine No: **08628329N52B30AF**

1. Index Mark and Registration Number of Vehicle: **SCM8636J**
2. Name of Policyholder: **TEO CHEN THYE**
3. Period of Insurance (both dates inclusive): **15 April 2017 to 14 April 2018**

4. Persons or Classes of Persons entitled to drive

- a) The Policyholder and all Named Drivers declared under the policy
b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

5. Limitations as to use

Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward, tuition, driving test, race, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

6. EXCESS APPLICABLE

WINDSCREEN

SGD 100.00

SECTION I - INSURED/NAMED DRIVER

SGD 0.00

ADDITIONAL EXCESS OTHER THAN NAMED DRIVERS:

SECTION I - AGE <25, AGE >70 OR DRIVING EXP <2 YEARS OLD

SGD 3,000.00

Signed for and on behalf of ECICS Limited

Chief Executive Officer

Important Notice:

- Policyholders are hereby warned that it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid insurance under the Act.
- On the sale of a motor vehicle, Policyholders must surrender all insurance papers issued including the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189).
- The Certificate of Insurance and the Policy will cease to be valid once the motor vehicle has been sold or transferred.
- The Payment Before Cover Warranty or Premium Payment Warranty found in the Policy must be complied with otherwise there would be no liability under the Policy and Certificate of Insurance.

gtes@gabrielteo.com

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)# CAR LEVEL 3 #
KEY LEVEL 3 #
call 93887178 PMH to see car

GST REG. NO : M2 - 0020081 - X

E S T I M A T EEstimate No. : b1 45549
Date Estimated : 18/01/2018
Prepared By : Merina Chia San San

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -Teo Chen Thye
33 Li Hwan Close

Singapore 557456

- ACCOUNT -

144674

ECICS Limited
7 Temasek Boulevard, #10-03 Suntec Tower
Singapore 038987

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCM8636J	DZ20938	15/04/2013	730LiA	0

DESCRIPTIONTo replace ICM control unit, front and rear speed sensor,
parking brake switch, air con blower including attachments
etc

5100 5,950.00

To remove and install front and rear carpets for drying
including to check both front seats electrical adjustment
drive unit for proper function

903 1,062.00

To check electrical wiring system at the front and rear
sections for proper function including adjustment of
headlights.

250 295.00

To tow accident vehicle to PML workshop.

195.00

Sundries.

150.00

Total Labour 1: 7,652.00

DESCRIPTION(S/L) PULSE GENERATOR DSC REAR
DSC PULSE GENERATOR FRT
ICM CONTROL UNIT
SWITCH PARKING BRAKE/AUTO HOLD
HOUSING COVER WITH COARSE FILTER

QTY	PRIC	VALUE
1	185.60	185.60
1	185.60	185.60
1	2,634.55	2,634.55
1	185.45	185.45
1	61.25	61.25

Total Parts : 3,252.45

11006-30

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 2

Estimate No. : b1 45549
Date Estimated : 18/01/2018
Prepared By : Merina Chia San San

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCM8636J	DZ20938	15/04/2013	730Li	0

Claims / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____

Surveyor's Name _____

Surveyor's Tel _____

Authorized Date _____

BY SURVEYOR Yes / No PML Yes / No

Resurvey Parts Photo by Surveyor _____

Claims 3rd Party / Uninsured losses / Direct

Regn No. _____ Claim No. _____

Date & Time 18/01/18 @ 1445 Excess _____

Surveyor's Name RAN Sign _____

Surveyor's Tel 90010068

Authorized Date _____

RECURVEY PARTS PHOTO BY SURVEYOR

Surveyor's E-mail _____

No. of Working Days Recommended 7 days

Signature
23/1/18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

20618.40

Labour 1	:	7,652.00
Parts	:	3,252.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	763.31
Grand Total	:	11,667.76

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197491559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45549
Date Estimated : 18/01/2018
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
Teo Chen Thye
33 Li Hwan Close

- ACCOUNT - 144674
ECICS Limited
7 Temasek Boulevard, #10-03 Suntec Tower 1
Singapore 038987

Singapore 557456

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SCM8636J	DZ20938	15/04/2013	730LiA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To remove and install air con blower housing assembly to facilitate repairs	451.00		451.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BASIC CONTROL UNIT DME (CODED) *	2,702.20	1.00		2,702.20
# SEALING GROMMET *	0.65	5.00		3.25
# SEALING GROMMET *	0.85	5.00		4.25
# (S/L) RP HYDRAULIC UNIT DSC *	5,017.80	1.00		5,017.80
# COVERING CAP (D=10MM) *	2.75	1.00		2.75
# RIVET *	0.45	3.00		1.35
# COVER STEERING COLUMN *	50.90	1.00		50.90
# UNIVERSAL SOCKET HOUSING UNCODED *	18.85	1.00		18.85
# COVERING CAP 38 POL *	13.80	1.00		13.80
# JACK MCP 2.8 0.2-0.35MM *	2.75	5.00		13.75
# JACK MCP 2.8 1.5-1.0MM *	2.75	5.00		13.75
# FLAT CONTACT MCP 1.5-2.5MM *	0.60	5.00		3.00
# JACK MCP 2.8 4.1-6.0MM *	3.85	5.00		19.25
# SEALING GROMMET *	2.55	5.00		12.75
# SOCKET HOUSING *	21.55	1.00		21.55
# AUXILLARY HEATER ELECTRIC LH *	411.90	1.00		411.90

Total Labour :	451.00
Total Parts :	8,311.10
Total Labour & Parts :	8,762.10

* To diagnose and replace basic control unit DME (coded), RP-hydraulic unit DSC include conducting checks for proper function.

8,500.00
9,612.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45549
Date Estimated : 18/01/2018
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
Teo Chen Thye
33 Li Hwan Close

- ACCOUNT - 144674
ECICS Limited
7 Temasek Boulevard, #10-03 Suntec Tower (C)
Singapore 038987

Singapore 557456

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SCM8636J	DZ20938	15/04/2013	730LiA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace ICM control unit, front and rear speed sensors, parking brake switch, LH auxillary heater electric include removing attachments to facilitate repairs	5100.00		5,100.00
To remove and install front and rear carpets for drying including to check both front seats electrical adjustment drive unit for proper function	903.00		903.00
To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.	250.00		250.00
To tow accident vehicle to PML workshop.	195.00		195.00
* To diagnose and replace basic control unit DME (Coded), RP hydraulic unit DSC include conducting checks for proper function	850.00		850.00
# To remove and install air con blower housing assembly to facilitate repairs	451.00		451.00
Sundries	150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BASIC CONTROL UNIT DME (CODED) *	2,702.20	1.00		2,702.20
# SEALING GROMMET *	0.65	5.00		3.25
# SEALING GROMMET *	0.85	5.00		4.25
# (S/L) RP HYDRAULIC UNIT DSC *	5,017.80	1.00		5,017.80
(S/L) PULSE GENERATOR DSC REAR	203.60	1.00		203.60
DSC PULSE GENERATOR FRT	203.60	1.00		203.60
ICM CONTROL UNIT	2,700.40	1.00		2,700.40
# COVERING CAP (D=10MM) *	2.75	1.00		2.75
# RIVET *	0.45	3.00		1.35
# COVER STEERING COLUMN *	50.90	1.00		50.90
# UNIVERSAL SOCKET HOUSING UNCODED *	18.85	1.00		18.85
# COVERING CAP 38 POL *	13.80	1.00		13.80
# JACK MCP 2.8 0.2-0.35MM *	2.75	5.00		13.75
# JACK MCP 2.8 1.5-1.0MM *	2.75	5.00		13.75
# FLAT CONTACT MCP 1.5-2.5MM *	0.60	5.00		3.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

# JACK MCP 2.8 4.1-6.0MM *	3.85	5.00	19.25 LH
# SEALING GROMMET *	2.55	5.00	12.75 LH
# SOCKET HOUSING *	21.55	1.00	21.55 LH
SWITCH PARKING BRAKE/AUTO HOLD	180.95	1.00	180.95
HOUSING COVER WITH COARSE FILTER	61.25	1.00	61.25
# AUXILLARY HEATER ELECTRIC LH *	411.90	1.00	411.90 LH

SUPPLEMENTARY ITEMS

Total Labour :	7,899.00
Total Parts :	11,660.90
Total Labour & Parts :	19,559.90
Deduction for Excess :	
Total Repair Costs less Excess:	19,559.90
GST @7%:	1,369.19
Grand Total :	20,929.09

30/01/2018

Supplementary Parts to be replaced:	Price (nett)
Parts:	
① Basic control unit DME (Coded)	\$2902.20
② (S/L) RP Hydraulic unit DSC	\$4895.40
Labour:	
To replace control unit (DME) & replacing DSC Control unit	\$1275

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 30/01/18 @ Excess \$5 _____

Surveyor's Name Pam Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PART'S PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's Email _____

No. of Working Days Recommended 1 day

Back Order Request By

Order No : _____

Workshop

Order Date : 30/1/18

STOCK / VOR / RUSH / CODED

Back Order : 341712

PR No : 480607

Date : 26/01/2018

Page No : 1

Entered by : p06asram
17:13:13

Customer Name : _____

Address : _____

Contact No : HP _____

S()

R _____

O _____

Regn No : _____

Model : _____

Chassis : _____

Regn Date : _____

St	R	C	CT	BO	Qty	Part Number	Description	Unit Price	Dis %	PDC SOH
						DZ20938	SCM8636J-CCS/1007			
k					1	12148623493	BASIC CONTROL UNIT DME (CO	2,702.20		
					1	34516876917	(S/L) RP HYDRAULIC UNIT DS	4,895.40		

Coded
D

Special Remarks : _____

Sub Total : 7,597.60
 Carriage/Handling :
 GST @ 7% : 531.83
 Total Amount : 8,129.43

Checked by : Sm

Confirmed by : _____

Approved by CSA : (CS) 1007 Ack. CSM : _____

Deposit Amount : _____
 Balance Amount : _____

POR No : _____

Date _____ Time _____

Date : _____

: _____ Receipt # : _____ Res. Bin : _____

Order Date : _____ Arrival Date : _____ Taken By : _____

A Date : _____ S/D : _____ Date : _____

RO No & Date : _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CS/ICS18001106/R1qd3e2		
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 14-05-2018		
		Code : ICS		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SCM 8636J	
Policy No.	MPC17A00235000	Coverage (\$)	0.00	
Claim No.	DMPC1800005H	Excess (\$)	0.00	
Assign From	PHOEBE JAY	Assign Date	18/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 730LI	c.c	2996	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WBAYE22090DZ20938	Colour	GREY	
Odometer	30768	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	245/50 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	245/50 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	245/50 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FLOOD PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/01/2018	Inspection Date	18/01/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE MARKET VALUE IS S\$140,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCM 8636J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	(S/L) PULSE GENERATOR DSC REAR (SN)	NOT WORKING	203.60	203.60
1	DSC PULSE GENERATOR FRT (SN)	NOT WORKING	203.60	203.60
1	ICM CONTROL UNIT (SN)	NOT WORKING	2,700.40	2,700.40
1	SWITCH PARKING BRAKE/AUTO HOLD (SN)	NOT WORKING	185.45	180.95
1	HOUSING COVER WITH COARSE FILTER (SN)	NOT WORKING	61.25	61.25
1	BASIC CONTROL UNIT DME (CODED) (ADDITIONAL) (SN)	NOT WORKING	2,702.20	2,702.20
5	SEALING GROMMET (ADDITIONAL) (SN)	NECESSARY	3.25	3.25
5	SEALING GROMMET (ADDITIONAL) (SN)	NECESSARY	4.25	4.25
1	(S/L) RP HYDRAULIC UNIT DSC (ADDITIONAL) (SN)	NOT WORKING	5,017.80	5,017.80
1	COVERING CAP (D=10MM) (ADDITIONAL) (SN)	NECESSARY	2.75	2.75
3	RIVET (ADDITIONAL) (SN)	NECESSARY	1.35	1.35
1	COVER STEERING COLUMN (ADDITIONAL) (SN)	NECESSARY	50.90	50.90
1	UNIVERSAL SOCKER HOUSING UNCODED (ADDITIONAL) (SN)	NECESSARY	18.85	18.85
1	COVERING CAP 38 POL (ADDITIONAL) (SN)	NECESSARY	13.80	13.80
5	JACK MCP 2.8 0.2-0.35MM (ADDITIONAL) (SN)	NECESSARY	13.75	13.75
5	JACK MCP 2.8 1.5-1.00MM (ADDITIONAL) (SN)	NECESSARY	13.75	13.75
5	FLAT CONTACT MCP 1.5-2.5MM (ADDITIONAL) (SN)	NECESSARY	3.00	3.00
5	JACK MCP 2.8 4.1-6.0MM (ADDITIONAL) (SN)	NECESSARY	19.25	19.25
5	SEALING GROMMET (ADDITIONAL) (SN)	NECESSARY	12.75	12.75
1	SOCKER HOUSING (ADDITIONAL) (SN)	NECESSARY	21.55	21.55
1	AUXILLARY HEATER ELECTRIC LH (ADDITIONAL) (SN)	NOT WORKING	411.90	411.90
			11,815.40	11,810.90
LABOUR				
TO REPLACE ICM CONTROL UNIT, FRONT AND REAR SPEED SENSOR, PARKING BRAKE SWITCH, AIR CON BLOWER INCLUDING ATTACHMENTS ETC.			5,950.00	5,100.00
TO REMOVE AND INSTALL FRONT AND REAR CARPETS FOR DRYING INCLUDING TO CHECK BOTH FRONT SEATS ELECTRICAL ADJUSTMENT DRIVE UNIT FOR PROPER FUNCTION.			1,062.00	903.00
TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT AND REAR SECTIONS FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS.			295.00	250.00
TO TOW ACCIDENT VEHICLE TO PML WORKSHOP.			195.00	195.00

Report Ref No. CS/ICS18001106/R1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL AIRCON BLOWER HOUSING ASSEMBLY TO FACILITATE REPAIRS. (ADDITIONAL)		451.00	451.00
	TO DIAGNOSE AND REPLACE BASIC CONTROL UNIT DME (CODED), RP HYDRAULIC UNIT DSC INCLUDE CONDUCTING CHECKS FOR PROPER FUNCTION. (ADDITIONAL)		850.00	850.00
			8,803.00	7,749.00
GRAND TOTAL			20,618.40	19,559.90
RECOMMENDED COST OF REPAIRS				19,559.90

Report Ref No. CS/ICS18001106/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.