

## REPAIR ESTIMATE\*

**DATE 17/1/2018 14:52**

Chicago

**MODEL : HYUNDAI i40**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Sponge ✗			\$ 142.20
	Front Bumper Reinforcement ✗			\$ 526.10
	Front Bumper Grille (LH) ✗			\$ 40.30
	Front Bumper Bracket Top (LH) ✗			\$ 22.40
	Front Bumper Retainer Mounting ✗✓			\$ 9.20
	Headlamp Support Panel Assy ✗			\$ 1,067.50
	Headlamp (LH) ✓			\$ 1,388.00
	<i>Front Fender (LH) repair</i>			
	<b>SUB TOTAL</b>			<b>\$ 3,758.00</b>
	LESS 20%			\$ 751.60
	<b>DISCOUNTED TOTAL</b>			<b>\$ 3,006.40</b>
	Frt Fender Advertisement Logo (LH) ✓			\$ 100.00
				<b>\$ 100.00</b>
	<b>Labour Charge</b>			<b>200</b>
	Panel Beating			\$ <del>350.00</del>
	Spray Painting Charge			\$ <del>400.00</del>
	Wiring Charge			\$ <del>50.00</del>
	Tuff Kote			\$ <del>50.00</del>
	Remove/Refix Aircon & Refill Gas			\$ <del>150.00</del>
	<b>TOTAL LABOUR</b>			<b>\$ 1,000.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 4,106.40</b>
	Kalin LICKY V 17/1/18 15:10 hrs. 2 Days 45 <i>After Repair photo</i>			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  Acknowledged by Repairer Signature: Date:			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.