

2/10/2018

ASS. REC. BY

REF:

CS/C7I18001111/Grd3n2

Special Instructions

9Q

ASSIGNMENT (Office)

Menimen

FROM (Person)

Irene Tay

of

CTI

Date/Time

18/01/2018 @ 11:13am

Estimated Cost

Bill to

OD/FF/WS/TP RES / OD RES / EVA / DV / MV / CS

To Inspect Vehicle No.

SJD 4237 T

Insured

SJH 7497 T

at Workshop no.

Ethicar2

Tel

6384 4404

of

56 Loyang Way #04-04

Policy No.

DMPCSN 3095731700

Claim No.

SNM18D00264 C02

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

14/01/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement

Date/Time

11:22am @ 18/01/18

Person Contacted

john

Vehicle

OUT

Date/Time

Action/Inspection

✓

Signature

SJD 4237 T-X

SJH 7497 T-X

REF: CTI

ASSIGNMENT

(-2018)

From: Date: 18/01/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJD 4237 T

at Workshop/mis: Ethicarz

of: 56 Loyang Way #04-04

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh.:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SJD4237T

Yr Regn:

20 Mar 2008

Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda stream

cc:

1799

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp Reading:

257543

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JH MRN 684 085202338

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

205/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18-01-18

Survey held at

w/s

4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

near w/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/1 17:00 hrs \$ 2000 with kelvin.

Ref: 89423.76, 821.

RECEIVED 2 JAN 2018

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐ Site Insp
☐ Interview
☐ Tech. Insp
☐ Weekend

\$

\$

\$

\$

\$

Phone

Other

\$

Report Format:

Lump Sum / I.B.I./S

2000

TOTAL:

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2018		18 Jan 2018 11:13 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	OMARAIN OFFSHORE PTE. LTD., Co. Reg. No.: 201526271E		
Main Claimant:	SKYLINE AUTO CREDIT, Co. Reg. No.: 53342372D		
Vehicle Reg. No.:	SJD4237T	Date of Loss:	14/01/2018 12:00 - :59
Claim Type:	TP / SNM18D00264C02	Policy/Cover Note No.:	DMPCSN3095731700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJH7497T	Policy No. (Claimant):	5082690314-01 TP
		Excess:	S\$0.00
Repairer:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/01/2018]		
Driver/Custodian (Insured):	SHEFFY KALAPURACKAL MAIDEEN (39 / Male), NRIC: S7B61050F, Tel: +6591467453		
Adj Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18001111/Grd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 18-01-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 7497T	Veh. Inspected	SJD 4237T
Policy No.	DMPCSN3095731700	Coverage (\$)	0.00
Claim No.	SNM18D00264C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	18/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/01/2018	Inspection Date	18/01/2018
Survey held at	ETHICARZ PTE LTD 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2018 14:31
Date Of Accident	14/01/2018 12:50
Exact Location Of Accident	BUKIT BATOK WEST AVE 5 TO BUKIT BATOK WEST AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJD4237T
Insured/Policyholder	
Name Of Registered Owner	SKYLINE AUTO CREDIT
Co Reg No	53342372D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97285587

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM 1.8L A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5082690314-01 TP
Cover Note Number	

Driver

Name of Driver	MD IMRUZZAMAN
NRIC No	S7181822E
Date Of Birth	27/09/1971
Occupation	OUTDOOR
Date Of Driving Pass	04/08/2001
Driving Experience	16 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96883630
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 272B JURONG WEST ST 24 #16-90
Postcode	642272
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH7497T
Vehicle Make/Model/Colour	TOYOTA HARRIER 2.0 PREMIUM AT AIRBAG 2WD 5DR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: **15 JAN 2018**

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492306
Email: vackbi@sinonet.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


Sketch Plan #2 Pg. 1

SKETCH PLAN

Bukit Batok West Ave 5 > Bukit Batok West Ave 2

Veh A - SJD4237T

Veh B - SJH7497T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the Stated date and time, I vehicle A was stationary on stated lane.
 Suddenly I felt an impact from the back and realise vehicle B hit onto
 my Rear portion.

DECLARATION OF

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

15 JAN 2018

IDAC KAKI BUKIT (VAG)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@sinonef.com.sg

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 2372D

Vehicle Details

Vehicle No.: SJD4237T

Vehicle to be Exported: Yes

Intended De-registration Date: 16 Jan 2018

Vehicle Make: HONDA

Vehicle Model: STREAM 1.8L A

Primary Colour: Silver

Manufacturing Year: 2007

Engine No.: R18A12802337

Chassis No.: JHMRN684085202338

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$20,486.00

Original Registration Date: 20 Mar 2008

First Registration Date: 20 Mar 2008

Transfer Count: 2

Actual ARF Paid: \$22,535.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Mar 2018

PARF Rebate Amount: \$11,267.00

Intended COE Rebate Details

COE Expiry Date: 19 Mar 2018

COE Category: B - Car (1601cc & above)

Tel: 63844404, FAX: 63840444

VEHICLE NUM:

MAKE & MODEL:

MILEAGE:

TYRE:

CHASSIS NUM:

SJD4237T

HONDA STREAM

RN6



QTY	DESCRIPTION - PARTS	PRICE
1	BOOTLID X repair	\$ 963.00
1	BOOTLID LOCK X	\$ 286.00
1	BOOTLID WEATHERSTRIP X	\$ 191.20
1	BOOTLID INNER TRIM X	\$ 232.00
10	BOOTLID INNER TRIM CLIPS X	\$ 50.00
1	BOOTLID INNER HANDLE X	\$ 48.00
1	BOOTLID W/S GLASS MOULDING X	\$ 128.00
1	BOOTLID LOGO / NBC	\$ 54.00
1	BOOTLID EMBLEM - STREAM / NBC	\$ 68.00
1	BOOTLID OUTER HANDLE X	\$ 225.00
1	BOOTLID CENTER MOULDING X	\$ 298.00
6	BOOTLID CENTER MOULDING CLIPS X	\$ 30.00
2	REAR NUMBER PLATE LAMP L+R X	\$ 290.00
1	REAR BUMPER / de	\$ 832.00
10	REAR BUMPER CLIPS / NBC	\$ 50.00
2	REAR BUMPER SIDE RETAINER L+R / NBC	\$ 112.00
1	REAR BUMPER TOWING CAP X	\$ 65.00
2	REAR BUMPER BRACKET L+R X	\$ 86.00
1	REAR END PANEL X	\$ 486.00
1	REAR END PANEL TOP GARNISH X	\$ 156.00
10	REAR END PANEL TOP GARNISH CLIPS X	\$ 50.00
1	REAR FLOOR PANEL X	REPAIR
1	TAILLAMP LH / CBS	\$ 426.00
1	TAILLAMP PANEL LH X	\$ 140.00
1	TAILLAMP CLIPS LH X	\$ 20.00
1	REAR FENDER LH X repair.	\$ 978.00
1	REAR FENDER INNER TRIM LH X	\$ 397.00
10	REAR FENDER INNER TRIM CLIPS LH X	\$ 50.00
1	REAR FENDER COWLING LH X	\$ 110.00
10	REAR FENDER COWLING CLIPS LH X	\$ 10.00
1	REAR FENDER QUARTER PANEL GLASS MOULDING X	\$ 138.00
1	EXHAUST PIPE X	\$ 985.00
1	EXHAUST PIPE HEAT SHIELD X	\$ 132.00
1	EXHAUST PIPE MOUNTING X	\$ 64.00
1	EXHAUST PIPE GASKET X	\$ 42.00
	SUBTOTAL	\$ 8,192.20
	LESS 20%	\$ 1,638.44

		PARTS TOTAL	\$ 6,553.76
QTY	SPECIAL NETT		PRICE
	REVERSE SENSOR ✓ DM	\$ 200	250.00 ✓
	WINDSCREEN SEALANT X	\$	80.00
	QUARTER GLASS SEALANT X } NN	\$	80.00
	REAR END PANEL SEALANT X	\$	80.00
		SPECIAL NETT TOTAL	\$ 490.00
QTY	LABOUR		PRICE
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	\$	1,800.00 600
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	\$	1,600.00 600
	TO RUST PROOF ACCIDENT AFFECTED AREA	\$	80.00 X
	TO RNR REAR BOOT MECHANISM	\$	150.00 X
	TO RNR REAR LUGGAGE COMPARTMENT	\$	150.00 X
	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	\$	150.00 80
	TO RNR REVERSE SENSOR & CHECK FUNCTION.	\$	100.00 40
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$	100.00 X NN
	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	\$	100.00 30
	TO DO WATER LEAK TEST .	\$	150.00 X NN
			1350
		LABOUR TOTAL	\$ 4,380.00
		REPAIR COST	\$ 11,423.76
		LESS 20%	\$ 2,284.75
		GRAND TOTAL	\$ 9,139.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

~~2503.76~~ 2503.76
20% = 2000

5 Days.

Lump sum repair

After repair photos.

Guo Qiang - 8288 0282

18/11/18

PAGE 2 OF 2

[Signature]
23/1/2018

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118001111/GRD3N2

Date: 24/01/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3095731700
Claimant Vehicle No :	SJD4237T	Insured Vehicle No :	SJH7497T
Date of Loss:	14/01/2018	Nature of Claim:	TP
		Claim No:	SNM18D00264C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD4237T	Engine No:	R18A12802337
Make & Model:	HONDA STREAM, 1.8 L (A)	Chassis No:	JHMRN68408S202338
Reg. Date:	20/03/2008 (Man. Year: 2007)	Odometer:	257543 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,043.76	1,153.36	5,890.40	83.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	1,350.00	3,030.00	69.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,423.76	2,503.36	8,920.40	78.09
Approved Total (Overridden) (\$\$)		2,000.00		
Nett Amount (\$\$)	11,423.76	2,000.00	9,423.76	82.49

INSPECTION

Date of Assignment:	18/01/2018	
Date Inspected:	18/01/2018 Inspected At:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING Singapore 508775
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2018)
Parts:	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD4237T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	963.00 FL	*- FL
2	1		*BOOTLID LOCK	Not Necessary	286.00 FL	*- FL
3	1		*BOOTLID WEATHERSTRIP	Not Necessary	191.20 FL	*- FL
4	1		*BOOTLID INNER TRIM	Not Necessary	232.00 FL	*- FL
5	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FL	*- FL
6	1		*BOOTLID INNER HANDLE	Not Necessary	48.00 FL	*- FL
7	1		*BOOTLID W/S GLASS MOULDING	Not Necessary	128.00 FL	*- FL
8	1		*BOOTLID LOGO	Necessary	54.00 FL	*35.50 FL
9	1		*BOOTLID EMBLEM-STREAM	Necessary	68.00 FL	*31.60 FL
10	1		*BOOTLID OUTER HANDLE	Not Necessary	225.00 FL	*- FL
11	1		*BOOTLID CENTER MOULDING	Not Necessary	298.00 FL	*- FL
12	6		*BOOTLID CENTER MOULDING CLIPS	Not Necessary	30.00 FL	*- FL
13	2		*REAR NUMBER PLATE LAMP L+R	Not Necessary	290.00 FL	*- FL
14	1		*REAR BUMPER	Deformed	832.00 FL	*665.40 FL
15	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
16	2		*REAR BUMPER SIDE RETAINER L+R	Necessary	112.00 FL	*70.40 FL
17	1		*REAR BUMPER TOWING CAP	Not Necessary	65.00 FL	*- FL
18	2		*REAR BUMPER BRACKET L+R	Not Necessary	86.00 FL	*- FL
19	1		*REAR END PANEL	Not Necessary	486.00 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Not Necessary	156.00 FL	*- FL
21	10		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FL	*- FL
22	1		*REAR FLOOR PANEL (NPA)	Not Necessary	0.00 FL	*- FL
23	1		*TAILLAMP LH	Cracked	426.00 FL	*338.80 FL
24	1		*TAILLAMP PANEL LH	Not Necessary	140.00 FL	*- FL
25	1		*TAILLAMP CLIPS LH	Not Necessary	20.00 FL	*- FL
26	1		*REAR FENDER LH	Repair	978.00 FL	*- FL
27	1		*REAR FENDER INNER TRIM LH	Not Necessary	397.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	10		*REAR FENDER INNER TRIM CLIPS LH	Not Necessary	50.00 FL	*- FL
29	1		*REAR FENDER COWLING LH	Not Necessary	110.00 FL	*- FL
30	10		*REAR FENDER COWLING CLIPS LH	Not Necessary	10.00 FL	*- FL
31	1		*REAR FENDER QUARTER PANEL GLASS MOULDING	Not Necessary	138.00 FL	*- FL
32	1		*EXHAUST PIPE	Not Necessary	985.00 FL	*- FL
33	1		*EXHAUST PIPE HEAT SHIELD	Not Necessary	132.00 FL	*- FL
34	1		*EXHAUST PIPE MOUNTING	Not Necessary	64.00 FL	*- FL
35	1		*EXHAUST PIPE GASKET	Not Necessary	42.00 FL	*- FL
36	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
37	1		*WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,682.20	1,391.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,638.44	238.34
Total Parts (\$\$)	7,043.76	1,153.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD,KNOCK & REALIGN	New	1,800.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,600.00	600.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	80.00	-
4	TO RNR REAR BOOT MECHANISM	New	150.00	-
5	TO RNR REAR LUGGAGE COMPARTMENT	New	150.00	-
6	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	New	150.00	80.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	100.00	40.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	100.00	-
9	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	New	100.00	30.00
10	TO DO WATER LEAK TEST	New	150.00	-
Gross Labour Cost (S\$)			4,380.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >