

## REPAIR ESTIMATE\*

Ty

AZ4

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover X repair			\$ 562.30
	Front Wheel Hub Cap (RH) ✓			\$ 150.70
	Front Fender (RH) x 14 = 18			
	SUB TOTAL			\$ 713.00
	LESS 20%			\$ 142.60
	DISCOUNTED TOTAL			\$ 570.40
	Labour Charge			200
	Panel Beating			\$ <del>350.00</del>
	Spray Painting Charge			\$ <del>400.00</del>
	Wiring Charge			\$ <del>50.00</del>
	TOTAL LABOUR			\$ 800.00
	ESTIMATE TOTAL			\$ 1,370.40
	Ko Lin LKK 16/1/18 1100 hrs. 2 days P/P After Repair p/LH			
	LKK Auto Consultants hence notify the Reparer of the following: • To resurvey before enter spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a Without Prejudice basis • No illegal modifications allowed • Supplementary item(s) must be reviewed and is subject to final approval from Insurance Company  Acknowledged by Reparer Signature: Date:			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.