

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2984L

DATE 16/1/2018 14:55

MAKE :

MODEL : HYUNDAI SONATA

Handwritten notes:
 400/kalvin
 4/5/18
 ALG
 LK

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 282.10
	Radiator Grille U Moulding X			\$ 108.90
	Front Bumper Cover X Repair			\$ 538.80
	Front Bumper Bracket Top (LH/RH) ?		\$ 22.40	\$ 44.80
	Front Bumper Protector (LH/RH) X Repair		\$ 29.20	\$ 58.40
	Front Bumper Side Bracket ?		\$ 14.30	\$ 28.60
	SUB TOTAL			\$ 1,061.60
	LESS 20%			\$ 212.32
	DISCOUNTED TOTAL			\$ 849.28
	Front Number Plate			\$ 25.00
	Front No Plate Trim Cover			\$ 30.00
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 350.00 200
	Spray Painting Charge			\$ 200.00 180
	TOTAL LABOUR			\$ 550.00
	ESTIMATE TOTAL			\$ 1,454.28

Handwritten notes:
 Kalvi (CCKK)
 16/1/18 1520hrs
 2 Days
 4/5
 After Repair - photo

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.