

REF: CS/CTI18001120/Gvd3n2

## ASSIGNMENT (ORIG)

Merimen

Joel Goh

CTI

17/01/2018 @ 4:49pm

Estimated Cost:

① / TP / WS / TP RES / OD RES / EVA / EVV / MV / CS

to Inspect Vehicle No:

GBF1158S

to Working for:

Mcwell Ventures

9106 0030

at 51 ubi Ave 1 #01-05

Policy No: DMCVSN1642021701

Claim No: SNM18D00296C01/8

Sum Insured:

\$500.00

Make of Veh:

D.O.A. 15/01/2018

(Client's Record)

CA (REV) REP. / REV 24 HRS

Date/Time: 9:05am @ 18/1/18

Person Contacted:

Alan

Vehicle: OUT

Date/Time Action/Instruction (✓) EC#/M/T

GBF1158S - NA/CTI18000941/24

D.O.A: 15/01/2018

23/1/18 Revert by merimen, LS est \$9100

25/1/18 Recd approved from Susan by merimen

25/1/18 Informed Alan c/A on LS ex \$500 by email

21/3/18 @1044am Confirmed RS 11,800 with Alan (Red 4728-15, 29/1)

REF: CTI

8935K

## ASSIGNMENT

From: Date: 18/01/2018

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBF11585

at Workshop no: Mcwell Ventures

of 51 ubi Ave 1 #01-05

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$500.00

(Client's Record)

Make of Veh: 4389 300L - Alan

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bel. or Market Value: \$68k.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBF11585 Yr Regn: 30 Jun 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350 cc 2488

Colour: white A/O: Insured / Std / NI / NA

Sp. Reading: 81191 T/Radio: Insured / Std / NI / NA

Eng No:

C No: JN1MC2E 268 000 6689

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ N / S/Rim / STD A/Rim or

Tyre Size: F: 195R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A.

Survey held at

Des. of Damages: ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/3/18 check with Bryan use repairer parts prices

RECEIVED 22 MAR 2018

Date/Time File Pass to?

☐ : Prel. Report☐ : Final Report

1.

Date/Time File Return to?

2. 22/3-tyrist

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

3-PS-3

Fees:

Chen:

Report Format: merimen

Lump Sum / I.B. RS \$11,800

Add Fee:

☐ Site Insp: \$☐ Interview: \$☐ Tech. Insp: \$☐ Workshop: \$

220

# Survey Department Check List (Case Handler)

Reference No.: CS/CTI 18001120/Grd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all information created by the assignment team are ACCURATE.

## (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

## (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 22/8/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/201




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18001120/Gvd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 18-01-2018	
		Code : CTI	
<b>1. Policy Particulars :- OWN DAMAGE</b>			
Insured Veh.		Veh. Inspected	GBF 1158S
Policy No.	DMCVSN1642021701	Coverage (\$)	0.00
Claim No.	SNM18D00296C01/8	Excess (\$)	500.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	18/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	15/01/2018	Inspection Date	
Survey held at	MCWELL VENTURES PTE LTD 51 UBI AVE 1 #01-05/06 PAYA UBI IND. PARK SINGAPORE 408933		
<b>5a. Remarks</b>			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2018		17 Jan 2018 16:49 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	M/S CYCLEWHERE PTE LTD, Co. Reg. No.: 201418935K		
Vehicle Reg. No.:	GBF1158S	Date of Loss:	15/01/2018 17:00 - :59
Claim Type:	OD / SNM18D00296C01/8	Policy/Cover Note No.:	DMCVSN1642021701 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Mcwell Ventures Pte Ltd (HQ) 51 Ubi Ave 1, #01-05 Paya Ubi Industrial Park, 408933 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/01/2018]		
Driver/Custodian:	GOH KAH TECK (50 / Male), NRIC: S1804251G, Tel: +6590300300		
Adj Asg. Remarks:	NO ESTIMATES PROVIDED BY WORKSHOP. PLEASE ASSIST TO OBTAIN THE ESTIMATES FROM WORKSHOP		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Received Message

This mail is associated with :

**\*GBF1158S (SNM18D00296C01/8)**

OD

Jan 15 2018 5:00PM

[M/S CYCLEWHERE PTE LTD]

Mcwell Ventures Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 06/03/2018 14:44 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$12878.18) - GBF1158S - Claim Handler: Joel Goh

Approved:12878.18.

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Joel Goh	Date: 02 Mar 2018
<b><u>Preliminary Advice</u></b>	

Vehicle No	: GBF1158S	Accident Date	: 15/01/2018
Make	: NISSAN NV350	Policy No.	: DMCVSN1642021701
Assignment Date	: 17/01/2018	Excess	: S\$500.00
Date of Inspection	: 22/01/2018	Est. Duration of Repair	: 7.00
Inspection At	: MCWELL VENTURES PTE LTD (HQ) 51 UBI AVE 1, #01-05 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,528.15	(incl.supplementary \$2845.33)
Revised Amount	:S\$	12,878.18	(incl.supplementary \$2845.33)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	12,878.18	

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	39,172.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,828.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Vehicle repair on parts by parts basis due to non availability of spare parts. Our surveyor has verify parts have been replaced.



**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 25 January 2018 12:57 PM  
**To:** 'alanchua@mcwellventures.com'  
**Cc:** SUR  
**Subject:** RE: GBF 1158S-DOA: 15/1/2018

Dear Alan,

As instructed by our client **CTI**, please proceed to repair the insured vehicle **GBF 1158S on Lump Sum Basis (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 25 January 2018 10:20 AM  
**To:** 'alanchua@mcwellventures.com' <alanchua@mcwellventures.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** GBF 1158S-DOA: 15/1/2018

Dear Alan,

As requested.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## View Received Message

This mail is associated with :

**\*GBF1158S (SNM18D00296C01/8)**

OD

Jan 15 2018 5:00PM

[M/S CYCLEWHERE PTE LTD]

Mcwell Ventures Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on **25/01/2018 12:42 PM**.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (\$\$9100.00) - GBF1158S - Claim Handler: Joel Goh

Approved:9100.00.

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Joel Goh	Date:	23 Jan 2018
<b><u>Preliminary Advice</u></b>			

Vehicle No	: GBF1158S	Accident Date	: 15/01/2018
Make	: NISSAN NV350	Policy No.	: DMCVSN1642021701
Assignment Date	: 17/01/2018	Excess	: S\$500.00
Date of Inspection	: 22/01/2018	Est. Duration of Repair	: 7.00
Inspection At	MCWELL VENTURES PTE LTD (HQ) 51 UBI AVE 1, #01-05 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,682.82
Revised Amount	:S\$	5,300.71
Check Items (Estimated)	:S\$	6,050.39
Total	:S\$	11,351.10
Lump Sum Repair (Estimated)	:S\$	9,100.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	39,172.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,828.00

**Remarks**

Brake System : In Order  
 Steering System : In Order  
 Tyre Condition (Front) : 6/6 mm  
 Tyre Condition (Rear) : 6/6 mm

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8935K
Vehicle Details	
Vehicle No.:	GBF1158S
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jan 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5AT 5DR EURO V
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	YD25398853A
Chassis No.:	JN1MC2E26Z0006689
Maximum Power Output:	-
Open Market Value:	\$23,990.00
Original Registration Date:	30 Jun 2016
First Registration Date:	30 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$1,200.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,434.00
COE Rebate Amount:	\$39,172.00
<b>Total Rebate Amount:</b>	<b>\$39,172.00</b>

The information contained herein is correct as at 22 Jan 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/01/2018 15:00
Date Of Accident	15/01/2018 17:45
Exact Location Of Accident	ALONG W COAST HIGHWAY TWDS HARBOURFRONT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF1158S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	M/S CYCLEWHERE PTE LTD
Co Reg No	201418935K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-899999999

### Vehicle Particulars

Manufacturer	NISSAN
Model	NV350 PANEL VAN 2.5 5AT 5DR EURO V
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1642021701
Cover Note Number	

### Driver

Name of Driver	GOH KAH TECK
NRIC No	S1804251G
Date Of Birth	04/02/1967
Occupation	OUTDOOR
Date Of Driving Pass	09/11/2015
Driving Experience	2 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90300300
Fax Number	
Contact Number	OFFICE-90300300
Email Address	NOEMAIL

Address BLK 13 BEDOK SOUTH ROAD  
#12-621  
Postcode 460013  
Was driver an employee of the Insured's Company YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLB7683E  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver) 1

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SCZ2227C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


#### E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15/12 17:45 I was travelling along W coast Highway towards Harbourfront. Suddenly vehicle C step on the break of his vehicle. In a result, vehicle B couldn't break in time and hit onto vehicle C rear portion. In a same way, I couldn't break my vehicle and hit onto vehicle B rear portion.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Photo



## Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
6 Raffles Quay #18-00 Singapore 048580  
Tel (65) 6224 0030 Fax (65) 6224 0030  
Operating Hours: Monday to Friday, 09:00 - 17:00  
UEN: S65500206 / GST Reg. No.: M400017735

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

#### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MHA118008040 Vehicle Registration No: ADF11865  
Name (as shown in NRIC): Goh Kah Teck NRIC/FIN/Passport No: S18042316  
(\*Vehicle Driver / Vehicle Owner(\*) Please delete as appropriate)  
Address: Blk 13 Bedok South Road #12-621 Singapore (460131)  
Contact (Tel): \_\_\_\_\_ Mobile No.: 90300300  
Email Address: \_\_\_\_\_  
Date of Accident: 15/1/18 Time of Accident: 17:45  
Place of Accident: Along w Coast Highway twds Harbourfront  
Insurance Company: CTI

#### (B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend to OD.

Policyholder/Driver's Signature  
Date:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
Date:



## MCWELL VENTURES PTE LTD

51 Ubi Ave 1 #01-05

Paya Ubi Industrial Park

Singapore 408933

(65) 6844 4640 / 9838 7743

(65) 6844 4641

international@mcwellventures.com

www.mcwellventures.com

Co. / GST Reg. No.: 200103711R

To: LKK

51 ubi ave 1 paya ubi industrial park #01-25 S(408933)

DATE: 22/01/2018

Vehicle No. : GBF1158S  
 Make/Model : Nissan NV350  
 Chassis No. : JN1MC2E26Z0006689  
 Policy No. :  
 D.O.A. :

ESTIMATE COST OF REPAIRS TO VEHICLE GBF1158S.

No.	QTY	ITEMS	AMOUNTS (\$S)
-----	-----	-------	---------------

PARTS LIST

1	1 pc	Frt panel	\$ 1,160.90
2	2 pcs	Frt corner panel R/L	\$ 1,010.40
3	1 pc	Frt grille assy	\$ 438.70
4	1 pc	Frt bumper	\$ 892.70
5	2 pcs	Frt bumper bracket R/L	\$ 331.20
6	1 pc	Frt bumper reinforcement	\$ 667.10
			\$ 4,501.00
Less 30%			\$ 1,350.30
List Parts Sub-Total :			\$ 3,150.70

PARTS NETT

1	1 pc	Frt windscreen	\$ 995.60
2	1 pc	Frt windscreen moulding	\$ 53.20
3	1 pc	Frt wiper garnish	\$ 420.40
4	2 pcs	Headlamp R/L	\$ 649.00
5	1 pc	Frt grille emblem (Logo)	\$ 21.60
6	1 pc	Frt bumper tow cover	\$ 31.20
7	2 pcs	Frt bumper fog lamp R/L	\$ 515.00
8	2 pcs	Frt bumper fog lamp grille R/L	\$ 183.80
			\$ 2,919.80
Less 10%			\$ 291.98
Nett Parts Sub-Total :			\$ 2,627.82

PARTS S/NETT

1	1 pc	Frt no. plate	\$ 50.00
2	1 pc	Air inlet duct (A/c)	\$ 300.00
3	1 pc	A/c suction pipe	\$ 268.20
4	1 pc	A/c discharge pipe	\$ 237.40
5	1 pc	A/c liquid pipe	\$ 242.80
6	1 pc	A/c receiver drier	\$ 151.10
7	1 pc	A/c cooling coil assy	\$ 2,181.50

Sp: 103.00

8	1 pc	A/c blower assy	R / OK
9	1 pc	Frt windscreen sealant	-
10	1 pc	Frt windscreen inner seal	-
11	1 pc	Frt windscreen L.U. bracket	-
12	1 pc	Frt panel sealant	X
13	1 pc	Frt panel sticker (Co. logo)	X

\$	813.60	588.5
\$	50.00	/
\$	50.00	20
\$	30.00	/
\$	50.00	X
\$	150.00	X
Special Net Sub-Total :	\$ 4,574.30	3067.9
\$	10,352.82	

Labour Charge

To check electrical system, repair wire harness and focus headlamp.

\$ 80.00 30

To remove, replace and reinstall front windscreen.

\$ 150.00 100

To remove and reinstall dashboard for necessary repairs.

\$ 400.00 200

To remove, replace and reinstall a/c blower and a/c cooling coil assy.  
(Include vacuum & recharge a/c gas)

\$ 150.00 R /

To straighten, repair, realign on affected area and replace damaged parts.

\$ 1,200.00 600 / 1000

To conduct chassis alignments.

\$ 350.00 X NN

To spray painting on affected area.

\$ 1,000.00 500 800

Total \$ 3,330.00

2280

Total : 10861.04  
- 15% = 9200

Total \$ 13,682.82

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7 Days. L/S  
~~Transport Repair P/P.~~  
After repair photos.

Guo Qiang - 82880282

Guo Qiang @ lkkauto.com

Excess \$500

Not Authorised

22/1/18.

HH Catherine Chong



## MCWELL VENTURES PTE LTD

51 Ubi Ave 1 #01-05  
 Paya Ubi Industrial Park  
 Singapore 408933  
 (65) 6844 4040 / 9838 7743  
 (65) 6844 4841  
 international@mcwellventures.com  
 www.mcwellventures.com  
 Co. / GST Reg. No.: 200103711R

To: LKK

DATE: 22/01/2018

51 ubi ave 1 paya ubi industrial park #01-25 S(408933)

Vehicle No. : GBF1158S  
 Make/Model : Nissan NV350  
 Chassis No. : JN1MC2E2620006689  
 Policy No. :  
 D.O.A. :

## ESTIMATE COST OF REPAIRS TO VEHICLE GBF1158S.

No.	QTY	ITEMS	AMOUNTS (\$S)
<b>PARTS LIST</b>			
1	1 pc	Frt panel <i>one</i>	\$ 1,160.90
2	2 pcs	Frt corner panel R/L <i>CH - one</i>	\$ 505.20
3	1 pc	Frt grille assy <i>CH</i>	\$ 438.70
4	1 pc	Frt bumper <i>cut</i>	\$ 892.70
5	2 pcs	Frt bumper bracket R/L <i>Best</i>	\$ 331.20
6	1 pc	Frt bumper reinforcement <i>Best</i>	\$ 667.10
			\$ 4,501.00
			Less 30% \$ 1,350.30
List Parts Sub-Total :			\$ 3,150.70

## PARTS NETT

1	1 pc	Frt windscreen <i>CH</i>	\$ 995.60
2	1 pc	Frt windscreen moulding <i>del. - Best</i>	\$ 53.20
3	1 pc	Frt wiper garnish <i>CH</i>	\$ 420.40
4	2 pcs	Headlamp R/L <i>CH</i>	\$ 324.50
5	1 pc	Frt grille emblem (Logo) <i>mis</i>	\$ 71.60
6	1 pc	Frt bumper tow cover <i>X</i>	\$ 31.20
7	2 pcs	Frt bumper fog lamp R/L <i>CH</i>	\$ 257.50
8	2 pcs	Frt bumper fog lamp grille R/L <i>CH</i>	\$ 183.80
			\$ 2,919.80
			Less 10% \$ 291.98
Nett Parts Sub-Total :			\$ 2,627.82

## PARTS S/NETT

1	1 pc	Frt no. plate <i>cut</i>	\$ 50.00
2	1 pc	Air inlet duct (A/c) <i>could</i>	\$ 300.00
3	1 pc	A/c suction pipe <i>Best</i>	\$ 268.20
4	1 pc	A/c discharge pipe <i>Best</i>	\$ 237.40
5	1 pc	A/c liquid pipe <i>Best</i>	\$ 242.50
6	1 pc	A/c receiver drier <i>he in</i>	\$ 151.10
7	1 pc	A/c cooling coil assy <i>could</i>	\$ 2,181.50



8	1 pc	A/c blower assy ? cancelled ✓	\$	813.60
9	1 pc	Frt windscreen sealant - 4pc.	\$	50.00
10	1 pc	Frt windscreen inner seal - 4pc.	\$	50.00
11	1 pc	Frt windscreen I.U. bracket	\$	30.00
12	1 pc	Frt panel sealant	\$	50.00
13	1 pc	Frt panel sticker (Co. logo) X NH	\$	150.00
Special Net Sub-Total :			\$	4,574.30
			\$	10,352.82

Labour Charge

To check electrical system, repair wire harness and focus headlamp.	\$	80.00	30
To remove, replace and reinstall front windscreen.	\$	150.00	100
To remove and reinstall dashboard for necessary repairs.	\$	400.00	200
To remove, replace and reinstall a/c blower and a/c cooling coil assy. (Include vacuum & recharge a/c gas)	\$	150.00	2
To straighten, repair, realign on affected area and replace damaged parts.	\$	1,200.00	600 1000. sls
To conduct chassis alignments.	\$	350.00	X
To spray painting on affected area.	\$	1,000.00	500 800 sls.
Total	\$	3,330.00	

Total \$ 13,682.82 16,538.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7 Days.  
Lump Sum Repair.

After repair photos:

Guo Qiang - 82880282

Guo Qiang @ lkkauto.com

Express \$500

Not Authorised

22/1/18.

Resurveyed 26/01/18

Adrian King

sls



22/1

# MCWELL VENTURES PTE LTD

51 Ubi Ave. 1, #01-05,  
Paya Ubi Ind. Park,  
Singapore 408933  
T (65) 68444640 / 98387743  
F (65) 68444641  
E international@mcwellventures.com  
W www.mcwellventures.com  
Co. Reg No.: 200103711R

To.

DATE: 27/01/2018

Vehicle No. : GBF1158S  
Make/Model : Nissan NV350  
Chassis No. : JN1MC2E26Z0006689  
Policy No. :  
D.O.A. :

## SUPPLEMENTARY COST OF REPAIRS TO VEHICLE GBF1158S.

No.	QTY	ITEMS	AMOUNTS (\$S)
-----	-----	-------	---------------

### PARTS LIST

1	1 pc	Frt wiper motor X NN	\$ 234.80 X
2	1 pc	Frt wiper linkage assy - BT	\$ 302.10 227
3	1 pc	Brake booster pump X NN	\$ 1,208.30 X
			\$ 1,745.20
		Less 30%	\$ 523.56
		List Parts Sub-Total :	\$ 1,221.64 158.9

### PARTS NETT

1	1 pc	Frt wiper motor bracket / BR	\$ 59.10 /
2	1 pc	Brake booster pump hose joint X NN	\$ 44.00 X
3	2 pcs	Frt bumper bracket R/L X Repeat	\$ 104.70 \$ 209.40 X
4	2 pcs	Frt bumper retainer R/L - abc	\$ 147.00 \$ 294.00
5	1 pc	Dashboard lower center garnish trim - ORA	\$ 259.20 181
6	2 pcs	Frt lower panel R/L { Repeat } - blue	\$ 315.00 \$ 630.00 588
7	1 pc	Frt lower center panel	\$ 98.40 /
8	1 pc	Frt lower bar - BT	\$ 210.00 /
			\$ 1,804.10 1430.5
		Less 10%	\$ 180.41
		Nett Parts Sub-Total :	\$ 1,623.69 1287.45

Guo Qianf.  
8288 0282

Add GST

TOTAL

Total parts: \$ 2,845.33  
\$ 199.17

\$ 3,044.50



12

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CTI18001120/GVD3N2

Date: 23/03/2018

### REFERENCE

Insured/Claimant: M/S CYCLEWHERE PTE LTD  
Policy No: DMCVSN1642021701  
Date of Loss: 15/01/2018  
Nature of Claim: OD  
Claim No: SNM18D00296C01/8

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF1158S  
Make & Model: NISSAN NV350, 2.5 5AT 5DR EURO V (A)  
Reg. Date: 30/06/2016 (Man. Year: 2016)  
Colour: White  
Engine Capacity: 2488 cc  
Market Value/New Car Price: S\$68,000.00  
Sum Insured (S\$): Market Value/New Car Price  
Engine No: YD25398853A  
Chassis No: JN1MC2E26Z0006689  
Odometer: 81191 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No  
Footbrake (Serviceable): Yes  
Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 195 R15  
Front Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm  
Rear Tyre Size: 195 R15  
Rear Left Side: Yokohama 6 mm  
Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,198.15	10,598.18	2,599.97	19.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	2,280.00	1,050.00	31.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,528.15</b>	<b>12,878.18</b>	<b>3,649.97</b>	<b>22.08</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>11,800.00</b>		
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	16,028.15	11,300.00	4,728.15	29.50
<b>+ GST 7.00/7.00% (S\$)</b>	1,121.97	791.00	330.97	29.50
<b>Nett Amount (S\$)</b>	<b>17,150.12</b>	<b>12,091.00</b>	<b>5,059.12</b>	<b>29.50</b>

### INSPECTION

Date of Assignment: 17/01/2018  
Date Inspected: 22/01/2018 Inspected At:

Mcwell Ventures Pte Ltd (HQ)  
51 Ubi Ave 1, #01-05 Paya Ubi  
Industrial Park  
Singapore 408933

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Mar 2018)	
<b>Parts:</b>	N/A	NISSAN NV350 2.5 5AT 5DR EURO V (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF1158S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT PANEL	Buckled	1,160.90 FL	*1,160.90 FL
2	1		*FRT CORNER PANEL R/L	N/s Buckled/O/s Not Necessary	1,010.40 FL	*505.20 FL
3	1		*FRT GRILLE ASSY	Cracked	438.70 FL	*438.70 FL
4	1		*FRT BUMPER	Cut	892.70 FL	*892.70 FL
5	2		*FRT BUMPER BRACKET R/L	Bent	331.20 FL	*331.20 FL
6	1		*FRT BUMPER REINFORCEMENT	Bent	667.10 FL	*667.10 FL
7	1		*FRT WIPER MOTOR	Not Necessary	234.80 FL	*- FL
8	1		*FRT WIPER LINKAGE ASSY	Bent	302.10 FL	*302.10 FL
9	1		*BRAKE BOOSTER PUMP	Not Necessary	1,208.30 FL	*- FL
10	1		*FRT WINDSCREEN	Cracked	995.60 FN	*995.60 FN
11	1		*FRT WINDSCREEN MOULDING	Necessary	53.20 FN	*53.20 FN
12	1		*FRT WIPER GARNISH	Deformed	420.40 FN	*420.40 FN
13	2		*HEADLAMP R/L	Cracked	649.00 FN	*649.00 FN
14	1		*FRT GRILLE EMBLEM (LOGO)	Missing	71.60 FN	*71.60 FN
15	1		*FRT BUMPER LOW COVER	Not Necessary	31.20 FN	*- FN
16	2		*FRT BUMPER FOG LAMP R/L	Not Necessary	515.00 FN	*- FN
17	2		*FRT BUMPER FOG LAMP GRILLE R/L	Not Necessary	183.80 FN	*- FN
18	1		*FRT WIPER MOTOR BRACKET	Broken	59.10 FN	*59.10 FN
19	1		*BRAKE BOOSTER PUMP HOSE JOINT	Not Necessary	44.00 FN	*- FN
20	2		*FRT BUMPER BRACKET R/L	Repeated	209.40 FN	*- FN
21	2		*FRT BUMPER RETAINER R/L	Necessary	294.00 FN	*294.00 FN
22	1		*DASHBOARD LOWER CENTER GARNISH TRIM	Cracked	259.20 FN	*259.20 FN
23	2		*FRT LOWER PANEL R/L	Buckled	630.00 FN	*630.00 FN
24	1		*FRT LOWER CENTER PANEL	Buckled	98.40 FN	*98.40 FN
25	1		*FRT LOWER BAR	Bent	210.00 FN	*210.00 FN
26	1		*FRT NO PLATE	Cut	50.00 FS	*50.00 FS
27	1		*AIR INLET DUCT (A/C)	Cracked	300.00 FS	*300.00 FS
28	1		*A/C SUCTION PIPE	Bent	268.20 FS	*268.20 FS
29	1		*A/C DISCHARGE PIPE	Bent	237.40 FS	*237.40 FS
30	1		*A/C LIQUID PIPE	Bent	242.50 FS	*242.50 FS
31	1		*A/C RECEIVER DRIER	Not Necessary	151.10 FS	*- FS
32	1		*A/C COOLING COIL ASSY	Cracked	2,181.50 FS	*2,181.50 FS
33	1		*A/C BLOWER ASSY	Cracked	813.60 FS	*813.60 FS
34	1		*FRT WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
35	1		*FRT WINDSCREEN INNER SEAL	Necessary	50.00 FS	*50.00 FS
36	1		*FRT WINDSCREEN I U BRACKET	Necessary	30.00 FS	*30.00 FS
37	1		*FRT PANEL SEALANT	Not Necessary	50.00 FS	*- FS
38	1		*FRT PANEL STICKER (CO LOGO)	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$) **15,544.40** **12,261.60**  
 - List Item Discount on L Items 30.00/30.00% (S\$) **1,873.86** **1,289.37**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- Nett Item Discount on N Items 10.00/10.00% (S\$)					472.39	374.05
Total Parts (S\$)					13,198.15	10,598.18

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL SYSTEM,REPAIR WIRE HARNESS AND FOCUS HEADLAMP	New	80.00	30.00
2	TO REMOVE,REPLACE AND REINSTALL FRONT WINDSCREEN	New	150.00	100.00
3	TO REMOVE AND REINSTALL DASHBOARD FOR NECESSARY REPAIRS	New	400.00	200.00
4	TO REMOVE,REPLACE AND REINSTALL A/C BLOWER AND A/C COOLING COIL ASSY (INCLUDE VACUUM & RECHARGE A/C GAS)	New	150.00	150.00
5	TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,200.00	1,000.00
6	TO CONDUCT CHASSIS ALIGNMENTS	New	350.00	-
7	TO SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>3,330.00</b>	<b>2,280.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;