

12/00/00

ASS. REC BY

REF: CS/FCI18001127/MHd302

void for void

MA ASSIGNMENT (Office)

CWS

Person: Lurene Jaw

at: FCI

Date/Time: 9:50am @ 18/01/18

Estimated Cost

BLN

OD: ~~WSP~~ IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 59202

Insured: SHB 3420X

at Workshop no: Cycle & Carriage Industries
188 pandan loop

Tel: 9186 5112

Policy No:

Chassis No: D180006342MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

Date: 14/01/2018

CA - REV / REP. / REV 24 HRS lwp

PROD. Equipment

Date/Time: 9:52am @ 18/1/18

Person Conducted: Alan

Vehicle: ~~IN~~ OUT

Date/Time: Action/Description

✓

SLD 59202 x

SHB 3420X - CS/FCI17015976/T1/bc2

D.O.A. 18/01/2017

Part by Part \$14,130.96 (Red: 1640.44 : 10%)

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop mis CLC
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N.S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Ver No SLD59202 Page JUN 2016
 Type (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: MBRC E200 1991
 Colour SILVER A.C. Insured / Std / NI / NA
 So. Reading 2598 T Radio Insured / Std / NI / NA
 Eng No: _____
 C No: WDD220342B297630
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245/40R18
 R: 265/35R18
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or CON.
 Front Rear
 R/Bal. 8 mm R/Bal. 8 mm
 L/Bal. 8 mm L/Bal. 8 mm
 D.O.A. 14/1/2018 D.O.I. 18/1/2018
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time File Pass to: ☐ Preli. Report
20/3 Typist ☒ Final Report
 Date/Time File Return to: _____

Days Of Repair: 8

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp \$
☐ Inter. ev. \$
☐ Tech. ins. \$
☐ Dressing \$

Survey Fee

Transportation

_____ \$ - P.L. \$

Printed

Others

TOTAL

Report Format: TPLump Sum (I.B.H.S) 4,130.96

5X15

170 175

50

50

67

412

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	16-01-2018	Our Ref No. D18000342MFSH
Accident Date	14-01-2018	Claim Type. Third Party
Insured Vehicle	SHB3420X	Third Party Vehicle. SLD5920Z
Survey Location	PANDAN LOOP SERVICE CENTER 188 PANDAN LOOP	
Contact Person.	ALAN QUEK	
Contact No.	67714377/ 91865112	Fax No. 68721272
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE INDUSTRIES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/233552)



PRI Documents



Close



PRI Header Details

Claim No	D18000342MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CYCLE & (LTD
Workshop Name	CYCLE & CARRIAGE INDUSTRIES PTE LTD (Contact Person : ALAN QUEK)	Survey Location & Contact Details	PANDAN LOOP SERVICE CENTER 188 PANDAN LOOP Mobile: 91865112 , Phone: 67714377 , Fax: 6872127; EmailId: ALAN.QUEK@CYCLECARRIAGE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3420X	TP Vehicle No	SLD5920Z
PRI Recieved Date	16-01-2018 09:06:12 PM	Surveyor Appointed Date	18-01-2018 09:49:26 AM	Surveyor Accept Date	18-01-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	18-01-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001127/M1td3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 18-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3420X	Veh. Inspected	SLD 5920Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18000342MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	18/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/01/2018	Inspection Date	18/01/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2018 17:35
Date Of Accident	14/01/2018 20:40
Exact Location Of Accident	C.T.E
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD5920Z
Insured/Policyholder	
Name Of Registered Owner	LEE HUEI MING @ JONATHAN LEE
NRIC No	S2685538A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98185848
Alternative Phone No	OFFICE-98185848

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100471224-01000
Cover Note Number	

Driver

Name of Driver	ROYSTON LEE HERNG KHAI
NRIC No	S9629027F
Date Of Birth	13/08/1996
Occupation	INDOOR
Date Of Driving Pass	18/02/2015
Driving Experience	2 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91295519
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 925 HOUGANG STREET 91 #04-51
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REPORT NO: T/20180115/2000

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REFER AQ
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB3420X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's

Name: Alan Quah

NRIC/FIN No.:



Ref police report for detail.

I/We declare the foregoing particulars are true in every respect.

(Please contact your insurance company for any further details)

Reporting Centre Personnel's
Name: Alan Quirk
NRIC/FIN No.:

15/01/18



SINGAPORE POLICE FORCE



T/20180115/2000

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180115/2000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/01/2018 00:32		Vide Report No.: E/20180114/0198		Station Diary No.:	
Informant's Particulars					
Name of Informant: ROYSTON LEE HERNG KHAI			Address: APT BLK 925 HOUGANG ST 91 #04-51 HDB-HOUGANG SINGAPORE 530925		
ID Type / ID No.: NRIC NO / S9629027F			Contact No.: Home/Office: Mobile: 91295519		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 21	Date of Birth: 13/08/1996	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Student			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 14/01/2018 20:40	Type of Location: Straight Road
Location: CENTRAL EXPRESSWAY to CTE(SLE) 11.8KM L/P 186				
Weather: Clear		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passengers
SHB3420X	Car	HYUNDAI	I40 1.7L CRDI AT ABS AIRBAG 4DR	Yellow		4
SLD5920Z	Car	MERCEDES BENZ	E200 SEDAN EDITION E (R18 LED SR)	Silver		1



**SINGAPORE
POLICE FORCE**



T/20180115/2000

2 of 3

Report No. T/20180115/2000

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date time and location I was travelling on the extreme right lane of a 4 lanes traffic from CTE towards SLE due to slow traffic in front of me slow down, I also slowed down, suddenly I felt a strong impact from my rear of my vehicle.

Witness name and contact num : Zac , 91273028



**SINGAPORE
POLICE FORCE**



T/20180115/2000

3 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000






Report No. T/20180115/2000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: TP / MUHAMMAD MIRZA SYAHMI BIN HARMIZI 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 15/01/2018 00:32
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436	Classification Of Case:
Authentication Stamp NP168  Signature: 	



HOTLINE TEL: (65) 6419 3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

MERCEDES-BENZ MOTOR INSURANCE

CERTIFICATE NO. 2100471224-01000

OWN DAMAGE EXCESS S\$800.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value

INSURING WITH COE/PARF Yes

SLD5920Z

Lee Hwei Ming @Jonathan Lee

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

23 Jun 2017

4) DATE OF EXPIRY OF INSURANCE

22 Jun 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION -All Age Condition

a) The Insured

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / MERCEDES-BENZ AUTHORISED REPAIRERS

1. Cycle & Carriage Pandan Loop Service Center - 188 Pandan Loop (Tel: 6777 8388)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. Ethos - 30 Bukit Batok Cres (Tel: 66547777)

4. Glass-Pix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only 5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)

6. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110) 7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)

8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336) 9. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE 15 Days Replacement Car only for repairs at C & C - Refer to policy wordings for details

NAMED DRIVER Royston Lee Heng Khai, Alex Lee Heng Rui

HIRE PURCHASE COMPANY DBS BANK LTD
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 19 Jun 2017

AIG Asia Pacific Insurance Pte. Ltd.

504380-248
CYCLE & CARRIAGE - STHAN
239 ALEXANDRA ROAD
SINGAPORE 159930

AUTHORISED REPRESENTATIVE

ORIGINAL

SSPEMC.

Co. Reg. No. 201009404A

9041-02/13

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S9629027F**
Name **ROYSTON LEE HERNG KHAI**

Birth Date: **13 Aug 1996**
Issue Date: **18 Feb 2015**

FOR C&C USE ONLY

002397996E

SG 50


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars= \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg 18 Feb 2015

FOR C&C USE ONLY

NP 428A





Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLD5920Z

FIRST CAPITAL INSURANCE LTD

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Mv Ma

Vehicle & Document Information

WIP No 20500
Reg No/Reg Date SLD5920Z / 23/06/2016
Date In/Mileage 18/01/2018 / 25918
Chassis No WDD2120342B2976301
Engine No 27492030563131
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 029 988 Diamond Sil / 042 241 Leather Bla

SLD5920Z

Account No	Terms	Date/Time Printed	CSE	Operator
WFO01862	Credit	20/02/2018/ 20:27	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services Qty Unit Price Disc% Amount

M. BRNSUN

POLICY NO/ACC DATE : 21004712247 / 14-01-2018
DRIVE IN: 15-01-2018 // TP CAR NO: SHP3420X (FIRST CAPITAL INSURANCE)
DATE IN/DATE SURVEY: 18-01-2018 // LKK MR MA
BY/AUTHORIZED ON : LURENE // 18-01-2018

OFFICIAL TAX INVOICE

8 working Days
ESTIMATE

A BPILAB	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT	0.10	380.00	✓		
A BPILAB	RE-ADJUST NECKPRO HEADREST TO STANDARD SETTING.		240.00	✓		
A BPILAB	REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.		2400.00	✓		
A BPIRES	RESPRAY REAR BUMPER, REAR BOOT LID, REAR LEFT FENDER & REAR END PANEL	0.03	2200.00	✓		
S BPNTOW	ACCIDENT TOWING FROM BLK 925A HOUGANG ST 91 TO PLSC USING KING DOLLEY NO: 142161		140.00	✓		
A BPILAB	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT		120.00	✓		
X	REAR BUMPER	1.00	1839.64	00.00	1839.64	✓
X	LH/R BUMPER GARNISH	1.00	56.74	00.00	56.74	✓
X	REAR BOTTOM PANEL	1.00	283.61	00.00	283.61	✓
X	REAR BOTTOM PANEL GARNISH	1.00	302.94	00.00	302.94	✓
X	LH/R EXHAUST TAIL PIPE	1.00	302.94	00.00	302.94	✓
X	LH/R EXHAUST TAIL PIPE BRACKET	1.00	27.18	00.00	27.18	✓
X	LH/R BASIC MOUNTING FOR BUMPER	1.00	36.24	00.00	36.24	✓
X	LH/R PARKING SENSOR	2.00	172.07	00.00	344.14	✓
X	LH/R PARKING SENSOR SEAL	3.00	6.42	00.00	19.26	✓
X	LH/R BUMPER SIDE BRACKET	1.00	30.77	00.00	30.77	✓

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8368
Fax: 6779 5383
www.mercedes-benz.com.sg

Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLD5920Z

FIRST CAPITAL INSURANCE LTD

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No **20500**
Reg No/Reg Date **SLD5920Z / 23/06/2016**
Date In/Mileage **0**
Chassis No **WDD2120342B297630**
Engine No **27492030563131**
Make/Model **MB/MB E 200 2.0 SEDAN (W212) "EDITION E"**
Colour/Trim **029 988 Diamond Sil/ 042 241 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	16/01/2018/ 09:14	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :2100471224 // 14-01-2018 DRIVE IN:15-01-2018 // TP CAR NO:SHB3420X (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00 ✓
A BPILAB RE-ADJUST NECKPRO HEADREST TO STANDARD SETTING.				240 300.00 ✓
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				2400 2880.00 ✓
A BPIRES RESPRAY REAR BUMPER, REAR BOOT LID, REAR LEFT FENDER & REAR END PANEL			0.02	2200 2800.00 ✓
S BPNTOW ACCIDENT TOWING FROM BLK 925A HOUGANG ST 91 TO PLSC USING KING DOLLEY WO: 142161				140.00 ✓
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT				120.00 ✓
M REAR BUMPER	1.00	1839.64	00.00	1839.64 ✓
M LH/R BUMPER GARNISH	1.00	56.74	00.00	56.74 ✓
M RH/R BUMPER GARNISH	1.00	56.74	00.00	56.74 ✓
M REAR BOTTOM PANEL	1.00	283.61	00.00	283.61 ✓
M REAR BOTTOM PANEL GARNISH	1.00	302.94	00.00	302.94 ✓
M LH/R EXHAUST TAIL PIPE	1.00	302.94	00.00	302.94 ✓
M LH/R EXHAUST TAIL PIPE BRACKET	1.00	27.18	00.00	27.18 ✓
M LH/R BASIC MOUNTING FOR BUMPER	1.00	36.24	00.00	36.24 ✓
M CT/R BASIC MOUNTING FOR BUMPER	1.00	173.85	00.00	173.85 ✓
M REAR PARKING SENSOR WIRING HARNESS	1.00	271.63	00.00	271.63 ✓

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLD5920Z

FIRST CAPITAL INSURANCE LTD

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No **20500**
Reg No/Reg Date **SLD5920Z / 23/06/2016**
Date In/Mileage **0**
Chassis No **WDD2120342B297630**
Engine No **27492030563131**
Make/Model **MB/MB E 200 2.0 SEDAN (W212) "EDITION E"**
Colour/Trim **029 988 Diamond Sil/ 042 241 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	16/01/2018/ 09:14	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LH/R PARKING SENSOR	3.00	172.07	00.00	516.21
M LH/R PARKING SENSOR SEAL	3.00	6.22	00.00	19.26
M LH/R BUMPER SIDE BRACKET	1.00	30.77	00.00	30.77
M REAR CROSS MEMBER	1.00	789.45	00.00	789.45
M LH/R TAIL LAMP	1.00	698.09	00.00	698.09
M REAR STAR EMBLEM	1.00	46.63	00.00	46.63
M GROMMET	3.00	2.23	00.00	6.69
M E200 EMBLEM	1.00	81.15	00.00	81.15

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Branch & Repair Center
188 Pandan Loop, Singapore 128378
Tel: 6777 8388 Fax: 6779 5383
www.mercedes-benz.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15945.25

Confirmed & accepted by

Nett **12,159.76**
7% GST on **12159.76** **851.18**

Total Payable 13,010.94

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLD5920Z

FIRST CAPITAL INSURANCE LTD

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 20500
Reg No/Reg Date SLD5920Z / 23/06/2016
Date In/Mileage 18/01/2018 / 25918
Chassis No SWDD2120342B297630
Engine No 27492030563131
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 029 988 Diamond Sil/ 042 241 Leather Bls

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	20/02/2018/ 20:27	AQ	305 / Alan Quek A1 Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X REAR CROSS MEMBER	1.00	789.45	00.00	789.45
X LH/R TAIL LAMP	1.00	698.09	00.00	698.09
X REAR STAR EMBLEM	1.00	46.63	00.00	46.63
X GROMMET	3.00	2.23	00.00	6.69
X E200 EMBLEM	1.00	81.15	00.00	81.15
X LH/R EXHAUST MUFFLER	1.00	1267.05	00.00	1267.05
X RUBBER STOPPER	1.00	13.19	00.00	13.19
X LH/R EXHAUST PIPE SUSPENSION	1.00	60.62	00.00	60.62
X REAR EXHAUST PIPE STRAP	1.00	106.97	00.00	106.97
X LH/R EXHAUST MUFFLER BRACKET	1.00	67.26	00.00	67.26
X LH/R EXHAUST OUTER SCREENING PLATE	1.00	81.44	00.00	81.44
X LH/R EXHAUST INNER SCREENING PLATE	1.00	113.23	00.00	113.23
X LH/R BUMPER GUIDE BRACKET	1.00	14.84	00.00	14.84
X CT/R BASIC MOUNTING FOR BUMPER	1.00	173.85	00.00	173.85
X REAR RADAR SENSOR	1.00	1589.40	00.00	1589.40
X LH/R EXHAUST RUBBER MOUNT	1.00	38.15	00.00	38.15
X LH/R WHEEL ARCH COVER	1.00	234.25	00.00	234.25
X LH/R FENDER AIR FLAP	1.00	25.24	00.00	25.24

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 14,130.96
7% GST on 14130.96 989.17

Authorized signatory and company stamp

Total Payable 15,120.13

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally more or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
180 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

SUPPLEMENTARY

ESTIMATE FOR SLD5920Z

FIRST CAPITAL INSURANCE LTD

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

M M

Vehicle & Document Information

WIP No 20500
Reg No/Reg Date SLD5920Z / 23/06/2016
Date In/Mileage 18/01/2018 / 25918
Chassis No SWDD2120342B2976301
Engine No 27492030563131
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 029 988 Diamond Sil/ 042 241 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	
WF001862	Credit	20/02/2018/ 20:26	AQ	305 / Alan Quok Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M. BPNSUN

POLICY NO/ACC DATE : 2100471224 // 14-01-2018
DRIVE IN : 15-01-2018 // TP CAR NO: SHB3420X (FIRST CAPITAL INSURANCE)
DATE IN/DATE SURVEY: 18-01-2018 // LKK MR MA
BY/AUTHORIZED ON : LURENE // 18-01-2018

X LH/R EXHAUST MUFFLER	1.00	1267.05	00.00	✓ 1267.05 dt
X RUBBER STOPPER	1.00	13.19	00.00	✓ 13.19 dis
X LH/R EXHAUST PIPE SUSPENSION	1.00	60.62	00.00	✓ 60.62 bt
X REAR EXHAUST PIPE STRAP	1.00	106.97	00.00	✓ 106.97 dis
X LH/R EXHAUST MUFFLER BRACKET	1.00	67.26	00.00	✓ 67.26 bt
X LH/R EXHAUST OUTER SCREENING PLATE	1.00	81.44	00.00	✓ 81.44 dis
X LH/R EXHAUST INNER SCREENING PLATE	1.00	113.23	00.00	✓ 113.23 buc
X LH/R BUMPER GUIDE BRACKET	1.00	14.84	00.00	✓ 14.84 dis
X REAR RADAR SENSOR	1.00	1589.40	00.00	✓ 1589.40 short
X LH/R EXHAUST RUBBER MOUNT	1.00	38.15	00.00	✓ 38.15 ds
X LH/R WHEEL ARCH COVER	1.00	234.25	00.00	✓ 234.25 dic
X LH/R FENDER AIR FLAP	1.00	25.24	00.00	✓ 25.24 dis

ESTIMATE

SUPPLEMENTARY

Alan Quok
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quok@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett** 3,611.64
252.81

Authorized signatory and company stamp

Total Payable 3,864.45

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001127/M1td3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3420X	Veh. Inspected	SLD 5920Z
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18000342MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	18/01/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E200	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2120342B297630	Colour	SILVER
Odometer	25918	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R18	CONTINENTAL	8 mm
L/H Front Tyre	245/40 R18	CONTINENTAL	8 mm
R/H Rear Tyre	265/35 R18	CONTINENTAL	8 mm
L/H Rear Tyre	265/35 R18	CONTINENTAL	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/01/2018	Inspection Date	18/01/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 5920Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	1,839.64	1,839.64
1	LH/R BUMPER GARNISH (SN)	DISTORTED	56.74	56.74
1	RH/R BUMPER GARNISH (SN)	NOT NECESSARY	56.74	-
1	REAR BOTTOM PANEL (SN)	DISTORTED	283.61	283.61
1	REAR BOTTOM PANEL GARNISH (SN)	DISTORTED	302.94	302.94
1	LH/R EXHAUST TAIL PIPE (SN)	BENT	302.94	302.94
1	LH/R EXHAUST TAIL PIPE BRACKET (SN)	DISTORTED	27.18	27.18
1	LH/R BASIC MOUNTING FOR BUMPER (SN)	NECESSARY	36.24	36.24
1	CT/R BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	173.85	-
1	REAR PARKING SENSOR WIRING HARNESS (SN)	NOT NECESSARY	271.63	-
3	LH/R PARKING SENSOR @\$172.07 (SN)	MISSING-ONLY 2 PCS	516.21	344.14
3	LH/R PARKING SENSOR SEAL @\$6.42 (SN)	NECESSARY	19.26	19.26
1	LH/R BUMPER SIDE BRACKET (SN)	DISTORTED	30.77	30.77
1	REAR CROSS MEMBER (SN)	BENT	789.45	789.45
1	LH/R TAIL LAMP (SN)	CUT	698.09	698.09
1	REAR STAR EMBLEM (SN)	NECESSARY	46.63	46.63
3	GROMMET @\$2.23 (SN)	NECESSARY	6.69	6.69
1	E200 EMBLEM (SN)	NECESSARY	81.15	81.15
1	LH/R EXHAUST MUFFLER (SN)(ADDITIONAL)	DENTED	1,267.05	1,267.05
1	RUBBER STOPPER (SN) (ADDITIONAL)	DISTORTED	13.16	13.19
1	LH/R EXHAUST PIPE SUSPENSION (SN) (ADDITIONAL)	BENT	60.62	60.62
1	REAR EXHAUST PIPE STRAP (SN) (ADDITIONAL)	DISTORTED	106.97	106.97
1	LH/R EXHAUST MUFFLER BRACKET (ADDITIONAL) (SN)	BENT	67.26	67.26
1	LH/R EXHAUST OUTER SCREENING PLATE (SN) (ADDITIONAL)	DISTORTED	81.44	81.44
1	LH/R EXHAUST INNER SCREENING PLATE (SN) (ADDITIONAL)	BUCKLED	113.23	113.23
1	LH/R BUMPER GUIDE BRACKET (SN) (ADDITIONAL)	DISTORTED	14.84	14.84
1	REAR RADAR SENSOR (SN) (ADDITIONAL)	SHORTED	1,589.40	1,589.40
1	LH/R EXHAUST RUBBER MOUNT (SN)(ADDITIONAL)	DISTORTED	38.15	38.15
1	LH/R WHEEL ARCH COVER (SN) (ADDITIONAL)	DISTORTED	234.25	234.25

Report Ref No. CS/FCI18001127/M1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Quoted (\$)
1	LH/R FENDER AIR FLAP (SN) (ADDITIONAL)	DISTORTED	25.24	25.24
1	CT/R BASIC MOUNTING FOR BUMPER (SN) (ADDITIONAL)	NECESSARY	173.85	173.85
			9,325.22	8,650.96
	LABOUR			
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	RE-ADJUST NECKPRO HEADREST TO STANDARD SETTING.		300.00	240.00
	REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENT & REFINISH.		2,880.00	2,400.00
	RESPRAY REAR BUMPER, REAR BOOT LID, REAR LEFT FENDER & REAR END PANEL.		2,800.00	2,200.00
	ACCIDENT TOWING FROM BLK 925A HOUGANG ST 91 TO PLSC USING KING DOLLEY.		140.00	140.00
	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.		120.00	120.00
			6,620.00	5,480.00
GRAND TOTAL			15,945.22	14,130.96

RECOMMENDED COST OF REPAIRS			14,130.96
------------------------------------	--	--	------------------

Report Ref No. CS/FCI18001127/M1td3e2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.