



Mercedes-Benz
Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLD5920Z

FIRST CAPITAL INSURANCE LTD

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 20500
Reg No/Reg Date SLD5920Z / 23/06/2016
Date In/Mileage 18/01/2018/ 25918
Chassis No SWDD2120342B297630
Engine No 27492030563131
Make/Model MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 029 988 Diamond Sil/ 042 241 Leather B1a

Account No	Terms	Date/Time Printed	CSE	Operator
WF001962	Credit	20/02/2018/ 20:27	AQ	305 / Alan Quek A1 Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X REAR CROSS MEMBER	1.00	789.45	00.00	789.45
X LH/R TAIL LAMP	1.00	698.09	00.00	698.09
X REAR STAR EMBLEM	1.00	46.63	00.00	46.63
X GROMMET	3.00	2.23	00.00	6.69
X E200 EMBLEM	1.00	81.15	00.00	81.15
X LH/R EXHAUST MUFFLER	1.00	1267.05	00.00	1267.05
X RUBBER STOPPER	1.00	13.19	00.00	13.19
X LH/R EXHAUST PIPE SUSPENSION	1.00	60.62	00.00	60.62
X REAR EXHAUST PIPE STRAP	1.00	106.97	00.00	106.97
X LH/R EXHAUST MUFFLER BRACKET	1.00	67.26	00.00	67.26
X LH/R EXHAUST OUTER SCREENING PLATE	1.00	81.44	00.00	81.44
X LH/R EXHAUST INNER SCREENING PLATE	1.00	113.23	00.00	113.23
X LH/R BUMPER GUIDE BRACKET	1.00	14.84	00.00	14.84
X CT/R BASIC MOUNTING FOR BUMPER	1.00	173.85	00.00	173.85
X REAR RADAR SENSOR	1.00	1589.40	00.00	1589.40
X LH/R EXHAUST RUBBER MOUNT	1.00	38.15	00.00	38.15
X LH/R WHEEL ARCH COVER	1.00	234.25	00.00	234.25
X LH/R FENDER AIR FLAP	1.00	25.24	00.00	25.24

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclccarriage.com.sg

Confirmed & accepted by

7% GST on 14130.96 989.17

Total Payable 15,120.13

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
180 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg