

REPAIR ESTIMATE*

VEHICLE NO : SHA 7438A

DATE 15/1/2018 9:52

AYH

MAKE :

Chaco

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Grille (RH) ✓			\$ 40.30
	Front Bumper Bracket Top (RH) ✓			\$ 22.40
	Front Bumper Retainer Mounting ✓ (RH)			\$ 9.20
	Headlamp Support Top Cover ✓			\$ 398.00
	Headlamp Support Panel Assy ?			\$ 1,067.50
	Headlamp (RH) ✓			\$ 1,388.00
	Front Fender (RH) ✓			\$ 619.00
	Front Fender Shield (RH) ✓			\$ 169.80
	Front Fender Retainer ✓			\$ 9.20
	Front Door Mirror (RH) ✓			\$ 980.50
	Front Wheel Rim (RH) X			\$ 351.90
	Front Wheel Hub Cap (RH) ✓			\$ 150.70
	SUB TOTAL			\$ 6,437.10
	LESS 20%			\$ 1,287.42
	DISCOUNTED TOTAL			\$ 5,149.68
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
	Front Door Comfort Logo (RH) X			\$ 75.00
				\$ 175.00
	Labour Charge			
	Panel Beating			\$ 400
	Spray Painting Charge			\$ 560.00
	Wiring Charge			\$ 700.00
	Tuff Kote			\$ 50.00
	FRT Wheel Alignment			\$ 50.00
				\$ 120.00
	TOTAL LABOUR			\$ 1,480.00
	ESTIMATE TOTAL			\$ 6,804.68
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalin RUKY

17/1/18 15:20hrs

2 Days

P/P

Before Paint photo