

Boon Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2 #01-267

Singapore 569536

Tel:64820801 Email: CS.Boonauto@gmail.com

*1 case
Hp 9000068
4 days
L/S
17/01/18 @ 1230
Resurvey after repair*

Date: 17-01-2018

Our Ref: DC-20181401SKC6254Z

Vehicle No. : **SKC6254Z**

Accident Date: 14/1/2018

Name of Owner: DON WONG SHYUN YANN

To Insurance Co India International Insurance

Yr of Manufactur 2011

Model: Hyundai ELANTRA 1.6 AT

RE: ESTIMATED COST FOR REPAIR VEHICLE NO. SKC6254Z

List Item:

			<u>List Price</u>
1pc	Rear bumper		\$ 460.40 <i>DE</i>
2pc	Rear Bumper Side Retainer (RH& LH)	28 each	\$ 56.00 <i>NE</i>
1pc	Rear Bumper Reinforcement		\$ 350.20 <i>X</i>
2pc	Tail lamp (RH & LH)	350.10each	\$ 700.20 <i>X</i>
1pc	End Panel		\$ 380.00 <i>R</i>
2pc	Reflector (RH & LH)	42 each	\$ 84.00 <i>CR</i>
	<i>480.32</i>	Total	\$ 2,030.80
	<i>700.00</i>	Less 20%	\$ 406.16
	<i>1060.00</i>	Balance	\$ 1,624.64

Special NETT item:

1 set	Reverse Sensor		\$ 250.00 <i>200.00</i>
1pc	Rear Bodykit		\$ 680.00 <i>500</i>
	<i>209</i>	Total	\$ 930.00 <i>700</i>
	<i>1792.25</i>		

Labour charges:

Wiring charges: tail lamp & reverse sensor		\$ 80.00 <i>60</i>
To mount vehicle on jig/celette bench in order to re-align chassis members charges		\$ 350.00 <i>X</i>
To knock and repair end panel. To install & dismantle tail lamps, bumper, retainers, reinforcement, reflectors, bodykit straighten all necessary parts including replacing of all damaged parts and align same panel beating other affected parts.		\$ 680.00 <i>450</i> <i>1060</i>
To putty and spray painting rear body kit, end panel & rear bumper and all affected part from the accident		\$ 700.00 <i>550</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Repair Cost Total \$ 4,364.64