

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : AXA INSURANCE PTE LTD

8 Shenton Way #24-01

AXA Tower

Singapore 068811

TEL: 68804741

FAX: 68804838

ATTN: Motor Claim Department

Your Ref No: 18/AXA/TP-012 (01)

Claim Type: Third Party

Accident Date: 13/01/2018

TP Veh Reg No: SKV2287E

Estimate No: EST0003888

Date: 16 Jan 2018

Policy No: B27611866QMX

Veh Reg No: SKF4020D

Make/Model: BMW 520i

Chasis No: WBAXG12000DX48220

Engine No: A4610143N20B20B

Reg. Date:

Estimate Repair Cost to Vehicle No :SKF4020D

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1 REAR BUMPER <i>DO/OE</i>	1 PC	1,431.40 ✓	
2 REAR BUMPER RETAINER LH <i>11</i>	1 PC	141.65 X	
3 REAR BUMPER CLIP <i>11</i>	1 PC	3.00 ✓	
4 REAR BUMPER REFLECTOR LH <i>11</i>	1 PC	34.35 X	
5 REAR PARKING SENSOR LH (CORNER) <i>should</i>	1 PC	236.85 ✓	
6 TAIL LAMP LH <i>SCN</i>	1 PC	572.25 ✓	
		2,419.50	
	Less 10%	241.95	2,177.57
Labour			
7 WIRE CHECKING	1 UNIT	20.00 ✓	
8 LABOUR CHARGE	1 UNIT	400.00 <i>200</i>	
9 SPRAY PAINTING	1 UNIT	400.00 <i>200</i>	
		820.00	820.00
		Total	S\$ 2,997.57
		Add GST @ 7%	209.83
		Total Amount Payable	S\$ 3,207.40

TOTAL: SINGAPORE DOLLAR THREE THOUSAND TWO HUNDRED AND SEVEN AND CENTS FORTY ONLY

For SME Motor Pte Ltd

Not Affected
L/L
L/S
2 day
Take photo after repair
29/1/18

AUTHORISED SIGNATURE

I, the undersigned, hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____