



Pte Ltd

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475 Fax : 6844 2474
E-mail : claims@teamworkgarage.com
Register number : 201015366H
3RD PARTY CLAIM ESTIMATION

ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Vehicle number : SDS8110R
Make / Model : TOYOTA/HARRIER
Chassis number : ZSU600037936
Accident date : 12 January 2018
Reference : 1801-22

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	TAILGATE <i>Dental</i>	1852.20 ✓
1	TAILGATE LOGO <i>svz</i>	96.12 x
2	TAILGATE INNER LAMP <i>HW</i>	1080.96 x
2	REAR TAILGATE LOCK <i>svz</i>	319.30 x
1	REAR BUMPER <i>distorted</i>	1361.04 ✓
2	REAR BUMPER RETAINER <i>svz</i>	209.52 x
2	REAR BUMPER BRACKET <i>svz</i>	158.40 x
1	REAR BUMPER LOWER GARNISH <i>cost distorted</i>	457.68 ✓
2	REAR BUMPER REFLECTOR <i>crack mounting</i>	171.60 ✓
1	END PANEL <i>Dental</i>	860.76 ✓
1	END PANEL TOP GARNISH <i>svz</i>	443.28 x
1	SPARE TYRE COVER <i>HW</i>	381.40 x
1	REAR EXHAUST SILENCER <i>HW</i>	720.00 x
2	REAR EXHAUST MOUNTING <i>HW</i>	70.00 x
		8182.26
	Less 25%	2045.57
	Subtotal	6136.70
	Balance C/F	6136.70
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	6136.70
1 SET	REAR BUMPER CLIP <i>HW</i>	60.00 30/-
1 SET	REAR REVERSE SENSOR <i>Dam</i>	400.00 220/-
1	JOINT SEALANT <i>HW</i>	450.00 40/-
	Subtotal	610.00
	Balance C/F	6746.70
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	6746.70
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 HW
2	REMOVE AND RENEW REAR LINING, TRIM AND GARNISH	200.00 60/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 HW
5	REMOVE AND RENEW REAR BUMPER BRACKET, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 60/-
6	PANEL BEATING ON AFFECTED AREAS	1400.00 600/-
7	SPRAY PAINTING ON AFFECTED AREAS	1400.00 600/-
8	SPRAY PAINTING ON AFFECTED AREAS	150.00 40/-
	Subtotal	3710.00
	Grand total	10456.70

LKK Auto Consultants Pte Ltd

the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged parts during resurvey

• Parts prices are subject to market rates

• Third party survey is not "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurer's Company

Acknowledged by Repairer

Signature:

Date:

15/01/2018 21:00m

nta Adam

2/Jan

LKK And

Grand total

3 days

Check 7m prior.