ause -	Kalvin	ASSIGN	MENT (Office)	
CWS —	Lurene Jaw	ef	FCI	18/01/2018@3:44P
Estimated Cos		Albasan vaso venera	Bill to:	
To Inspect Ve	STIPRES / OD RES	NIMIT		SHB 48804
ne Weskshop :	Pren 23 changi s	vier Autom	otive	6544 6671
ef	23 changi s	bouth Ave :	#03-02	
Policy No		4	Claim Not	D18000412MFSH
Sum Insured:		Simon van de la company	Excess:	
Make of Veh (Client's Recor				00= 16/01/2018
	/ REP. / REV 24 HE	= "wp"		SE C. D. Redognament
	3.46 pm@18/01/18		Gary	TIO OUT
Date/Time	Action Instruction	V =	a+7	1
	SHDIDIOT-A	AlINCOGOO	2033/81	N.O.A. 29/01/2009
	SHB 48804-	×		
MILLONDS	3.08m revised	to Luna.	la consil	

24/18 " (about 1/p + 1224. 40/ 2/72 (Red & 970, 44%))

Person Contacted

FIZ

The U/C | Chassis frame | Body Structure affected que to collision

RECEIVED 2 6 JAN 2018

veniole IN OUT

Preli. Report	Days Of Repair: 2		
26/1 Miss Final Report	Resurvey No. of Trip	Juney Fee	110
Cite Time File Racum of		7110-12 P00000	50
	Add Fee Stations S	584 II I	02
7	Internal B		18
Report Format //	Feb 1 5		
Lump 8um / 1.3 1 1 1 274,40	(1,42°+)0 °		
			228



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter	nationale Des Experts En Auton	nobile	
FIRS	ST CAPITAL INSU	RANCE LTD	Ref : CS/FCI180011	44/K1qd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 18-01-2018 Code: FCI2			
1.		Policy Particul	lars :- THIRD PARTY CLA	IM	
	Insured Veh.	SHB 4880U	Veh. Inspected	SHD 1012T	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D18000412MFSH	Excess (\$)	0.00	
	Assign From	CWS (LURENE JAW)	Assign Date	18/01/2018	
2.		Vehicle P	articulars & Condition		
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No. Colour				
	Odometer -		Steering		
	Brakes		Modification		
	General				
3.		Col	nditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.		Desc	ription of Damages	ilia 7 loke szálatoltását	
5.		Go	neral Information		
J.	Accident Date	16/01/2018	Inspection Date	18/01/2018	
-	Survey held at	PREMIER AUTOMOTIVE S			
	Survey field at		UE 2 #01-02 SINGAPORE 48	6443	
5a.	L Capparation for		Remarks		
	A)THE INSPECTION	ON WAS CONDUCTED ON A CE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BA IS, WE HAVE NOT AUTHORI	SIS. SED REPAIRS.	

Reference No.: Coltut8001144 Klad3
Policy Type: OD / TP / TP RES / TL / EVA SHO 1012T Typist Admin (Mutha): Case handler to make sure all Information created by the assignment team are ACCURATE. Y-Date N-Date Y-Date N-Date (1) Office Assign Form Reference No. Customer Code N Assign From Assign Date C Veh No (Inspected) C Veh No (Insured) C D.O.A C Policy No C C Claim No Insurance Authorisation (CA /REV/REP) C Report Type C Weekend Charges C Survey held at/Repairer N Excess C): Case handler to make sure the surveryor completed all required information. Kalvin Surveyor ((1) Assignment Form Vehicle No Regn Month/Year C Vehicle Type Make & Model N C Engine Capacity. (C.C) N Colour Odometer. (Sp.Reading) C Chassis No C General Condition Steering N Brake N Modification (Modi) N C Tyre Size Tyre Make N C Tyre Balance Date of Inspection C Survey held Des.of Damages N (2) System - (Views/Merimen) Damaged Vehicle Photographs Uploaded (3) Workshop Estimate/Assignment Form ALL Parts condition Market Value for OD cases C Estimate Repair Cost for PRI (RSI, TMI, MSIG) C Days of repair C Finalised Amount Re-inspection Cases to Finalize within 5 Days (4) System - (Views/Merimen) Resurvey photo Uploaded

First Capital Insurance Limited

Company Reg. No. 195000106C GST Reg. No. M2-0001676-9

A FAIRFAX Company

MOTOR SURVEY ASSIGNMENT

Date

16-01-2018

Our Ref No. D18000412MFSH

Accident Date

16-01-2018

Claim Type. Third Party

Insured Vehicle

SHB4880U

Third Party Vehicle. SHD1012T

Survey Location

23 CHANGI SOUTH AVENUE 2 #03-02

Contact Person.

GARY SHI

Contact No.

62148880/65446671

Fax No. 62141511

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

PREMIER AUTOMOTIVE

SERVICES PTE LTD

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

LURENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

lob Sheet (/C	ClaimWS/Surveyor/JobSheet/	233853) 🚣 PR	RI Documents 🙆	Close 💥		
			PRI Header D	etails		
Claim No	D18000412MFSH	Policy No	D-18088937MFS	н	Claimant S.No & Name	1 & PREMIER LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GARY SHI)	Survey Location & Contact Details	23 CHANGI SOU Mobile: 654466 EmailId: GARY.S	71 , Phone	: 62148880 ,	
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJU	DICE: WE	ADMIT LIABIL	ITY QUANTUM
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB4880U		TP Vehicle No	SHD1012T
PRI Recieved Date	17-01-2018 03:59:01 PM	Surveyor Appointed Date	18-01-2018 03:4	13:40 PM	Surveyor Accept Date	18-01-2018
			Survey Report	Upload		
Surveyor Inspection Date *:		Surveyor Report Date	18-01-2018		Upload Survey Report *:	Choose File
			Vehicle Partic	ulars		J
Make	Please Select Make ▼	Model	Please Select M	odel 🔻	Year	Select Year
Chasis No		Engine No			Mileage	
Color		Cubic Capacity				
Multiple D	ocuments Upload					
		Upload Multiple	e Documents			
File Nar	me				Action	

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 19 January 2018 3:08 PM

To:

'Claim Workflow System'; assignments

Cc:

CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR

Subject:

RE: SURVEY ASSESSMENT - D18000412MFSH/1

Attachments:

CSFCI18001144K1qd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SHD 1012T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 18 January 2018 3:48 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR

<sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18000412MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 18 January 2018 3:43 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18000412MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards, Admin Team

Claim Workflow System



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18000412MFSH

Date: 19 January 2018

Our Ref: CS/FCI18001144/K1qd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1012T .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/01/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$	2,194.40	
Revised Estimate Amount	: S\$	1,224.40	
"Check" Items Amount	: <u>S\$</u>	•	
Market Value	: <u>S\$</u>	0 = 3	
LTA Reimbursement Value	: <u>S\$</u>		
Nett Value	: <u>S\$</u>	-	

Description of Damage:

<u>The vehicle sustained damages</u>
at the n/s rear portion.



Yours faithfully

Kalvin Ang Automotive Assessor

Page 1 of 2

Text size +

Enquire Transaction History

Transaction History Details

Log Date/Time:

21 Jan 2016 / 08:45:11

Receipt No .:

AACCK001-AX239-160121-000007

Asset Type:

Vehicle

Transaction Amount:

\$68,642.00

Asset ID:

SHD1012T

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

Business Transaction

01.02 Register New Vehicle (AA)

Reference No.:

20160121084511408533

Vehicle No.:

SHD1012T

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1: Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 21 Jan 2016

Original Registration

Date:

21 Jan 2016 KIA

Vehicle Make:

OPTIMA 1.7(A) DIESEL

Vehicle Model: Chassis No .:

KNAGM414MF5658689

Engine No.:

D4FDFH314468

Motor No.:

Trailer Chassis No.:

Diesel

Propellant: Passenger Capacity:

4

Engine Capacity:

1685

Power Rating:

Unladen Weight:

1584

Maximum Laden Weight:

2050 Silver

Primary Color:

Secondary Color: Manufacturing Year:

2015

Open Market Value:

\$22,282.00

Minimum PARF Benefit: \$13,917.00

PARF Eligibility:

Y

No. of Transfer.

Effective Ownership

Date/Time:

21 Jan 2016 08:45:11

COE No .:

Amount:

2016012101003555R

COE Expiry Date:

20 Jan 2024

COE Bid Category:

Actual QP/PQP Paid

\$45,307.00

Lifespan Expiry Date:

20 Jan 2024

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

16-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1012 T

1 pc	Rear n/s wheel cover / hwyd	\$ 116.00
. 60		\$ 116.00
	Less 10%	\$ 11.60
		\$ 104.40
S/NETT		
1 pc	Rear n/s fender sticker	\$ 60.00
1 set	n/s door sticker	\$ 100.00
	Sundry nu	\$ 50.00 20
	To check wheel alignment	\$ 50.00 20 80.00 Xm
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door, rear n/s fender, rear bumper, n/s rocker panel garnish	\$ 7,50.00 Koo
	To putty and spray painting on the rear n/s door, rear n/s fender, rear tumper, n/s rocker panel garnish.	\$ 900.00 5 % 150.00 × 1
	To apply rustproofing on the repaired and replaced panels.	\$ 150.00 201
		\$ 2,194.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalux (CKK) 18/1/8 1625hs. 2 Dys PIP Ather Repair photo

LKK Auto Cree enter notify the Repairer wing:

To resurvey tell elan any painting To display damaged part s) during resurvey · Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No degal modification(s) is allowed

 Supplementary demist must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	ationale Des Experts En Auton	nobile
IRS	CAPITAL INSUF	RANCE LTD	Ref : CS/FCI1800114	44/K1qd3n2
36 R(#16-0	OBINSON ROAD 11 CITY HOUSESI	NGAPORE 068877	Date: 30-01-2018 Code: FCI2	
	HEALTH LINE	Policy Particula	rs :- THIRD PARTY CLA	IM
	Insured Veh.	SHB 4880U	Veh. Inspected	SHD 1012T
	Policy No.	D-18088937MFSH	Coverage (\$)	0.00
	Claim No.	D18000412MFSH	Excess (\$)	0.00
	Assign From	LURENE	Assign Date	18/01/2018
2.		Vehicle Pa	rticulars & Condition	
	Make & Model	KIA OPTIMA	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KNAGM414MF5658689	Colour	SILVER
	Odometer	221094	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	205/65 R16	MAXXIS	7 mm
	L/H Front Tyre	205/65 R16	MAXXIS	7 mm
	R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
	L/H Rear Tyre	205/65 R16	MAXXIS	7 mm
4.			iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	N/S REAR PORTION.	
5.	DANNAGES GEE D		eral Information	是大量的图案 1.40°
	Accident Date	16/01/2018	Inspection Date	18/01/2018
	Survey held at	PREMIER AUTOMOTIVE S		
			JE 2 #01-02 SINGAPORE 48	6443
5a.			Remarks	
	BITHE INSPECTI	NSISTENT TO ACCIDENT RE ON WAS CONDUCTED ON A CE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BA	SIS. ISED REPAIRS.
5b.		Estim	nate Days of Repair	
	ESTIMATED NOF	RMAL PERIOD FOR REPAIR:	2 Working Da	ays



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1012T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			744.5700
1	REAR N/S WHEEL COVER	GRAZED	116.00	116.00
	LESS 10% DISCOUNT		-11.60	-11.60
			104.40	104.40
	SPECIAL NETT ITEMS			
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SET N/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
	8-42 5 to 16-44 145 c 1 1 1 2 C 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		210.00	180.00
	LABOUR			
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	10
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE REAR N/S DOOR, REAR N/S FENDER, REAR BUMPER, N/S ROCKER PANEL GARNISH.		750.00	400.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR N/S DOOR, REAR N/S FENDER, REAR BUMPER, N/S ROCKER PANEL GARNISH.		900.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	150.00	6-
	TO CENTROL MEDIAN PRESIDENCIA PRODUCTION CONTROL CONTR		1,880.00	940.00
	GRAND TOTAL		2,194.40	1,224.40

RECOMMENDED COST OF REPAIRS	1,224.40

Report Ref No. CS/FCI18001144/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.