

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJP3500B
TP/EO

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433
ATTN: Motor Claim Department

FAX: 62243903

WS Ref: TP-EQ
Claim Type: Third Party
Accident Date: 10/01/2018
TP Veh Reg No: SKD5405G

Claim No: ES1890039
Estimate No: ES1890039/WS
Date: 16 Jan 2018
Policy No: PNPV2017-00007731
Veh Reg No: SJP3500B
Make/Model: NISSAN QASHQAI 2.0
CVT ABS
Chassis No: SJNFBAJ11U1752068
Engine No: MR20425629W
Reg. Date: 30/09/2016

Estimate Repair Cost to Vehicle No : SJP3500B

Pages: 1/1

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 REAR BUMPER	420.00	1 PC	420.00 ✓	
2 REAR BUMPER REINFORCEMENT	280.00	1 PC	280.00 ✓	
3 REAR BUMPER CLIPS	4.00	6 PCS	24.00 ✓	
4 REAR PANEL	260.00	1 PC	260.00 ✓	
5 TAILGATE INNER LOCK	115.00	1 PC	115.00 ✓	
6 TAILGATE INNER LOCK SWITCH	90.00	1 PC	90.00 ✓	
7 TAILGATE INNER RUBBER	95.00	1 PC	95.00 ✓	
8 TAILGATE LOGO	38.00	1 PC	38.00 ✓	
9 TAILGATE EMBLEM (QASHQAI)	35.00	1 PC	35.00 ✓	
10 TAILGATE EMBLEM	34.00	1 PC	34.00 ✓	
			1,391.00	
	Add 20%		278.20	1,669.20
Special Net				
11 REVERSE SENSOR (4 PCS)	280.00	1 SET	280.00 ✓	280.00
Labour				
12 PANEL BEATING	700.00	1 LA	700.00 ✓	
13 PUTTY AND RESPRAY	700.00	1 LA	700.00 ✓	
14 RUSTPROOFING	30.00	1 LA	30.00 ✓	
				1,430.00

Total S\$ 3,379.20

Add GST @ 7% 236.54

Total Amount payable S\$ 3,615.74

LKK Auto Consultants hence notify
the Repairer of the following: For Cheng Hoe Motor Pte Ltd

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AUTHORISED SIGNATURE

Acknowledged by Repairer

Signature: