

ASSIGNMENT (Office)
CWS Kenneth
From (Person): Aung Yin Ming of FCI Date/Time: 18/01/18 @ 2:46pm
Estimated Cost: Bill to:
OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS
To Inspect Vehicle No: PA 5383S Insured: SHC0805J
at Workshop m/s: Cheng Hoe Motor Tel: 67556142
of: BLK 1019, Yishun Ind. Park A #01-374
Policy No: D-1507770ymfsh Claim No: D17011392MFSH
Sum Insured: Excess:
Make of Veh: D.O.A. 08/12/2017
(Client's Record)
CA / REV / REP. / REV 24 HRS 'wp'
Date/Time: 4:18pm @ 18/1/18 Person Contacted: Sharon Vehicle: D17011392MFSH

Date/Time: Action/Instruction: ✓ PA 5383S - Y
SHC0805J - CC4 / AXA17003716/Rlwg3s2 D.O.A. 21/02/2017
7/3/18 @ 4.13pm Informed Aung Yin Ming, we are pending estimate from repairer.

F15 L1Ry 830501 Car former Eke (Red @ 1484.79, 33%)

ASS. REC. BY:

REF:

F021

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

5/20

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PA 53835 Yr Regn: 05, 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Regius c.c. 2494

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 298134 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 1CD11200 0012496

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or 0117R

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 8/12/17

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 24/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13 Pm pass to Cct home, ch not ready

RECEIVED 07 MAY 2018

Date/Time, File Pass to?

1) 07/5/18 : Prel. Report

Date/Time, File Return to? : Final Report

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format: TP

Lump Sum / I.B.I. (\$ 3050)

135
50
50+50
23
308



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001150/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 805J	Veh. Inspected	PA 5383S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17011392MFSH	Excess (\$)	0.00	
Assign From	CWS (AUNG YIN MING)	Assign Date	18/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/12/2017	Inspection Date		
Survey held at	CHENG HOE MOTOR SERVICE BLK 1019, YISHUN INDUSTRIAL PARK A #01-374 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	11-12-2017	Our Ref No. D17011392MFSH
Accident Date	08-12-2017	Claim Type. Third Party
Insured Vehicle	SHC0805J	Third Party Vehicle. PA5383S
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231715)



PRI Documents



Close



PRI Header Details

Claim No	D17011392MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & CHENG H
Workshop Name	CHENG HOE MOTOR PTE LTD (Contact Person : JUNE)	Survey Location & Contact Details	BLK 1019 YISHUN IND. PARK A #01-374 Mobile: 0 , Phone: 67556142 , Fax: 67557719 EmailId: CHMOTOR@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0805J	TP Vehicle No	PA5383S
PRI Recieved Date	17-01-2018 09:52:23 PM	Surveyor Appointed Date	18-01-2018 02:45:38 PM	Surveyor Accept Date	18-01-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-01-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 27 March 2018 4:13 PM
To: 'Claim Workflow System'; assignments
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011392MFSH/1

Dear Yin Min,

Please be informed that we have inspected the vehicle PA 5383S on 24/03/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 18 January 2018 4:51 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011392MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 18 January 2018 2:45 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011392MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9482G
Vehicle Details	
Vehicle No.:	PA5383S
Vehicle to be Exported:	Yes
Intended De-registration Date:	15 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	REGIUS 2.5 A
Primary Colour:	White
Manufacturing Year:	2005
Engine No.:	2KD1240360
Chassis No.:	KDH2000012496
Maximum Power Output:	-
Open Market Value:	\$33,200.00
Original Registration Date:	19 May 2005
First Registration Date:	19 May 2005
Transfer Count:	1
Actual ARF Paid:	\$1,660.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 May 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$28,234.00
COE Rebate Amount:	\$13,221.00
Total Rebate Amount:	\$13,221.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 15 Jan 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

PA53838
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 08/12/2017

TP Veh Reg No: SHC805J

Estimate No: ES1890312/YISHUN

Date: 24 Mar 2018

Policy No: 8-V0000247-MVA-R009

Veh Reg No: PA5383S

Make/Model: TOYOTA REGIUS 2.5 A

Chassis No: KDH2000012496

Engine No: 2KD1240360

Reg. Date: 19/05/2005

Estimate Repair Cost to Vehicle No :PA5383S

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	396.96	1 PC	396.96	✓
2 REAR BUMPER CENTRE STEP PANEL	299.80	1 PC	299.80	✓
3 REAR END PANEL OUTER	294.70	1 PC	294.70	✓
4 REAR TAILGATE	1,921.90	1 PC	1,921.90	✓
5 TAILGATE LOGO	56.94	1 PC	56.94	✓
6 TAILGATE INNER LOCK	265.13	1 PC	265.13	✓
7 TAILGATE INNER RUBBER	391.20	1 PC	391.20	✓
8 TAILLAMP RH	291.95	1 PC	291.95	✓
9 RH TAILLAMP LOWER GARNISH	71.80	1 PC	71.80	✓
			3,990.38	
		Less 25%	997.60	2,992.79
Special Net				
10 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
11 SPEED LIMIT STICKER	10.00	1 PC	10.00	✓
12 TAILGATE COY LOGO STICKER	12.00	1 PC	12.00	✓
			62.00	62.00
Labour				
13 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
14 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, TO CUT, WELD & RENEW REAR PANEL OUTER, KNOCK & REPAIR REAR END PANEL INNER & REALIGN THE SAME	700.00	1 LA	700.00	600
15 PUTTY & RESPRAY ON TAILGATE, REAR END PANEL & REAR AFFECTED AREAS	600.00	1 LA	600.00	520
16 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,480.00	1,480.00
			Total	S\$ 4,534.79
			Add GST @ 7%	317.44
			Total Amount Payable	S\$ 4,852.23

LKK Auto Consultants hence notify
the Repairer of the following:
* To respray before/after painting
* To display damaged part(s) during respray
* Parts prices are subject to confirmation
* Third party survey is on a "Without Prejudice" basis
* No illegal modification(s) is allowed
* Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001150/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 805J	Veh. Inspected	PA 5383S	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011392MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	18/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA REGIUS	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	KDH2000012496	Colour	WHITE	
Odometer	298134	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	OHTSU	7 mm	
L/H Front Tyre	195 R15X8	OHTSU	7 mm	
R/H Rear Tyre	195 R15X8	OHTSU	7 mm	
L/H Rear Tyre	195 R15X8	OHTSU	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/12/2017	Inspection Date	24/03/2018	
Survey held at	CHENG HOE MOTOR SERVICE BLK 1019, YISHUN INDUSTRIAL PARK A #01-374 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 5383S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	396.96	396.96
1	REAR BUMPER CENTRE STEP PANEL	MTG CRACKED	299.80	299.80
1	REAR END PANEL OUTER	BENT	294.70	294.70
1	REAR TAILGATE	BENT	1,921.90	1,921.90
1	TAILGATE LOGO	NECESSARY	56.94	56.94
1	TAILGATE INNER LOCK	TO REPAIR SEE LABOUR	265.13	-
1	TAILGATE INNER RUBBER	SERVICEABLE	391.20	-
1	TAILLAMP RH	CRACKED	291.95	291.95
1	RH TAILLAMP LOWER GARNISH	BUCKLED	71.80	71.80
	LESS 25% DISCOUNT		-997.59	-833.51
			2,992.79	2,500.54
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN GLASS GUM (SN)	NECESSARY	40.00	40.00
1	SPEED LIMIT STICKER (SN)	NECESSARY	10.00	10.00
1	TAILGATE COY LOGO STICKER (SN)	NECESSARY	12.00	12.00
			62.00	62.00
LABOUR				
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		120.00	120.00
	REMOVE AND REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, TO CUT, WELD & RENEW REAR PANEL OUTER, KNOCK & REPAIR REAR END PANEL INNER & REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF TAILGATE INNER LOCK.		700.00	600.00
	PUTTY & RESPRAY ON TAILGATE, REAR END PANEL & REAR AFFECTED AREAS.		600.00	520.00
	RUSTPROOFING.		60.00	60.00
			1,480.00	1,300.00
GRAND TOTAL			4,534.79	3,862.54
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,050.00

Report Ref No. CS/FCI18001150/Kqd3n2



Report Ref No. CS/FCI18001150/Kqd3n2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.