

fax on 04/10/18 @ 1530

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 26 January 2018

To : LKK

Attn : Rasul

By Fax: 6256-4315

Tel: 90010068

VEHICLE NO : JSB 5231

Yamaha FZ 150I

ACCIDENT DATE: 10 January 2018

Description	Qty	Quotation \$
1 Handle Bar	1	195.00 X 1
2 Brake Lever	1	85.00 sc /
3 Mirror	1	90.00 sc /
4 Front Mudguard	1	135.00 repair
5 Front Signal	1	75.00 sc /
6 Brake Disc	1	265.00 X 2 sc
7 Fork Tube	1 set	480.00 X 2 sc
8 Exhaust Cover	1	195.00 sc /
9 Footrest RH	1	75.00 sc /
10 Balancer	1	95.00 sc /

Sub-Total 1,690.00 540
Less 10% 169.00 102
Sub-Total 1,521.00 486

Nett items

- 1 Rear box
- 2 Touch up paint scratches
- 3 Labour for dismantle & fix up
- 4 Labour for fork & top up fork oil

350.00 150 sc /
350.00 150
250.00 150
230.00 X 2 sc 450

Sub-Total 1,180.00
Nett Total 2,701.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: