

REF: CS/LAW18001153 /RINbez

Special Instruction:

L/S: \$ 10700-00

Third Parties:

Claimant:

Surveyor: Constant Appraiser

Workshop: Mega Auto

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJE 8075L Insured: JDB 931D

at Workshop m/s Mega Auto Tel: 6345 5884

of Blk 10 Sin Ming Ind Est # 01-04

Policy No: DP. SG. 8006.13.MEGA Claim No: CLS.2017.213860

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21-05-2013

(Client's Record) _____ D.O.A. 21-09-2013

30. 01. 2018 (Tuesday) @ 10am

STL

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 11/12/12 Confirmed with Final Fig , days (Red \$ / %; Original 6 days)

Date/Time: 2/3/18 Submit Final Fig LS 4600, 6 days (Red \$ 600 / 57 %; Original days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 1940

Para(3) : Nett Value

Market Value :

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1000

1) Date/Time 21/3- typist File Pass to

2) Date/Time

File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time

File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time

File Return to




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
COMLAW LLC*		Ref : CS/LAW18001155/vb	
64 CECIL ST #06-01 IOB BLDG SINGAPORE 049711		Date : 18-01-2018	
		Code : L050	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.		Veh. Inspected	SJE 8075L
Policy No.	DP.sa.8006.13.MEGA	Coverage (\$)	0.00
Claim No.	CLS.2017.213860	Excess (\$)	0.00
Assign From	CHUA LI SUAN	Assign Date	18/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/05/2013	Inspection Date	30/01/2018
Survey held at	MEGA AUTO PTE LTD BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-04 SINGAPORE 575645		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 24271

Vehicle Details

Vehicle No.: SJE8075L
Vehicle to be Exported: No
Intended De-registration Date: 21 Mar 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA AXIO 1.5X A
Primary Colour: Beige
Manufacturing Year: 2008
Engine No.: 1NZD001460
Chassis No.: NZE1416077009
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$12,310.00
Original Registration Date: 08 May 2008
First Registration Date: 08 May 2008
Transfer Count: 0
Actual ARF Paid: \$12,310.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 May 2018
PARF Rebate Amount: \$6,155.00

Intended COE Rebate Details

COE Expiry Date: 07 May 2018
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$11,009.00
COE Rebate Amount: \$139.00
Total Rebate Amount: \$6,294.00

The information contained herein is correct as at 21 Mar 2018

OK

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999



T/20130521/4116

3rd party

1 of 3

Report No. T/20130521/4116

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/05/2013 17:58			Vide Report No.:		Station Diary No.: 9
Informant's Particulars					
Name of Informant: Md Don Bin Brau			Address: 26 kampung teluk iskandar sri pantai 86800 mersing johor		
ID Type / ID No.: NEW MALAYSIAN IC / 611202016493			Contact No.: Home/Office: Mobile/Pager: 0167055436		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 52	Date of Birth: 02/12/1961	Type of Informant: Driver		
Race: Malay			Language:	Institution / School Name:	
Occupation: Driver			Driving Licence Information: Class: Date of Expiry: 31/03/2014		

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 21/05/2013 05:10	Type of Location: Straight Road
Location: Along Road 1 WOODLANDS CHECKPOINT near traffic lights towards city				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved									
Vehicle No.	Type	Make	Color	Condition	No of Passenger	Insurance Company	Insurance No.	Effective Date	Expiry Date
JDB9310	Bus	MERCEDES BENZ	blue	No Damage	20				
SJES075L	Car	TOYOTA	gold	Slightly Damaged	0				

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999



T/20130521/4116

2 of 3

Report No. T/20130521/4116

CONTINUATION OF REPORT

Brief Details.

On 21/05/2013 @ 0510 hrs , I was driving a bus from woodlands checkpoint with passengers on board. After leaving the checkpoint , I wanted to stop at the traffic lights. I noticed a car was already waiting at the traffic lights. I stepped on my brake , however stop too close to the car and hit onto the rear part of the car. There is no damage to my bus. That's all.

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999



T/20130521/4116

3 of 3


Report No. T/20130521/4116


CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  ISMAIL Signature : _____	
Singapore Police Force Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / Contact No.:	

Signature Of Informant: 
Date: 21/05/2013 17:58
Classification Of Case:

Authentication Stamp
NP168

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/05/2013 11:37
Date Of Accident	21/05/2013 05:10
Exact Location Of Accident	AFTER WOODLANDS CHECKPOINT AT TRAFFIC LIGHT

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE8075L
Insured/Policyholder	
Name Of Registered Owner	ABDUL RAHMAN BIN BAKAR
NRIC No	S1392427I
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA AXIO 1.5X A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
Insurance Company	
Name of Insurance Company	Liberty Insurance Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SI13V04963/VPE/R05
Cover Note Number	08/05/13-07/05/14
Driver	
Name of Driver	ABDUL RAHMAN BIN BAKAR
NRIC No	S1392427I
Date Of Birth	28/06/1959
Occupation	Outdoor
Date Of Driving Pass	10/10/1980
Driving Experience	32 Years And 7 Months
Gender	Male
Mobile Number	(Local) +65-90037137
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL
Address	BLK 659 WOODLANDS RING ROAD #04-172
Postcode	730659
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident Collision- Head to Rear (TP Hit Insured)
Weather Conditions Clear
Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? Yes
Foreign Vehicle Registration Number JDB9310 (Bus)
Was any body injured in the Accident? No
Was any other material or property damaged? Yes
Was there any video captured by Car Camera? No

Details of Police Action

Was the accident reported to the police? Yes
If Yes, Please state which Police Station

Police Station Name Woodlands East N.p.c
Police Station Address ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: Singapore
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? No
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH SKETCH PLAN AND POLICE REPORT

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number JDB9310
Vehicle Make/Model/Colour MERCEDES BENZ/BUS/BLUE
Details Of Properties VEH B
Name of Driver MD DON BIN BRAU
NRIC/Passport Number 611202016493
Contact Number 0167055436
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

Sketch Plan Pg.1

SIGTE 13 P. 40

IMPORTANT NOTICE

1. Please report correctly the details of the accident in regard to the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misstatements or omissions of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.

Sketch Plan

CAR A (ΣJE 3075L)
CAR B (TDB 9310)

FOIA b7D - DISCLOSURE OF INFORMATION

CLASS

25-10-1947

Describe Circumstances of the Accident

PLEASE REFER TO THE POLICE REPORT. T/SW/30521/4008

Declaration

USN declare the foregoing particulars are true in every respect.

Policeholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Repeating Centre Personnel

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20130521/4008

1 of 3

Report No. T/20130521/4008

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/05/2013 05:46			Vide Report No.:		Station Diary No.: 17
Informant's Particulars					
Name of Informant: ABDUL RAHMAN BIN BAKAR			Address: APT BLK 659 WOODLANDS RING ROAD #04-172 SINGAPORE 730659		
ID Type / ID No.: NRIC NO / S1392427I			Contact No.: Home/Office: Mobile/Pager: 90037137		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 54	Date of Birth: 28/06/1959	Type of Informant: Driver		
Race: Malay			Language:	Institution / School Name:	
Occupation: Driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 21/05/2013 05:10	Type of Location: Traffic light stop
Location: Along Road 1 WOODLANDS CHECKPOINT At traffic light towards Woodlands Checkpoint				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved									
Vehicle No.	Type	Make	Color	Condition	No. of Passenger	Insurance Company	Insurance No.	Effective Date	Expiry Date
JDB9310	Bus	MERCEDES BENZ	Blue	Slightly Damaged	20				
SJE8075L	Car	TOYOTA	Champaign	Seriously Damaged	0				

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20130521/4008

2 of 3

Report No. T/20130521/4008

CONTINUATION OF REPORT

Brief Details.

On the 21/05/2013 at about 0510hrs, I was driving to work and as I drove past the Woodlands Checkpoint, I approached the traffic light, there were 04 cars in front when the traffic light turns red. Thus I had applied brake and put my car to a complete stop behind the car in front. Out of a sudden I felt a huge impact on the rear portion of my car. I did not suffer any injury and I went out of my car to make a check on my car. I noticed that JDB9310 had hit onto the rear portion of my car causing the rear bumper and the boot of my car to be dented. There were some scratches on the front bumper of the JDB9310. The driver MD DON BIN BRAU 611202-01-6493 HP: 016 7055436 had came down after making a check with all his passengers. The driver MD DON and I exchanged particulars and we then proceed to the nearest Police station to make a Police report. At the point of time of the accident, no TP or AB were at scene.

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20130521/4008

3 of 3

Report No. T/20130521/4008

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
J /
FUNG ZHENG KANG

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP /
Contact No.:

Signature Of Informant:

Date:
21/05/2013 05:46

Classification Of Case:

Authentication Stamp

NP168	SN 130
	Signature: _____
Signature of Police Officer	

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Abdul Rahman Bin Bakar
Blk 659 Woodlands Ring Road
#04-172
Singapore 730659

Date : 04/06/2013

Reference No : CAS/13-06/007

General Information

Registration No. : STE 8075L
Accident Date : 21/05/2013

Particulars of Damaged Vehicle

Colour	: Gold	Make & Model	: Toyota Corolla Axio 1.5X A
Engine Capacity	: 1496 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 96438	Engine No.	: 1NZD001460
Chassis No.	: NZE1416077009	Steering	: In Order
Registration Date	: 08/05/2008	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	195/60R15	Sumitomo	90%
L/H Front Tyre	195/60R15	Sumitomo	90%
R/H Rear Tyre	195/60R15	Bridgestone	70%
L/H Rear Tyre	195/60R15	Dunlop	70%

Inspection

Repairer : Mega Auto Pte Ltd
Blk 10, Sin Min Ind. Est. Sector C, #01-04, Singapore 575645

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$15,318.77
Revised Amount : \$10,700.00
Less Excess : -
Nett Total : \$10,700.00

Remarks

- (A) Survey was done on 29/05/2013
- (B) Re-survey was done on 29/05/2013
- (C) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (D) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Catherine Chong (LKK Auto)

From: Chua Li Suan <cls@comlaw.com.sg>
Sent: Thursday, 18 January, 2018 3:53 PM
To: assignments
Cc: law@dpco.com.sg
Subject: RE-INSPECTION OF SJE 8075L by you as the SJE ACCIDENT ON 21.5.2013 INV SJE 8075L & JDB 9310 AT WOODLANDS CHECKPOINT MC 566/2017 (OUR REF: CLS.2017.213860)(Daniel Poon Ref: DP.sa.8006.13.MEGA)
Attachments: INSPECTION REPORT.PDF; COLOUR PHOTOS.PDF; REPAIR BILL.PDF; TRAFFIC ACCIDENT REPORT OF JDB 9310.pdf; SINGAPORE ACCIDENT STATEMENT OF SJE 807L.PDF

Dear Sirs

1. We act for MPI Generali Insurans Berhad, the insurers of JDB 9310 which was involved in a road accident on 21 May 2013. Our clients are facing a claim by the owner of SJE 8075L (represented by Daniel Poon & Co - copied on this email) for repair costs and loss of use.
2. Both parties have agreed to jointly appoint your surveyor to be the SINGLE JOINT EXPERT (SJE) in this case.
3. We refer to our Ms Rohana's telephone conversation with your Ms Vernis on 18 January 2018 and confirm that an appointment has been fixed for your surveyor to re-inspect the above vehicle on Tuesday, 30 January 2018 at 10.00 am at the Plaintiff's residential premises at Blk 783C Woodlands Rise, #10-11 Singapore 733783 (contact person is the Plaintiff Mr Abdul Rahman at 90037137).
4. We attach herewith copies of the following documents for your consideration in putting up your report :-
 - a. Inspection report of Constant Appraiser Services dated 4 June 2013 and 17 pages colour copied photographs of SJE 8075L.
 - b. Repair Bill of Mega Auto Pte Ltd dated 14 June 2013.
 - c. Police report of driver JDB 9310.
 - d. Accident Statement of driver SJE 8075L.
5. We shall be obliged if you will carry out the re-inspection of SJE 8075L and let both parties us have your SJE report as soon as possible.

Warm regards
Ms Chua Li Suan
DID: 6506 9132

ComLaw LLC
64 Cecil St #06-01
IOB Building
Singapore 049711

Constant Appraiser Services

Vehicle No : SJE 8075L

Our ref : CAS/13-06/007

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
		<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1pc	Rear bumper	Broken	1,685.95	1,685.95	900
2	2pcs	Rear bumper side retainer @ \$193.80 ^{78.50}	Broken	387.60	387.60	157
3	2pcs	Rear bumper bracket @ \$168.50 ^{88.00}	Dented/Bent	337.00	337.00	176
4	2pcs	Taillamp assy @ \$552.00 ^{464.50}	Cracked/Broken	1,104.00	1,104.00	929
5	2pcs	Taillamp lower bracket @ \$61.80	Broken	123.60	123.60	
6	1pc	Bootlid	Dented/Buckled	1,593.00	1,593.00	800
7	1pc	Bootlid inner lock	Bent/Jammed	385.15	385.15	142
8	1pc	Bootlid inner lock catch	Bent	69.80	69.80	
9	1pc	Bootlid rubber	Torn	311.50	311.50	189
10	2pcs	Bootlid hinge @ \$169.20	Bent	338.40	338.40	SVC
11	1pc	Bootlid emblem	Necessary	59.90	59.90	
12	1pc	Bootlid 'Axio' badge	Necessary	68.50	68.50	
13	1pc	Bootlid 'X' badge	Necessary	58.00	58.00	
14	2pcs	Rear number plate lamp @ \$52.30	Serviceable	104.60	-	
15	1pc	Bootlid outer garnish	Broken	328.30	328.30	289
16	1pc	Rear end panel	Dented	795.85	795.85	494.80
17	1pc	Rear end panel top garnish	Deformed	405.50	405.50	218.80
18	2pcs	Taillamp panel @ \$353.60	Dented	707.20	707.20	R
19	1pc	Rear fender RH	Repair	965.90	-	
20	2pcs	Rear fender inner shield @ \$93.10	O/S Torn	186.20	93.10	SVC
21	2pcs	Rear fender air vent @ \$97.40	Serviceable	194.80	-	
22	2pcs	Rear fender inner trim @ \$478.45	Deformed	956.90	956.90	SVC
23	1pc	Spare tyre cover	Dented/Broken	514.15	514.15	SVC
24	1pc	Spare tool tray	Serviceable	135.60	-	
25	1pc	Spare tyre panel	Dented/Buckled	1,160.25	1,160.25	SVC
26	1pc	Rear exhaust silencer	Bent	1,092.10	1,092.10	SVC
27	2pcs	Rear exhaust mounting @ \$60.30	Distorted	120.60	120.60	SVC
				14,190.35	12,696.35	4482.00
		Less 25%		(3,547.58)	(3,174.08)	25%
		Sub total		10,642.77	9,522.27	3361.50

Constant Appraiser Services

Vehicle No : SJE 8075L

Our ref : CAS/13-06/007

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1pc	Rear number plate	Twisted	60.00	60.00 X
2	1set	Rear bumper clip	Necessary	45.00	45.00
3	1set	Rear end panel top garnish clip	Necessary	25.00	25.00
4	2sets	Rear fender inner trim clip @ \$48.00	Necessary	96.00	96.00
5	1set	Reverse sensor	Damaged	300.00	300.00 200
6	2sets	Rear fender inner shield clip @ \$40.00	O/S Necessary	80.00	40.00
7	1pc	Rear windscreen sealant	Not Necessary	60.00	- 406
Sub total				11,308.77	10,088.27
<u>LABOUR & MISC. CHARGES</u>					
1		Repair accident damages & replace above parts		1,600.00	1,400.00 800
2		Remove & renew rear exhaust silencer		150.00	80.00 X
3		Remove out interior upholstery to facilitate repair		180.00	120.00 60
4		Respray paintwork on accident affected portions		1,800.00	1,500.00 900
5		Check electrical wiring		100.00	60.00 30
6		Rust proofing on accident affected portions		180.00	120.00 80
Grand total				15,318.77	13,368.27
Recommended cost of lump sum repair (To its pre-accident condition)					10,700.00 1870

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$10,700.00 on a contractual basis. Under normal circumstances, the repair period would be about 6 (Six) working days.

Yours faithfully,
Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

3361.50
406.00
1870.00
5637.50

202
4510.00

413 - 4,500
6 days

MEGA AUTO PTE LTD
Business Reg. No. 200209020W
355 East Coast Road
Singapore 428972
Tel: 6345 5884

TAX INVOICE

Bill To
Abdul Rahman Bin
Bakar

Service Details
Vehicle No. : SJE8075L
Vehicle Make : Toyota Axio

Invoice Date : 14-Jun-13
Invoice No : P13-70031
GST REG NO : 20-0209020-W
TP Claim Ref : TP/13-0799

Blk 659 Woodlands Ring Road
#04-172
Singapore 730659

Item No	Description	Quantity	Unit Price	Amount
1	Being parts and labour supplied to the above-mentioned vehicle as per surveyor report Constant Appraiser Services Invoice no. IV13-06007/CAS dated 04/06/2013	1		\$10,700.00
Remarks Accident on 21 May 2013 at after Woodlands Checkpoint at Traffic Light			Sub Total	\$10,700.00
			GST 7%	\$749.00
			Amount Due	\$11,449.00

for Mega Auto Pte Ltd



CUSTOMER SIGNATURE

I have inspected and hereby confirmed that
the job done and the amount due herein are
entirely to my satisfaction.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
COMLAW LLC*		Ref : CS/LAW18001155/R1vbe2		
64 CECIL ST #06-01 IOB BLDG SINGAPORE 049711		Date : 22-03-2018		
		Code : L050		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	JDB 9310	Veh. Inspected	SJE 8075L	
Policy No.	DP.sa.8006.13.MEGA	Coverage (\$)	0.00	
Claim No.	CLS.2017.213860	Excess (\$)	0.00	
Assign From	CHUA LI SUAN	Assign Date	18/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA AXIO 1.5X A	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NZE1416077009	Colour	GOLD	
Odometer	221572	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	MICHELIN	5 mm	
L/H Front Tyre	195/60 R15	MICHELIN	5 mm	
R/H Rear Tyre	195/60 R15	MICHELIN	5 mm	
L/H Rear Tyre	195/60 R15	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	21/05/2013	Inspection Date	30/01/2018	
Survey held at	BLK 783C WOODLANDS RISE#10-11 SINGAPORE733783			
Repairer	MEGA AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 8075L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	REPLACED	1,685.95	900.00
2	REAR BUMPER SIDE RETAINER @\$193.80	REPLACED	387.60	157.00
2	REAR BUMPER BRACKET @\$168.50	REPLACED	337.00	176.00
2	TAILLAMP ASSY @\$552.00	REPLACED	1,104.00	929.00
2	TAILLAMP LOWER BRACKET @\$61.80	REPLACED	123.60	123.60
1	BOOTLID	REPLACED	1,593.00	800.00
1	BOOTLID INNER LOCK	REPLACED	385.15	142.00
1	BOOTLID INNER LOCK CATCH	REPLACED	69.80	69.80
1	BOOTLID RUBBER	REPLACED	311.50	189.00
2	BOOTLID HINGE @\$169.20	SERVICEABLE	338.40	-
1	BOOTLID EMBLEM	REPLACED	59.90	59.90
1	BOOTLID 'AXIO' BADGE	REPLACED	68.50	68.50
1	BOOTLID 'X' BADGE	REPLACED	58.00	58.00
2	REAR NUMBER PLATE LAMP @\$52.30	SERVICEABLE	104.60	-
1	BOOTLID OUTER GARNISH	REPLACED	328.30	289.00
1	REAR END PANEL	REPLACED	795.85	494.80
1	REAR END PANEL TOP GARNISH	REPLACED	405.50	218.80
2	TAILLAMP PANEL @\$353.60	REPAIRED SEE LABOUR	707.20	-
1	REAR FENDER RH	REPAIRED SEE LABOUR	965.90	-
2	REAR FENDER INNER SHIELD @\$93.10	SERVICEABLE	186.20	-
2	REAR FENDER AIR VENT @\$97.40	SERVICEABLE	194.80	-
2	REAR FENDER INNER TRIM @\$478.45	SERVICEABLE	956.90	-
1	SPARE TYRE COVER	SERVICEABLE	514.15	-
1	SPARE TOOL TRAY	SERVICEABLE	135.60	-
1	SPARE TYRE PANEL	SERVICEABLE	1,160.25	-
1	REAR EXHAUST SILENCER	SERVICEABLE	1,092.10	-
2	REAR EXHAUST MOUNTING @\$60.30	SERVICEABLE	120.60	-
	LESS 25% DISCOUNT		-3,547.59	-1,168.85
			10,642.76	3,506.55

Report Ref No. CS/LAW18001155/R1vbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	SERVICEABLE	60.00	-
1	SET REAR BUMPER CLIP (SN)	REPLACED	45.00	45.00
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	REPLACED	25.00	25.00
2	SETS REAR FENDER INNER TRIM CLIP @\$48.00 (SN)	REPLACED	96.00	96.00
1	SET REVERSE SENSOR (SN)	REPLACED	300.00	200.00
2	SETS REAR FENDER INNER SHIELD CLIP @\$40.00	O/S REPLACED	80.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			666.00	406.00
	LABOUR			
	REPAIR ACCIDENT DAMAGES & REPLACE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL AND REAR FENDER RH.		1,600.00	800.00
	REMOVE & RENEW REAR EXHAUST SILENCER.	NOT NECESSARY	150.00	-
	REMOVE OUT INTERIOR UPHOLSTERY TO FACILITATE REPAIR.		180.00	60.00
	RESPRAY PAINTWORK ON ACCIDENT AFFECTED PORTIONS.		1,800.00	900.00
	CHECK ELECTRICAL WIRING.		100.00	30.00
	RUST PROOFING ON ACCIDENT AFFECTED PORTIONS.		180.00	80.00
			4,010.00	1,870.00
	GRAND TOTAL		15,318.76	5,782.55
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,600.00

Report Ref No. CS/LAW18001155/R1vbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.