

T & T Auto Services Pte Ltd

Blk 19 Sin Ming Industrial Estate Sector A

#01-19 Singapore 575677

Tel: 64593319 Fax: 64593019

SEAH KOK HWEI
BLK 443B FERVALE ROAD
#14-361
SINGAPORE 792443

Not Authorized
11 Sep 8 50501
Running After Paint

ESTIMATE

DATE : 18/01/2018
VEHICLE NO : SJT 7012 X
MAKE/MODEL : Toyota Altis
ACC DATE : 18/01/2018

PARTICULAR 9 days AMOUNT S\$

LIST ITEMS:				
1	1	BOOTLID		Bj 675.90 ✓
2	1	BOOTLID INNER TRIM		Sm 271.60 X
3	1	BOOTLID TOP LOCK		nu 165.60 ✓
4	1	BOOTLID LOWER LOCK		R 75.10 X
5	1	BOOTLID WEATHERSTRIP		Dis 185.60 50pin
6	2	BOOTLID REFLECTOR	MS mty: 189.20	378.40 ✓
7	1	BOOTLID OUTER GARNISH		Sm 169.20 X
8	1	BOOLTID LOGO		nu 58.45 ✓
9	1	BOOLTID EMBLEM - 1.6		nu 57.65 ✓
10	1	BOOLTID EMBLEM - COROLLA		nu 60.30 ✓
11	1	BOOTLID EMBLEM - ALTIS		nu 61.45 ✓
12	1	BOOTLID EMBLEM - LX		nu 59.45 ✓
13	1	REAR BUMPER		Bj 495.80 ✓
14	2	REAR BUMPER SIDE RETAINER - OUTER	91.50	Dis 183.00 ✓
15	2	REAR BUMPER SIDE RETAINER - INNER	90.95	Dis 181.90 ✓
16	1	REAR BUMPER SPONGE		CRM 155.80 ✓
17	2	REAR BUMPER REFLECTOR	85.60	Sm 171.20 X
18	2	REAR BUMPER BRACKET	89.45	MS Bj 178.90 ✓
19	2	REAR TAIL LAMP	381.90	CRM 763.80 ✓
20	2	REAR TAIL LAMP LOWER BRACKET	48.90	Sm 97.80 X
21	1	REAR END PANEL		Bj 495.90 ✓
22	1	REAR FLOOR PANEL		Bj 1Bn 765.90 ✓
23	1	REAR FLOOR PANEL TOP BOARD		CRM 359.90 ✓
				6,068.60
Less Discount:			25%	1,517.15
				4,551.45

SPECIAL NETT ITEMS:				
1	1	REAR NUMPER PLATE		Sm 50.00 X
2	9	BOOTLID INNER TRIM CLIP	5.00	nu 45.00 ✓
3	10	REAR BUMPER CLIP	5.00	nu 50.00 ✓
4	4	REAR TAIL LAMP CLIP	5.00	nu 20.00 ✓
5	2	REAR END PANEL TOP GARNISH CLIP	5.00	nu 10.00 ✓
6	1	REAR FLOOR PANEL INSULATOR		nu 150.00 60pin
7	1	REAR REVERSE SENSOR		Red 350.00 20pin
				675.00

CONTINUE/...

T & T Auto Services Pte Ltd

Blk 19 Sin Ming Industrial Estate Sector A

#01-19 Singapore 575677

Tel: 64593319 Fax: 64593019

SEAH KOK HWEI
BLK 443B FERNSVALE ROAD
#14-361
SINGAPORE 792443


ESTIMATE

DATE : 18/01/2018
VEHICLE NO : SJT 7012 X
MAKE/MODEL : Toyota Altis
ACC DATE : 18/01/2018

PARTICULAR	AMOUNT S\$
LABOUR CHARGES:	
1 TO CHECK WIRING	50.00 201
2 TO TUFF KOTE	250.00 901
3 TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING	150.00 801
4 TO REMOVE/REFIX REVERSE SENSOR	100.00 501
5 TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS	1,500.00 1200
6 TO SPRAY PAINTING ON AFFECTED AREA	1,500.00 1100
	<u>3,550.00</u>

GRAND TOTAL: 8,776.45

Singapore Dollars: Eight Thousand Seven Hundred And Seventy Six And Cents Forty Five Only.


T & T Auto Services Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: