

ASSIGNMENT

From: Date: 19/01/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLK 2621M

at Workshop m/s: MBM Wheelpower

of: 160 Gin Ming Ave #06-09

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Joseph

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 07 days Res: Yes or No

Lum Sum: 1.31 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Veh No: SLK 2621M / Page: 06 17

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Honda Vezel CC: 1496

Colour: M. Grey A.O. Insured / Std / NI / NA

Sp. Reading: 009663 Tr. Radio: Insured / Std / NI / NA

Eng. No:

C.No: R43 - 1244339

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: Fr: 215/60R16

R:

BS: ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 9 mm R/Bal: 9 mm

L/Bal: 9 mm L/Bal: 9 mm

D.O.A: 17/1/118 D.O.I: 19/1/118

Survey held at: ☒

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body & etc

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

22/1 File pass to Catherine

917.43.439 (RED: 4.995 48%)

Date/Time File Pass to?

☐

: Preli. Report

Date/Time File Return to?

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transporter:

Report Format:

Lump Sum / I.B.I.C.S

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Insp. \$

☐

Witness \$

TOTAL

MBM WHEELPOWER PTE LTD

Your Ref: SJQ1896S

Our Ref: SLQ2621M

To: AXA

CC


Email

Fax

Not Authorised
1.31
Penney B4 point
7 days
19/01/2018

\$5439.00

Date: 18/1/2018
From: Joseph
Fax: 62509015
Contact: 86865188
Make / Model: HONDA VEZEL 1.5X HYBRID
Chassis No.: RU31244339
Engine No.: LEB5944355
Year of Make: 2017
Accident Date: 17/1/2018



ESTIMATE FOR VEHICLE NO.: SLQ2621M

DESCRIPTION	QTY	List Price
FRONT BUMPER	1	\$ 900.00 ✓
FRONT BUMPER CLIPS @ \$5.00	10	\$ 50.00 ✓
FRONT BUMPER BRACKET RH	1	\$ 35.00 X
FRONT BUMPER LIP	1	\$ 110.00 X
FRONT RH FENDER	1	\$ 470.00 ✓
FRONT RH FENDER PROTECTOR 74105T7B000	1	\$ 50.00 X
FRONT RH FENDER "HYBRID" EMBLEM CHROME	1	\$ 65.00 ✓
FRONT RH FENDER INNERSHIELD	1	\$ 140.00 X
FRONT RH FENDER INNERSHIELD CLIPS @ \$5.00	8	\$ 40.00 X
FRONT RH WHEEL ARCH MOULDING	1	\$ 170.00 ✓
FRONT RH DOOR	1	\$ 970.00 ✓
FRONT RH DOOR WEATHERSTRIP FRT	1	\$ 45.00 ✓
FRONT RH DOOR WEATHERSTRIP TOP	1	\$ 80.00 X
FRONT RH DOOR WEATHERSTRIP LWR	1	\$ 50.00 X
FRONT RH DOOR WEATHERSTRIP RR	1	\$ 85.00 X
FRONT RH DOOR HINGE UPPER	1	\$ 60.00 X
FRONT RH DOOR HINGE LOWER	1	\$ 60.00 X
FRONT RH DOOR CHECKER	1	\$ 65.00
FRONT RH DOOR LOCK	1	\$ 290.00
FRONT RH DOOR POWER WINDOW MOTOR	1	\$ 430.00
REAR RH DOOR	1	\$ 980.00
RH ROCKER PANEL GARNISH	1	\$ 480.00 ✓
RH ROCKER PANEL GARNISH CLIPS @ \$5.00	10	\$ 50.00 ✓
REAR RH WHEEL ARCH MOULDING	1	\$ 190.00

700.00

RIM
 FRONT RH SHOCK ABSORBER X
 FRONT RH KNUCKLE ARM X
 FRONT RH KNUCKLE ARM BEARING X
 FRONT RH BALL JOINT X
 FRONT RH TIE ROD END X
 FRONT RH LOWER ARM X
 FRONT RH STABILIZER BAR
 FRONT RH STABILIZER BAR LINK X

1	\$	nd 1,080.00 ✓
1	\$	IB 380.00 X
1	\$	nn ✓ 320.00 X
1	\$	nn x 170.00 X
1	\$	sn 7 110.00 X
1	\$	sn 7 80.00 X
1	\$	sn 7 420.00 X
1	\$	sn X 220.00
1	\$	sn 7 80.00 X
Total: \$		8,725.00
Less 20% \$		(1,745.00)
Parts Total: \$		6,980.00

SPECIAL NETT
 ANTIRUST COATING
 BODY SEALANT

\$	601 150.00
\$	Not 80.00 X

LABOUR

TOWING

\$	455 80.00
----	-----------

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, STRAIGHTEN, REPAIR OF THE FRONT RH WHEEL HOUSING, REAR RH DOOR, ETC.

\$	800 1,200.00
----	--------------

TO CHECK WIRING

TO REMOVE & REFIT FRONT RH UNDERCARRIAGE ITEMS

\$	nn 120.00 X
\$	1100 1,500.00

TO SPRAY PAINTING ON THE AFFECTED AREA

Total: \$	10,110.00
7% GST: \$	707.70
Grand Total: \$	10,817.70


10434

11164.38

MBM WHEELPOWER PTE LTD

Your Ref: SJQ1896S

Our Ref: SLQ2621M



To: AXA

CC

Email

Fax

Date: 18/1/2018

From: Joseph

Fax: 62509015

Contact: 86865188

Make / Model: HONDA VEZEL 1.5X HYBRID

Chassis No.: RU31244339

Engine No.: LEB5944355

Year of Make: 2017

Accident Date: 17/1/2018

SUPPLEMENTARY FOR VEHICLE NO.: SLQ2621M

DESCRIPTION

REAR RH DOOR SEAL FRONT

FRONT RH DOOR TAPE PROTECTION

REAR RH DOOR TAPE LOWER PROTECTION

RH ROCKER PANEL GARNISH TAPE PROTECTION

QTY		List Price
1	\$	50.00
1	\$	40.00
1	\$	35.00
1	\$	30.00
	\$	155.00
Less 20%	\$	(31.00)
Parts Total:	\$	124.00

SPECIAL NETT

TYRE

1	\$	200.00
Total:	\$	324.00
7% GST:	\$	22.68
Grand Total:	\$	346.68

Mbm wheelpower pte ltd


160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t 62628888 f 62509015

Company Registration Number : 200204110W



城市拖車服務 CITY LINK TOWING SERVICE

REG NO : 52841959E
MAILING ADD : BLK 43 TEBAN GARDENS ROAD, #02-389 SINGAPORE 600043
HP : 96910664
Service in Singapore and Malaysia

Insurance
L.

Cash/W.O. No. 11958
Messers : MRM Service Date : 12/1/18
Vehicle No : S2Q 2621 M Vehicle Model : _____
Location From : 129 Whitley Rd Time Arrived : _____
Location To : Sin Ming Time Completed : _____
Order By : _____ Contact No : 90603555
Issued By : _____ Received By : _____
Remarks : _____ Tow Truck No : _____

ADDITIONAL SERVICES :

Accident	Breakdown	Jump Start	Vehicle Over Turn
Multi Story Car Park	Basement Car Park	Change Tyre & Towing	Crane Up
Using King Dolley	Use Car Carrier	Door Opening Service	Dismantle Shaft
Transport Charged	Collection Car Key	Unloading Cargo	Waiting T.P - lo
Low Bodykit & Spoiler	Loaded Cargo	Causeway	2nd Link
Day Service	Night Service	Mid-Nigh Service	Use Winch

ERP Charged \$ _____ CBD Charged \$ _____ Parking Charged \$ _____

Towing Amount \$ 55

注意：本公司對所拖之車輛，在運行中如有任何損失或破壞，一概由車主自行負責。
NOTE : Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

Order No - 5005622

MBM WHEELPOWER PTE LTD

Your Ref: SJQ1896S
Our Ref: SLQ2621M

To: AXA

CC

Email

Fax

Net Authorise
1-B1
Pinny B4 pin
7 days

Date: 18/1/2018
From: Joseph
Fax: 62509015
Contact: 86865188
Make / Model: HONDA VEZEL 1.5X HYBRID
Chassis No.: RU31244339
Engine No.: LEB5944355
Year of Make: 2017
Accident Date: 17/1/2018

ESTIMATE FOR VEHICLE NO. : SLQ2621M

DESCRIPTION	QTY	List Price
FRONT BUMPER	1	\$ 900.00 ✓
FRONT BUMPER CLIPS @ \$5.00	10	\$ 50.00 ✓
FRONT BUMPER BRACKET RH	1	\$ 35.00 X
FRONT BUMPER LIP	1	\$ 110.00 ?
FRONT RH FENDER	1	\$ 470.00 ✓
FRONT RH FENDER PROTECTOR 74105T7B000	1	\$ 50.00 ?
FRONT RH FENDER "HYBRID" EMBLEM CHROME	1	\$ 65.00 ✓
FRONT RH FENDER INNERSHIELD	1	\$ 140.00 ?
FRONT RH FENDER INNERSHIELD CLIPS @ \$5.00	8	\$ 40.00 ?
FRONT RH WHEEL ARCH MOULDING	1	\$ 170.00 ✓
FRONT RH DOOR	1	\$ 970.00 ✓
FRONT RH DOOR WEATHERSTRIP FRT	1	\$ 45.00 ?
FRONT RH DOOR WEATHERSTRIP TOP	1	\$ 80.00 ?
FRONT RH DOOR WEATHERSTRIP LWR	1	\$ 50.00 ?
FRONT RH DOOR WEATHERSTRIP RR	1	\$ 85.00 ?
FRONT RH DOOR HINGE UPPER	1	\$ 60.00 ?
FRONT RH DOOR HINGE LOWER	1	\$ 60.00 ?
FRONT RH DOOR CHECKER	1	\$ 65.00 X
FRONT RH DOOR LOCK	1	\$ 290.00 X
FRONT RH DOOR POWER WINDOW MOTOR	1	\$ 430.00 X
REAR RH DOOR	1	\$ 980.00 X
RH ROCKER PANEL GARNISH	1	\$ 480.00 ✓
RH ROCKER PANEL GARNISH CLIPS @ \$5.00	10	\$ 50.00 ✓
REAR RH WHEEL ARCH MOULDING	1	\$ 190.00 X



RIM	1	\$	✓ 1,080.00
FRONT RH SHOCK ABSORBER	1	\$	? 380 380.00
FRONT RH KNUCKLE ARM	1	\$	✓ 320.00
FRONT RH KNUCKLE ARM BEARING	1	\$	✓ 170.00
FRONT RH BALL JOINT	1	\$	? 110.00
FRONT RH TIE ROD END	1	\$	? 80.00
FRONT RH LOWER ARM	1	\$	? 420.00
FRONT RH STABILIZER BAR	1	\$	✓ X 220.00
FRONT RH STABILIZER BAR LINK	1	\$	? 80.00
Total:		\$	8,725.00
Less 20%:		\$	(1,745.00)
Parts Total:		\$	6,980.00

SPECIAL NETT

ANTIRUST COATING	\$	601 150.00
BODY SEALANT	\$	✓ X 80.00

LABOUR

TOWING	\$	501 80.00
TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, STRAIGHTEN, REPAIR OF THE FRONT RH WHEEL HOUSING, REAR RH DOOR, ETC.	\$	800 1,200.00
TO CHECK WIRING		
TO REMOVE & REFIT FRONT RH UNDERCARRIAGE ITEMS	\$	✓ 120.00
TO SPRAY PAINTING ON THE AFFECTED AREA	\$	1100 1,500.00
Total:		\$ 10,110.00
7% GST:		\$ 707.70
Grand Total:		\$ 10,817.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t 62628888 f 62509015

Company Registration Number : 200204110W



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M007DI

Our ref: CC4/ASM18001160/Kea3

Date: 23.01.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLQ 2621M


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.01.2018 at the premises of M/s MBM Wheelpower Pte Ltd - Sin Ming and have the following to report:-

Workshop Estimate Amount	: S\$	10,110.00
Revised Estimate Amount	: S\$	5,910.00
"Check" Items Amount	: S\$	1,432.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Body and U/C



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 29 January 2018 12:11 PM
To: 'Kenneth'; 'joseph.tan@mbmwheelpower.com.sg'
Cc: Vic (LKKAuto)
Subject: Your Ref: SLQ 2621M, ACCIDENT INVOLVING SLQ 2621M & SJQ 1896S ON 17/01/2018
Attachments: OI SKETCH PLAN.pdf

Without Prejudice

Your Ref: SLQ 2621M
Our Ref: CC4/ASM18001160/Kea3

Dear Sirs,

ACCIDENT INVOLVING SLQ 2621M & SJQ 1896S ON 17/01/2018

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured driver reported that your client hit our insured vehicle while she was reversing. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



MANDATE REQUEST FOR S8M007D1

Story.

Type

 Question

Message

Liability: Insured encroached into TP lane (Refer to TP video). Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$5,819.73 (w/GST) Loss of Use: \$480.00 (8days x \$60) GIA Search: \$2.00 Total: \$6,301.73 Revised Immediate Advice with Mandate and marked estimate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (29/06/2018)

Answer



Re:MANDATE REQUEST FOR S8M007D1

Type

📘 Information

Message

Pls proceed

Reply



SATISFACTION VOUCHER

Vehicle No : **SLQ2621M**

This is to certify that **MBM WHEELPOWER PTE LTD** has repaired the
abovementioned vehicle to my satisfaction and I had taken delivery at
1300 hrs on this date 29/01/18.

Owner Signature & Co. Stamp (If applicable)

We **MBM WHEELPOWER PTE LTD** hereby guarantee the workmanship of the
repairs carried out on the accident portion of your vehicle. The guarantee is valid for
a period of 6 month from the date of discharge and it is non-transferable. We will
promptly carry out any necessary rectification work.

Mbm wheelpower pte ltd
176 SIN MING DRIVE
#01-11/14/15/16
SIN MING AUTOCARE
t 66430983 f 64529823

Company Registration Number : 200204110W

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJQ 1896S (Insd veh)	Model:	HONDA
	SLQ 2621M (TP veh)		VEZEL HYBRID 1.5X AUTO
Date of Accident:	17/01/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	11,164.38
Final Repair Cost	:	\$	5,819.73
Loss of Use	:	\$	480.00
Rental (if any)	:	\$	8 days at \$60.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	6,301.73

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____ 100 ____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown			
1)	MBM WHEELPOWER PTE LTD	:	\$ 6,301.73

NUR SHAQILAH BTE ABDOL
WAHAB

29/08/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

<< Service Request Details

Claim	S8M007DI			
Reference				
CC4/ASM18001160/Kea3s2	Loss Date			
January 17, 2018	Request Date			
January 18, 2018	Due Date			
October 31, 2018	Vendor Name			
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss			
Third Party Vehicle Damage	Services			
Pending verification - Direct Settlement				
Additional Instructions				
Please interview insured and establish liability. To seek approval before settlement.				
Actions	Document Type			
Next Step	Document Sub Type			
Finish the work				
Complete Work				
Make				
Upload Documents				
Vehicle Information				
Incident Vehicle Registration #	SLO2521M			
Make	Service Address			
TPVD HONDA	Model			
VEZEL-1.5 HYBRID X (A)	Primary Contact/Insured			
CHAN LAI YING				
1 JALAN ANAK BUKIT, 588996, Singapore				
96371175				
Claim Handler				
NG Stacey				
6568804351				
stacey.ng@axa.com.sg				
Messages	Invoices	History	Documents	
Assessment	Metrics	Notes		
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED

<< Service Request Details

Claim

SBMU07DI

Reference

CC4IASM18001160Kea3s2 

Loss Date

January 17, 2018

Request Date

January 18, 2018

Due Date

October 31, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

Please interview insured and establish liability. To seek approval before settlement.

Actions

Next Step

Finish the work

Complete Work

Add

Vehicle Information

Incident Vehicle Registration #

SLQ2621M

Make

Service Address

TPVD HONDA

Model

VEZEL-1.5 HYBRID X (A)

Primary Contact/Insured

CHAN LAI YING

1 JALAN ANAK BUKIT, 588996, Singapore

96371175

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

CREATED USER

VERSION DATE

ESTIMATED AMOUNT

APPROVED AMOUNT

STATUS

SHARE

CLONE



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

[General & Workshop Details](#) [Vehicle & Driver Details](#) [Taxes & Ratio](#) [Parts & Labour](#) [Miscellaneous](#) [Summary](#)

Vehicle & Driver Details

Vehicle Registration #	SLQ2621M	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	06/30/2017
Mileage	9663	Age of Vehicle	0
Driver Details			
CATEGORY	POLICY INFORMATION	FNOL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2017	Driver Name	KUANG LIXIA
Make	TPVD HONDA	Date of Birth	December 31, 1899
Model	VEZEL-1.5 HYBRID X (A)	Age	118
Type	v	Occupation	Unknown
Type of Paint		Education Qualification	Other
Chassis No	RU31244339	Driving Experience	0
Engine No	LEB5944355	Driver License #	
Engine Capacity	1496 cc		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	01/19/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Unarmed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	215/60R16	Rear Tyre Size	215/60R16
Front left side	DUNLOP 9mm	Rear left side	DUNLOP 9mm
Front right side	DUNLOP 9mm	Rear right side	DUNLOP 9mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details										Vehicle & Driver Details					Vehicle Condition					Taxes & Ratio					Parts & Labour					Miscellaneous					Summary					Parts									
Add Approve Deny Submit All																																																	
EDIT	S/N	QUAN	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./BTR%	DISC QUNTS	SALV AGEN	PART PRICE(NET)	ACTION (PARTS)	REMOVE																																		
	1	1			FRONT BUMPER			Buckled	900		20		720	Reviewing																																			
	2	10			FRONT BUMPER CLIPS			Necessary	5		20		40	Reviewing																																			
	3	1			FRONT BUMPER BRACKET RH			Serviceable	0		20		0	Reviewing																																			
	4	1			FRONT BUMPER LIP			Serviceable	0		20		0	Reviewing																																			
	5	1			FRONT RH FENDER			Bent	470		20		376	Reviewing																																			
	6	1			FRONT RH FENDER PROTECTOR 74105T78000			Serviceable	0		20		0	Reviewing																																			
	7	1			FRONT RH FENDER "HYBRID" EMBLEM CHROME			Necessary	65		20		52	Reviewing																																			
	8	1			FRONT RH FENDER INNERSHIELD			Serviceable	0		20		0	Reviewing																																			
	9	8			FRONT RH FENDER INNERSHIELD CLIPS			Serviceable	0		20		0	Reviewing																																			
	10	1			FRONT RH WHEEL ARCH MOULDING			Denied	170		20		136	Reviewing																																			

3/4

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		7	
	2	BODY SEALANT	Reviewing	0	NOT NECESSARY	
	3	TYRE (90%)	Reviewing	180	CUT	

<< **Assessment Details**

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$5,439.00

Claim Amount \$5,439.00

CATEGORY	ESTIMATE	REVISED AMOUNT
----------	----------	----------------

Labour	\$2,015.00	\$2,015.00
--------	------------	------------

Miscellaneous	\$180.00	\$180.00
---------------	----------	----------

Spare Parts	\$3,244.00	\$3,244.00
-------------	------------	------------

Submit for Review