

REF:

CC3 / msh18001168 / Stbez

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

CC / TP / WS / TP RES / OD RES / EVA / INV / MO

To inspect Vehicle No: _____

at Workshop no: _____

Insured: SLK 7119XPolicy No: 29069766 MKF

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Ball or Market Value: _____

IDAO Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S4C 4134K Yr Reg: 22/11/13Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make: Toyota Prins CC 1798Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 427 078 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: J7DKW 364X 05765798Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ N/A / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 24/2/18 D.O.I. 26/2/18Survey held at SMARTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orC/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

SHE 11311X - RM / TEL 11023396 52 JRM: 13/11/11 TA X/02/18/2149

SLK 7119X - RM / TEL 18002199 / 11653 JRM: 31/12/12 LKK

MS19.

Sent EST & GIA to Eileen

19/3 Confirmed LE @ 1400/-; 3 days with Poh Sun. (Red. 5215.80, 78%).

19/3

19/3

19/3

19/3

19/3

19/3

19/3

19/3

19/3

19/3

19/3

19/3

19/3

19/3

19/3

19/3

19/3

19/3

Date/Time: File Pass U?



: Prel. Report

1) typis 1

: Final Report

Date/Time: File Return U?

2) _____

Report Format: TPLump Sum / I.B.I.: (\$ 1400/-)Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

TOTAL

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/MSG18001168/Srb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 19-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 7119X	Veh. Inspected	SHC 4134K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	24/02/2018	Inspection Date	26/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5369K

Vehicle Details

Vehicle No.: SHC4134K

Vehicle to be Exported: No

Intended De-registration Date: 27 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: PRIUS TAXI (SMRT)

Primary Colour: Maroon

Manufacturing Year: 2013

Engine No.: 2ZR1311789

Chassis No.: JTDKN36UX05705798

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$33,120.00

Original Registration Date: 22 Nov 2013

First Registration Date: 22 Nov 2013

Transfer Count: 0

Actual ARF Paid: \$8,368.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 21 Nov 2021

PARF Rebate Amount: \$6,276.00

Intended COE Rebate Details

COE Expiry Date: 21 Nov 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$63,297.00

COE Rebate Amount: \$29,557.00

Total Rebate Amount: \$35,833.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/02/2018 10:35
Date Of Accident	24/02/2018 11:50
Exact Location Of Accident	KAMPONG JAVA RD TO OWEN RD JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4134K
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	WONG TEE PIAU KENNETH
NRIC No	S1712102B
Date Of Birth	27/02/1965
Occupation	OUTDOOR
Date Of Driving Pass	30/12/1994
Driving Experience	23 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	201
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STOPPING ALONG THE SECOND LEFT RIGHT LANE OF KAMPONG JAVA ROAD DUE TO RED TRAFFIC LIGHT. WHEN THE LIGHT TURNED GREEN, I STARTED TO MOVE. SUDDENLY THE VEHICLE SLK7119X FROM THE MOST RIGHT LANE CUT INTO MY TRAVEL PATH AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK7119X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	SABESAN
NRIC/Passport Number	S1760020F
Contact Number	86687249
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

[illegible]

I/We declare the foregoing particulars are true in every respect.




Date & Time:

Wu 20/1/2018

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4134K
 Ref. No : TAX/02/18/2149
 Reg. Date : 22/11/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : WONG TEE PAU KENNETH
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 24/02/2018 11:50:00 AM
 Accident Reported Date / Time : 26/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 24/02/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094775
 Special Instruction to ARC, if any :
 TOWED \$60 / SLK7119X
 Prepared Date : 26/02/2018 12:03:21 PM



Sebastian.
 26/2/18.
 - Lump Sum Repair.
 - Question Mark Item Photo
 - Photo After Paint.


 8/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36UX0-5705798

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,494.00	0.00
Total Material Charges	: 2,197.55	2,197.55
Other Charges	: 664.00	0.00
TOTAL	: 5,200.55 6615.80	0.00
Lum Sum Total	: 5,200.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	3 days.
Arc / Surveyor Sign Off Date	: 26/02/2018 04:35:21 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/02/2018 04:35:21 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
REPAIR RH PORTION	845.00	0.00 400
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
RESPRAY FRONT DOOR RH	378.00	0.00 200
RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
RESPRAY REAR DOOR RH	378.00	0.00 200
RESPRAY REAR FENDER RH	378.00	0.00 200
RESPRAY WHEEL CAP	180.00	0.00 50
Total Spray Painting & Panel Beating	1,494.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
DIAGNOSING CHARGE	84.00	0.00 ✓
APPLY RUST-PROOFING ON AFFECTED REAR	100.00	0.00 30
CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 ✗
TRANSFER DOOR MECHANISM	240.00	0.00 ✗
REPLACE SUNDRY PARTS	100.00	0.00 ✗
WASH AND VACUUM	60.00	0.00 ✗
Total Other Costs	664.00	0.00

art 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7001-7070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No
5851-7900			MOULDING BODY, RH	1	673.60	25.00	505.20	Replace	Replace	No
7003-7080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace	No
1604-7090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
2602-7060		6505676	CAP SUB-ASSY, WHEEL	1	174.10	25.00	130.57	Replace	Replace	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace	No
TOTAL MATERIALS								2,746.95	2,746.94	
TOTAL MATERIALS(Discounted)							2,197.55	2,197.55		

dded Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

2-3-18 / 12:43


2-3-18 / 16:43

SMRT Accident Vehicle Repair Estimates

27
26-2-18 / 16:43

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4134K
Ref. No : TAX/02/18/2149
Reg. Date : 22/11/2013
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : WONG TEE PIAU KENNETH
Type of Accident : SIDE SWIPE
Date / Time of Accident : 24/02/2018 11:50:00 AM
Accident Reported Date / Time : 26/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 24/02/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094775
Special Instruction to ARC, if any :



TOWED \$60 / SLK7119X inslg 4S
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO ,FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email :sebastianyeang @lkkauto.com HP:90036121
LUMP SUM REPAIR

Prepared Date : 26/02/2018 12:03:21 PM

8m d .

Recording Camera

☐ ☒

Radio Antenna

☐ ☒


1st witness

Date

26-2-18

2nd witness

Date

Vehicle to Wega Date In:	27/2	Towing:
Time In:	1530	Driver:
Wega Job No:	02/057	
Vehicle sent to SMRT Date In:	2-3-2018	Towing:
Time In:	10:30	
Received by (SMRT):		

2/3/18 14:16 Reject

Wheel Cap Paint Peel

Rear Door Paint Peel

15:38 PG LLS

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36UX0-5705798

Mileage


: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	400.00
Total Spray Painting Charges	: 1,494.00	750.00
Total Material Charges	: 119.52	119.52
Other Charges	: 664.00	114.00
TOTAL	: 3,122.52	1,383.52
Lum Sum Total	: 3,100.00	1,400.00
No. of Repair Days	: 6.00	3.00
Prepared / Adjusted By	:	/
Arc / Surveyor Sing Off Date	: 26/02/2018 04:35:21 PM	26/02/2018 04:43:31 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/02/2018 04:35:21 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-6246

Invoice No :

Quotation Date : 13/3

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
REPAIR RH PORTION	845.00 ✓	400.00 /
Total Labour	845.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
RESPRAY FRONT DOOR RH	378.00 ✓	200.00 /
RESPRAY ROCKER PANEL MOULDING	180.00 ✓	100.00 /
RESPRAY REAR DOOR RH	378.00 ✓	200.00 /
RESPRAY REAR FENDER RH	378.00 ✓	200.00 /
RESPRAY WHEEL CAP	180.00 ✓	50.00 /
Total Spray Painting & Panel Beating	1,494.00	750.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
DOWING CHARGE	84.00	84.00 /
APPLY RUST-PROOFING ON AFFECTED REA	100.00	30.00 /
CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TRANSFER DOOR MECHANISM	240.00	0.00
REPLACE SUNDRY PARTS	100.00	0.00
WASH AND VACUUM	60.00	0.00
Total Other Costs	664.00	114.00

6615 8

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
001-070		6505528	DOOR FRT/RH	R 1	894.40	100.00	0.00	Replace	Repair	No R
			STICKER DECAL SMRT (DOOR)	✓ 1	60.00	0.00	60.00	Replace	Replace	No ✓
851-900			MOULDING BODY, RH	R 1	673.60	100.00	0.00	Replace	Repair	No R
003-080		6505486	DOOR RR/RH	R 1	954.50	100.00	0.00	Replace	Repair	No R
604-090			FENDER RR/RH	R 1	766.80	100.00	0.00	Replace	Repair	No R
			STICKER DECAL SMRT	✓ 1	7.80	0.00	7.80	Replace	Replace	No ✓
			STICKER DECAL 6555 8888	✓ 1	21.60	0.00	21.60	Replace	Replace	No ✓
602-060		6505676	CAP SUB-ASSY, WHEEL	X 0	174.10	30.00	0.00	Replace	Not given	No X
			PIXEL STICKER	✓ 1	60.00	0.00	60.00	Replace	Replace	No ✓
TOTAL MATERIALS							149.40	149.40		
TOTAL MATERIALS(Discounted)							119.52	119.52		

Additional Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

149.40 /
 - 207
 119.52 /
 + 400.00 /
 + 864.00 /
 1383.52 /

415 \$1400/- ✓

Sebastian
 19/3/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Feb 2018		28 Feb 2018 17:21 Edit Adj Rpt	S\$1,413.40 Edit Estimates	S\$1,413.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

























CLAIM SUBFOLDER DETAILS			[Created by insurer]			
Insured:	GRAB RENTALS PTE. LTD., Co. Reg. No.: 201617200G					
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K					
Vehicle Reg. No.:	SHC4134K	Date of Loss:	24/02/2018 11:00 - :59			
Claim Type:	TP / 550940	Policy/Cover Note No.:	29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019			
Vehicle Reg. No. (Insured):	SLK7119X	Policy No. (Claimant):				
		Excess:				
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628					
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Koh Ming Shao - 6594 2546]					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Imm.Advice due 01/03/2018]					

ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
There are no mail for this case.				

ALL ASSOCIATED TASKS			View All	Search Tasks	Create New Task	Complete			
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC4134K (550940)**
[SLK7119X]
TP
SMRT TAXIS PTE LTD
Feb 24 2018 11:00AM
[GRAB RENTALS PTE. LTD.]
SMRT Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images							3 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
2	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
3	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
4	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
5	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
6	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
7	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
8	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
9	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
10	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
11	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
12	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
13	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
14	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
15	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
16	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
17	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
18	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
19	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
20	27/03/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>		
21	27/03/18 15:43	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>		
22	27/03/18 15:43	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>		
Documentation							1 per page		<input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print		
1	28/02/18 17:23	Direct Survey by LKK						Load PDF			
2	28/02/18 17:23	SHC4134K E-FILE REPORT						Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18001168/SRBE2

Date: 29/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29069766MKF

Claimant Vehicle No : SHC4134K

Insured Vehicle No : SLK7119X

Date of Loss: 24/02/2018

Nature of Claim: TP

Claim No: 550940

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC4134K

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR1311789

Reg. Date: 22/11/2013 (Man. Year: 2013)

Chassis No: JTDKN36UX05705798

Colour: Maroon

Odometer: 427078 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,612.80	149.40	3,463.40	95.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,003.00	1,264.00	1,739.00	57.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,615.80	1,413.40	5,202.40	78.64
Approved Total (Overridden) (S\$)		1,400.00		
Nett Amount (S\$)	6,615.80	1,400.00	5,215.80	78.84

INSPECTION

Date of Assignment: 28/02/2018

Date Inspected: 26/02/2018 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 29 Mar 2018)
Parts: 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC4134K)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
2	1		*STICKER DECAL SMRT (SN)	Necessary	7.80 F	*7.80 F
3	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
4	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
5	1		*CAP SUB-ASSY, WHEEL	Not Necessary	174.10 F	*- F
6	1		*DOOR FRT / RH	Repair	894.40 F	*- F
7	1		*MOULDING BODY, RH	Repair	673.60 F	*- F
8	1		*DOOR RR/RH	Repair	954.50 F	*- F
9	1		*FENDER RR/RH	Repair	766.80 F	*- F
Total Parts (S\$)					3,612.80	149.40

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	845.00	400.00
2	SPRAY PAINT	New	1,494.00	750.00
3	TOWING CHARGE	New	84.00	84.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
6	TO TRANSFER DOOR MECHANISM	New	240.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			3,003.00	1,264.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >