

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0595/2018
DATE : 19-JAN-2018

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 66431335/6827 7880
FAX : 66431349/6827 7809
7313 DAVID

OWNER'S NAME : TAY YU XIANG, JONATHAN
ADDRESS : APT BLK 446 BRIGHT HILL DRIVE
#06-105
S(570446)
TELEPHONE NO : 8298 8479

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : A29014611QMY
VEHICLE NO : SKS5045H
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YA86734
CHASSIS NO : JF1SJ5KC5JG098097
MILEAGE : 1 KM
DATE IN : 19/01/2018
LIABILITY : 0.00
EXCESS CLAUSE : 700.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 17/01/2018

Print Date : 19/01/2018
Print Time : 12:02:45

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKS5045H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM MSIG LOCATION SERVICE ROAD BESIDE UIC BUILDING DATE:17/01/2018 TIME:1520HRS		
3	ZZ/002	REMOVE/REPLACE FRT BUMPER,PANEL,HOOD,LH FENDER, LH WHEEL APRON	2800.00	1400
4	ZZ/003	RESPRAY FRT BUMPER,PANEL,HOOD,LH FENDER,LH WHEEL APRON	2100.00	1680
5	ZZ/004	REMOVE & REFIX AIR CON CONDENSER & RADIATOR TO FACILITATE REPAIR	220.00	?
6	ZZ/005	REMOVE & REFIX WIRE HARNES	300.00	?
7	ZZ/006	TO CONDUCT (FRT / REAR) LIGHTING TEST	50.00	✓
8	ZZ/007	REMOVE/REFIX FRT HEAD LAMP WASHER AND PIPING	300.00	100
9	ZZ/008	SUNDRIES	100.00	50
TOTAL LABOUR CHARGES			5870.00	

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKS5045H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
			NETT	LIST	S/NETT		
1	WHEEL APR FF C RPLH	51610SG1309P	<i>CR</i> 172.80			✓	
2	RAD PNL COMPL RPR	53029SG0009P	360.00			?	
3	HOOD F CPL	57229SG0009P	<i>R</i> 882.00			X	
4	LOCK ASSY F HOOD ISR	57310SG020	<i>R</i> 72.00			X	
5	BRKT CORNER F RH	57707SG000	36.00			?	
6	BRKT CORNER F LH	57707SG010	<i>D.1</i> 36.00			—	
7	BRKT SD F RH	57707SG020	12.60			?	
8	BRKT SD F LH	57707SG030	12.60			?	
9	MOLDING BMFR F	57708SG000	43.20			?	
10	MOLDING BMFR F	57708SG010	43.20			?	
11	FRT BUMPER	57709SG030A	<i>Bu</i> 594.00			—	
12	BACK BEAM CPL F	57711SG0009P	<i>R</i> 288.00			✓	
13	ENERGY ABSOR F	57722SG020	<i>R</i> 126.00			?	
14	COVER HOOK F STD	57731SG220	<i>Bu</i> 4.40			X	
15	PACKING RAD	57780SG010	<i>Mit</i> 9.00			—	
16	PACKING RAD	57780SG020	<i>Mit</i> 9.00			—	
17	LAMP ASSY HEAD EOF RH	84002SG220	2380.00			?	
18	LAMP ASSY HEAD EOF LH	84002SG230	<i>Mit</i> 2380.00			—	
19	FOG LAMP ASSY F	84501AJ060	544.00			?	
20	BRKT F FOG ASSY RH	84927SG020	19.80			?	
21	BRKT F FOG ASSY LH	84927SG030	19.80			?	
22	MOTOR & PUMP ASSYFR	86611SG000	61.20			?	
23	MOTOR & PUMP ASSYRR	86611SG010	64.80			?	
24	MOTOR & PUMP ASSYHL	86611VA000	170.00			?	
25	TANK HLS	86631SG030	<i>ND</i> 93.60			✓	

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKS5045H

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT
S/LIST REMARKS					
26	NOZZLE H L WASHERRH	86636SG361	79.20	7	
27	NOZZLE H L WASHERLH	86636SG371	79.20	7	
28	NOZZLE COVER ASSYRH	86636SG380E1	54.00	MIT	
29	NOZZLE COVER ASSYLH	86636SG390E1	54.00	MIT	
30	INSULATOR HOOD NA	90815SG051	79.20	SL	X
31	GRILLE ASSY F UPRHG	PDI STOCK 91121SG210A	140.40	7	
32	GRILLE ASSY F CTRHG	PDI STOCK 91121SG240A	180.00	7	
33	GRILLE ASSY F LWRHG	PDI STOCK 91121SG280A	316.80	7	
34	BRKT GRILLE LWR NA	91165SG000	21.60	7	
SUB TOTAL			9438.40	0.00	0.00
LESS DISCOUNT (NETT-20 %)			1887.68	0.00	0.00
GRAND TOTAL			7550.72	0.00	0.00
OVERALL TOTAL			7550.72		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKS5045H

TOTAL LABOUR CHARGES	5870.00
TOTAL SPARE PARTS CHARGES	7550.72
GRAND TOTAL	13420.72 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 700.00
LIABILITY	: 0.00
REMARKS	:

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

NISTA & UIC



Not Authorized

Heavy B4 paint
Ex 8700h

Fax: 62564315

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: