

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 22 Jan 2018

Preliminary Advice

Vehicle No	: SKS5045H	Accident Date	: 17/01/2018
Make	: SUBARU FORESTER	Policy No.	: A29014611QMY
Assignment Date	: 19/01/2018	Excess	: S\$700.00
Date of Inspection	: 19/01/2018	Est. Duration of Repair	: 6.00
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD (TOA PAYOH) 19 LORONG 8 TOA PAYOH SINGAPORE 319255		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,420.72
Revised Amount	:S\$	6,001.92
Check Items (Estimated)	:S\$	4,288.32
Total	:S\$	10,290.24

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	61,835.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,165.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.