

REF CS/MSIG/18001181/Kvd3c2

Merimen Kenneth
Joslin Lim of MSIG Date 19/01/2018 @ 11:36am

Estimated Cost Bill

OD TP WS / TP RES / OD RES / EVA / EVY / NY / CG

To Inspect Vehicle No SKS 5045H

at Workshop no Motor Image To 6703 8104

of 19 Lorong 8, Toa Payoh

Policy No 129014611QMY

Sum Insured 546599

Excess \$700.00

Date of Vch 17/01/2018

CA (REV) REP: / REV 24 HRS

Date Time 12:39pm @ 19/1/18 Period Cont Ref Shahid

Date Time Action Instructions ✓ SKS 5045H-X

22/1/18 Revert by merimen

22/1/18 Rere approved from they Hi by merimen

22/1/18 Informed Sayed c/a ex \$700 by email

4/6/18 Final fig \$10,760.72 confirmed by email (Real - 8070.20, 4375)

ASS. REC. BY:

REF: MSG 1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vsh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 8125k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

22/1 1st pass to Carline

Veh No: SKS 5045H Yr Regn: OD, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Subaru Forester cc 1995

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 10392 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JFISJ5KC5J G098097

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SI/Rim / STD A/Rim or

Tyre Size: F: 225/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 17/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Data/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Data/Time, File Return to?

2) 4/6 - typist

Report Format:

merimen

Lump Sum / L.B.I. (\$

10,760.72

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

300

10

310

RECEIVED 04 JUN 2018

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/18001/81/Kvab
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 4/6/16
Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001181/Kvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 19-01-2018	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKS 5045H
Policy No.	A29014611QMY	Coverage (\$)	0.00
Claim No.	546599	Excess (\$)	700.00
Assign From	MERIMEN (JOSLIN LIM)	Assign Date	19/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/01/2018	Inspection Date	19/01/2018
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jan 2018		19 Jan 2018 11:36 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAY YU XIANG JONATHAN, ID: S8719195H, Tel: +6582988479, Email: jonathantyx@gmail.com		
Vehicle Reg. No.:	SKS5045H	Date of Loss:	17/01/2018 15:00 - :59
Claim Type:	OD / 546599	Policy/Cover Note No.:	A29014611QMY (Comprehensive) Coverage: 31/08/2017 - 30/08/2018
		Excess:	S\$700.00
Repairer:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038104		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/01/2018]		
Driver/Custodian:	TAY YU XIANG JONATHAN (30 / Male), NRIC: S8719195H, Tel: +6582988479		
Adj Asg. Remarks:	Estimate not ready. Please survey and revert.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

[ID](#)
[Name](#)
[Priority](#)
[Type](#)
[Task Group](#)
[Subject](#)
[Handler](#)
[Assigned By](#)
[Completed On](#)
[Created On](#)
[Done?](#)

No results.

View Received Message

This mail is associated with :

***SKS5045H (546599)**

OD

Jan 17 2018 3:00PM

[TAY YU XIANG JONATHAN]

Motor Image Enterprises Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 04/06/2018 11:49 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$10760.72) - SKS5045H - Claim Handler: Joslin Lim

Approved:10760.72:Approved mandate \$10290.24 (including check items \$4288.32) before excess \$700

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Joslin Lim	Date: 31 May 2018
<u>Preliminary Advice</u>	

Vehicle No	: SKS5045H	Accident Date	: 17/01/2018
Make	: SUBARU FORESTER	Policy No.	: A29014611QMY
Assignment Date	: 19/01/2018	Excess	: S\$700.00
Date of Inspection	: 19/01/2018	Est. Duration of Repair	: 6.00
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD (TOA PAYOH) 19 LORONG 8 TOA PAYOH SINGAPORE 319255		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,830.92	(incl.supplementary \$5410.20)
Revised Amount	:S\$	10,760.72	(incl.supplementary \$5410.20)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	10,760.72	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	61,835.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,165.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 22 January 2018 3:55 PM
To: Sayedinah Bin Ali /MIE - Svc
Cc: daniellim (daniellim@motorimage.net); 'reyricamora@motorimage.net'; 'olivergracilla@motorimage.net'; SUR
Subject: SKS 5045H-DOA: 17/1/2018 (MSIG OD)

Dear Sayed,

As instructed by our client MSIG , please proceed to repair the insured vehicle **SKS 5045H (Excess \$700/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKS5045H (546599)**

OD

Jan 17 2018 3:00PM

[TAY YU XIANG JONATHAN]

Motor Image Enterprises Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 22/01/2018 15:39 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$10290.24) - SKS5045H - Claim Handler: Joslin Lim

Approved:10290.24:Approved mandate \$10290.24 (including check items \$4288.32) before excess \$700

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Joslin Lim	Date: 22 Jan 2018
<u>Preliminary Advice</u>	

Vehicle No	: SKS5045H	Accident Date	: 17/01/2018
Make	: SUBARU FORESTER	Policy No.	: A29014611QMY
Assignment Date	: 19/01/2018	Excess	: S\$700.00
Date of Inspection	: 19/01/2018	Est. Duration of Repair	: 6.00
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD (TOA PAYOH) 19 LORONG 8 TOA PAYOH SINGAPORE 319255		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,420.72
Revised Amount	:S\$	6,001.92
Check Items (Estimated)	:S\$	4,288.32
Total	:S\$	10,290.24
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	61,835.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,165.00

Remarks

☒ The vehicle is economical for repair.

☐ The above survey was conducted on a 'without prejudice' basis.

Joslin Lim

From: Woon Choo Kwok
Sent: Friday, 19 January, 2018 9:12 AM
To: Joslin Lim
Cc: Christopher Chionh; Foo Ai Ngho; Jason Sim
Subject: FW: SKS5045H-OD-MSIG-SURVEY-URGENT BASIS-VEHICLE NON-DRIVABLE-19/01/2018-1300HRS
Attachments: SKS5045H ID DL AND CERT.PDF; SKS5045H GIA REPORT MSIG.PDF
Importance: High

Dear JL

FYA

Best Regards

Kwok Woon Choo

Senior Administrative Officer, Claims Services

Direct line +65 6643 1330 | Direct fax +65 6225 7402 | woonchoo_kwok@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Koh Lay Hoon
Sent: Friday, January 19, 2018 8:46 AM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>
Subject: FW: SKS5045H-OD-MSIG-SURVEY-URGENT BASIS-VEHICLE NON-DRIVABLE-19/01/2018-1300HRS
Importance: High

From: Sayedinah Bin Ali [<mailto:sayedinah@motorimage.net>]
Sent: Friday, January 19, 2018 2:22 AM
To: Claims <claims@sg.msig-asia.com>
Cc: Daniel Lim <daniellim@motorimage.net>; Rey Ricamora <reyricamora@motorimage.net>; Oliver Zubiri <olivergracilla@motorimage.net>
Subject: SKS5045H-OD-MSIG-SURVEY-URGENT BASIS-VEHICLE NON-DRIVABLE-19/01/2018-1300HRS
Importance: High

Hi Claims Team,
Kindly arrange survey of your insured vehicle on an urgent basis. Vehicle non drivable. We will forward the estimate shortly.

Regards
Sayedinah Ali
Service Executive

Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
H1: 62992693 DID: 67038109 FAX: +65-62535535
Email: sayedinah@motorimage.net
Website: www.tanchong.com :: www.motorimage.net

The all-new Subaru XV

GO FOR BOLD



JUMP ON IT



SUBARU



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, or use or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9195H
Vehicle Details	
Vehicle No.:	SKS5045H
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jan 2018
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0I-L CVT AWD SR
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	FB20YA86734
Chassis No.:	JF1SJ5KC5JG098097
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,663.00
Original Registration Date:	31 Aug 2017
First Registration Date:	31 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$13,663.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2027
PARF Rebate Amount:	\$10,247.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$51,588.00
Total Rebate Amount:	\$61,835.00

The information contained herein is correct as at 22 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/01/2018 17:08
Date Of Accident	17/01/2018 15:20
Exact Location Of Accident	SERVICE ROAD BESIDE UIC BUILDING
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS5045H
Insured/Policyholder	
Name Of Registered Owner	TAY YU XIANG JONATHAN
NRIC No	S8719195H
Email Address	JONATHANTYX@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82988479
Alternative Phone No	OTHERS-82988479

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29014611 QMY
Cover Note Number	

Driver

Name of Driver	TAY YU XIANG JONATHAN
NRIC No	S8719195H
Date Of Birth	02/07/1987
Occupation	INDOOR
Date Of Driving Pass	22/12/2006
Driving Experience	11 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82988479
Fax Number	
Contact Number	OTHERS-82988479
EEmail Address	JONATHANTYX@GMAIL.COM

Address	BLK 446 BRIGHT HILL DRIVE #06-105 SINGAPORE
Postcode	570446
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CLEMENT SAR GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH OWNER
Was there any audio recorded?	NO

Details of Witness 1

Name	GAN A
Phone Number	93736349
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS2788P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAY CHOON SENG
NRIC/Passport Number	S7103690A
Contact Number	97707571

- Address
- Postcode
- Insurance Company Name
- Nature Of Damage
- No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

18/1/18 10:07AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

18/1/18 10:07AM


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

(Stamp) (Green/Black/Red)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was parked along the single white line two lane road outside VIC Centre, perpendicular to Union Street. As I was driving out, and turning left, a car driving straight bang into me. There was a van parked illegally that block both car views, creating a blind spot.


The vehicle that bang into me (SG52788P) came out of the car, citing that he was distracted looking for his grab passenger as the road in front of VIC building cannot be found in google map, thus, he has to physically check out the building premise while driving. This was heard and witness by building security guard ~~Lee~~ Grand (tel: 93736349). He also stated that the van was blocking his view.

The weather was clear and the accident happened at 15:21. No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 18/1/15 16:07am


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 18/1/15 16:07am


 Reporting Centre Personnel's Signature
 Name:
 NRC/FIN No.:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INR/IC/CHI/6595/2018
DATE : 19-JAN-2018

HSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 66431335/6627 7880
FAX : 66431349/6627 7809
7313 DAVID

OWNER'S NAME : TAY YU XIANG, JONATHAN
ADDRESS : APT BLK 446 BRIGHT HILL DRIVE
#06-105
S(570446)
TELEPHONE NO : 8298 8479

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : A29014611QMY
VEHICLE NO : SKS5045H
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AND CVT
ENGINE NO : FB20YA86734
CHASSIS NO : JF1BJ5KCSJG098097
MILEAGE : 1 KM
DATE IN : 19/01/2018
LIABILITY : 0.00
EXCESS CLAUSE : 700.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 17/01/2018

Print Date : 19/01/2018
Print Time : 12:02:45

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SK25045H

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 00CLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2 22/001	CONDUCT OD CLAIM MSIG LOCATION SERVICE ROAD RESIDE UIC BUILDING DATE:17/01/2018 TIME:1520HRS		
3 22/002	REMOVE/REPLACE FRT BUMPER,PANEL,HOOD,LH FENDER, LH WHEEL APRON	2800.00	1400 ✓
4 22/003	RESPRAY FRT BUMPER,PANEL,HOOD,LH FENDER,LH WHEEL APRON	2100.00	1680 ✓
5 22/004	REMOVE & REFIX AIR CON CONDENSER & RADIATOR TO FACILITATE REPAIR	220.00	? X
6 22/005	REMOVE & REFIX WIRE HARNESS	300.00	? X
7 22/006	TO CONDUCT (FRT / REAR) LIGHTING TEST	50.00	✓ ✓
8 22/007	REMOVE/REFIX FRT HEAD LAMP WASHER AND PIPING	300.00	100 ✓
9 22/008	SUNDRIES	100.00	50 ✓
	TOTAL LABOUR CHARGES	5870.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
18 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SK85045H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
1	WHEEL APR FF C RPLH	516108G1309P	172.80	✓ X	94	
2	RAD FNL COMPL RPR	530295G0009P	360.00	✓ X		
3	HOOD F CPL	572295G0009P	882.00	X		
4	LOCK ASSY F HOOD ISM	573108G020	72.00	X		
5	BRKT CORNER F RH	577078G000	36.00	✓ X		
6	BRKT CORNER F LH	577078G010	36.00	✓		
7	BRKT SD F RH	577078G020	12.60	✓ X		
8	BRKT SD F LH	577078G030	12.60	✓		
9	HOLDING BMPR F	577088G000	43.20	✓ X		
10	HOLDING BMPR F	577088G010	43.20	✓ X		
11	FRT BUMPER	577098G030A	594.00	✓		
12	BACK BEAM CPL F	577118G0009P	288.00	X		
13	ENERGY ABSOR F	577228G020	126.00	X X		
14	COVER HOOK F STD	577318G220	4.40	X		
15	PACKING RAD	577808G010	9.00	✓		
16	PACKING RAD	577808G020	9.00	✓		
17	LAMP ASSY HEAD EOT RH	840028G220	2380.00	✓ X		
18	LAMP ASSY HEAD EOT LH	840028G230	2380.00	✓		
19	FOG LAMP ASSY F	84501A7060	344.00	✓ X		
20	BRKT F FOG ASSY RH	849278G020	19.80	✓ X		
21	BRKT F FOG ASSY LH	849278G030	19.80	✓ X		
22	MOTOR & PUMP ASSYFR	866118G000	61.20	✓ X		
23	MOTOR & PUMP ASSYRR	866118G010	64.80	✓ X		
24	MOTOR & PUMP ASSYHL	86611VA000	170.00	✓ X		
25	TANK	866318G030	93.60	✓		

Photo taken by Ray *B* 30/01/18

Estimate

Date 01-25-2018

001 / 001

Name	TT254612/TT254607 SKS5045H/SAYED	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SJ5KC5JG-098097

Part Number	Part Code Name	Part Code	Q'ty	Price
20310SG110	STRUT COMPLETE-FRONT LEFT CN2-2	FIG-210 20310B	1	<i>A1</i> 262.80 ✓
20320FG012	STRUT MOUNT-FRONT BE 1-1/1	FIG-210 20320	1	<i>A1</i> 72.00 ✓
28313SC011	HOUSING-FRONT AXLE, L EFT CG11-2	FIG-280 28313A	1	<i>A1</i> 209.90 ✓
28373FL000	HUB COMPLETE-FRONT A XLE CH5-3	FIG-280 28362	1	<i>A1</i> 165.60 ✓
902170049	NUT BA3-1/7	FIG-280 N170049	1	<i>Sn</i> 10.80 X
34110SG050	STEERING GEAR BOX AS SEMBLY, EPS DA4-1	FIG-347 34110A	1	<i>A1/J1</i> 2,545.20 ✓
051030300	COTTER PIN BA2-3/9	FIG-347 0510S	2	<i>Sn</i> 0.20 X
23142GA040	VALVE-TIRE BA2-3/2	FIG-290 28102	1	<i>Sn</i> 8.50 X
28111SG130	DISK WHEEL-ALUMINIUM E7-SIDE	FIG-290 28111	1	<i>DL</i> 750.00 ✓
		Page-Total		4,025.00
		Sub-Total		4,025.00
		Total		4,025.00
		Tax		
		Grand Total		4,025.00

Memo	Grand Total
------	-------------

Estimate

Date 01-26-2018

001 / 001


Name	TT254607	Tel (Home)	
Address	SKS5045H/SAYED	Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SJ5KC5JG-098097

Part Number	Part Code Name	Part Code	Q'ty	Price
57120SG0309P	FENDER COMPLETE-FRONT, LEFT K2-1	FIG-540 57110A	1	B1 * 270.00 ✓
57707SG030	BRACKET-FRONT BUMPER SIDE, LEFT AAL-3/2	FIG-590 57707G	1	R = 12.60 X
		Page-Total		282.60
		Sub-Total		282.60
		Total		282.60
		Tax		
		Grand Total		282.60

5045

Memo

Grand Total
282.60



Tel

Estimate

Date 01-26-2018

001 / 001

Name	TT254607 SKS5045H/SAYED	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SJ5KC5JG-098097

Part Number	Part Code Name	Part Code	Q'ty	Price
59110SG031	MUD GUARD, FRONT LEFT AH4-2	FIG-541 59110C	1	CM 86.40 ✓
909140065	CLIP-2PIECE D8	FIG-541 W140065	9	NN 16.20 X
		Page-Total		102.60
		Sub-Total		102.60
		Total		102.60
		Tax		
		Grand Total		102.60

5045

Memo

Grand Total
102.60



Tel

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LOHONG A, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0595/2018
DATE : 19-JAN-2018

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 66431335/6827 7880
FAX : 66431349/6827 7809
7313 DAVID

OWNER'S NAME : TAY YU XIANG, JONATHAN
ADDRESS : APT BLK 446 BRIGHT HILL DRIVE
#06-105
S(570446)
TELEPHONE NO : 8298 8479

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : A29014611QMY
VEHICLE NO : SRS5045H
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AND CVT
ENGINE NO : FB20YA86734
CHASSIS NO : JF1SJ5KC5JG098097
MILEAGE : 10397 KM
DATE IN : 19/01/2018
LIABILITY : 0.00
EXCESS CLAUSE : 700.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 17/01/2018

Print Date : 30/05/2018
Print Time : 15:01:23

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LOBOING 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKS5045H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	OD/CLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM MSG LOCATION SERVICE ROAD RESIDE UTC BUILDING DATE:17/01/2018 TIME:1520HRS		
3	ZZ/002	REMOVE/REPLACE FRT BUMPER,PANEL,HOOD,LH FENDER, LH WHEEL APRON	2800.00	1400.00
4	ZZ/003	RESPRAY FRT BUMPER,PANEL,HOOD,LH FENDER,LH WHEEL APRON	2100.00	1680.00
5	ZZ/004	REMOVE & REFIX AIR CON CONDENSER & RADIATOR TO FACILITATE REPAIR	220.00	.00
6	ZZ/005	REMOVE & REFIX WIRE HARNES	300.00	.00
7	ZZ/006	TO CONDUCT (FRT / REAR) LIGHTING TEST	50.00	50.00
8	ZZ/007	REMOVE/REFIX FRT HEAD LAMP WASHER AND PIPING	300.00	100.00
9	ZZ/008	SUNDRIES	100.00	50.00
10	ZZ/009	TRANSFER / BALANCE TYRE / RIM (SUPP)	50.00	50.00
11	ZZ/011	WHEEL ALIGNMENT (SUPP)	200.00	200.00
12	ZZ/012	REMOVE & REFIX EXHAUST(SUPP)	150.00	150.00
13	ZZ/10	DISMANTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIR (SUPP)	600.00	600.00
TOTAL LABOUR CHARGES			6870.00	4280.00

CA)

MOTORIMAGE ENTERPRISES PTE. LTD.
10 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKS5045H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	STRUT COMPL F LH	20310SG110	262.80			OK
2	STRUT MT F	20320PG012	72.00			OK
3	DISC WHEEL AL 17	28111SG130	750.00			OK
4	TOUSING F LH (SUPP)	28313SC011	209.90			OK
5	HUB UNIT COMPL F	28373FL000	165.60			OK
6	GR BOX ASSY P/S EPS	34110SG050	2545.20			OK
7	FRT FENDER LH (W/O SIGNAL LP)	57120SG0309P	270.00			OK
8	BRKT CORNER F LH	57707SG010	36.00			OK
9	BRKT SD F LH	57707SG030	12.60			OK
10	FRT BUMPER	57709SG030A	594.00			OK
11	PACKING RAD	57780SG010	9.00			OK
12	PACKING RAD	57780SG020	9.00			OK
13	MUD GUARD ASSY F LH SEE SC030	59110SG031	86.40			OK
14	LAMP ASSY HEAD EOF LH	84002SG230	2380.00			OK
15	TANK HLS	86631SG030	93.60			OK
16	NOZZLE H L WASHERRH	86636SG361	79.20			OK
17	NOZZLE H L WASHERLH	86636SG371	79.20			OK
18	NOZZLE COVER ASSY RH PDI PARTS	86636SG380A	54.00			OK
19	NOZZLE COVER ASSY LH PDI PARTS	86636SG390A	54.00			OK
20	GRILLE ASSY F LMRHC PDI STOCK	91121SG280A	316.80			OK
21	BRKT GRILLE LMR NA	91165SG000	21.60			OK
SUB TOTAL			8100.90	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			1620.18	0.00	0.00	0.00
GRAND TOTAL			6480.72	0.00	0.00	0.00
OVERALL TOTAL			6480.72			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKS5045H

			DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319235

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKSS045H

NETT ITEM 8100.90
LESS 20 % -1620.18
NETT AMOUNT 6480.72

LIST ITEM 0.00
LESS 50 % 0.00
LIST AMOUNT 0.00

SPECIAL NETT AMOUNT 0.00

S/LIST ITEM 0.00
LESS 30 % 0.00
S/LIST AMOUNT 0.00

TOTAL LABOUR CHARGES 4280.00
TOTAL SPARE PARTS CHARGES 6480.72

TOTAL CHARGES 10760.72
LESS EXCESS 700.00

TOTAL 10060.72
ADD 7 % GST 704.25

GRAND TOTAL 10764.97

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 4 June 2018 12:05 PM
To: Sayedinah; Kenneth Kong (LKKAUTO)
Cc: Daniel Lim; Daniel Jude; Kuan Wei Loong; SUR
Subject: RE: SKS5045H-OD-MSIG-FINALIZED

Dear Sayed,

Confirmed finalize amount \$10,760.72 before excess \$700 and GST @ 6 working days.

Final invoice and all supporting documents sent over to MSIG INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sayedinah [mailto:sayedinah@motorimage.net]
Sent: Wednesday, 30 May 2018 3:25 PM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Daniel Lim <daniellim@motorimage.net>; Daniel Jude <danieljude@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>
Subject: SKS5045H-OD-MSIG-FINALIZED
Importance: High

Hi Kenneth & Veron,
Attached for your reference. Supplementary items photos attached as requested by Kenneth.

Regards
Sayedinah Ali
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:92992693 DID:67038109 FAX:+65-62535535
Email:sayedinah@motorimage.net
Website:www.tanchong.com :: www.motorimage.net



**LESS SLIP.
MORE GRIP.
SYMMETRICAL AWD**

**SUBARU
TECHNOLOGY**

LEARN MORE



SUBARU



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jan 2018		19 Jan 2018 11:36 Edit Adj Rpt	S\$10,760.72 Edit Estimates	S\$10,760.72 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAY YU XIANG JONATHAN, ID: S8719195H, Tel: +6582988479, Email: jonathantyx@gmail.com								
Vehicle Reg. No.:	SKS5045H	Date of Loss:	17/01/2018 15:00 - :59 [4 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 546599	Policy/Cover Note No.:	A29014611QMY (Comprehensive) Coverage: 31/08/2017 - 30/08/2018						
		Excess:	S\$700.00						
Repairer:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038104								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/02/2018]								
Driver/Custodian:	TAY YU XIANG JONATHAN (30 / Male), NRIC: S8719195H, Tel: +6582988479								
Adj Asg. Remarks:	Estimate not ready. Please survey and revert.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (04/06/2018): Alert - Adj Mandate Approved (S\$10760.72) - SKS5045H - Claim Handler: Joslin Lim - MSIG_SG (22/01/2018): Alert - Adj Mandate Approved (S\$10290.24) - SKS5045H - Claim Handler: Joslin Lim									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKS5045H (546599)
OD
Jan 17 2018 3:00PM
[TAY YU XIANG JONATHAN]
Motor Image Enterprises Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
1	18/01/18 17:15	STA INSPECTION PTE LTD (Sin Ming)		 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/01/18 12:54	Adjuster Immediate Advice		 Load HTM	
2	31/05/18 17:07	Adjuster Immediate Advice		 Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/01/18 13:41	General View		 Load JPG	☒
2	22/01/18 13:41	General View		 Load JPG	☒
3	22/01/18 13:41	General View		 Load JPG	☒
4	22/01/18 13:41	General View		 Load JPG	☒
5	22/01/18 13:41	General View		 Load JPG	☒
6	22/01/18 13:41	General View		 Load JPG	☒
7	22/01/18 13:41	General View		 Load JPG	☒
8	22/01/18 13:41	General View		 Load JPG	☒
9	22/01/18 13:41	General View		 Load JPG	☒
10	22/01/18 13:41	General View		 Load JPG	☒
11	22/01/18 13:41	General View		 Load JPG	☒
12	22/01/18 13:41	General View		 Load JPG	☒
13	22/01/18 13:41	General View		 Load JPG	☒
14	22/01/18 13:41	General View		 Load JPG	☒
15	22/01/18 13:41	General View		 Load JPG	☒
16	22/01/18 13:41	General View		 Load JPG	☒
17	22/01/18 13:41	General View		 Load JPG	☒
18	22/01/18 13:41	General View		 Load JPG	☒
19	22/01/18 13:41	General View		 Load JPG	☒
20	22/01/18 13:41	General View		 Load JPG	☒
21	22/01/18 13:41	General View		 Load JPG	☒
22	22/01/18 13:41	General View		 Load JPG	☒
23	22/01/18 13:41	General View		 Load JPG	☒
24	22/01/18 13:41	General View		 Load JPG	☒
25	22/01/18 13:41	General View		 Load JPG	☒
26	31/05/18 16:14	Reinspection Photo		 Load JPG	☒
27	31/05/18 16:14	Reinspection Photo		 Load JPG	☒
28	31/05/18 16:14	Reinspection Photo		 Load JPG	☒
29	31/05/18 16:14	Reinspection Photo		 Load JPG	☒
30	31/05/18 16:14	Reinspection Photo		 Load JPG	☒
31	31/05/18 16:14	Reinspection Photo		 Load JPG	☒
32	31/05/18 16:14	Reinspection Photo		 Load JPG	☒
33	31/05/18 16:14	Reinspection Photo		 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
		STA INSPECTION PTE LTD (Sin Ming)		☒
34	31/05/18 16:14	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On		Thumbnail	Print
1	19/01/18 11:29	Email from Motor Image	 Load PDF	
		STA INSPECTION PTE LTD (Sin Ming)		☒
1	18/01/18 17:14	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	18/01/18 17:14	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder		Thumbnail	Print
1	22/01/18 13:43	ESTIMATE	 Load PDF	
2	31/05/18 16:45	1ST MARK ESTIMATE	 Load PDF	
3	31/05/18 16:46	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
1	18/01/18 17:15	Accident Statement	 Load HTML	
Photos/Images			3 per page	☒
No	Finalized On		Thumbnail	Print
1	18/01/18 17:14	Accident Photo	 Load JPG	☒
2	18/01/18 17:14	Accident Photo	 Load JPG	☒
3	18/01/18 17:14	Accident Photo	 Load JPG	☒
4	18/01/18 17:14	Accident Photo	 Load JPG	☒
5	18/01/18 17:14	Accident Photo	 Load JPG	☒
6	18/01/18 17:14	Accident Photo	 Load JPG	☒
7	18/01/18 17:14	Accident Photo	 Load JPG	☒
8	18/01/18 17:14	Accident Photo	 Load JPG	☒
9	18/01/18 17:14	Accident Photo	 Load JPG	☒
10	18/01/18 17:14	Accident Photo	 Load JPG	☒
11	18/01/18 17:14	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On		Thumbnail	Print
1	18/01/18 17:14	Sketch Plan	 Load TIF	
2	18/01/18 17:14	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18001181/KVD3E2

Date: 05/06/2018

REFERENCE

Insured/Claimant:	TAY YU XIANG JONATHAN	Policy No:	A29014611QMY	
Date of Loss:	17/01/2018	Nature of Claim:	OD	Claim No: 546599

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS5045H	Engine No:	FB20YA86734
Make & Model:	SUBARU FORESTER, 2.0 (A)	Chassis No:	JF1SJ5KC5JG098097
Reg. Date:	31/08/2017 (Man. Year: 2017)	Odometer:	10392 km
Colour:	Metallic Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$125,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,178.88	6,530.72	4,648.16	41.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,770.00	4,230.00	2,540.00	37.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,948.88	10,760.72	7,188.16	40.05
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	17,248.88	10,060.72	7,188.16	41.67
+ GST 7.00/7.00% (S\$)	1,207.42	704.25	503.17	41.67
Nett Amount (S\$)	18,456.30	10,764.97	7,691.33	41.67

INSPECTION

Date of Assignment:	19/01/2018	
Date Inspected:	19/01/2018 Inspected At:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh Singapore 319255
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2018)
Parts: M1-SUV	SUBARU FORESTER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKS5045H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*WHEEL APR FF C RPLH	Serviceable	172.80 FN	*- FN
3	1		*RAD PNL COMPL RPR	Repair	360.00 FN	*- FN
4	1		*HOOD F CPL	Repair	882.00 FN	*- FN
5	1		*LOCK ASSY F HOOD ISR	Repair	72.00 FN	*- FN
6	1		*BRKT CORNER F RH	Serviceable	36.00 FN	*- FN
7	1		*BRKT CORNER F LH	Distorted	36.00 FN	*36.00 FN
8	1		*BRKT SD F LH	Necessary	12.60 FN	*12.60 FN
9	1		*MOLDING BMPR F	Serviceable	43.20 FN	*- FN
10	1		*MOLDING BMPR F	Serviceable	43.20 FN	*- FN
11	1		*FRT BUMPER	Buckled	594.00 FN	*594.00 FN
12	1		*BACK BEAM CPL F	Repair	288.00 FN	*- FN
13	1		*ENERGY ABSOR F	Repair	126.00 FN	*- FN
14	1		*COVER HOOK F STD	Serviceable	4.40 FN	*- FN
15	1		*PACKING RAD	Missing	9.00 FN	*9.00 FN
16	1		*PACKING RAD	Missing	9.00 FN	*9.00 FN
17	1		*LAMP ASSY HEAD E0F RH	Serviceable	2,380.00 FN	*- FN
18	1		*LAMP ASSY HEAD E0F LH	MTG Cracked	2,380.00 FN	*2,380.00 FN
19	1		*FOG LAMP ASSY F	Serviceable	544.00 FN	*- FN
20	1		*BRKT F FOG ASSY RH	Repair	19.80 FN	*- FN
21	1		*MOTOR & PUMP ASSYFR	Serviceable	61.20 FN	*- FN
22	1		*MOTOR & PUMP ASSYHL	Serviceable	170.00 FN	*- FN
23	1		*TANK HLS	Dented	93.60 FN	*93.60 FN
24	1		*NOZZLE H L WASHER RH	Missing	79.20 FN	*79.20 FN
25	1		*NOZZLE H L WASHER LH	Missing	79.20 FN	*79.20 FN
26	1		*NOZZLE COVER ASSYRH	Missing	54.00 FN	*54.00 FN
27	1		*NOZZLE COVER ASSYLH	Missing	54.00 FN	*54.00 FN
28	1		*INSULATOR HOOD NA	Serviceable	79.20 FN	*- FN
29	1		*GRILLE ASSY F UPRHG	Serviceable	140.40 FN	*- FN
30	1		*GRILLE ASSY F CTRHG	Serviceable	180.00 FN	*- FN
31	1		*GRILLE ASSY F LWRHG	Dented / Distorted	316.80 FN	*316.80 FN
32	1		*BRKT GRILLE LWR NA	Distorted	21.60 FN	*21.60 FN
33	1		*STRUT COMPLETE-FRONT LEFT CN2-2	Bent	262.80 FN	*262.80 FN
34	1		*STRUT MOUNT-FRONT BE1-1/1	Bent	72.00 FN	*72.00 FN
35	1		*HOUSING-FRONT AXLE, LEFT CG11-2	Bent	209.90 FN	*209.90 FN
36	1		*HUB COMPLETE-FRONT AXLE CH5-3	Bent	165.60 FN	*165.60 FN
37	1		*NUT BA3-1/7	Serviceable	10.80 FN	*- FN
38	1		*STEERING GEAR BOX ASSEMBLY, EPS DA4-1	Bent / Jammed	2,545.20 FN	*2,545.20 FN
39	2		*COTTER PIN BA2-3/9	Serviceable	0.20 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*VALVE-TIRE BA2-3/2	Serviceable	8.50 FN	*- FN
41	1		*DISK WHEEL-ALUMINIUM E7-SIDE	Dented	750.00 FN	*750.00 FN
42	1		*FENDER COMPLETE-FRONT, LEFT K2-1	Bent	270.00 FN	*270.00 FN
43	1		*BRACKET-FRONT BUMPER SIDE, LEFT AA1-3/2	Repair	12.60 FN	*- FN
44	1		*MUD GUARD, FRONT LEFT AH4-2	Cracked	86.40 FN	*86.40 FN
45	9		*CLIP-2PIECE D8	Not Necessary	16.20 FN	*- FN
46	1		*BRKT SD F RH	Repair	12.60 FN	*- FN
47	1		*BRKT F FOG ASSY LH	Repair	19.80 FN	*- FN
48	1		*MOTOR & PUMP ASSYRR	Serviceable	64.80 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$) **13,948.60** **8,150.90**

- Nett Item Discount on N Items 20.00/20.00% (S\$) **2,769.72** **1,620.18**

Total Parts (S\$) **11,178.88** **6,530.72**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / REPLACE FRT BUMPER, PANEL, HOOD, LH FENDER, LH WHEEL APRON	New	2,800.00	1,400.00
2	RESPRAY FRT BUMPER, PANEL, HOOD, LH FENDER, LH WHEEL APRON	New	2,100.00	1,680.00
3	REMOVE & REFIX AIR CON CONDENSER & RADIATOR TO FACILITATE REPAIR	New	220.00	0.00
4	REMOVE & REFIX WIRE HARNESS	New	300.00	0.00
5	TO CONDUCT (FRT/REAR) LIGHTING TEST	New	50.00	50.00
6	REMOVE & REFIX FRT HEAD LAMP WASHER AND PIPING	New	300.00	100.00
7	TRANSFER / BALANCE TYRE / RIM	New	50.00	50.00
8	WHEEL ALIGNMENT	New	200.00	200.00
9	REMOVE & REFIX EXHAUST	New	150.00	150.00
10	DISMANTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIR	New	600.00	600.00
Gross Labour Cost (S\$)			6,770.00	4,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >