

12/03/2002

ASS. REC. BY:

REF:

C3/EQ18001182/Kub3

Special Instruction:

Supervisor:

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

EQ2

Date/Time: 18/01/2018 505pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 1333M

Insured:

at Workshop m/s

Ah Lim motor

Tel:

64831244

of

Blk 10 AMK Ind Park 2A #01-09

Policy No:

DMCPHQ17 - 003117

Claim No:

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A. 15-01-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

22.01.2018 @ 10am

H.O.D. Endorsement:

Date/Time:

19.01.2018 9.06am

Person Contacted:

Zila

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	GBD 1333M - C3/EQ18001044/Kub3 Date: 15/01/2018
20/3/18 @ 7.49pm	revert to Elaine Cheong via Messenger. (supplementary).
20/3/18 @ 4.44pm	Josel Goh informed C/A at \$5857.60 is ex. \$500 via Messenger.
	Kenneth confirmed final fig to \$5857.60.
	(Add to 893.75, 15%.)
	no lump sum

ASSIGNMENT

RECEIVED 23 MAR 2013

~~Lump Sum (L.S.) = 8757.60~~

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQ18001182/Kqb

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 19-01-2018



Code : EQI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	GBD 1333M
Policy No. DMCPHQ17-003117	Coverage (\$)	0.00
Claim No.	Excess (\$)	500.00
Assign From MERIMEN (ELAINE CHEONG)	Assign Date	18/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/01/2018	Inspection Date	22/01/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jan 2018 11:25 Sendback Est	18 Jan 2018 11:26 S\$5,647.65	18 Jan 2018 17:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: MULTI IMAGE PTE LTD, Co. Reg. No.: 201206501M, Tel: +6591902124									
Vehicle Reg. No.: GBD1333M		Date of Loss: 15/01/2018 15:00 - :59							
Claim Type: OD		Policy/Cover Note No.: DMCPHQ17-003117 (Comprehensive)							
		Excess: S\$500.00							
Repairer: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244									
Handling Insurer: EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Elaine Cheong - 6500 6772]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/01/2018]									
Driver/Custodian: MUHAMMAD KHAIRIL BIN AHMAD SAYUTI (34 / Male), NRIC: S8312621C, Tel: +6591902124									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	18 Jan 2018 11:21	Clim Veh Model Changed	(204531) TOYOTA HIACE 3.0 D TURBO 5 DR (M).	[R] Zila
2	18 Jan 2018 11:21	Clim Created	Reg No: GBD1333M. Policy No: DMCPHQ17-003117. Acct Date: 2018/01/15. Claim Type: OD. Insurer: EQ Insurance Company Ltd (HQ). Workshop: Ah Lim Motor Company (AMK). Created from SAS:MALM18008124	[R] Zila
3	18 Jan 2018 11:26	Clim Submitted	5647.65.	[R] Zila
4	18 Jan 2018 17:05	Clim Registration Modified	Excess: -> 500.00.	[I] Elaine Cheong
5	18 Jan 2018 17:05	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[I] Elaine Cheong
6	18 Jan 2018 17:05	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/29	[I] Elaine Cheong
7	18 Jan 2018 17:05	Adj Mandate Set	Approved:0.00.	[I] Elaine Cheong
8	18 Jan 2018 17:40	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	19 Jan 2018 14:05	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] CATHERINE CHONG KAI LING
10	26 Jan 2018 11:06	Clim Supp Created (S:678452)		[R] Eileen Chua
11	26 Jan 2018 11:08	Clim Submitted (S:678452)	503.70.	[R] Eileen Chua
12	26 Jan 2018 11:08	Adj Co Assigned (S:678452)	LKK Auto Consultants Pte Ltd (HQ):	[I] Merimen Administrator
13	14 Mar 2018 08:58	Supp Combined (S:678452)		[A] SHIAU CHAN
14	20 Mar 2018 15:45	Adj Rpt Initiated		[A] SHIAU CHAN
15	20 Mar 2018 15:49	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/29	[A] SHIAU CHAN
16	20 Mar 2018 15:49	Adj Mandate Request	Cur.Req:5257.60:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
17	21 Mar 2018 16:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/29. Mandate Remarks: OD AUTHORISED AT \$5,257.60 BEFORE EXCESS OF \$500.00	[I] Joel Goh
18	21 Mar 2018 16:44	Adj Mandate Set	Approved:5257.60:OD AUTHORISED AT \$5,257.60 BEFORE EXCESS OF \$500.00	[I] Joel Goh

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1698845	18/01/2018 11:21	Motor	Ah Lim Motor Company (AMK)	Ah Lim Motor Company (AMK)	GBD1333M		xx.xx
1753202	20/03/2018 15:45	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBD1333M		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 20 Mar 2018

Preliminary Advice

Vehicle No	: GBD1333M	Accident Date	: 15/01/2018
Make	: TOYOTA HIACE	Policy No.	: DMCPHQ17-003117
Assignment Date	: 18/01/2018	Excess	: S\$500.00
Date of Inspection	: 23/01/2018	Est. Duration of Repair	: 6.00
Inspection At	: AH LIM MOTOR COMPANY (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,151.35	(ESTIMATE \$5,647.65 + SUPPLEMENTARY \$503.70)
Revised Amount	:S\$	5,257.60	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	5,257.60	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	54,000.00
COE / PARF Rebate	:S\$	23,363.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,637.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/01/2018 16:04
Date Of Accident	15/01/2018 15:00
Exact Location Of Accident	HOUGANG AVE 8 OPP BLK 620
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD1333M
Insured/Policyholder	
Name Of Registered Owner	MULTI IMAGE PTE LTD
Co Reg No	201206501M
Email Address	CHARLEEN.CHIN@MULTIIMAGE.COM.SG
Mobile Phone No	(LOCAL) +65-91902124
Alternative Phone No	OFFICE-65471648

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 D TURBO 5 DR (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ17-003117
Cover Note Number	24/06/2017 - 23/06/2018

Driver

Name of Driver	MUHAMMAD KHIRIL BIN AHMAD SAYUTI
NRIC No	S8312621C
Date Of Birth	26/04/1983
Occupation	OUTDOOR
Date Of Driving Pass	27/06/2003
Driving Experience	14 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91902124
Fax Number	
Contact Number	OFFICE-65471648
EMail Address	NOEMAIL

Sketch Plan Pg. 1

16-01-18:15:34 : Ah Lim Motor Company AMK

: +55 6483 6170

1 / 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X  

Policyholder's Signature
Date & Time: 16/1/18



Driver's Signature
(If driver is not the policyholder)
Date & Time:

 

Reporting Officer's Signature
Name:
NRIC/FIN No.:

EQ Insurance Company Limited

5 Maxwell Road #17-06 Tower Block MND Complex Singapore 069110
tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg
reg no. 1978-00490-N



CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

COMMERCIAL VEHICLE PRIVATE (SCH I)

Comprehensive

Certificate No. : DMCPHQ17-003117

1. Index Mark and Registration Number of Vehicles

GBD1333M

2. Name of Policyholder

Multi Image Pte Ltd

3. Effective Date of the Commencement of Insurance for the purpose of the Act

24/06/2017

4. Date of Expiry of Insurance

23/06/2018

5. Person or Classes of persons entitled to drive*

Goods carrying - (MZ300) Authorised Driver.

Any of the following :-

1. The Policyholder
2. Any person on the order or with the permission of the Policyholder

* Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitation as to use*

- 1) Use in connection with the Insured's business.
 - 2) Use for the carriage of passengers (other than for hire or reward) in connection with the insured's business.
 - 3) Use for social domestic and pleasure purposes.
- THE POLICY DOES NOT COVER
- 1) Use for hire or reward or for racing pace-making reliability trial or speed testing.
 - 2) Use whilst drawing a greater number of trailers in all than is permitted by Law.
 - 3) Use for the carriage of passengers for hire or reward.
 - 4) Liability arising from or in connection with the carriage of hazardous materials, high explosives, inflammable liquid or gases including LPG in cylinders.

* Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

Hire Purchase : United Overseas Finance Ltd

A000007/Astra Assurance Agencies LLP
Date of Issue : 07/06/2017 11:57

Exp No. : DMCPHQ16-002970

A Member of Citistate

Authorised Signatory
EQ Insurance Company Limited

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 6501M

Vehicle Details

Vehicle No.: GBD1333M

Vehicle to be Exported: No

Intended De-registration
Date: 16 Jan 2018

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA HIACE VAN
TURBO 5 DR MANUAL

Primary Colour: Silver

Manufacturing Year: 2014

Engine No.: 1KD2413007

Chassis No.: JTFHT02P600142980

Maximum Power Output: -

Open Market Value: \$27,502.00

Original Registration Date: 24 Jun 2014

First Registration Date: 24 Jun 2014

Transfer Count: 0

Actual ARF Paid: \$1,376.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Jun 2024

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$36,301.00

COE Rebate Amount: \$23,363.00

Total Rebate Amount: \$23,363.00

The information contained herein is correct as at 16 Jan 2018

OK

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047
Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
GST Reg No: M9-0009639-E

INSURER: EQ Insurance Company Ltd (HQ)

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)
Policy No:	DMCPHQ17-003117
Vehicle Reg. No.:	GBD1333M
Driver Age/Info:	34 / MALE
TP Injury Involved?	NO
Insured/Claimant:	MULTI IMAGE PTE LTD
Driver:	MUHAMMAD KHAIRIL BIN AHMAD SAYUTI

Ref. No:	
Date of Loss:	15/01/2018
Driveable?	
Party At Fault:	UNKNOWN
Third Party Involved?	YES
Contact No:	+6591902124

Make/Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)
Vehicle Colour:	SILVER
Engine No:	1KD2413007
Odometer:	0 KM

Vehicle Reg. Date:	24/06/2014
Chassis No:	JTFHT02P600142980

Paint Type: _____
Total Loss? **NO**
Est. Duration of Repair **76 days**
(day)

Description of Accident/Loss	REFER TO THE SKETCH PLAN BY DRIVER
Remarks:	CAR NOT IN - TO BE ARRANGE
Present Location:	AH LIM MOTOR COMPANY (AMK)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

COST OF CLAIMS

Parts
Miscellaneous Items
Labour
Paintwork Labour
Towing

Amount
3,907.65
0.00
1,740.00
0.00
0.00

Gross Total (\$\$)	5,647.65
+ GST 7.00% (\$\$)	395.34
Nett Amount (\$\$)	6,042.99

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

6151.34

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 18 Jan 2018)**Parts:** 213 TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Ah Lim Motor Company/GBD1333M/18/01/2018 11:26**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	0.00	0.00	*250.00 F	✓
2	2		*FRONT BONNET HINGE LH & RH	0.00	0.00	*40.00 F	✓
3	1		*FRONT BONNET EMBLEM	0.00	0.00	*25.00 F	✓
4	6		*FRONT BONNET CLIPS	0.00	0.00	*9.00 F	X
5	1		*FRONT BONNET INNER LOCK	0.00	0.00	*48.00 F	✓
6	1		*FRONT GRILLE INNER	0.00	0.00	*165.00 F	✓
7	1		*FRONT GRILLE TOP	0.00	0.00	*75.00 F	✓
8	1		*FRONT GRILLE LOWER	0.00	0.00	*125.00 F	✓
9	10		*FRONT GRILLE CLIPS	0.00	0.00	*15.00 F	✓
10	1		*CORNER PANEL LH	0.00	0.00	*55.00 F	✓
11	2		*HEADLAMP LH & RH	0.00	0.00	*440.00 F	✓
12	2		*HEADLAMP CLIPS	0.00	0.00	*24.00 F	✓
13	1		*FRONT BUMPER	0.00	0.00	*180.00 F	✓
14	2		*FRONT BUMPER SIDE RETAINER LH & RH	0.00	0.00	*90.00 F	✓
15	10		*FRONT BUMPER CLIPS	0.00	0.00	*15.00 F	✓
16	1		*FRONT BUMPER TOW COVER	0.00	0.00	*15.00 F	✓
17	1		*FRONT BUMPER REINFORCEMENT TOP	0.00	0.00	*75.00 F	✓
18	1		*FRONT BUMPER REINFORCEMENT LOWER	0.00	0.00	*105.00 F	✓
19	2		*FRONT BUMPER REINFORCEMENT LOWER BRACKET LH & RH	0.00	0.00	*110.00 F	✓
20	2		*FOGLAMP COVER LH & RH	0.00	0.00	*70.00 F	X
21	1		*WIPER WASHER TANK	0.00	0.00	*35.00 F	✓
22	1		*WIPER WASHER MOTOR	0.00	0.00	*70.00 F	✓
23	1		*WIPER WASHER TANK CAP	0.00	0.00	*15.00 F	X
24	1		*AIR CON CONDENSER	0.00	0.00	*480.00 F	✓
25	1		*RADIATOR ASSY	0.00	0.00	*580.00 F	✓
26	1		*RADIATOR SUPPORT PANEL	0.00	0.00	*160.00 F	✓
27	1		*BRACE PANEL	0.00	0.00	*40.00 F	✓
28	1		*FRONT DOOR COMPANY STICKER LH	0.00	0.00	*35.00 FS	✓
29	1		*NUMBER PLATE	0.00	0.00	*35.00 FS	✓
30	1		*RADIATOR COOLANT	0.00	0.00	*30.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (S\$) **3,411.00**+ Margin on L,N Items 15.00% (S\$) **496.65**Total Parts (S\$) **3,907.65**

Ah Lim Motor Company/GBD1333M/18/01/2018 11:26. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00
2		New	100.00

Ah Lim Motor Company/GBD1333M/18/01/2018 11:26. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		650
3	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD CORNER PANEL LH;RADIATOR SUPPORT PANEL.TO KNOCK & REPAIR FRONT DOOR LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00
4	TO SPRAY FRONT BONNET;FRONT GRILLE;CORNER PANEL LH;FRONT DOOR LH.	New	800.00
Gross Labour Cost (S\$)			1,740.00

Ah Lim Motor Company/GBD1333M/18/01/2018 11:26. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jan 2018)

Parts: 213 TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/GBD1333M/26/01/2018 11:08

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RADIATOR COWLING	CM 0.00	0.00	*105.00 F
2	1		*BUMPER LOWER CENTRE GRILLE	CM 0.00	0.00	*65.00 F
3	1		*BUMPER DASH PANEL BRACKET	0.00	0.00	Az *190.00 F
4	1		*STEP GARNISH LH	0.00	0.00	CM *50.00 F
5	4		*STEP GARNISH CLIPS	0.00	0.00	me *6.00 F
6	1		*WIPER SIDE GARNISH LH	0.00	0.00	m/*10.00 F
7	1		*BONNET SIDE COVER LH	0.00	0.00	CM *12.00 F

F=Franchise part.

Sub Total (S\$) 438.00

+ Margin on L,N Items 15.00% (S\$) 65.70

Total Parts (S\$) 503.70

Ah Lim Motor Company/GBD1333M/26/01/2018 11:08. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Ah Lim Motor Company/GBD1333M/26/01/2018 11:08. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Kerry
26/1/18

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A

#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg

GST Reg No: M9-0009639-E

INSURER:

EQ Insurance Company Ltd (HQ)

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCPHQ17-003117	Date of Loss:	15/01/2018
Vehicle Reg. No.:	GBD1333M	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MULTI IMAGE PTE LTD	Contact No:	+6591902124
Driver:	MUHAMMAD KHAIRIL BIN AHMAD SAYUTI		
Make/Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Vehicle Reg. Date:	24/06/2014
Vehicle Colour:	SILVER	Chassis No:	JTFHT02P600142980
Engine No:	1KD2413007		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7-6 days		
Description of Accident/Loss	REFER TO THE SKETCH PLAN BY DRIVER		
Remarks:	CAR NOT IN - TO BE ARRANGE		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS

	Amount
Parts	3,907.65
Miscellaneous Items	0.00
Labour	1,740.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,647.65
+ GST 7.00% (S\$)	395.34
Nett Amount (S\$)	6,042.99

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Jan 2018)

Parts: 213 TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/GBD1333M/18/01/2018 11:26

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	0.00	0.00	*250.00 F	✓
2	2		*FRONT BONNET HINGE LH & RH	0.00	0.00	*40.00 F	?
3	1		*FRONT BONNET EMBLEM	0.00	0.00	*25.00 F	✓
4	6		*FRONT BONNET CLIPS	0.00	0.00	*9.00 F	X
5	1		*FRONT BONNET INNER LOCK	0.00	0.00	*48.00 F	?
6	1		*FRONT GRILLE INNER	0.00	0.00	*165.00 F	✓
7	1		*FRONT GRILLE TOP	0.00	0.00	*75.00 F	✓
8	1		*FRONT GRILLE LOWER	0.00	0.00	*125.00 F	✓
9	10		*FRONT GRILLE CLIPS	0.00	0.00	*15.00 F	✓
10	1		*CORNER PANEL LH	0.00	0.00	*55.00 F	✓
11	2		*HEADLAMP LH & RH	0.00	0.00	*440.00 F	✓
12	2		*HEADLAMP CLIPS	0.00	0.00	*24.00 F	✓
13	1		*FRONT BUMPER	0.00	0.00	*180.00 F	✓
14	2		*FRONT BUMPER SIDE RETAINER LH & RH	0.00	0.00	*90.00 F	4
15	10		*FRONT BUMPER CLIPS	0.00	0.00	*15.00 F	✓
16	1		*FRONT BUMPER TOW COVER	0.00	0.00	*15.00 F	✓
17	1		*FRONT BUMPER REINFORCEMENT TOP	0.00	0.00	*75.00 F	2
18	1		*FRONT BUMPER REINFORCEMENT LOWER	0.00	0.00	*105.00 F	?
19	2		*FRONT BUMPER REINFORCEMENT LOWER BRACKET LH & RH	0.00	0.00	*110.00 F	4
20	2		*FOGLAMP COVER LH & RH	0.00	0.00	*70.00 F	X
21	1		*WIPER WASHER TANK	0.00	0.00	*35.00 F	✓
22	1		*WIPER WASHER MOTOR	0.00	0.00	*70.00 F	?
23	1		*WIPER WASHER TANK CAP	0.00	0.00	*15.00 F	X
24	1		*AIR CON CONDENSER	0.00	0.00	*480.00 F	✓
25	1		*RADIATOR ASSY	0.00	0.00	*580.00 F	✓
26	1		*RADIATOR SUPPORT PANEL	0.00	0.00	*160.00 F	✓
27	1		*BRACE PANEL	0.00	0.00	*40.00 F	?
28	1		*FRONT DOOR COMPANY STICKER LH	0.00	0.00	*35.00 FS	✓
29	1		*NUMBER PLATE	0.00	0.00	*35.00 FS	✓
30	1		*RADIATOR COOLANT	0.00	0.00	*30.00 FS	✓

F=Franchise part. S=SpcNett

Sub Total (\$\$) **3,411.00**

+ Margin on L,N Items 15.00% (\$\$) **496.65**

Total Parts (\$\$) **3,907.65**

Ah Lim Motor Company/GBD1333M/18/01/2018 11:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00
2		New	100.00

Ah Lim Motor Company/GBD1333M/18/01/2018 11:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		650
3	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD CORNER PANEL LH;RADIATOR SUPPORT PANEL.TO KNOCK & REPAIR FRONT DOOR LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00
4	TO SPRAY FRONT BONNET;FRONT GRILLE;CORNER PANEL LH;FRONT DOOR LH.	New	800.00
Gross Labour Cost (S\$)			1,740.00

Ah Lim Motor Company/GBD1333M/18/01/2018 11:26. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110
TEL: 62239433 FAX: 62234190
ATTN: Motor Claim Department

Claim No: MC0912777
Ref No: MF0910887
Date: 07 Mar 2018
Policy No: DMCPHQ17-003117
Veh Reg No: GBD1333M
Make/Model: TOYOTA HIACE VAN
TURBO 5 DR

Your Ref No: GBD1333M
Claim Type: Own Damage
Accident Date: 15/01/2018

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):GBD1333M

Description	U/Price	Quantity	Cost SS	Amount SS
SPARE PARTS				
1 FRONT BONNET		1 PC	250.00	
2 FRONT BONNET EMBLEM		1 PC	25.00	
3 FRONT GRILLE INNER		1 PC	165.00	
4 FRONT GRILLE TOP		1 PC	75.00	
5 FRONT GRILLE LOWER		1 PC	125.00	
6 FRONT GRILLE CLIPS		10 PC	15.00	
7 CORNER PANEL LH		1 PC	55.00	
8 HEADLAMP LH & RH		2 PC	440.00	
9 HEADLAMP CLIPS		2 PC	24.00	
10 FRONT BUMPER		1 PC	180.00	
11 FRONT BUMPER SIDE RETAINER LH		1 PC	45.00	
12 FRONT BUMPER CLIPS		10 PC	15.00	
13 FRONT BUMPER TOW COVER		1 PC	12.00	
14 FRONT BUMPER REINFORCEMENT TOP		1 PC	75.00	
15 FRONT BUMPER REINFORCEMENT LOWER BRACKET LH		1 PC	30.00	
16 WIPER WASHER TANK		1 PC	35.00	
17 AIR CON CONDENSER		1 PC	480.00	
18 RADIATOR ASSY		1 PC	580.00	
19 RADIATOR SUPPORT PANEL		1 PC	160.00	
20 RADIATOR COWLING		1 PC	105.00	
21 BUMPER LOWER CENTRE GRILLE		1 PC	65.00	
22 BUMPER DASH PANEL BRACKET		1 PC	190.00	
23 STEP GARNISH LH		1 PC	50.00	
24 STEP GARNISH CLIPS X 4		4 PC	6.00	
25 WIPER SIDE GARNISH LH		1 PC	10.00	
26 BONNET SIDE COVER LH		1 PC	12.00	
			3,224.00	
	Add 15%		483.60	3,707.60
Special Nett				
27 FRONT DOOR COMPANY STICKER LH		1 PC	35.00	
28 NUMBER PLATE		1 PC	35.00	
29 RADIATOR COOLANT		1 PC	30.00	

LABOUR

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

100.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110
TEL: 62239433 FAX: 62234190
ATTN: Motor Claim Department

Claim No: MC0912777
Ref No: MF0910887
Date: 07 Mar 2018
Policy No: DMCPhQ17-003117
Veh Reg No: GBD1333M
Make/Model: TOYOTA HIACE VAN
TURBO 5 DR

Your Ref No: GBD1333M
Claim Type: Own Damage
Accident Date: 15/01/2018

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):GBD1333M

Description	U/Price	Quantity	Cost SS	Amount SS
30 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
31 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	
32 TO DISMANTLE ALL DAMAGED PARTS.T0 CUT & WELD CORNER PANEL LH,RADIATOR SUPPORT PANEL.T0 KNOCK & REPAIR FRONT DOOR LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	650.00	
33 TO SPRAY FRONT BONNET,FRONT GRILLE,CORNER PANEL LH,FRONT DOOR LH.		1 PC	680.00	
				1,450.00

Amount Before Excess	SS 5,257.60
Less Excess	SS 500.00
Amount Before GST	SS 4,757.60
Add GST @ 7%	333.03
Total Amount payable	SS 5,090.63

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINETY AND CENTS SIXTY THREE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 23/01/2018

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
10 Ang Mo Kio Industrial Park 2A
Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047
Tel: 6483 1244 Fax: 6483 6170 Email: ahlmmc@singnet.com.sg
GST Reg No: M9-0009639-E

INSURER: EQ Insurance Company Ltd (HQ)

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCPHQ17-003117	Date of Loss:	15/01/2018
Vehicle Reg. No.:	GBD1333M	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MULTI IMAGE PTE LTD	Contact No:	+6591902124
Driver:	MUHAMMAD KHAIRIL BIN AHMAD SAYUTI		
Make/Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Vehicle Reg. Date:	24/06/2014
Vehicle Colour:	SILVER	Chassis No:	JTFHT02P600142980
Engine No:	1KD2413007		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7-6 days		
Description of Accident/Loss	REFER TO THE SKETCH PLAN BY DRIVER		
Remarks:	CAR NOT IN - TO BE ARRANGE		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS

	Amount
Parts	3,907.65
Miscellaneous Items	0.00
Labour	1,740.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,647.65
+ GST 7.00% (S\$)	395.34
Nett Amount (S\$)	6,042.99

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System