

ASS. REG. B21

REP: cs/fci18001190 / Kld3n2

ASSIGNMENT (Office)

CWS

Kenneth

From (Person): Joanne Yong

of FCI

Date/Time: 5.45pm @ 18/11/2018

Estimated Cost: Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJY 9971M

Insured: SHA 7057R

at Workshop no: 10H Hong

Tel: 90111 432

of 176 Sin Ming Drive #03-08

Policy No: Claim No: D18000560MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 16/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

MOD Estimated

Date/Time: 9.15am @ 19/11/18 Person Contacted: Danny

Vehicle IN OUT

Date/Time: Action/Inspection ☒ Estimate

SJY 9971M-X

SHA 7057R-CC3/LCR17019046/K1zb3q2

D.O.A: 30/09/2017

26/11- Revert prior advise.

8/2 11 Sy 827501 email & confirm (Red: 2539.40:48%.)

ASS. REC. BY:

REF: FC21Hennerh

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☒ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s Lab. Henry

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STY 9971 Yr Regn: 10, 10Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: NIS Sylphy c.c. 1498Colour: M. Grey A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 232012 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: JN1BAA G11.7 0111 & 02Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 205/55R16R: FalkenBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 16/1/18

Rear

R/Bal. 3 mmL/Bal. 3 mmD.O.A. 23/1/18

Survey held at _____

Des. of Damages: ☒ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/1 File pass to Catherine.

RECEIVED 10 FEB 2018

Date/Time, File Pass to?

13/2 Typst

Date/Time, File Return to?

Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$)

2450/-1405050+5020310

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	18-01-2018	Our Ref No. D18000560MFSH
Accident Date	16-01-2018	Claim Type. Third Party
Insured Vehicle	SHA7057R	Third Party Vehicle. SJY9971M
Survey Location	176 SIN MING DRIVE #03-08 SIN MING AUTO CARE	
Contact Person.	DANNY	
Contact No.	64532237/ 90111432	Fax No. 64556384
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LOH HENG	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001190/Ktd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7057R	Veh. Inspected	SJY 9971M
Policy No.		Coverage (\$)	0.00
Claim No.	D18000560MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	19/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/01/2018	Inspection Date	
Survey held at	LOH HENG BLK 176 #03-08 SIN MING DRIVE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 25 January 2018 5:54 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG;
JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000560MFSH/1
Attachments: PRELI ADVISED SJY 9971M.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJY 9971M**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 19 January 2018 9:19 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
<sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000560MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 18 January 2018 5:43 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000560MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

LOH HENG

Automotive Repair Services
Accident Insurance Claims

20 Jan 2018

First Capital Insurance Pte Ltd

Singapore

Attn. : Motor Claim Department

Re : Estimated Quotation

Vehicle No. : SJY 9971 M

Not Authorised
Loh Heng 827501
Resurvey After Paint
Ydg

S/N	Description	Amount (\$)
Parts Replacement		
	Front Bumper	\$ 769.20
	Front right mudguard	\$ 687.90
	front headlamp	\$ 743.10
	Wheel cowling	\$ 176.80
	Headlamp bracket	\$ 29.90
	Top panel garnish	\$ 472.40
	Bumper lower spoiler	\$ 839.50
	Front right shock Absorber	\$ 497.20
	Above are nett items	
		\$ 4,216.00
	less 10% <i>30%</i>	\$ 3,749.40
Labour Charges		
	To remove and replace new parts. Panel beating and knock out left pillar.	\$ 580.00
	To rustproofing and seal joints on the affected area.	\$ 80.00
	Adjust front wheel alignment	\$ 80.00
	To putty and spray paint on the affected area.	\$ 800.00
	Total:	\$ 5,289.40

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Block 176 #03-08 Sin Ming Autocare

Sin Ming Drive

Singapore 575721

Tel : 64532237 / 64530797

Fax : 64556384

5334.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001190/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7057R	Veh. Inspected	SJY 9971M	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18000560MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	18/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JN1BAAG11Z0111402	Colour	METALLIC GREY	
Odometer	232012	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	TOYO	7 mm	
L/H Front Tyre	205/55 R16	TOYO	7 mm	
R/H Rear Tyre	205/55 R16	FALKEN	3 mm	
L/H Rear Tyre	205/55 R16	FALKEN	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/01/2018	Inspection Date	23/01/2018	
Survey held at	LOH HENG BLK 176 #03-08 SIN MING DRIVE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC1801866
INV Date 14/02/2018
Reference CS/FCI18001190/Ktd3n2
Code FCI2

**PROFESSIONAL SERVICE FEE**

Vehicle No. SJY 9971M
Insured Veh. SHA 7057R
Claim No. D18000560MFSH
Policy No. D-18088936MFSH
Accident Date 16/01/2018
Inspection Date 23/01/2018

Description	Total
Survey Inspection	310.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	310.00
GST (7%)	21.70
Grand Total	331.70

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 9971M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	769.20	769.20
1	FRONT RIGHT MUDGUARD	BENT	687.90	687.90
1	FRONT HEADLAMP	CUT	743.10	743.10
1	WHEEL COWLING	CRACKED	176.80	176.80
1	HEADLAMP BRAKET	SERVICEABLE	29.90	-
1	TOP PANEL GARNISH	CRACKED	472.40	472.40
1	BUMPER LOWER SPOILER	TO REPAIR SEE LABOUR	839.50	-
1	FRONT RIGHT SHOCK ABSORBER	BENT	497.20	497.20
	LESS 10% DISCOUNT		-421.60	-
	LESS 30% DISCOUNT		-	-1,003.98
			3,794.40	2,342.62
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE NEW PARTS. PANEL BEATING AND KNOCK OUT LEFT PILLAR. INCLUSIVE OF THE REPAIR OF BUMPER LOWER SPOILER.		580.00	450.00
	TO RUSTPROOFING AND SEAL JOINT ON THE AFFECTED AREA.		80.00	30.00
	ADJUST FRONT WHEEL ALIGNMENT.		80.00	60.00
	TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREA.		800.00	600.00
			1,540.00	1,140.00
	GRAND TOTAL		5,334.40	3,482.62
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,750.00

Report Ref No. CS/FC118001190/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.