

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD341A - AXA

AAD1801-199

Not Authored
Recovery B4 part **83073.5P**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD341A - JHOW

VF1ABL15AUC282722

RENAULT

LATITUDE

17.01.2018

AXA**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>nut</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	✓
10	1	BUMPER BEAM REAR	\$	<i>Bu</i> 777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95	X
13	1	BOOT REAR	\$	<i>N</i> 2,872.68	} X
14	1	BOOT FINISHER	\$	<i>Sn</i> 470.06	
15	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	
16	1	BOOT REFLECTOR LAMP LH	\$	<i>N/C (CM)</i> 493.35	
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	
18	1	BOOT BADGE 'RENAULT'	\$	<i>N</i> 225.36	
19	1	BOOT BADGE	\$	<i>N</i> 225.36	
20	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08	
21	1	BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1	BOOT HINGE LH	\$	<i>N</i> 367.84	
23	1	BOOT HINGE RH	\$	<i>N</i> 367.84	
24	1	BOOT INNER TRIM	\$	<i>Sn</i> 586.45	
25	1	BOOT SWITCH	\$	<i>Sn</i> 168.13	
26	1	BOOT LOCK	\$	<i>N</i> 202.67	
27	1	BOOT LOCK CATCH	\$	<i>N</i> 74.40	
28	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
29	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45	
31	1	FENDER PANEL REAR LH	\$	<i>N</i> 3,299.13	
32	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47	
33	1	FENDER PANEL REAR RH	\$	<i>N</i> 3,299.13	
34	1	TAILLAMP LH	\$	<i>Sn</i> 552.55	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-199**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD341A -

35	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70 <i>X</i>
36	1	OUTER PANEL REAR (End Panel)	\$	<i>N</i> 1,471.77 <i>X</i>
37	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>P</i> 404.56 <i>X</i>

TOTAL	\$	22,593.14
10%	\$	2,259.31
	\$	20,333.82

Specical Nett

1	1SET	PARKING AID	\$	<i>P</i> 700.00 <i>X</i>
2	1SET	REAR BUMPER CLIP	\$	<i>N</i> 66.00 <i>—</i>
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>N</i> 33.00 <i>—</i>
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>N</i> 10.00 <i>X</i>
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>N</i> 20.00 <i>X</i>
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>N</i> 10.00 <i>X</i>
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>N</i> 20.00 <i>X</i>
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>N</i> 22.00 <i>X</i>
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>N</i> 66.00 <i>—</i>
10	1SET	BOOT FINISHER CLIP	\$	<i>N</i> 24.20 <i>—</i>
11	1	BOOT STICKER "Trans-cab"	\$	<i>N</i> 30.00 <i>—</i>
12	1	BOOT STICKER "6555-3333"	\$	<i>N</i> 30.00 <i>—</i>
13	1	BOOT INNER TRIM CLIP	\$	<i>N</i> 45.00 <i>—</i>
14	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>N</i> 35.00 <i>—</i>
15	1	FENDER INNER TRIM CLIP LH	\$	<i>N</i> 28.00 <i>—</i>
16	1	TAILLAMP CLIP LH	\$	<i>N</i> 5.00 <i>—</i>
17	2	REAR WINDSCREEN SELANT	\$	<i>N</i> 80.00 <i>—</i>
18	1	WINDSCREEN MOULDING	\$	<i>P</i> 100.00 <i>—</i>
19	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>N</i> 100.00 <i>—</i>
20	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>P</i> 385.00 <i>—</i>
21	1	SPARE TYRE	\$	<i>P</i> 330.00 <i>—</i>

TOTAL	\$	2,139.20
TOTAL PARTS	\$	22,473.02

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 *2201*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,800.00 *2001*

To Rust-Proofing Of The Affected Areas.

\$ *N* 170.00 *X*

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-199**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD341A -

To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
Towing Fees	\$	<i>nn</i> 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X

TOTAL \$ 7,710.00**Over All Total \$ 30,183.02****(PARTS BY PARTS)****Repair Days****~~10~~Days***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: