

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6152M

DATE 17/1/2018 16:58

MAKE :

MODEL : HYUNDAI i40

PbyP
AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Retainer Mounting ?			\$ 9.20
	Front Fender (RH) ✓			\$ 619.00
	Front Fender Shield (RH) ✓			\$ 169.80
	Front Fender Retainer ✓			\$ 9.20
	SUB TOTAL			\$ 1,391.90
	LESS 20%			\$ 278.38
	DISCOUNTED TOTAL			\$ 1,113.52
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00 300
	Spray Painting Charge			\$ 400.00 360
	Tuff Kote			\$ 50.00 20
	TOTAL LABOUR			\$ 1,010.00
	ESTIMATE TOTAL			\$ 2,223.52

Kalvin 16/1/18
 19/1/18 10/10hrs.
 2 Days
 P/P
 Before Point photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No litigation, arbitration is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.