

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore (068811)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6338 7288 Fax : 6880 4838

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SFY7488C

MODEL : TOYOTA ALTIS

POLICY NO : GA190185/1

CHASSIS NO : MR053ZEC107096719

ENGINE NO : 3ZZ4502291

DATE / TIME OF ACCIDENT: 16/01/2018 Time: 0750Hrs ALONG EXITING KJE (PIE-TUAS)

THIRD PARTY VEHICLE NO: GV6767H

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 19/01/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Front Bumper	1	331.00	Not used	331.00
2 Front Bumper Side Retainer LH	1	50.00	Not used	50.00
3 Front Bumper Side Retainer RH	1	50.00	Not used	50.00
4 Front Bumper Upper Grille with Chrome	1	271.00		271.00
5 Front Bumper Emblem	1	45.00		45.00
6 Front Bumper Reinforcement	1	345.00		345.00
7 Headlamp LH	1	389.00		389.00
8 Headlamp RH	1	389.00		389.00
Sub-Total:				1,870.00
Parts Discount 25%				467.50
Total Parts:				1,402.50

Special Nett Items

1 Anti-rust coating	1	80.00	Not used	80.00
2 Front Bumper Clips	10	5.50	Not used	55.00
3 Front Number Plate With Casing	1	50.00	Not used	50.00
Total Parts:				185.00

Labour Charges For Front and Rear Side Portion

1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	250	600.00
2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	220	600.00
3 Provide skill labour to disconnect and check electrical wiring	150	80.00
Total Labour:		1,280.00
Total Parts & Labour:		2,867.50
GST 7%		200.73
Grand Total:		3,068.23

Estimate Repair Duration

7 days

2 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Kenneth
Company : LK/c
Date : 26/1/18
Time : 10.10am
Contact No: 96910663
Email : _____